WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Document Nun	nber Override	Э				,			g Officer/Deputy A. WILCOX		
Crash Date 01/20/2024			Crash Time 12:34 PM		Date Arrived 01/20/2024		Time Arrived 12:50 PM				
01/20/2024 Date Notified 01/20/2024 On Emer Gov			Time Notified 12:42 PM		Total Ur	nits	Total Injure	ed	Total Kille	d	
On Emer	gency	Hit	and Run	Lane Closu	ure	Work Zone	Traile	r or 1	Towed	Reporting Threshold	
Gov Pr	ernment		Active So	chool Zone	School NO	Bus Related	Tags				
Reportal			Crash Type DT4000 (STA	ANDARD CRASH	1)		Amen	ded		Secondary Crash	
Description	n 💻										
Diagram 01									construction	Ву	
								Add	ditional Infor	mation	
			ole slid of								
						any CJIS data in t		ACCID	ENT LIPON	MY ARRIVAL I	
OBSERVED TH SHE OBSERVE UNIT 1'S OPER	E ROADWAY D THE TRUC ATOR STATI	Y TO BE CK AHEA ED THAT	ICY AND SNOW D OF HER SLID AS SHE TRIED	/-COVERED. UNIT 1 E OFF INTO THE DI TO PULL OUT THE	WAS ALF TCH. UNI TRUCK, I	READY PULLED OUT O	F THE DITCH WH D SHE STOPPED DITCH, CAUSING	EN I A AND UNIT	RRIVED. UN TRIED TO P 1 TO GET S	NIT 1 OPERATOR STATED ULL OUT THE TRUCK.	

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 01/20/2024

Crash Time 12:34 PM

L	OC	ation								
F	ON	ISHNALA RD			Latitud	de		Longitu	de	
	1110 FT S					43.579557847		-89.797187762		
	OF ALCAN DR IN THE TOWN OF DELTON IN SAUK COUNTY					X Coordinate 274155.78125		Y Coordinate 4828979		
						Structure Type				
				TRUCTURE						
C) Cra	sh Scene								
Τ	First	Harmful Event			First H	Harmful Event I	_ocation			
	DIT	СН	ON R	ROADWAY						
F	Manı	ner of Collision	Light (Condition						
						LIGHT				
H	Road	d Surface Condition(s)	Roady	way Factor(s)						
	ICE	` ,				, ,,				
ŀ	Envir	ronment Factor(s)								
	NON	NE			ROA ETC)		CONDITION	(WET, IC	CY, SNOW, SLUSH,	
}	Wea	ther Condition(s)								
	CLE	()								
-	Anim	nal Type			Relati	on To Trafficwa	ау			
L						FFICWAY - C				
		sh Classification - Location			_	Crash Classification - Jurisdiction				
	PUBLIC PROPERTY Tribal Land					NO SPECIAL JURISDICTION Access Control Special Study				
						Access Control Special Study NO CONTROL				
		in Interchange Area					· ·			
L	NO		NON-JUNCTION		NOT AN INTER	RSECTION				
ι	Jnit	t Summary 💳			J					
		t Summary Status		Vehicle Ope	erating As Classifica	ation	Unit Type			
	Unit			Vehicle Ope	erating As Classifica	ation	Unit Type TRUCK			
	Unit :	Status			erating As Classifica	ation		s Endorse	ements	
_	Unit IN T Vehic	Status RANSIT	TRUCK		erating As Classifica	ation	TRUCK	s Endorse	rments	
;	Unit IN T Vehic UTIL	Status *RANSIT cle Type	TRUCK Train/Bus # Recorded	D CLASS	erating As Classifica	ation Total Tra	TRUCK Operating As		ements zMat Types	
;	Unit IN T Vehic UTIL	Status RANSIT ICLE Type LITY TRUCK/PICKUP		D CLASS	-		TRUCK Operating As			
;	Unit in the second of the seco	Status RANSIT ICLE Type LITY TRUCK/PICKUP		D CLASS Total # Cita 0	-	Total Tra	TRUCK Operating As	Total Haz	zMat Types	
;	Unit: IN T Vehic UTII Total 1 Insur YES	Status RANSIT cle Type LITY TRUCK/PICKUP I Occs rance?	Train/Bus # Recorded Direction Of Travel SOUTHBOUND	Total # Cita 0 Pre	tions Issued CrashTire Mark	Total Tra	TRUCK Operating As illers	Total Haz 0 Total Lar 2	zMat Types nes	
	Unit: IN T Vehic UTII Total 1 Insur YES	Status RANSIT cle Type LITY TRUCK/PICKUP I Occs rance? S t Harmful Event: Collision 1	Train/Bus # Recorded Direction Of Travel SOUTHBOUND	Total # Cita 0 Pre Special Fur	tions Issued CrashTire Mark	Total Tra 0 Speed Li	TRUCK Operating As illers mit Emergency I	Total Haz 0 Total Lar 2 Motor Veh	zMat Types nes nicle Use	
	Unit: IN T Vehic UTII Total 1 Insur YES Most DIT(Status RANSIT cle Type LITY TRUCK/PICKUP I Occs rance? St Harmful Event: Collision of the collision of	Train/Bus # Recorded Direction Of Travel SOUTHBOUND	Total # Cita 0 Pre Special Fur NO SPEC	crashTire Mark	Total Tra 0 Speed Li	TRUCK Operating As ilers mit Emergency I	Total Haz 0 Total Lar 2 Motor Veh	zMat Types nes nicle Use	
	Unit : IN T Vehice UTII Total 1 Insur YES Most DIT(Status RANSIT cle Type LITY TRUCK/PICKUP I Occs rance? St Harmful Event: Collision of the Collision of	Train/Bus # Recorded Direction Of Travel SOUTHBOUND With	Total # Cita 0 Pre Special Fur NO SPEC	tions Issued CrashTire Mark iction CIAL FUNCTION	Total Tra 0 Speed Li	TRUCK Operating As illers mit Emergency I NOT APPL Traffic Contr	Total Haz 0 Total Lar 2 Motor Veh	zMat Types nes nicle Use	
-	Unit : IN T Vehice UTII Total Insur YES Most DIT(Traff	Status RANSIT cle Type LITY TRUCK/PICKUP I Occs rance? St Harmful Event: Collision of the Collision of	Train/Bus # Recorded Direction Of Travel SOUTHBOUND With	Total # Cita 0 Pre Special Fur NO SPEC Traffic Cont	tions Issued CrashTire Mark action HAL FUNCTION arol	Total Tra 0 Speed Li	TRUCK Operating As illers mit Emergency I NOT APPL Traffic Contr	Total Haz 0 Total Lan 2 Motor Veh ICABLE	zMat Types nes nicle Use	
-	Unit : IN T Vehic UTII Total Insur YES Most DITC Traff TWC	Status TRANSIT ICID Type LITY TRUCK/PICKUP I Occs Trance? St Harmful Event: Collision of the collision	Train/Bus # Recorded Direction Of Travel SOUTHBOUND With	D CLASS Total # Cita 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva	tions Issued CrashTire Mark action EIAL FUNCTION EROL	Total Tra 0 Speed Li	TRUCK Operating As illers mit Emergency I NOT APPL Traffic Contr NO Road Grade	Total Haz 0 Total Lan 2 Motor Veh ICABLE	zMat Types nes nicle Use	
	Unit: IN T Vehic UTII Total 1 Insur YES Most DIT(Traff TW(Surfa	Status RANSIT cle Type LITY TRUCK/PICKUP I Occs rance? St Harmful Event: Collision of the Collision of	Train/Bus # Recorded Direction Of Travel SOUTHBOUND With	Total # Cita 0 Pre Special Fur NO SPEC Traffic Cont	tions Issued CrashTire Mark action EIAL FUNCTION EROL	Total Tra 0 Speed Li	TRUCK Operating As illers mit Emergency I NOT APPL Traffic Contr	Total Haz 0 Total Lan 2 Motor Veh ICABLE	zMat Types nes nicle Use	
	Unit IN T Vehic UTII Total 1 Insur YES Most DITC Traff TWC Surfa BLA Trucl NO	Status RANSIT cle Type LITY TRUCK/PICKUP I Occs rance? St Harmful Event: Collision of the collision of t	Train/Bus # Recorded Direction Of Travel SOUTHBOUND With	D CLASS Total # Cita 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva	tions Issued CrashTire Mark action EIAL FUNCTION EROL	Total Tra 0 Speed Li	TRUCK Operating As illers mit Emergency I NOT APPL Traffic Contr NO Road Grade	Total Haz 0 Total Lan 2 Motor Veh ICABLE	zMat Types nes nicle Use	
	Unit IN T Vehic UTII Total 1 Insur YES Most DITC Traff TWC Surfa BLA Trucl NO	Status RANSIT cle Type LITY TRUCK/PICKUP I Occs rance? St Harmful Event: Collision of the collision of	Train/Bus # Recorded Direction Of Travel SOUTHBOUND With	Total # Cita 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva STRAIGH	tions Issued CrashTire Mark action EIAL FUNCTION ETGI ETGI TROL ature T	Total Tra 0 Speed Li 55	TRUCK Operating As illers mit Emergency I NOT APPL Traffic Contr NO Road Grade LEVEL	Total Haz 0 Total Lar 2 Motor Veh IICABLE	zMat Types nes nicle Use	
	Unit IN T Vehic UTII Total 1 Insur YES Most DITC Traff TWC Surfa BLA Trucl NO	Status RANSIT cle Type LITY TRUCK/PICKUP I Occs rance? St Harmful Event: Collision of the collision of	Train/Bus # Recorded Direction Of Travel SOUTHBOUND With	Total # Cita 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva STRAIGH	tions Issued CrashTire Mark action HAL FUNCTION Brol ROL ature T	Total Tra 0 Speed Li 55	TRUCK Operating As ilers mit Emergency I NOT APPL Traffic Contr NO Road Grade LEVEL Country of Iss	Total Haz 0 Total Lar 2 Motor Veh IICABLE ol Inopera	zMat Types nes nicle Use	
-	Unit IN T Vehic UTII Total 1 Insur YES Most DITC Traff TWC Surfa BLA Trucl NO	Status RANSIT cle Type LITY TRUCK/PICKUP I Occs rance? St Harmful Event: Collision of the collision of	Train/Bus # Recorded Direction Of Travel SOUTHBOUND With	Total # Cita 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva STRAIGH	tions Issued CrashTire Mark action EIAL FUNCTION ETGI ETGI TROL ature T	Total Tra 0 Speed Li 55	TRUCK Operating As illers mit Emergency I NOT APPL Traffic Contr NO Road Grade LEVEL	Total Haz 0 Total Lar 2 Motor Veh IICABLE ol Inopera	zMat Types nes nicle Use	
	Unit IN T Vehice UTIL Total 1 Insur YES Most DITC Traff TWC Surfa BLA Truc	Status RANSIT cle Type LITY TRUCK/PICKUP I Occs rance? St Harmful Event: Collision of the collision of	Train/Bus # Recorded Direction Of Travel SOUTHBOUND With S)	Total # Cita 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva STRAIGH Plate Type LTK - LIC Make	CrashTire Mark action BIAL FUNCTION BROL ature T	Total Tra 0 Speed Li 55	TRUCK Operating Asilers mit Emergency INOT APPL Traffic Contr NO Road Grade LEVEL Country of Iss UNITED ST Model	Total Haz 0 Total Lar 2 Motor Veh IICABLE ol Inopera	zMat Types nes nicle Use	
	Unit IN T Vehic UTII Total 1 Insur YES Most DITC Traff TWC Surfa BLA Trucl NO	Status RANSIT cle Type LITY TRUCK/PICKUP I Occs rance? St Harmful Event: Collision of the collision of	Train/Bus # Recorded Direction Of Travel SOUTHBOUND With S)	Total # Cita 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva STRAIGH Plate Type LTK - LIC Make GENERA	crashTire Mark Detion FIAL FUNCTION FROL Stature T SHT TRUCK SL MOTORS COR	Total Tra 0 Speed Li 55 St WI Year	TRUCK Operating As illers mit Emergency I NOT APPL Traffic Contr NO Road Grade LEVEL Country of Iss UNITED ST Model SIERRA	Total Haz 0 Total Lar 2 Motor Veh IICABLE ol Inopera	zMat Types nes nicle Use	
	Unit IN T Vehice UTIL Total 1 Insur YES Most DITC Traff TWC Surfa BLA Truc	Status RANSIT cle Type LITY TRUCK/PICKUP I Occs rance? St Harmful Event: Collision of the color CH fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS) k Bus or HazMat Vehicle License Plate Number UM4970 Vehicle Identification Nur 1GT12TEY0JF10116- Color	Train/Bus # Recorded Direction Of Travel SOUTHBOUND With S)	Total # Cita 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva STRAIGH Plate Type LTK - LIC Make GENERA Body Style	CrashTire Mark Detion FIAL FUNCTION FROL STATE SHT TRUCK SL MOTORS COR	Total Tra 0 Speed Li 55	TRUCK Operating Asilers mit Emergency INOT APPL Traffic Contr NO Road Grade LEVEL Country of Iss UNITED ST Model	Total Haz 0 Total Lar 2 Motor Veh IICABLE ol Inopera	zMat Types nes nicle Use	
	Unit IN T Vehice UTIL Total 1 Insur YES Most DITC Traff TWC Surfa BLA Truc	Status RANSIT cle Type LITY TRUCK/PICKUP I Occs rance? St Harmful Event: Collision of the color of the cle License Plate Number UM4970 Vehicle Identification Nur 1GT12TEY0JF10116 Color SIL - SILVER (ALUM)	Train/Bus # Recorded Direction Of Travel SOUTHBOUND With S)	Total # Cita 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva STRAIGH Plate Type LTK - LIC Make GENERA Body Style PK - PIC	CrashTire Mark Detion FIAL FUNCTION FROL STATE SHITT TRUCK SL MOTORS CORE KUP	Total Tra 0 Speed Li 55	TRUCK Operating As illers mit Emergency I NOT APPL Traffic Contr NO Road Grade LEVEL Country of Iss UNITED ST Model SIERRA	Total Haz 0 Total Lar 2 Motor Veh IICABLE ol Inopera	zMat Types nes nicle Use	
	Unit: IN T Vehic UTII Total 1 Insurr YES Most DITC Surfa BLA Trucl	Status RANSIT cle Type LITY TRUCK/PICKUP I Occs rance? St Harmful Event: Collision of the color of the	Train/Bus # Recorded Direction Of Travel SOUTHBOUND With S) mber 4 INUM)	Total # Cita 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva STRAIGH Plate Type LTK - LIC Make GENERA Body Style	CrashTire Mark Detion FIAL FUNCTION FROL STATE SHITT TRUCK SL MOTORS CORE KUP	Total Tra 0 Speed Li 55	TRUCK Operating As illers mit Emergency I NOT APPL Traffic Contr NO Road Grade LEVEL Country of Iss UNITED ST Model SIERRA	Total Haz 0 Total Lar 2 Motor Veh IICABLE ol Inopera	zMat Types nes nicle Use ative/Missing	
	Unit: IN T Vehic UTII Total 1 Insurr YES Most DITC Surfa BLA Trucl	Status RANSIT Cle Type LITY TRUCK/PICKUP I Occs rance? St Harmful Event: Collision of the collision of	Train/Bus # Recorded Direction Of Travel SOUTHBOUND With S) mber 4 INUM)	Total # Cita 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva STRAIGH Plate Type LTK - LIC Make GENERA Body Style PK - PICI Vehicle Da	CrashTire Mark Inction ITAL FUNCTION ITAL ITAL ITAL ITAL ITAL ITAL ITAL ITAL	Total Tra 0 Speed Li 55	TRUCK Operating As illers mit Emergency I NOT APPL Traffic Contr NO Road Grade LEVEL Country of Iss UNITED ST Model SIERRA	Total Haz 0 Total Lar 2 Motor Veh IICABLE ol Inopera	zMat Types nes nicle Use ative/Missing	
	Unit IN T Vehical Vehi	Status RANSIT cle Type LITY TRUCK/PICKUP I Occs rance? St Harmful Event: Collision of the color of the	Train/Bus # Recorded Direction Of Travel SOUTHBOUND With S) mber 4 INUM)	Total # Cita 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva STRAIGH Plate Type LTK - LIC Make GENERA Body Style PK - PICI Vehicle Da	CrashTire Mark Detion FIAL FUNCTION FROL STATE SHITT TRUCK SL MOTORS CORE KUP	Total Tra 0 Speed Li 55	TRUCK Operating As illers mit Emergency I NOT APPL Traffic Contr NO Road Grade LEVEL Country of Iss UNITED ST Model SIERRA	Total Haz 0 Total Lar 2 Motor Veh IICABLE ol Inopera	zMat Types nes nicle Use ative/Missing	

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 01/20/2024

Crash Time 12:34 PM

		Towed Due To Damage		Vel	nicle Removed By				
		NOT TOWED		PL	ATTS WRECKER				
		GOING STRAIGHT			Vehicle Factors				
					NOT APPLICABLE				
		Driver Actions							
	ш	NO CONTRIBUTING ACT	ION						
╘	VEHICLE								
LNO	Ĭ								
_	VE								
		Owner Name			Owner Address				
7	01	TONIA MCCOY (608) 393-5713			S1795 TOWN HAL REEDSBURG, WI				
0	0	(666) 666 61 16			ittees south, in t	, 20			
		0.5							
		Sequence Of Events Event							
	01	DITCH							
	02	Event							
		Event							
	03	LVOIN							
	04	Event							
_		Policy Holder							
LIND		Insurance Company		Ti	Individual				
5		USAA-CASUALTY-INS-C	0		TONIA MCCOY				
		Individual							
		Driver		1	Citations Issued	Sex			
	_	TONIA MCCOY)	FEMALE			
	JA	(608) 393-5713		ī	Date of Birth Race				
⊨	INDIVIDUAL					WHITE			
	\leq	Address		[Driver License Number				
_	Ä	S1795 TOWN HALL RD REEDSBURG, WI 53959	. US		STATE: WISCONSIN COUNTRY: UNITED STATES				
			,						
		On Duty	v Crash		Safety Equipment				
	Sat	ety Equipment	y Oldon	(Salety Equipment				
		Row	Seat Position	— ;	SHOULDER & LAP BELT				
		01 - FRONT ROW	07 - LEFT						
		Helmet Use	net Use		Helmet Compliance				
		Eye Protection			Tint Compliance				
_	Ξ	Injury Severity			Airbag				
2	00	<i>Injury</i> NO APPARENT INJURY			NON DEPLOYED				
		Ejected	Ejection Path		·		Trapped/Extricated		
		NOT EJECTED NOT EJECTED/NOT API					NOT TRAPPED		
		Medical Transport			EMS Agency Identifier		EMS Run #		
		NOT TRANSPORTED Hospital			Date of Death Time of Death				
					Salo oi Boalli		Time of Bodal		
		Distracted By NOT A	ted By Source	TRACT	ED)				
		Distracted By Action	,		•				
		NOT DISTRACTED							

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 01/20/2024

Crash Time 12:34 PM

		Non Motorist Striking Unit #	Location				
		Prior Action					
LIND	INDIVIDUAL	Action					
		Action Other					To/From School
	ı	Drug & Alcohol NO	ol Use	Suspected Drug Use NO			
		Alcohol Test Given TEST NOT GIVEN	Alcohol Test Type	е		Alcohol Test Results	
		Drug Test Given TEST NOT GIVEN	Drug Test Type		Drug Test Results	3	
2	001	Drug Type					
		Individual Condition					
		APPEARED NORMAL					