

6TL0C22Z0F
24-03090

WISCONSIN MOTOR VEHICLE
CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMENT
1300 LANGE COURT
BARABOO, WI 53913
(608) 356-4895

6TL0C22Z0F

Document Number Override		Primary Crash Document #		Agency Crash Number 24-03090		Investigating Officer/Deputy DEPUTY A. WILCOX	
Crash Date 03/29/2024		Crash Time 06:45 AM		Date Arrived 03/29/2024		Time Arrived 06:56 AM	
Date Notified 03/29/2024		Time Notified 06:47 AM		Total Units 01		Total Injured 00	Total Killed 00
<input type="checkbox"/> On Emergency		<input type="checkbox"/> Hit and Run		<input type="checkbox"/> Lane Closure		<input type="checkbox"/> Work Zone	
<input type="checkbox"/> Government Property		<input type="checkbox"/> Active School Zone		School Bus Related NO		Tags	
<input checked="" type="checkbox"/> Reportable		Crash Type DT4000 (STANDARD CRASH)		<input type="checkbox"/> Amended		<input type="checkbox"/> Secondary Crash	
<input type="checkbox"/> Trailer or Towed		<input type="checkbox"/> Reporting Threshold					

Description

Diagram		Reconstruction By	
		Photos By A. WILCOX	
		Additional Information PHOTOS	

I, a sworn law enforcement officer, agree that I have not added any CJIS data in this report.

ON 03/29/2024, I WAS DISPATCHED TO STH 60 AND WILLIAMS ROAD IN THE TOWN OF SPRING GREEN FOR A TRAFFIC ACCIDENT. UPON MY ARRIVAL, I OBSERVED UNIT ONE PULLED OVER ON THE SIDE OF THE ROADWAY WITH DAMAGE TO THE RIGHT REAR OF UNIT 1. UNIT 1 OPERATOR STATED SHE WAS TRAVELING W/B ON STH 60 WHEN A SEMI SWERVED INTO HER LANE. UNIT 1 OPERATOR STATED SHE WENT INTO THE GRAVEL PORTION OF THE ROADWAY TO AVOID HITTING THE SEMI. UNIT 1 OPERATOR STATED THE GRAVEL PULLED HER INTO THE DITCH WHERE SHE STRUCK A ROAD SIGN, CAUSING DAMAGE TO THE REAR RIGHT PORTION OF HER VEHICLE. THERE WAS NO DAMAGE TO THE ROAD SIGN. UNIT 1 OPERATOR WAS ABLE TO DRIVE FROM THE SCENE.

6TL0C22Z0F
24-03090

WISCONSIN MOTOR VEHICLE
CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMENT
1300 LANGE COURT
BARABOO, WI 53913
(608) 356-4895

Location

ON STH60 WB 372 FT W OF WILLIAMS RD IN THE TOWN OF TROY IN SAUK COUNTY	Latitude 43.201614355	Longitude -89.961576296
	X Coordinate 259390.671875	Y Coordinate 4787463
	Structure Type NO STRUCTURE	

Crash Scene

First Harmful Event DITCH	First Harmful Event Location ON ROADWAY	
Manner of Collision 00 - NO COLLISION W/VEHICLE IN TRANSPORT	Light Condition DAWN	
Road Surface Condition(s) DRY	Roadway Factor(s) NONE	
Environment Factor(s) NONE		
Weather Condition(s) CLEAR		
Animal Type	Relation To Trafficway TRAFFICWAY - ON ROAD	
Crash Classification - Location PUBLIC PROPERTY	Crash Classification - Jurisdiction NO SPECIAL JURISDICTION	
Tribal Land	Access Control NO CONTROL	Special Study
Within Interchange Area NO	Junction Location NON-JUNCTION	Intersection Type NOT AN INTERSECTION

Unit Summary

UNIT 01	Unit Status IN TRANSIT	Vehicle Operating As Classification D CLASS	Unit Type AUTOMOBILE		
	Vehicle Type (SPORT) UTILITY VEHICLE			Operating As Endorsements	
	Total Occs 1	Train/Bus # Recorded	Total # Citations Issued 0	Total Trailers 0	Total HazMat Types 0
	Insurance? YES	Direction Of Travel WESTBOUND	<input type="checkbox"/> Pre Crash Tire Mark	Speed Limit 55	Total Lanes 2
	Most Harmful Event: Collision With OTHER POST, POLE OR SUPPORT		Special Function NO SPECIAL FUNCTION	Emergency Motor Vehicle Use NOT APPLICABLE	
	Traffic Way TWO-WAY, NOT DIVIDED		Traffic Control NO CONTROL	Traffic Control Inoperative/Missing NO	
	Surface Type BLACKTOP (BITUMINOUS)		Road Curvature CURVE LEFT	Road Grade LEVEL	
	Truck Bus or HazMat NO				

Vehicle

UNIT 01 VEHICLE	License Plate Number 11190LE	Plate Type LEM - LAW ENFORCEME	St WI	Country of Issuance UNITED STATES
	Vehicle Identification Number KM8K5CA52KU250630	Make HYUNDAI	Year 2019	Model KONA
	Color RED - RED	Body Style UT - SPORT UTILITY VEHICLE		Bus Use
	Initial Contact Point 04 - RIGHT SIDE REAR	Vehicle Damage 04 - RIGHT SIDE REAR, 05 - RIGHT REAR CORNER		
	Extent Of Damage MINOR DAMAGE			



WISCONSIN MOTOR VEHICLE
CRASH REPORT

UNIT	Towed Due To Damage NOT TOWED		Vehicle Removed By OPERATOR		
	What Driver Was Doing NEGOTIATING CURVE		Vehicle Factors		
	Driver Prior Action Other		NOT APPLICABLE		
	Driver Actions NO CONTRIBUTING ACTION				
01	01	Owner Name BRIAN MIKULA (608) 316-5797		Owner Address 6545 CORTLAND PARK DR DEFOREST, WI 53532 , US	
		Sequence Of Events			
UNIT	01	Event DITCH			
		Event OTHER POST, POLE OR SUPPORT			
		Event			
		Event			
UNIT	Policy Holder				
	Insurance Company STATE-FARM-GENERAL-INS-CO		Individual ABIGAIL MIKULA		
UNIT	01	Individual			
		Driver ABIGAIL MIKULA (608) 316-5797		Citations Issued 0	Sex FEMALE
		Date of Birth		Race WHITE	
		Address 6545 CORTLAND PARK DR DEFOREST, WI 53532 , US		Driver License Number	
01	001	Safety Equipment		On Duty Crash	
		Row 01 - FRONT ROW		Seat Position 07 - LEFT	
		Safety Equipment SHOULDER & LAP BELT		Helmet Compliance	
		Helmet Use		Tint Compliance	
Eye Protection		Airbag NON DEPLOYED			
Injury		Injury Severity NO APPARENT INJURY		Airbag NON DEPLOYED	
Ejected NOT EJECTED		Ejection Path NOT EJECTED/NOT APPLICABLE		Trapped/Extricated NOT TRAPPED	
Medical Transport NOT TRANSPORTED		EMS Agency Identifier		EMS Run #	
Hospital		Date of Death		Time of Death	
Distracted By		Distracted By Source NOT APPLICABLE (NOT DISTRACTED)			
Distracted By Action NOT DISTRACTED					

WISCONSIN MOTOR VEHICLE
CRASH REPORT

UNIT	INDIVIDUAL	Non Motorist		Striking Unit #	Location	
		Prior Action				
	Action					
	Action Other				To/From School	
	Drug & Alcohol		Suspected Alcohol Use NO		Suspected Drug Use NO	
	Alcohol Test Given TEST NOT GIVEN		Alcohol Test Type		Alcohol Test Results	
	Drug Test Given TEST NOT GIVEN		Drug Test Type		Drug Test Results	
	Drug Type					
	Individual Condition		APPEARED NORMAL			
	01	001				