6TL0D6N05K

24-03183

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Document Number Override	Primary Crash	Document #	Agenc 24-03	y Crash Number 183		Officer/Deputy		
Crash Date 04/01/2024	Crash Time 05:00 AM		Date Arrived 04/01/2024		Time Arrived 07:55 AM			
Date Notified 04/01/2024	Time Notified 07:28 AM			Total Units 01		I Total Kill	эd	
On Emergency	lit and Run	Lane Clos		Work Zone	Trailer	or Towed	Reporting Threshold	
Government Property	Active S	chool Zone	School NO	Bus Related	Tags			
Reportable	Crash Type DT4000 (ST	ANDARD CRASH	H)		Ameno	led	Secondary Crash	
Description Diagram						Reconstructio	» Dv	
$\mathbf{\mathbf{Q}}$				01		Photos By CLAUER		
_				Plow	ed Field	Additional Info PHOTOS, B	ormation SODY CAMERA VIDEO	
Kraemer Ave		 Field Drive			\sim			
01))	Carlos Carlos				
		_						
				Not to Scale				
✔ I, a sworn law enforcen	nent officer, ag	ree that I have n	ot adde	d any CJIS data in th	is report.			
UNIT 1 WAS EAST ON KRAEMER CONTINUED INTO A PLOWED F/ SOUTH IN THE FIELD AND THEN	ARM FIELD THAT \	NAS SOFT. UNIT 1	CONTINU	JED NORTH IN THE FIELD	AND GOT STUC	For Approxin XK. Unit 1 ope	MATELY 30 YARDS. UNIT 1 RATOR TRIED TO BACK	

24-03183

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

	Loc	ation							
Ì		KRAEMER AVE			Latitu	lde		Longitu	de
		I MI E		43.282946115		-90.037558965			
		LEED PKWY	X Co	X Coordinate		Y Coord	linate		
	IN THE VILLAGE OF PLAIN IN SAUK COUNTY					253545.578125		47967	
	IN S	SAUK COUNTY	Struc	Structure Type					
(Cra	sh Scene							
1	First	Harmful Event			First	Harmful Event	ocation		
	DIT	СН				OUTSIDE RIGHT-OF-WAY (TRAFFICWAY)			
	Man	ner of Collision							
	00 -	NO COLLISION W/VE	HICLE IN TRANSPORT		0	RK/UNLIT			
	Road	d Surface Condition(s)			Road	way Factor(s)			
	DR۱					, ,			
	Envi	ronment Factor(s)							
	NO	NE			NOM	IE			
	Wea	ther Condition(s)							
	CLC	DUDY							
	Anim	nal Type			Relat	Relation To Trafficway			
						FFICWAY - N		D	
		h Classification - Location			Crasl	Crash Classification - Jurisdiction			
	-					NO SPECIAL JURISDICTION			
	Tribal Land					Access Control Special Study NO CONTROL			
		in Interchange Area	•			ection Type AN INTERSECTION			
	NO		NON-JUNCTION		NOTANINIE	RSECTION			
	Uni	t Summary	NON-JUNCTION				-		
	Unit	Status	NON-JUNC HON		erating As Classific		Unit Type		
	Unit Unit IN T	Status RANSIT	NON-JUNC HUN	Vehicle Ope D CLASS	erating As Classific		AUTOMO		
	Unit Unit IN T Vehi	Status RANSIT cle Type	NON-JUNCTION		erating As Classific				ments
01	Unit Unit IN T Vehi PAS	Status TRANSIT Icle Type SSENGER CAR		D CLASS	erating As Classific	cation	AUTOMOI Operating A	s Endorse	
	Unit Unit IN T Vehi PAS	Status RANSIT cle Type	Train/Bus # Recorded	D CLASS	erating As Classific		AUTOMOI Operating A	s Endorse	ments zMat Types
	Unit Unit IN T Vehi PAS Tota 1	Status TRANSIT Icle Type SSENGER CAR		D CLASS	erating As Classific	ation	AUTOMOI Operating A	s Endorse Total Haz	zMat Types
01	Unit Unit IN T Vehi PAS Tota 1	Status TRANSIT Icle Type SSENGER CAR I Occs	Train/Bus # Recorded	D CLASS	erating As Classific	Total Tra	AUTOMOI Operating A	s Endorse Total Haz 0	zMat Types
01	Unit Unit IN T Vehi PAS Tota 1 Insur NO	Status TRANSIT Icle Type SSENGER CAR I Occs	Train/Bus # Recorded Direction Of Travel EASTBOUND	D CLASS	erating As Classific tions Issued CrashTire Mark	Total Tra 0 Speed L 35	AUTOMOI Operating A illers mit Emergency	s Endorse Total Haz 0 Total Lan 2 Motor Veh	zMat Types nes nicle Use
	Unit Unit IN T Vehi PAS Tota 1 Insut NO Most	Status RANSIT Icle Type SSENGER CAR I Occs rance? t Harmful Event: Collision N CH	Train/Bus # Recorded Direction Of Travel EASTBOUND	D CLASS	erating As Classific tions Issued CrashTire Mark	Total Tra 0 Speed L 35	AUTOMOI Operating A illers	s Endorse Total Haz 0 Total Lan 2 Motor Veh	zMat Types nes nicle Use
01	Unit Unit IN T Vehi PAS Tota 1 Insut NO Most DIT Traff	Status RANSIT Icle Type SSENGER CAR I Occs rance? t Harmful Event: Collision N CH fic Way	Train/Bus # Recorded Direction Of Travel EASTBOUND With	D CLASS	erating As Classific tions Issued CrashTire Mark Iction EIAL FUNCTION	Total Tra 0 Speed L 35	AUTOMOI Operating A illers mit Emergency NOT APPI Traffic Cont	s Endorse Total Haz 0 Total Lan 2 Motor Veh LICABLE	zMat Types nes nicle Use
01	Unit Unit IN T Vehi PAS Tota 1 Insut NO Mosi DIT Traff	Status RANSIT Icle Type SSENGER CAR I Occs rance? t Harmful Event: Collision N CH fic Way D-WAY, NOT DIVIDED	Train/Bus # Recorded Direction Of Travel EASTBOUND With	D CLASS	tions Issued CrashTire Mark iction CiAL FUNCTION trol FOL	Total Tra 0 Speed L 35	AUTOMOI Operating A illers mit Emergency NOT APPI Traffic Cont NO	s Endorse Total Haz 0 Total Lan 2 Motor Veh LICABLE rol Inopera	zMat Types nes nicle Use
01	Unit Unit IN T Vehi PAS Tota 1 Insuu NO Mosi DIT Traff TWC	Status FRANSIT CICLE Type SSENGER CAR I Occs t Harmful Event: Collision N CH fic Way D-WAY, NOT DIVIDED ace Type	Train/Bus # Recorded Direction Of Travel EASTBOUND With	D CLASS	tions Issued CrashTire Mark Cial FUNCTION trol ROL ature	Total Tra 0 Speed L 35	AUTOMOI Operating A illers mit Emergency NOT APPI Traffic Cont NO Road Grade	s Endorse Total Haz 0 Total Lan 2 Motor Veh LICABLE rol Inopera	zMat Types nes nicle Use
01	Unit Unit IN T Vehi PAS Tota 1 Insur NO Most DIT Traff TWO Surfa	Status RANSIT ICICE Type SSENGER CAR I Occs I Occs t Harmful Event: Collision N CH fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU:	Train/Bus # Recorded Direction Of Travel EASTBOUND With	D CLASS	tions Issued CrashTire Mark Cial FUNCTION trol ROL ature	Total Tra 0 Speed L 35	AUTOMOI Operating A illers mit Emergency NOT APPI Traffic Cont NO	s Endorse Total Haz 0 Total Lan 2 Motor Veh LICABLE rol Inopera	zMat Types nes nicle Use
01	Unit Unit IN T Vehi PAS Tota 1 Insur NO Most DIT Traff TWO Surfa	Status FRANSIT CICLE Type SSENGER CAR I Occs t Harmful Event: Collision N CH fic Way D-WAY, NOT DIVIDED ace Type	Train/Bus # Recorded Direction Of Travel EASTBOUND With	D CLASS	tions Issued CrashTire Mark Cial FUNCTION trol ROL ature	Total Tra 0 Speed L 35	AUTOMOI Operating A illers mit Emergency NOT APPI Traffic Cont NO Road Grade	s Endorse Total Haz 0 Total Lan 2 Motor Veh LICABLE rol Inopera	zMat Types nes nicle Use
01	Unit Unit IN T Vehi PAS Tota 1 Insuu NO Most Traff TW(Surfa BLA Truc NO	Status RANSIT ICICE Type SSENGER CAR I Occs I Occs t Harmful Event: Collision N CH fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU:	Train/Bus # Recorded Direction Of Travel EASTBOUND With	D CLASS	tions Issued CrashTire Mark Cial FUNCTION trol ROL ature	Total Tra 0 Speed L 35	AUTOMOI Operating A illers mit Emergency NOT APPI Traffic Cont NO Road Grade	s Endorse Total Haz 0 Total Lan 2 Motor Veh LICABLE rol Inopera	zMat Types nes nicle Use
01	Unit Unit IN T Vehi PAS Tota 1 Insuu NO Most Traff TW(Surfa BLA Truc NO	Status RANSIT Cle Type SSENGER CAR I Occs rance? t Harmful Event: Collision N CH fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU: k Bus or HazMat Vehicle License Plate Number	Train/Bus # Recorded Direction Of Travel EASTBOUND With	D CLASS	tions Issued CrashTire Mark iction CrashTire Mark iction CrashTire Mark iction CrashTire Mark T T ature T	Total Tra 0 Speed L 35	AUTOMOI Operating A illers mit Emergency NOT APPI Traffic Cont NO Road Grade LEVEL	s Endorse Total Haz 0 Total Lan 2 Motor Veh LICABLE rol Inopera	zMat Types nes nicle Use
01	Unit Unit IN T Vehi PAS Tota 1 Insuu NO Most Traff TW(Surfa BLA Truc NO	Status RANSIT Cle Type SSENGER CAR I Occs rance? t Harmful Event: Collision N CH fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU: k Bus or HazMat Vehicle License Plate Number AMY1178	Train/Bus # Recorded Direction Of Travel EASTBOUND With	D CLASS	tions Issued CrashTire Mark CiAL FUNCTION trol TOL ature T	Total Tra 0 Speed L 35	AUTOMOI Operating A illers mit Emergency NOT APPI Traffic Cont NO Road Grade LEVEL	s Endorse Total Haz 0 Total Lan 2 Motor Veh LICABLE rol Inopera	zMat Types nes nicle Use
01	Unit Unit Unit IN T Vehi PAS Tota 1 Insuu NO Most DIT Traff TW(Surfa BLA Truc NO	Status RANSIT ICLE Type SSENGER CAR I OCCS I OCCS I Harmful Event: Collision N CH fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU: Ik Bus or HazMat Vehicle License Plate Number AMY1178 Vehicle Identification Nur	Train/Bus # Recorded Direction Of Travel EASTBOUND With S)	D CLASS	tions Issued CrashTire Mark iction CiAL FUNCTION irol T T J J J J J TOMOBILE	Total Tra 0 Speed L 35	AUTOMOI Operating A illers mit Emergency NOT APPI Traffic Cont NO Road Grade LEVEL	s Endorse Total Haz 0 Total Lan 2 Motor Veh LICABLE rol Inopera suance	zMat Types nes nicle Use
01	Unit Unit IN T Vehi PAS Tota 1 Insuu NO Most Traff TW(Surfa BLA Truc NO	Status RANSIT ICIE Type SSENGER CAR I OCCS I OCCS Trance? I Harmful Event: Collision V CH fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS k Bus or HazMat Vehicle License Plate Number AMY1178 Vehicle Identification Nur 1NXBR32E76Z76175	Train/Bus # Recorded Direction Of Travel EASTBOUND With S)	D CLASS	tions Issued CrashTire Mark Totion CiAL FUNCTION Trol T T JTOMOBILE	Total Tra 0 Speed L 35	AUTOMOI Operating A illers mit Emergency NOT APPI Traffic Cont NO Road Grade LEVEL Country of Is UNITED S1 Model COROLLA	s Endorse Total Haz 0 Total Lan 2 Motor Veh LICABLE rol Inopera suance	zMat Types nes nicle Use
01	Unit Unit Unit IN T Vehi PAS Tota 1 Insuu NO Most DIT Traff TW(Surfa BLA Truc NO	Status TRANSIT Cle Type SSENGER CAR I Occs I Occs Trance? t Harmful Event: Collision V CH fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU: k Bus or HazMat Vehicle License Plate Number AMY1178 Vehicle Identification Nur 1NXBR32E76Z76175 Color	Train/Bus # Recorded Direction Of Travel EASTBOUND With S)	D CLASS	tions Issued CrashTire Mark Inction IAL FUNCTION IAL FUNCTION Trol T IT I	Total Tra 0 Speed L 35	AUTOMOI Operating A illers mit Emergency NOT APPI Traffic Cont NO Road Grade LEVEL	s Endorse Total Haz 0 Total Lan 2 Motor Veh LICABLE rol Inopera suance	zMat Types nes nicle Use
01	Unit Unit Unit IN T Vehi PAS Tota 1 Insuu NO Most Traff TWC Surfa BLA Truc NO	Status Status RANSIT Cle Type SSENGER CAR I Occs rance? t Harmful Event: Collision V CH fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS k Bus or HazMat Vehicle License Plate Number AMY1178 Vehicle Identification Nur 1NXBR32E76Z76175 Color LGR - GREEN, LIGH	Train/Bus # Recorded Direction Of Travel EASTBOUND With S)	D CLASS	tions Issued CrashTire Mark Inction IAL FUNCTION ITAL FUNCTION TOI TOI T ITOI T ITOI ITOI ITOI ITO	Total Tra 0 Speed L 35	AUTOMOI Operating A illers mit Emergency NOT APPI Traffic Cont NO Road Grade LEVEL Country of Is UNITED S1 Model COROLLA	s Endorse Total Haz 0 Total Lan 2 Motor Veh LICABLE rol Inopera suance	zMat Types nes nicle Use
UNIT 01	Unit Unit Unit IN T Vehi PAS Tota 1 Insur NO Most DIT Traff Truc NO	Status RANSIT Cle Type SSENGER CAR I Occs rance? t Harmful Event: Collision V CH fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS k Bus or HazMat Vehicle License Plate Number AMY1178 Vehicle Identification Nur 1NXBR32E76Z76175 Color LGR - GREEN, LIGH Initial Contact Point	Train/Bus # Recorded Direction Of Travel EASTBOUND With S)	D CLASS	tions Issued CrashTire Mark Cial FUNCTION Trol T T T T T T T T T T T T T T T T T T T	Total Tra 0 Speed L 35 St WI Year 2006	AUTOMOI Operating A illers mit Emergency NOT APPI Traffic Cont NO Road Grade LEVEL	s Endorse Total Haz 0 Total Lan 2 Motor Veh LICABLE rol Inopera suance	zMat Types nes nicle Use
01	Unit Unit Unit IN T Vehi PAS Tota 1 Insuu NO Most Traff TWC Surfa BLA Truc NO	Status Status RANSIT Cle Type SSENGER CAR I Occs rance? t Harmful Event: Collision V CH fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS k Bus or HazMat Vehicle License Plate Number AMY1178 Vehicle Identification Nur 1NXBR32E76Z76175 Color LGR - GREEN, LIGH	Train/Bus # Recorded Direction Of Travel EASTBOUND With S)	D CLASS	tions Issued CrashTire Mark Inction IAL FUNCTION ITAL FUNCTION TOI TOI T ITOI T ITOI ITOI ITOI ITO	Total Tra 0 Speed L 35 St WI Year 2006	AUTOMOI Operating A illers mit Emergency NOT APPI Traffic Cont NO Road Grade LEVEL Country of Is UNITED ST Model COROLLA Bus Use	s Endorse Total Haz 0 Total Lan 2 Motor Veh LICABLE rol Inopera suance TATES CE	zMat Types nes nicle Use tive/Missing

24-03183

WISCONSIN MOTOR VEHICLE CRASH REPORT

Towed Due To Damage TOWED BUT NOT DUE TO DISABLING DAMAG			Vehicle Removed By NACHREINER TOWING					
			DISABLING DAMAG					
		What Driver Was Doing		Vehicle Factors				
		GOING STRAIGHT Driver Prior Action Other		NOT APPLICABLI	-			
					=			
		Driver Actions						
	щ	RAN OFF ROADWAY						
E	VEHICLE							
UNIT	H							
-	N N							
	-							
		Owner Name		Owner Address				
	01	ASHLEY HERRITZ (608) 547-9367		E3615 KESSI PLAIN, WI 535				
	0	(000) 041-0001			,			
		Sequence Of Events Event						
	01	DITCH						
	02	Event						
	03	Event						
	•	Firest						
	04	Event						
		ndividual Driver		Ottotione laguad	0			
		ASHLEY HERRITZ		Citations Issued 1	Sex FEMALE			
	AL	(608) 547-9367		Date of Birth	Race	<u> </u>		
F	INDIVIDUAL				WHITE	ITE		
UNIT	Σ	Address		Driver License Number				
	ND	E3615 KESSINICH RD PLAIN, WI 53577,US		STATE: WISCONSIN COUNTRY: UNITED STATES				
	-	F LAIN, WI 55577 , 05						
		On Duty	Crash	Cofety Equipment				
	Saf	fety Equipment	Glash	Safety Equipment				
		Row	Seat Position	SHOULDER & LAP BELT				
		01 - FRONT ROW	07 - LEFT					
		Helmet Use		Helmet Compliance				
				Tist Compliance				
		Eye Protection		Tint Compliance				
_	~	Injury Se	verity	Airbag				
6	001	Injury NO APP	PARENT INJURY	NON DEPLOYE	D			
		Ejected Ejection Path				Trapped/Extricated		
		NOT EJECTED NOT EJECTED/NOT AP				NOT TRAPPED		
		Medical Transport		EMS Agency Ident	ifier	EMS Run #		
				Date of Death		Time of Death		
		Hospital		Date of Death		Time of Death		
	Distracted By Source							
		Distracted By Action UNKNOWN						
	Non Motorist							

6TL0D6N05K

24-03183

WISCONSIN MOTOR VEHICLE CRASH REPORT

		Prior Action							
		Action							
	٩L								
F	INDIVIDUAL								
UNIT									
	IN								
		Action Other						To/From School	
			Suspected Alcoh	nol Use	Suspected Drug Use				
	L	Drug & Alcoh			YES		T		
				Alcohol Test Type BLOOD			Alcohol Test Results PENDING		
		Drug Test Given		Drug Test Type	Drug Test Type Drug Test Resul				
	_	TEŠT GIVEN Drug Type		BLOOD	BLOOD PENDING				
0	001								
		Individual Condition	ิท						
		UNDER THE IN	FLUENCE OF ME	DICATIONS/DRUGS	ALCOHOL				
		Violations UTC Number							
	01	BG110833	lssue To? 001	Statute Number 346.63(1)(a)	Description OPERATING WHILE	UNDER THE IN	IFLUENCE(3RD)		
		perty Owne	r		• •				
0	ROE	idual BERT PALMER		E	Address E5461 SANDSTONE L				
PROP OWNER	(608	8) 588-4273		F	PLAIN, WI 53577 ,US	6			
			-						
	Fixe	ed Objects St							
	01		Struck Object DITCH				Structure Number	Damage Tag Number	
1									