

6TL0F8QXWP
SC24-03229

WISCONSIN MOTOR VEHICLE
CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMENT
1300 LANGE COURT
BARABOO, WI 53913
(608) 356-4895

6TL0F8QXWP

Document Number Override		Primary Crash Document #		Agency Crash Number		Investigating Officer/Deputy DEPUTY J. GREENWOOD	
Crash Date 04/02/2024		Crash Time 02:38 PM		Date Arrived 04/02/2024		Time Arrived 02:44 PM	
Date Notified 04/02/2024		Time Notified 02:38 PM		Total Units 01		Total Injured 00	Total Killed 00
<input type="checkbox"/> On Emergency	<input type="checkbox"/> Hit and Run	<input type="checkbox"/> Lane Closure	<input type="checkbox"/> Work Zone		<input type="checkbox"/> Trailer or Towed	<input type="checkbox"/> Reporting Threshold	
<input type="checkbox"/> Government Property		<input type="checkbox"/> Active School Zone		School Bus Related NO		Tags	
<input checked="" type="checkbox"/> Reportable		Crash Type DT4000 (STANDARD CRASH)				<input type="checkbox"/> Amended	<input type="checkbox"/> Secondary Crash

Description

Diagram		Reconstruction By
		Photos By
		Additional Information NONE

I, a sworn law enforcement officer, agree that I have not added any CJIS data in this report.

UNIT 1 WAS NB ON USH 12. UNIT 1 HIT THE BREAKS AND SPUN 360 DEGREES AND ENTERED THE DITCH CAUSING DAMAGE.

Location

ON USH12 WB 0.50 MI S OF SHADY LANE RD IN THE TOWN OF DELTON IN SAUK COUNTY	Latitude 43.539757397	Longitude -89.786987313
	X Coordinate 274831.125	Y Coordinate 4824530.5
	Structure Type NO STRUCTURE	

Crash Scene


First Harmful Event DITCH	First Harmful Event Location ON ROADWAY	
Manner of Collision 00 - NO COLLISION W/VEHICLE IN TRANSPORT	Light Condition DAYLIGHT	
Road Surface Condition(s) SLUSH	Roadway Factor(s) ROAD SURFACE CONDITION (WET, ICY, SNOW, SLUSH, ETC)	
Environment Factor(s) WEATHER CONDITIONS		
Weather Condition(s) SNOW		
Animal Type	Relation To Trafficway TRAFFICWAY - ON ROAD	
Crash Classification - Location PUBLIC PROPERTY	Crash Classification - Jurisdiction NO SPECIAL JURISDICTION	
Tribal Land	Access Control NO CONTROL	Special Study
Within Interchange Area NO	Junction Location NON-JUNCTION	Intersection Type NOT AN INTERSECTION

Unit Summary

UNIT	Unit Status IN TRANSIT	Vehicle Operating As Classification D CLASS		Unit Type AUTOMOBILE	
	Vehicle Type PASSENGER CAR	Operating As Endorsements			
	Total Occs 1	Train/Bus # Recorded	Total # Citations Issued 1	Total Trailers 0	Total HazMat Types 0
	Insurance? NO	Direction Of Travel WESTBOUND	<input type="checkbox"/> Pre Crash Tire Mark	Speed Limit 55	Total Lanes 4
	Most Harmful Event: Collision With DITCH	Special Function NO SPECIAL FUNCTION		Emergency Motor Vehicle Use NOT APPLICABLE	
	Traffic Way DIVIDED HWY W/O TRAFFIC BARRIER	Traffic Control NO CONTROL		Traffic Control Inoperative/Missing NO	
	Surface Type BLACKTOP (BITUMINOUS)	Road Curvature STRAIGHT		Road Grade LEVEL	
	Truck Bus or HazMat NO				

Vehicle

UNIT	VEHICLE	License Plate Number AWU1135	Plate Type AUT - AUTOMOBILE	St WI	Country of Issuance UNITED STATES	
		Vehicle Identification Number 1G1ND52F24M616492	Make CHEVROLET	Year 2004	Model CLASSIC	
		Color SIL - SILVER (ALUMINUM)	Body Style SD - SEDAN		Bus Use	
		Initial Contact Point 02 - RIGHT SIDE FRONT	Vehicle Damage 02 - RIGHT SIDE FRONT, 05 - RIGHT REAR CORNER, 06 - REAR			
		Extent Of Damage FUNCTIONAL DAMAGE				



UNIT	Towed Due To Damage TOWED DUE TO DISABLING DAMAGE		Vehicle Removed By ARNESON SERVICE		
	What Driver Was Doing SLOW/STOPPING		Vehicle Factors		
	Driver Prior Action Other		NOT APPLICABLE		
	Driver Actions SPEED TOO FAST/COND				
01	01	Owner Name ANTONY MELENDEZ ARROYO		Owner Address 1231 BUNKER RD BARABOO, WI 53913 , US	
		Sequence Of Events			
01	01	Event DITCH			
		Event			
		Event			
		Event			
01	01	Individual			
		Driver ANTONY MELENDEZ ARROYO		Citations Issued 1	Sex MALE
		Date of Birth		Race HISPANIC	
		Address 1231 BUNKER RD BARABOO, WI 53913 , US		Driver License Number	
01	001	Safety Equipment		On Duty Crash	
		Row 01 - FRONT ROW		Seat Position 07 - LEFT	
		Safety Equipment SHOULDER & LAP BELT		Helmet Use	
		Helmet Compliance		Eye Protection	
Tint Compliance		Injury NO APPARENT INJURY			
Airbag NON DEPLOYED		Ejected NOT EJECTED		Ejection Path NOT EJECTED/NOT APPLICABLE	
Trapped/Extricated NOT TRAPPED		Medical Transport NOT TRANSPORTED		EMS Agency Identifier	
EMS Run #		Hospital		Date of Death	
Time of Death		Distracted By			
Distracted By Source NOT APPLICABLE (NOT DISTRACTED)		Distracted By Action NOT DISTRACTED			
Non Motorist		Striking Unit #		Location	

UNIT	Prior Action			
	Action			
	Action Other			To/From School
	Drug & Alcohol		Suspected Alcohol Use NO	Suspected Drug Use NO
	Alcohol Test Given TEST NOT GIVEN		Alcohol Test Type	Alcohol Test Results
	Drug Test Given TEST NOT GIVEN		Drug Test Type	Drug Test Results
	Drug Type			
	Individual Condition APPEARED NORMAL			
	Violations			
	01	UTC Number BK741360	Issue To? 001	Statute Number 344.62(1)