

WISCONSIN MOTOR VEHICLE
CRASH REPORT

6TL0D1PTPH

Document Number Override		Primary Crash Document #		Agency Crash Number 24-04757		Investigating Officer/Deputy DEPUTY S. MESSNER	
Crash Date 05/11/2024		Crash Time 01:14 PM		Date Arrived 05/11/2024		Time Arrived 01:23 PM	
Date Notified 05/11/2024		Time Notified 01:14 PM		Total Units 01		Total Injured 05	Total Killed 00
<input type="checkbox"/> On Emergency	<input type="checkbox"/> Hit and Run	<input checked="" type="checkbox"/> Lane Closure		<input type="checkbox"/> Work Zone		<input type="checkbox"/> Trailer or Towed	<input type="checkbox"/> Reporting Threshold
<input type="checkbox"/> Government Property		<input type="checkbox"/> Active School Zone		School Bus Related NO		Tags	
<input checked="" type="checkbox"/> Reportable		Crash Type DT4000 (STANDARD CRASH)		<input type="checkbox"/> Amended		<input type="checkbox"/> Secondary Crash	

Description

Diagram		Reconstruction By	
<p>Diagram</p> <p>STH 154</p> <p>Not to scale</p> <p>Unit 1 eastbound</p> <p>Unit 1 failed to negotiate a right turn and continues into the left ditch</p> <p>Unit 1 re-enters roadway</p> <p>Unit 1 oversteers and re-enters the left ditch</p> <p>Unit 1, entering the ditch, strikes the guide wire to an Alliant utility pole and overturns. No damage to the pole or guide wire.</p> <p>Unit 1 place of rest</p>		<p>Reconstruction By</p> <p>Photos By DEP. S. MESSNER</p> <p>Additional Information PHOTOS</p>	

I, a sworn law enforcement officer, agree that I have not added any CJIS data in this report.

ON 5/11/2024, AT APPROXIMATELY 1:14 PM, UNIT 1, A BLACK 2018 CHEVROLET SONIC SEDAN, BEARING WI # AC9940, WAS EASTBOUND ON STH 154. THE DRIVER WAS THE REGISTERED OWNER, RAFAEL HERNANDEZ GOMEZ. THE FRONT SEAT PASSENGER WAS CARLOS VELASCO PEREZ. THE REAR SEAT PASSENGER ON DRIVER SIDE WAS ABDIAS JIMENEZ JIMENEZ. THE MIDDLE REAR SEAT PASSENGER WAS DANIEL DIAZ GOMEZ. THE REAR SEAT PASSENGER ON PASSENGER SIDE WAS REYMUNDO GOMEZ DIAZ. ALL INDIVIDUALS WERE IDENTIFIED, LATER, BY THEIR MEXICAN IDENTIFICATION CARDS. UNIT 1 ATTEMPTED TO NEGOTIATE A RIGHT CORNER, BUT CONTINUED TO CROSS THE CENTER LINE AND INTO THE LEFT DITCH. WITNESSES, WAYLON EHLERS AND JESSICA EHLERS BOTH ADVISED THEY HEARD SCREECHING TIRES AND OBSERVED THE CAR GOING TOO FAST FOR THE CORNER. UNIT 1 RE-ENTERED THE ROADWAY, OVER CORRECTED AND RE-ENTERED THE LEFT DITCH. UNIT 1 STRUCK A GUIDE WIRE AND FLIPPED OVER TO ITS ROOF. THIS CAUSED DAMAGE TO ALL AREAS OF THE VEHICLE. NO OBSERVED DAMAGE TO THE UTILITY POLE OR GUIDE WIRE. ALL OCCUPANTS REMOVED THEMSELVES FROM THE VEHICLE. REEDSBURG EMS WAS REQUESTED TO THE SCENE TO ACCESS THE OCCUPANTS. ALL REFUSED TREATMENT. VEHICLE WAS REMOVED BY SHIELDS TOWING. OCCUPANTS WERE REMOVED BY LAW ENFORCEMENT TO KWIK TRIP WEST, REEDSBURG, TO WAIT FOR A RESCUE PARTY.

6TL0D1PTPH
24-04757

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMENT
1300 LANGE COURT
BARABOO, WI 53913
(608) 356-4895

Location

ON STH154 EB 102 FT N OF CTHCH SB IN THE TOWN OF REEDSBURG IN SAUK COUNTY	Latitude 43.480189722	Longitude -90.004163826
	X Coordinate 257044.9375	Y Coordinate 4818526
	Structure Type NO STRUCTURE	

Crash Scene

First Harmful Event OTHER POST, POLE OR SUPPORT		First Harmful Event Location SHOULDER LEFT	
Manner of Collision 00 - NO COLLISION W/VEHICLE IN TRANSPORT		Light Condition DAYLIGHT	
Road Surface Condition(s) DRY		Roadway Factor(s) NONE	
Environment Factor(s) NONE			
Weather Condition(s) CLOUDY			
Animal Type		Relation To Trafficway TRAFFICWAY - ON ROAD	
Crash Classification - Location PUBLIC PROPERTY		Crash Classification - Jurisdiction NO SPECIAL JURISDICTION	
Tribal Land		Access Control NO CONTROL	Special Study
Within Interchange Area NO	Junction Location NON-JUNCTION	Intersection Type NOT AN INTERSECTION	
Closure Type LANE CLOSURE		Reasons for Closure	
Date Initial Lane/Rd Closed 05/11/2024	Time Initial Lane/Rd Closed 01:23 PM	LAW ENFORCEMENT, TOW TRUCK, FIRE/EMS	
Date All Lanes Open 05/11/2024	Time All Lanes Open 02:22 PM	Date Scene Cleared 05/11/2024	Time Scene Cleared 02:22 PM

Unit Summary

UNIT 01	Unit Status IN TRANSIT	Vehicle Operating As Classification D CLASS		Unit Type AUTOMOBILE		
	Vehicle Type PASSENGER CAR			Operating As Endorsements		
	Total Occs 5	Train/Bus # Recorded	Total # Citations Issued 3	Total Trailers 0	Total HazMat Types 0	
	Insurance? NO	Direction Of Travel EASTBOUND	<input type="checkbox"/> Pre CrashTire Mark	Speed Limit 55	Total Lanes 2	
	Most Harmful Event: Collision With OTHER POST, POLE OR SUPPORT		Special Function NO SPECIAL FUNCTION		Emergency Motor Vehicle Use NOT APPLICABLE	
	Traffic Way TWO-WAY, NOT DIVIDED		Traffic Control NO CONTROL		Traffic Control Inoperative/Missing NO	
	Surface Type BLACKTOP (BITUMINOUS)		Road Curvature CURVE RIGHT		Road Grade LEVEL	
	Truck Bus or HazMat NO					
	01	Vehicle				
		License Plate Number AXC9940		Plate Type AUT - AUTOMOBILE	St WI	Country of Issuance UNITED STATES
Vehicle Identification Number 1G1JD5SB3J4109253		Make CHEVROLET	Year 2018	Model SONIC		

6TL0D1PTPH

24-04757

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMENT
1300 LANGE COURT
BARABOO, WI 53913
(608) 356-4895

Form containing vehicle information (Color: BLK - BLACK, Body Style: SD - SEDAN), driver information (Name: RAFAEL HERNANDEZ GOMEZ), sequence of events (RUN OFF ROADWAY LEFT, REENTERING ROADWAY), individual details (Sex: MALE, Race: HISPANIC), safety equipment (SHOULDER & LAP BELT), and injury status (POSSIBLE INJURY, DEPLOYED-COMBINATION).

WISCONSIN MOTOR VEHICLE CRASH REPORT

Form containing various sections: Distracted By, Non Motorist, Drug & Alcohol, Individual (Passenger CARLOS VELASCO PEREZ), Safety Equipment, Injury, and Hospital information.

WISCONSIN MOTOR VEHICLE CRASH REPORT

UNIT	Distracted By Action			
	Non Motorist			
	Striking Unit #	Location		
	Prior Action			
	Action			
	Action Other		To/From School	
	Drug & Alcohol			
	Suspected Alcohol Use NO		Suspected Drug Use NO	
	Alcohol Test Given TEST NOT GIVEN	Alcohol Test Type	Alcohol Test Results	
	Drug Test Given TEST NOT GIVEN	Drug Test Type	Drug Test Results	
01	002	Drug Type		
		Individual Condition APPEARED NORMAL		
		Individual		
		Passenger ABDIAS JIMENEZ JIMENEZ	Citations Issued 0	Sex MALE
			Date of Birth	Race HISPANIC
		Address 201 E COURT ST # 203 RICHLAND CENTER, WI 53581 , US		Driver License Number
		Safety Equipment		
		On Duty Crash		Safety Equipment SHOULDER & LAP BELT
		Row 02 - SECOND ROW	Seat Position 07 - LEFT	
		Helmet Use		Helmet Compliance
Eye Protection		Tint Compliance		
01	003	Injury		
		Injury Severity POSSIBLE INJURY	Airbag DEPLOYED-COMBINATION	
		Ejected NOT EJECTED	Ejection Path NOT EJECTED/NOT APPLICABLE	Trapped/Extricated NOT TRAPPED
		Medical Transport NOT TRANSPORTED		EMS Agency Identifier
		Hospital		EMS Run #
		Date of Death		Time of Death
		Distracted By		
		Distracted By Source		
		Distracted By Action		

WISCONSIN MOTOR VEHICLE CRASH REPORT

UNIT	INDIVIDUAL	Non Motorist		Striking Unit #	Location		
		Prior Action					
		Action					
01	003	Action Other					
		To/From School					
		Drug & Alcohol		Suspected Alcohol Use NO	Suspected Drug Use NO		
		Alcohol Test Given TEST NOT GIVEN		Alcohol Test Type		Alcohol Test Results	
		Drug Test Given TEST NOT GIVEN		Drug Test Type		Drug Test Results	
		Drug Type					
		Individual Condition APPEARED NORMAL					
		Individual					
		Passenger DANIEL DIAZ GOMEZ			Citations Issued 0	Sex MALE	
		Date of Birth			Race HISPANIC		
Address 201 E COURT ST # 203 RICHLAND CENTER, WI 53581 , US			Driver License Number				
01	004	Safety Equipment		On Duty Crash			
		Safety Equipment SHOULDER & LAP BELT					
		Row 02 - SECOND ROW	Seat Position 08 - MIDDLE				
		Helmet Use		Helmet Compliance			
		Eye Protection		Tint Compliance			
		Injury		Injury Severity POSSIBLE INJURY		Airbag NOT APPLICABLE	
		Ejected NOT EJECTED		Ejection Path NOT EJECTED/NOT APPLICABLE		Trapped/Extricated NOT TRAPPED	
		Medical Transport NOT TRANSPORTED		EMS Agency Identifier		EMS Run #	
		Hospital		Date of Death		Time of Death	
		Distracted By		Distracted By Source			
Distracted By Action							
Non Motorist		Striking Unit #		Location			

WISCONSIN MOTOR VEHICLE
CRASH REPORT

UNIT	INDIVIDUAL	Prior Action				
		Action				
		Action Other		To/From School		
		Drug & Alcohol	Suspected Alcohol Use NO	Suspected Drug Use NO		
		Alcohol Test Given TEST NOT GIVEN	Alcohol Test Type	Alcohol Test Results		
		Drug Test Given TEST NOT GIVEN	Drug Test Type	Drug Test Results		
		Drug Type				
		Individual Condition APPEARED NORMAL				
		Individual				
		UNIT	INDIVIDUAL	Passenger REYMUNDO GOMEZ DIAZ	Citations Issued 0	Sex MALE
	Date of Birth 07/01/1999			Race HISPANIC		
Address 201 E COURT ST # 203 RICHLAND CENTER, WI 53581 , US				Driver License Number		
Safety Equipment	On Duty Crash			Safety Equipment		
Row 02 - SECOND ROW	Seat Position 09 - RIGHT			SHOULDER & LAP BELT		
Helmet Use				Helmet Compliance		
Eye Protection				Tint Compliance		
UNIT	INDIVIDUAL			Injury	Injury Severity POSSIBLE INJURY	Airbag DEPLOYED-COMBINATION
				Ejected NOT EJECTED	Ejection Path NOT EJECTED/NOT APPLICABLE	Trapped/Extricated NOT TRAPPED
				Medical Transport NOT TRANSPORTED		EMS Agency Identifier
		Hospital		Date of Death	Time of Death	
		Distracted By	Distracted By Source			
Distracted By Action						
UNIT	INDIVIDUAL	Non Motorist	Striking Unit #	Location		
		Prior Action				

