6TL0D0GSP2

25-12428

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

	Document Number Override	Primary Crash [Primary Crash Document #		Agency Crash Number 25-12428		Investigating Officer/Deputy DEPUTY G. AKERS		
7	Crash Date 12/01/2025	Crash Time 06:18 PM			Date Arrived 12/01/2025 Total Units 01		Time Arrived 06:45 PM		
6 I LUDUGSPZ	Date Notified 12/01/2025						Total Kille	led	
ב	On Emergency	Hit and Run	Lane Closu	ıre	Work Zone	Trailer	or Towed	Reporting Threshold	
	Government Property	Active Sc	hool Zone	School NO	Bus Related	Tags			
	✓ Reportable	Crash Type DT4000 (STA	NDARD CRASH)		Amend	ed	Secondary Crash	
	Description Diagram	•				•		•	
							Photos By GA Additional Info	rmation	
	I, a sworn law enforce			ot added		nis report.	PHOTOS		
	V1 WAS TRAVELING EAST O CONTROL, CROSSED THE C	N CTY RD DL BEFORE	HWY 78 WHERE IT	WAS NE	GOTIATING A CURVE D	OOWNHILL, THE R			
	INJURED. V1 WAS TOWED B								

6TL0D0GSP2 25-12428

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 12/01/2025

Crash Time 06:18 PM

	Loc	ation								
	ON	CTHDL EB			Latitude			Longitu	de	
		FT W			43.418	43.418418514		-89.603355074		
		STH78 NB			X Coord	X Coordinate		Y Coord	dinate	
		HE TOWN OF MERRI	289246	289246.21875 4810573			73			
		ACIT COCITY			Structur	Structure Type				
	O	ah Caana								
,	_	sh Scene								
		Harmful Event		First Harmful Event Location ON ROADWAY						
	DIT	ner of Collision								
			EUICI E IN TRANSDORT		•	Light Condition DARK/UNLIT				
	00 - NO COLLISION W/VEHICLE IN TRANSPORT Road Surface Condition(s)					Roadway Factor(s)				
	SNO	. ,			rtodawe					
	Envi	ronment Factor(s)								
		ATHER CONDITIONS			NONE	NONE				
	Wea	ther Condition(s)								
	SNO	ow .								
	Anin	nal Type				Relation To Trafficway				
	Cras	sh Classification - Location	1			TRAFFICWAY - ON ROAD				
	PUE	BLIC PROPERTY	•		NO SP	Crash Classification - Jurisdiction NO SPECIAL JURISDICTION				
	Tribal Land				Access Control NO CONTROL			Special Study		
					Intersection Type NOT AN INTERS	ection Type AN INTERSECTION				
	llni	t Summary								
		t Summary Status		Vehicle Ope	erating As Classificati	on	Unit Type			
	Unit			Vehicle Ope	erating As Classificati	on	Unit Type AUTOMOI	BILE		
	Unit IN T	Status				on			ments	
	Unit IN T Vehi	Status RANSIT				on	AUTOMOI		ments	
	Unit IN T Vehi PAS Tota	Status RANSIT cle Type	Train/Bus # Recorded	D CLASS		Total Tra	AUTOMOI Operating A	s Endorse Total Haz	ments zMat Types	
	Unit IN T Vehi PAS Tota 1	Status RANSIT ICLE Type SSENGER CAR	Train/Bus # Recorded Direction Of Travel	D CLASS Total # Cita 0	tions Issued		AUTOMOI Operating A	s Endorse	zMat Types	
01	Unit IN T Vehi PAS Tota 1	Status RANSIT cle Type SSENGER CAR I Occs		D CLASS Total # Cita 0		Total Tra	AUTOMOI Operating A ailers	s Endorse Total Haz 0 Total Lar 2	zMat Types nes	
01	Unit IN T Vehi PAS Tota 1 Insu YES	Status RANSIT cle Type SSENGER CAR I Occs rance? Status	Direction Of Travel EASTBOUND	Total # Cita 0 Pre Special Fur	crashTire Mark	Total Tra 0 Speed L	AUTOMOI Operating A ailers imit Emergency	Total Haz 0 Total Lar 2 Motor Veh	zMat Types nes nicle Use	
01	Unit IN T Vehi PAS Tota 1 Insu YES Mos DIT	Status RANSIT cle Type SSENGER CAR I Occs rance? St Harmful Event: Collision CH	Direction Of Travel EASTBOUND	Total # Cita 0 Pre Special Fur NO SPEC	crashTire Mark Action	Total Tra 0 Speed L	AUTOMOI Operating A ailers imit Emergency NOT APPI	Total Haz 0 Total Lar 2 Motor Veh	zMat Types nes nicle Use	
01	Unit IN T Vehi PAS Tota 1 Insu YES Mos DIT Traff	Status RANSIT cle Type SSENGER CAR I Occs rance? St Harmful Event: Collision CH fic Way	Direction Of Travel EASTBOUND With	Total # Cita 0 Pre Special Fur NO SPEC	CrashTire Mark notion EIAL FUNCTION	Total Tra 0 Speed L	AUTOMOI Operating A ailers imit Emergency NOT APPI Traffic Control	Total Haz 0 Total Lar 2 Motor Veh	zMat Types nes nicle Use	
01	Unit IN T Vehi PAS Tota 1 Insu YES Mos: DIT Traff	Status RANSIT cle Type SSENGER CAR I Occs rance? St Harmful Event: Collision CH fic Way D-WAY, NOT DIVIDED	Direction Of Travel EASTBOUND With	Total # Cita 0 Pre Special Fur NO SPEC Traffic Cont	CrashTire Mark Inction ILAL FUNCTION Itrol	Total Tra 0 Speed L	AUTOMOI Operating A ailers imit Emergency NOT APPI Traffic Conti	Total Haz 0 Total Lan 2 Motor Veh LICABLE	zMat Types nes nicle Use	
01	Unit IN T Vehi PAS Tota 1 Insu YES Mos: DIT Traff TWO Surfa	Status TRANSIT ICIE Type SSENGER CAR I Occs Trance? St Harmful Event: Collision CH Ific Way D-WAY, NOT DIVIDED ace Type	Direction Of Travel EASTBOUND With	Total # Cita 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva	CrashTire Mark Inction BIAL FUNCTION BY TOOL BY TOOL BATTER TOOL BY TO	Total Tra 0 Speed L	AUTOMOI Operating A ailers imit Emergency NOT APPI Traffic Conti	Total Haz 0 Total Lan 2 Motor Veh LICABLE	zMat Types nes nicle Use	
01	Unit IN T Vehi PAS Tota 1 Insu YES DIT Traff TW0 Surf: BLA	Status RANSIT cle Type SSENGER CAR I Occs rance? St Harmful Event: Collision CH fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU	Direction Of Travel EASTBOUND With	Total # Cita 0 Pre Special Fur NO SPEC Traffic Cont	CrashTire Mark Inction BIAL FUNCTION BY TOOL BY TOOL BATTER TOOL BY TO	Total Tra 0 Speed L	AUTOMOI Operating A ailers imit Emergency NOT APPI Traffic Conti	Total Haz 0 Total Lan 2 Motor Veh LICABLE	zMat Types nes nicle Use	
01	Unit IN T Vehin PAS Tota 1 InsuryES DITC Traff TWO Surf. BLA	Status RANSIT cle Type SSENGER CAR I Occs rance? St Harmful Event: Collision CH fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU kk Bus or HazMat	Direction Of Travel EASTBOUND With	Total # Cita 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva	CrashTire Mark Inction BIAL FUNCTION BY TOOL BY TOOL BATTER TOOL BY TO	Total Tra 0 Speed L	AUTOMOI Operating A ailers imit Emergency NOT APPI Traffic Conti	Total Haz 0 Total Lan 2 Motor Veh LICABLE	zMat Types nes nicle Use	
01	Unit IN T Vehin PAS Tota 1 InsuryES DITC Traff TWO Surf. BLA	Status RANSIT cle Type SSENGER CAR I Occs rance? St Harmful Event: Collision CH fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU	Direction Of Travel EASTBOUND With	Total # Cita 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva CURVE R	CrashTire Mark Inction Italian FUNCTION	Total Tra 0 Speed L	AUTOMOI Operating A ailers imit Emergency NOT APPI Traffic Conti NO Road Grade DOWNHIL	Total Haz 0 Total Lar 2 Motor Veh LICABLE rol Inopera	zMat Types nes nicle Use	
01	Unit IN T Vehin PAS Tota 1 InsuryES DITC Traff TWO Surf. BLA	Status RANSIT cle Type SSENGER CAR I Occs rance? St Harmful Event: Collision CH fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU ik Bus or HazMat Vehicle License Plate Number	Direction Of Travel EASTBOUND With	Total # Cita 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva CURVE R	CrashTire Mark Inction Italian FUNCTION	Total Tra 0 Speed L 55	AUTOMOI Operating A ailers imit Emergency NOT APPI Traffic Conti NO Road Grade DOWNHIL	Total Haz 0 Total Lar 2 Motor Ven LICABLE rol Inopera	zMat Types nes nicle Use	
01	Unit IN T Vehin PAS Tota 1 InsuryES DITC Traff TWO Surf. BLA	Status RANSIT cle Type SSENGER CAR I Occs rance? St Harmful Event: Collision CH fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU k Bus or HazMat Vehicle License Plate Number ATP7539	Direction Of Travel EASTBOUND With	Total # Cita 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curve CURVE R	CrashTire Mark Inction Italian FUNCTION	Total Tra 0 Speed L 55	AUTOMOI Operating A ailers imit Emergency NOT APPI Traffic Contr NO Road Grade DOWNHIL Country of Is UNITED ST	Total Haz 0 Total Lar 2 Motor Ven LICABLE rol Inopera	zMat Types nes nicle Use	
UNIT 01	Unit IN T Vehin PAS Tota 1 InsuryES DITC Traff TWO Surf. BLA	Status RANSIT cle Type SSENGER CAR I Occs rance? St Harmful Event: Collision CH fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU ik Bus or HazMat Vehicle License Plate Number	Direction Of Travel EASTBOUND With	Total # Cita 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva CURVE R	CrashTire Mark Inction Italian FUNCTION	Total Tra 0 Speed L 55	AUTOMOI Operating A ailers imit Emergency NOT APPI Traffic Conti NO Road Grade DOWNHIL	Total Haz 0 Total Lar 2 Motor Ven LICABLE rol Inopera	zMat Types nes nicle Use	
UNIT 01	Unit IN T Vehi PAS Tota 1 Insu YES DIT Traff TWO Surf. BLA	Status RANSIT cle Type SSENGER CAR I Occs rance? St Harmful Event: Collision CH fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU k Bus or HazMat Vehicle License Plate Number ATP7539 Vehicle Identification Nu	Direction Of Travel EASTBOUND With	Total # Cita 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva CURVE R Plate Type AUT Make	CrashTire Mark Inction EIAL FUNCTION Itrol TROL ature	Total Tra 0 Speed L 55	AUTOMOI Operating A ailers imit Emergency NOT APPI Traffic Contr NO Road Grade DOWNHIL Country of Is UNITED S1 Model	Total Haz 0 Total Lar 2 Motor Ven LICABLE rol Inopera	zMat Types nes nicle Use	
UNIT 01	Unit IN T Vehi PAS Tota 1 Insu YES DIT Traff TWO Surf. BLA	Status RANSIT cle Type SSENGER CAR I Occs rance? St Harmful Event: Collision CH fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU k Bus or HazMat Vehicle License Plate Number ATP7539 Vehicle Identification Nu KNDJT2A56D763514 Color GRN - GREEN	Direction Of Travel EASTBOUND With	Total # Cita 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva CURVE R Plate Type AUT Make KIA Body Style UT - SPC	CrashTire Mark Detion EIAL FUNCTION ETCL BATTER BAT	St WI Year 2013	AUTOMOI Operating A ailers imit Emergency NOT APPI Traffic Conti NO Road Grade DOWNHIL Country of Is UNITED ST Model SOUL	Total Haz 0 Total Lar 2 Motor Ven LICABLE rol Inopera	zMat Types nes nicle Use	
01 UNIT 01	Unit IN T Vehi PAS Tota 1 InsuryES DITUTE Truck BLA Truck NO	Status RANSIT cle Type SSENGER CAR I Occs rance? St Harmful Event: Collision CH fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU ck Bus or HazMat Vehicle License Plate Number ATP7539 Vehicle Identification Nu KNDJT2A56D763514 Color GRN - GREEN Initial Contact Point	Direction Of Travel EASTBOUND With	Total # Cita 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva CURVE R Plate Type AUT Make KIA Body Style	CrashTire Mark Detion EIAL FUNCTION ETCL BATTER BAT	St WI Year 2013	AUTOMOI Operating A ailers imit Emergency NOT APPI Traffic Conti NO Road Grade DOWNHIL Country of Is UNITED ST Model SOUL	Total Haz 0 Total Lar 2 Motor Ven LICABLE rol Inopera	zMat Types nes nicle Use itative/Missing	
UNIT 01 UNIT 01	Unit IN T Vehi PAS Tota 1 Insu YES DITC Traff TWO Surf. NO	Status RANSIT cle Type SSENGER CAR I Occs rance? St Harmful Event: Collision CH fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU k Bus or HazMat Vehicle License Plate Number ATP7539 Vehicle Identification Nu KNDJT2A56D763514 Color GRN - GREEN	Direction Of Travel EASTBOUND With	Total # Cita 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curve CURVE R Plate Type AUT Make KIA Body Style UT - SPC Vehicle Da	CrashTire Mark Detion EIAL FUNCTION ETCL BATTER BAT	Total Tra 0 Speed L 55	AUTOMOI Operating A ailers imit Emergency NOT APPI Traffic Contr NO Road Grade DOWNHIL Country of Is UNITED S1 Model SOUL Bus Use	Total Haz 0 Total Lar 2 Motor Ven LICABLE rol Inopera	zMat Types nes nicle Use	

6TL0D0GSP2

25-12428

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 12/01/2025

Crash Time 06:18 PM

		Towed Due To Damage		Vehicle Removed By					
		TOWED DUE TO DISABL	ING DAMAGE	ARNESON SERVICE					
				Vehicle Factors					
		NEGOTIATING CURVE							
		Driver Prior Action Other		NOT APPLICABLE					
		Driver Actions							
	ш	SPEED TOO FAST/COND							
⊢	VEHICLE								
LNI	\								
–	回								
	>								
		Owner Name		Owner Address					
		JOSE LOPEZ PINEDA		3102 MAPLE VALLEY DR # 302					
5	01			MADISON, WI 53719 , US					
	ļ	L Sequence Of Events	anusanas Of Friends						
	ì	Event							
	01	CROSS CENTERLINE							
	~	Event							
	02	DITCH							
	03	Event							
	0	OTHER OBJECT - NOT F	IXED						
	04	Event							
╘		Policy Holder							
		Insurance Company	INC CO (ATTN: AUTO II	INDIVIDUAL					
			INS-CO-(ATTN:-AUTO-U	JOSE LOPEZ PINI	JOSE LOPEZ PINEDA				
	1	ndividual							
		DRIVER		Citations Issued Sex					
		JOSE LOPEZ PINEDA		0	MALE				
	NA I			Date of Birth Race					
╘	9								
EN	\leq	Address		Driver License Number					
	INDIVIDUAL	1 2402 MADIE VALLEV DD	# 202	Briver Election (Value)		STATE: WISCONSIN COUNTRY: UNITED STATES			
		3102 MAPLE VALLEY DR MADISON, WI 53719 . US			IN COUNTRY: UNITED STATES				
	_	3102 MAPLE VALLEY DR MADISON, WI 53719 , US			IN COUNTRY: UNITED STATES				
	_	MADISON, WI 53719 , US	3	STATE: WISCONS	IN COUNTRY: UNITED STATES				
		MADISON, WI 53719 , US	3		IN COUNTRY: UNITED STATES				
		MADISON, WI 53719 , US fety Equipment	y Crash	STATE: WISCONS Safety Equipment					
		MADISON, WI 53719 , US fety Equipment Row	y Crash Seat Position	STATE: WISCONS					
		MADISON, WI 53719 , US fety Equipment Row 01 - FRONT ROW	y Crash	STATE: WISCONS Safety Equipment SHOULDER & LAI					
		MADISON, WI 53719 , US fety Equipment Row	y Crash Seat Position	STATE: WISCONS Safety Equipment					
		MADISON, WI 53719 , US fety Equipment Row 01 - FRONT ROW	y Crash Seat Position	STATE: WISCONS Safety Equipment SHOULDER & LAI Helmet Compliance					
		fety Equipment Row 01 - FRONT ROW Helmet Use	y Crash Seat Position	STATE: WISCONS Safety Equipment SHOULDER & LAI					
-	Sat	MADISON, WI 53719 , US Fety Equipment Row 01 - FRONT ROW Helmet Use Eye Protection	y Crash Seat Position 07 - LEFT	STATE: WISCONS Safety Equipment SHOULDER & LAI Helmet Compliance					
10		MADISON, WI 53719 , US Fety Equipment Row 01 - FRONT ROW Helmet Use Eye Protection Injury S	y Crash Seat Position 07 - LEFT	STATE: WISCONS Safety Equipment SHOULDER & LAI Helmet Compliance Tint Compliance	P BELT				
01	Sat	MADISON, WI 53719 , US Fety Equipment Row 01 - FRONT ROW Helmet Use Eye Protection Injury S	Seat Position 07 - LEFT	STATE: WISCONS Safety Equipment SHOULDER & LAI Helmet Compliance Tint Compliance Airbag	P BELT				
10	Sat	Fety Equipment Row 01 - FRONT ROW Helmet Use Eye Protection Injury S NO AF Ejected NOT EJECTED	Seat Position 07 - LEFT Severity PPARENT INJURY	STATE: WISCONS Safety Equipment SHOULDER & LAI Helmet Compliance Tint Compliance Airbag DEPLOYED-FROM PLICABLE	P BELT IT Trapped/Extricated NOT TRAPPED				
01	Sat	Fety Equipment Row 01 - FRONT ROW Helmet Use Eye Protection Injury NO AF Ejected NOT EJECTED Medical Transport	Seat Position 07 - LEFT Severity PPARENT INJURY Ejection Path	STATE: WISCONS Safety Equipment SHOULDER & LAI Helmet Compliance Tint Compliance Airbag DEPLOYED-FRON	P BELT IT Trapped/Extricated NOT TRAPPED				
01	Sat	Fety Equipment Row 01 - FRONT ROW Helmet Use Eye Protection Injury NO AF Ejected NOT EJECTED Medical Transport NOT TRANSPORTED	Seat Position 07 - LEFT Severity PPARENT INJURY Ejection Path	STATE: WISCONS Safety Equipment SHOULDER & LAI Helmet Compliance Tint Compliance Airbag DEPLOYED-FROM PLICABLE EMS Agency Identifie	P BELT IT Trapped/Extricated NOT TRAPPED r EMS Run #				
01	Sat	Fety Equipment Row 01 - FRONT ROW Helmet Use Eye Protection Injury NO AF Ejected NOT EJECTED Medical Transport	Seat Position 07 - LEFT Severity PPARENT INJURY Ejection Path	STATE: WISCONS Safety Equipment SHOULDER & LAI Helmet Compliance Tint Compliance Airbag DEPLOYED-FROM PLICABLE	P BELT IT Trapped/Extricated NOT TRAPPED				
01	Sat	Fety Equipment Row 01 - FRONT ROW Helmet Use Eye Protection Injury NO AF Ejected NOT EJECTED Medical Transport NOT TRANSPORTED Hospital	Seat Position 07 - LEFT Severity PPARENT INJURY Ejection Path NOT EJECTED/NOT API	STATE: WISCONS Safety Equipment SHOULDER & LAI Helmet Compliance Tint Compliance Airbag DEPLOYED-FROM PLICABLE EMS Agency Identifie	P BELT IT Trapped/Extricated NOT TRAPPED r EMS Run #				
01	Sat	MADISON, WI 53719 , US Fety Equipment Row 01 - FRONT ROW Helmet Use Eye Protection Injury NO AF Ejected NOT EJECTED Medical Transport NOT TRANSPORTED Hospital	Seat Position 07 - LEFT Severity PPARENT INJURY Ejection Path NOT EJECTED/NOT API	STATE: WISCONS Safety Equipment SHOULDER & LAI Helmet Compliance Tint Compliance Airbag DEPLOYED-FROM PLICABLE EMS Agency Identifie Date of Death	P BELT IT Trapped/Extricated NOT TRAPPED r EMS Run #				
01	Sat	MADISON, WI 53719 , US Fety Equipment Row 01 - FRONT ROW Helmet Use Eye Protection Injury NO AF Ejected NOT EJECTED Medical Transport NOT TRANSPORTED Hospital	Seat Position 07 - LEFT Severity PPARENT INJURY Ejection Path NOT EJECTED/NOT API	STATE: WISCONS Safety Equipment SHOULDER & LAI Helmet Compliance Tint Compliance Airbag DEPLOYED-FROM PLICABLE EMS Agency Identifie Date of Death	P BELT IT Trapped/Extricated NOT TRAPPED r EMS Run #				

6TL0D0GSP2 25-12428

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 12/01/2025

Crash Time 06:18 PM

		Non Motorist Strikii	ng Unit#	Location				
		Prior Action						
LIND	INDIVIDUAL	Action						
		Action Other						To/From School
	L	Orug & Alcohol NO	ected Alcohol U	Jse	Suspected Drug Use NO			
		Alcohol Test Given TEST NOT GIVEN		Alcohol Test Type			Alcohol Test Results	
		Drug Test Given TEST NOT GIVEN		Drug Test Type		Drug Test Results		
٤	001	Drug Type						
		Individual Condition						
		APPEARED NORMAL						