

6TL0D5DZ56

26-01963

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMENT
1300 LANGE COURT
BARABOO, WI 53913
(608) 356-4895

6TL0D5DZ56

Document Number Override		Primary Crash Document #	Agency Crash Number 26-01963	Investigating Officer/Deputy DEPUTY J. HUNTER	
Crash Date 02/25/2026		Crash Time 04:26 PM	Date Arrived 02/25/2026	Time Arrived 04:33 PM	
Date Notified 02/25/2026		Time Notified 04:26 PM	Total Units 02	Total Injured 00	Total Killed 00
<input type="checkbox"/> On Emergency	<input type="checkbox"/> Hit and Run	<input type="checkbox"/> Lane Closure	<input type="checkbox"/> Work Zone	<input checked="" type="checkbox"/> Trailer or Towed	<input checked="" type="checkbox"/> Reporting Threshold
<input type="checkbox"/> Government Property	<input type="checkbox"/> Active School Zone	School Bus Related NO		Tags	
<input checked="" type="checkbox"/> Reportable	Crash Type DT4000 (STANDARD CRASH)		<input type="checkbox"/> Amended	<input type="checkbox"/> Secondary Crash	

Description

Diagram 	Reconstruction By
	Photos By DEPUTY HUNTER, DEPUTY VERTEIN
	Additional Information PHOTOS

I, a sworn law enforcement officer, agree that I have not added any CJIS data in this report.

UNIT 1 WAS TRAVELING E/B ON US HY 12. OPERATOR OF UNIT 1 ADVISED HE WAS TRAVELING AT 30MPH IN THE 55MPH ZONE, DELIVERING GROCERIES, AND HIS VEHICLE DID NOT GO ANY FASTER DUE TO KNOWN MECHANICAL ISSUES. OPERATOR OF UNIT 2 WAS BEHIND UNIT 1, ALSO E/B ON HY 12. UNIT 2 WAS TRAVELING NEAR THE POSTED 55MPH SPEED LIMIT. WHEN OPERATOR OF UNIT 2 REALIZED HE WAS RAPIDLY APPROACHING UNIT 1, THERE WAS A VEHICLE NEXT TO HIM IN THE OTHER LANE, PROHIBITING A LANE CHANGE. UNIT 2 ATTEMPTED TO STOP/SLOW, BUT WAS NOT ABLE TO STOP AND STRUCK UNIT 1 IN THE REAR. OPERATOR OF UNIT 1 STATED HIS FLASHERS/HAZARD LIGHTS WERE ON. OPERATOR OF UNIT 2 STATED THE VEHICLE DID NOT HAVE HAZARD LIGHTS ACTIVATED/VISIBLE.

6TL0D5DZ56

26-01963

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMENT
1300 LANGE COURT
BARABOO, WI 53913
(608) 356-4895

Location

ON USH12 EB 0.77 MI S OF SKIHI RD IN THE TOWN OF SUMPTER IN SAUK COUNTY	Latitude 43.409233115	Longitude -89.772071439
	X Coordinate 275553.3125	Y Coordinate 4809994
	Structure Type	

Crash Scene

First Harmful Event MOTOR VEH IN TRANSPORT	First Harmful Event Location ON ROADWAY	
Manner of Collision 03 - FRONT TO REAR	Light Condition DAYLIGHT	
Road Surface Condition(s) DRY	Roadway Factor(s) NONE	
Environment Factor(s) NONE		
Weather Condition(s) CLEAR		
Animal Type	Relation To Trafficway TRAFFICWAY - ON ROAD	
Crash Classification - Location PUBLIC PROPERTY	Crash Classification - Jurisdiction NO SPECIAL JURISDICTION	
Tribal Land	Access Control NO CONTROL	Special Study
Within Interchange Area NO	Junction Location NON-JUNCTION	Intersection Type NOT AN INTERSECTION

Unit Summary

UNIT	Unit Status IN TRANSIT	Vehicle Operating As Classification D CLASS		Unit Type AUTOMOBILE	
	Vehicle Type PASSENGER CAR	Operating As Endorsements			
	Total Occs 1	Train/Bus # Recorded	Total # Citations Issued 1	Total Trailers 0	Total HazMat Types 0
	Insurance? YES	Direction Of Travel EASTBOUND	<input type="checkbox"/> Pre CrashTire Mark	Speed Limit 55	Total Lanes 4
	Most Harmful Event: Collision With MOTOR VEH IN TRANSPORT	Special Function NO SPECIAL FUNCTION		Emergency Motor Vehicle Use NOT APPLICABLE	
	Traffic Way DIVIDED HWY W/O TRAFFIC BARRIER	Traffic Control NO CONTROL		Traffic Control Inoperative/Missing NO	
	Surface Type BLACKTOP (BITUMINOUS)	Road Curvature STRAIGHT		Road Grade LEVEL	
	Truck Bus or HazMat NO				

UNIT	VEHICLE	Vehicle			
		License Plate Number ADR7173	Plate Type AUT	St WI	Country of Issuance UNITED STATES
		Vehicle Identification Number 2FAFP71V08X150167	Make FORD	Year 2008	Model CROWN VICT
		Color WHI - WHITE	Body Style SD - SEDAN		Bus Use
		Initial Contact Point 06 - REAR	Vehicle Damage 04 - RIGHT SIDE REAR, 05 - RIGHT REAR CORNER, 06 - REAR, 07 - LEFT REAR CORNER, 08 - LEFT SIDE REAR, 14 - UNDERCARRIAGE		
		Extent Of Damage DISABLING DAMAGE			



6TL0D5DZ56

26-01963

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMENT
1300 LANGE COURT
BARABOO, WI 53913
(608) 356-4895

UNIT VEHICLE	Towed Due To Damage TOWED DUE TO DISABLING DAMAGE		Vehicle Removed By CRAIGS TOWING	
	What Driver Was Doing GOING STRAIGHT		Vehicle Factors	
	Driver Prior Action Other		POWER TRAIN, OTHER	
	Driver Actions OTHER CONTRIBUTING ACTION			
01 01	Owner Name AARON JEFFERS (608) 432-1895		Owner Address 1011 11TH ST BARABOO, WI 53913 , US	
	Sequence Of Events			
01 01	01	Event MOTOR VEH IN TRANSPORT		
	02	Event		
	03	Event		
	04	Event		
UNIT	Policy Holder			
	Insurance Company PROGRESSIVE-CASUALTY-INS-CO		INDIVIDUAL AARON JEFFERS	
UNIT INDIVIDUAL	Individual			
	DRIVER AARON JEFFERS (608) 432-1895		Citations Issued 1	Sex MALE
	Address 1011 11TH ST BARABOO, WI 53913 , US		Date of Birth	Race
	Driver License Number STATE: WISCONSIN COUNTRY: UNITED STATES			
01 001	Safety Equipment		On Duty Crash	
	Row 01 - FRONT ROW		Seat Position 07 - LEFT	
	Safety Equipment		SHOULDER & LAP BELT	
	Helmet Use		Helmet Compliance	
	Eye Protection		Tint Compliance	
	Injury		Injury Severity NO APPARENT INJURY	Airbag NON DEPLOYED
Ejected NOT EJECTED		Ejection Path NOT EJECTED/NOT APPLICABLE		Trapped/Extricated NOT TRAPPED
Medical Transport NOT TRANSPORTED		EMS Agency Identifier		EMS Run #
Hospital		Date of Death		Time of Death
Distracted By		Distracted By Source UNKNOWN		
Distracted By Action UNKNOWN				

6TL0D5DZ56

26-01963

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMENT
1300 LANGE COURT
BARABOO, WI 53913
(608) 356-4895

UNIT	INDIVIDUAL	Non Motorist		Striking Unit #	Location	
		Prior Action				
		Action				
	Action Other					To/From School
	Drug & Alcohol		Suspected Alcohol Use NO		Suspected Drug Use NO	
	Alcohol Test Given TEST NOT GIVEN		Alcohol Test Type		Alcohol Test Results	
	Drug Test Given TEST NOT GIVEN		Drug Test Type		Drug Test Results	
	Drug Type					
	Individual Condition APPEARED NORMAL					
	Violations					
01	001	UTC Number BG110453	Issue To? 001	Statute Number 346.59(1)	Description IMPEDING TRAFFIC BY SLOW SPEED	

Unit Summary

UNIT	02	Unit Status IN TRANSIT		Vehicle Operating As Classification D CLASS		Unit Type TRUCK			
		Vehicle Type UTILITY TRUCK/PICKUP TRUCK					Operating As Endorsements		
		Total Occs 1		Train/Bus # Recorded		Total # Citations Issued 0		Total Trailers 1	Total HazMat Types 0
		Insurance? YES		Direction Of Travel EASTBOUND		<input type="checkbox"/> Pre Crash Tire Mark		Speed Limit 55	Total Lanes 4
		Most Harmful Event: Collision With MOTOR VEH IN TRANSPORT			Special Function NO SPECIAL FUNCTION			Emergency Motor Vehicle Use NOT APPLICABLE	
		Traffic Way DIVIDED HWY W/O TRAFFIC BARRIER			Traffic Control NO CONTROL			Traffic Control Inoperative/Missing NO	
		Surface Type BLACKTOP (BITUMINOUS)			Road Curvature STRAIGHT			Road Grade LEVEL	
		Truck Bus or HazMat TRUCK OR TRUCK COMBINATION > 10,000LBS GVWR/GCWR							

Vehicle

02	02	License Plate Number EC64102		Plate Type LTK		St WI	Country of Issuance UNITED STATES	
		Vehicle Identification Number 1FDWF37F72EC83664		Make FORD		Year 2002	Model F350	
		Color GRN - GREEN		Body Style PK - PICKUP			Bus Use	
		Initial Contact Point 12 - FRONT						



6TL0D5DZ56

26-01963

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN
1300 LANGE COURT
BARABOO, WI 53913
(608) 356-4895

UNIT VEHICLE	Vehicle Damage					
	Extent Of Damage MINOR DAMAGE	12 - FRONT				
	Towed Due To Damage NOT TOWED	Vehicle Removed By OPERATOR				
	What Driver Was Doing GOING STRAIGHT	Vehicle Factors NOT APPLICABLE				
UNIT VEHICLE	Driver Prior Action Other					
	NO CONTRIBUTING ACTION					
02	Owner Name MEISE TRANSPORT LLC (608) 643-6822	Owner Address 232 MULBERRY ST PO BOX 118 SAUK CITY, WI 53583 , US				
	Sequence Of Events					
01 02 03 04	Event MOTOR VEH IN TRANSPORT					
	Event					
	Event					
	Event					
UNIT	Policy Holder					
	Insurance Company UNITED-FIRE-&-CASUALTY-CO	ORGANIZATION/COMPANY MEISE TRANSPORT LLC				
02	Trailer/Towed					
	Trailer Plate # GR12298	Plate Type TRL	Make TRLK	State WI	Country of Issuance UNITED STATES	
	Unit Type UTILITY TRAILER	ORGANIZATION/COMPANY MEISE TRANSPORT LLC (608) 643-6822			Address 232 MULBERRY ST PO BOX 118 SAUK CITY, WI 53583 , US	
UNIT TRAILER	Vehicle Identification Number 1TKU02626KR061950					
	Individual					
UNIT INDIVIDUAL	DRIVER DUANE RUHLAND (608) 570-0122		Citations Issued 0	Sex MALE		
			Date of Birth	Race WHITE		
	Address 1150 CLOVER ST PLAIN, WI 53577 , US		Driver License Number STATE: WISCONSIN COUNTRY: UNITED STATES			
	Safety Equipment					
On Duty Crash		Safety Equipment				
Row 01 - FRONT ROW	Seat Position 07 - LEFT		SHOULDER & LAP BELT			
Helmet Use		Helmet Compliance				
Eye Protection		Tint Compliance				

6TL0D5DZ56

26-01963

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMENT
1300 LANGE COURT
BARABOO, WI 53913
(608) 356-4895

02	002	Injury		Injury Severity NO APPARENT INJURY	Airbag NON DEPLOYED	
		Ejected NOT EJECTED	Ejection Path NOT EJECTED/NOT APPLICABLE	Trapped/Extricated NOT TRAPPED		
		Medical Transport NOT TRANSPORTED		EMS Agency Identifier	EMS Run #	
		Hospital		Date of Death	Time of Death	
		Distracted By		Distracted By Source UNKNOWN		
		Distracted By Action UNKNOWN				
		Non Motorist	Striking Unit #	Location		
		Prior Action				
UNIT	INDIVIDUAL	Action				
		Action Other				
		To/From School				
		Drug & Alcohol	Suspected Alcohol Use NO	Suspected Drug Use NO		
		Alcohol Test Given TEST NOT GIVEN	Alcohol Test Type		Alcohol Test Results	
		Drug Test Given TEST NOT GIVEN	Drug Test Type	Drug Test Results		
		Drug Type				
		Individual Condition APPEARED NORMAL				
Carrier						
02	002	<input checked="" type="checkbox"/> Use Vehicle Owner Same as Carrier		Source DRIVER		
		Name MEISE TRANSPORT LLC USDOT# 3116508		Address 232 MULBERRY ST PO BOX 118 SAUK CITY, WI 53583 , US		
UNIT	TRUCK BUS	GVWR 10,001-26,000 LBS	Vehicle Configuration VEHICLE PULLING TRAILERS		Cargo Body Type NO CARGO BODY - (BOBTAIL, LIGHT MOTOR	
		US DOT # 3116508	Carrier Type INTRASTATE CARRIER		Permitted Load NOT APPLICABLE	
		<input type="checkbox"/> OS/OW Load	WI Permit Number	<input type="checkbox"/> Permitted Vehicle On Permitted Route	<input type="checkbox"/> Escort Vehicle Required By Permit	<input type="checkbox"/> Escort Vehicle Present
		Measured Height	Measured Length	Measured Width	Measured Weight	