

6TLOGHS26P

26-06377

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMENT
1300 LANGE COURT
BARABOO, WI 53913
(608) 356-4895

6TLOGHS26P

Document Number Override		Primary Crash Document #	Agency Crash Number 26-06377	Investigating Officer/Deputy DEPUTY J. HUNTER	
Crash Date 06/18/2026		Crash Time 03:07 PM	Date Arrived 06/18/2026	Time Arrived 03:30 PM	
Date Notified 06/18/2026		Time Notified 03:07 PM	Total Units 01	Total Injured 01	Total Killed 00
<input type="checkbox"/> On Emergency	<input type="checkbox"/> Hit and Run	<input type="checkbox"/> Lane Closure	<input type="checkbox"/> Work Zone	<input type="checkbox"/> Trailer or Towed	<input type="checkbox"/> Reporting Threshold
<input type="checkbox"/> Government Property	<input type="checkbox"/> Active School Zone	School Bus Related NO		Tags	
<input checked="" type="checkbox"/> Reportable		Crash Type DT4000 (STANDARD CRASH)		<input type="checkbox"/> Amended	<input type="checkbox"/> Secondary Crash

Description

Diagram 	Reconstruction By
	Photos By DEPUTY HUNTER
	Additional Information PHOTOS

I, a sworn law enforcement officer, agree that I have not added any CJIS data in this report.

UNIT 1 WAS E/B ON HY 60. OPERATOR STATED HE WAS FEELING DROWSY BUT THOUGHT HE COULD STAY AWAKE. OPERATOR FELL ASLEEP AT THE WHEEL AND WOKE UP AS THE VEHICLE WAS EXITING THE ROADWAY. UNIT 1 ENTERED THE DITCH ON THE RIGHT HAND SIDE, CROSSED OVER CASSEL RD. AND WENT BACK INTO THE DITCH ON THE OTHER SIDE, WHERE THE VEHICLE CAME TO REST. PASSENGER IN UNIT 1 COMPLAINED OF A SORE NECK AND FOOT AND WAS TRANSPORTED TO SAUK PRAIRIE HOSPITAL VIA EMS.

6TL0GHS26P

26-06377

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMENT
1300 LANGE COURT
BARABOO, WI 53913
(608) 356-4895

Location

Table with location details: ON STH60 EB 232 FT S OF CASSELL RD IN THE TOWN OF TROY IN SAUK COUNTY. Includes Latitude (43.206097709), Longitude (-89.875673104), X Coordinate (266387.25), Y Coordinate (4787717.5), and Structure Type (NO STRUCTURE).

Crash Scene

Table with crash scene details: First Harmful Event (DITCH), Manner of Collision (00 - NO COLLISION W/VEHICLE IN TRANSPORT), Road Surface Condition (DRY), Environment Factor (NONE), Weather Condition (CLEAR), Animal Type, Crash Classification (PUBLIC PROPERTY), and Intersection Type (T-INTERSECTION).

Unit Summary

Table with unit summary details for Unit 01: Unit Status (IN TRANSIT), Vehicle Type (PASSENGER CAR), Total Occs (2), Direction of Travel (EASTBOUND), Most Harmful Event (DITCH), and Surface Type (BLACKTOP (BITUMINOUS)).

Table with vehicle details for Vehicle 01: License Plate Number (AC40331), Make (CHRY), Model (200), Color (GRY - GRAY), and Extent of Damage (DISABLING DAMAGE). Includes a diagram of a car with damage indicators.

WISCONSIN MOTOR VEHICLE
CRASH REPORT

UNIT VEHICLE	Towed Due To Damage TOWED DUE TO DISABLING DAMAGE		Vehicle Removed By EVERETTS TOWING	
	What Driver Was Doing NEGOTIATING CURVE		Vehicle Factors	
	Driver Prior Action Other		NOT APPLICABLE	
	Driver Actions FAILURE TO CONTROL, RAN OFF ROADWAY, OTHER CONTRIBUTING ACTION			
01 01	Owner Name GUADALUPE HERNANDEZ		Owner Address 1927 CLARENCE AVE APT 1 BERWYN, IL 60402 5040, US	
	Sequence Of Events			
01 01	01	Event DITCH		
	02	Event REENTERING ROADWAY		
	03	Event DITCH		
	04	Event		
UNIT	Policy Holder			
	Insurance Company STATE-FARM-GENERAL-INS-CO		INDIVIDUAL GUADALUPE HERNANDEZ	
UNIT INDIVIDUAL	Individual			
	DRIVER DIEGO MARQUEZ (708) 247-4405		Citations Issued 0	Sex MALE
	Address 5558 S MOBILE AVE CHICAGO, IL 60638 , US		Date of Birth	Race
			Driver License Number STATE: ILLINOIS COUNTRY: UNITED STATES	
01 001	Safety Equipment		On Duty Crash	
			Safety Equipment	
	Row 01 - FRONT ROW	Seat Position 07 - LEFT	SHOULDER & LAP BELT	
	Helmet Use		Helmet Compliance	
	Eye Protection		Tint Compliance	
	Injury		Injury Severity NO APPARENT INJURY	Airbag DEPLOYED-FRONT
Ejected NOT EJECTED		Ejection Path NOT EJECTED/NOT APPLICABLE		Trapped/Extricated NOT TRAPPED
Medical Transport NOT TRANSPORTED		EMS Agency Identifier		EMS Run #
Hospital		Date of Death		Time of Death
Distracted By		Distracted By Source OTHER DISTRACTION (ANIMAL, FOOD, GROOMING)		
Distracted By Action OTHER ACTION (LOOKING AWAY FROM TASK ETC)				

WISCONSIN MOTOR VEHICLE
CRASH REPORT

UNIT	INDIVIDUAL	Non Motorist		Striking Unit #	Location		
		Prior Action					
		Action					
01	001	Action Other					
		To/From School					
		Drug & Alcohol		Suspected Alcohol Use NO	Suspected Drug Use NO		
		Alcohol Test Given TEST NOT GIVEN		Alcohol Test Type		Alcohol Test Results	
		Drug Test Given TEST NOT GIVEN		Drug Test Type		Drug Test Results	
		Drug Type					
		Individual Condition APPEARED NORMAL					
		Individual					
		PASSENGER JAZMIN HERNANDEZ (224) 519-0987			Citations Issued 0	Sex FEMALE	
		Date of Birth			Race		
Address 1927 CLARENCE AVE BSMT BERWYN, IL 60402 , US			Driver License Number STATE: ILLINOIS COUNTRY: UNITED STATES				
01	002	Safety Equipment		On Duty Crash			
		Safety Equipment SHOULDER & LAP BELT					
		Row 01 - FRONT ROW	Seat Position 09 - RIGHT				
		Helmet Use		Helmet Compliance			
		Eye Protection		Tint Compliance			
		Injury		Injury Severity POSSIBLE INJURY	Airbag DEPLOYED-FRONT		
Ejected NOT EJECTED		Ejection Path NOT EJECTED/NOT APPLICABLE		Trapped/Extricated NOT TRAPPED			
Medical Transport EMS GROUND		EMS Agency Identifier 6000555		EMS Run #			
Hospital SAUK PRAIRIE HOSP		Date of Death		Time of Death			
Distracted By		Distracted By Source					
Distracted By Action							
Non Motorist		Striking Unit #	Location				

WISCONSIN MOTOR VEHICLE
CRASH REPORT

UNIT	INDIVIDUAL			
	Prior Action			
	Action			
	Action Other			To/From School
	Drug & Alcohol		Suspected Alcohol Use NO	Suspected Drug Use NO
	Alcohol Test Given TEST NOT GIVEN		Alcohol Test Type	Alcohol Test Results
	Drug Test Given TEST NOT GIVEN		Drug Test Type	Drug Test Results
	Drug Type			
	Individual Condition APPEARED NORMAL			
	01	002		