6TL09N3P4N

18-00598

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT **BARABOO, WI 53913** (608) 356-4895

	Document Number Override	18- Crash Time					ating Officer/Deputy TY C. FRANK		
7	Crash Date 01/17/2018			Date Arrived 01/17/2018 Total Units 01		Time Arrived 08:08 AM			
L	Date Notified 01/17/2018					Total Injured	d Total k	Killed	
OIFORING	On Emergency Hit	and Run	Lane Clos	ure	Work Zone	Trailer	or Towed	Reporting Threshold	
_ _ 0	Government Property	Active School Zone		School NO	Bus Related	Tags			
	✓ Reportable	Crash Type DT4000 (STANDARD CRASH) Amend					ded	Secondary Crash	
	Description								
	Diagram					(Photos By 9198		
	Georks Rd	failboxes			PHOTOS	momaton			
		E1	1411A 		N ot to s	scale			
	✓ I, a sworn law enforceme								
	ON THE ABOVE DATE AND TIME ROADWAY. UNIT ONE ENTERED NOTIFIED BY THIS DEPUTY.								

6TL09N3P4N 18-00598

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 01/17/2018

Crash Time 07:50 AM

	Loc	ation								
	_	E11411A GOERKS RI)		Latitu		Latitude			
	125	9 FT W			43	43.496441863		-89.753295022		
	OF	CRAWFORD ST			X	X Coordinate		Y Coordinate		
	(FIR	RE E11411A)		277394.03125		4819629				
		THE TOWN OF BARAE SAUK COUNTY	300			Structure Type FIRE				
	Cra	sh Scene								
	First	Harmful Event			l Fi	rst Harmful Event	Location			
	MAI	LBOX			ON ROADWAY					
	Man	ner of Collision			Lie	ght Condition				
	NO	COLLISION W/VEHIC	LE IN TRANSPORT			AYLIGHT				
		d Surface Condition(s)				oadway Factor(s)				
	SNO	OW, SLUSH								
	Envi	ronment Factor(s)								
	NOI	NE				OAD SURFACE TC)	CONDITION	I (WET, ICY, SNOW	, SLUSH,	
	Wea	ther Condition(s)				•				
	CLC	DUDY								
	Anim	nal Type			D ₄	Relation To Trafficway				
	/ (((((((((((((((((((таг турс				TRAFFICWAY - ON ROAD				
	Cras	sh Classification - Location			Cr	Crash Classification - Jurisdiction				
	PUE	BLIC PROPERTY			N	NO SPECIAL JURISDICTION				
	Triba	al Land				Access Control		Special St	udy	
	\\/ith	ithin Interchange Area				NO CONTROL				
	NO	in interchange Area	NON-JUNCTION		Intersection Type NOT AN INTERSECTION					
	Uni	t Summary			NOT AN IN	TERSECTION				
		t Summary Status		Vehicle Ope			Unit Type			
	Unit	Status		Vehicle Ope	erating As Class		Unit Type	BILE		
	Unit IN T			-	erating As Class		AUTOMO	BILE as Endorsements		
5	Unit IN T Vehi	Status RANSIT	.E	-	erating As Class		AUTOMO			
5	Unit IN T Vehi (SP	Status *RANSIT cle Type	.E Train/Bus # Injured	D CLASS	erating As Class		AUTOMO Operating A			
5	Unit IN T Vehi (SP	Status RANSIT cle Type ORT) UTILITY VEHICL		D CLASS	erating As Class	sification	AUTOMO Operating A	s Endorsements		
5	Unit IN T Vehi (SP) Tota 1	Status RANSIT cle Type ORT) UTILITY VEHICL I Occs	Train/Bus # Injured Direction Of Travel	Total # Cita 0 Pre	erating As Class	Total Tra 0 Speed L	AUTOMO Operating A	Total HazMat Types 0 Total Lanes		
	Unit IN T Vehi (SP) Tota 1 Insur YES	Status RANSIT cle Type ORT) UTILITY VEHICL I Occs rance?	Train/Bus # Injured Direction Of Travel WESTBOUND	Total # Cita 0 Pre	erating As Class utions Issued CrashTire Mark	Total Tra	AUTOMO Operating A ailers	Total HazMat Types Total Lanes 2		
	Unit IN T Vehi (SP) Tota 1 Insul YES	Status RANSIT cle Type ORT) UTILITY VEHICL I Occs rance? 6 t Harmful Event: Collision V	Train/Bus # Injured Direction Of Travel WESTBOUND	Total # Cita 0 Pre Special Fur	erating As Class utions Issued CrashTire Mark	Total Tra 0 Speed L 35	AUTOMO Operating A ailers	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use		
	Unit IN T Vehi (SP Tota 1 Insu YES Mosi	Status RANSIT cle Type ORT) UTILITY VEHICL I Occs rance? St t Harmful Event: Collision VILBOX	Train/Bus # Injured Direction Of Travel WESTBOUND	Total # Cita 0 Pre Special Fur NO SPEC	erating As Class ations Issued CrashTire Mark action CIAL FUNCTION	Total Tra 0 Speed L 35	AUTOMO Operating A ailers imit Emergency NOT APP	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE		
	Unit IN T Vehi (SP Tota 1 Insu YES Most MAI Traff	Status RANSIT cle Type ORT) UTILITY VEHICL I Occs rance? 6 t Harmful Event: Collision V	Train/Bus # Injured Direction Of Travel WESTBOUND With	Total # Cita 0 Pre Special Fur	erating As Class attions Issued CrashTire Mark action CIAL FUNCTIO	Total Tra 0 Speed L 35	AUTOMO Operating A ailers imit Emergency NOT APP	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use		
	Unit IN T Vehi (SP) Tota 1 Insui YES Mosi MAI Traff	Status RANSIT cle Type ORT) UTILITY VEHICL I Occs rance? St Harmful Event: Collision VILBOX fic Way	Train/Bus # Injured Direction Of Travel WESTBOUND With	Total # Cita 0 Pre Special Fur NO SPEC	erating As Class utions Issued CrashTire Mark nction CIAL FUNCTIO	Total Tra 0 Speed L 35	AUTOMO Operating A ailers imit Emergency NOT APP Traffic Cont	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing		
	Unit IN T Vehi (SP Tota 1 Insure YES MAI Traff TW(Surfa	Status RANSIT cle Type ORT) UTILITY VEHICL I Occs rance? St Harmful Event: Collision VilLBOX fic Way D-WAY, NOT DIVIDED	Train/Bus # Injured Direction Of Travel WESTBOUND With	Total # Cita 0 Pre Special Fur NO SPEC Traffic Cont	erating As Class utions Issued CrashTire Mark nation CIAL FUNCTION trol FROL ature	Total Tra 0 Speed L 35	AUTOMO Operating A ailers imit Emergency NOT APP Traffic Cont	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing		
	Unit IN T Vehi (SP Tota 1 Insur YES MASI Traff TWC Surfat BLA Truc	Status FRANSIT cle Type ORT) UTILITY VEHICL I Occs rance? St Harmful Event: Collision VILBOX iic Way D-WAY, NOT DIVIDED ace Type	Train/Bus # Injured Direction Of Travel WESTBOUND With	Total # Cita 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva	erating As Class utions Issued CrashTire Mark nation CIAL FUNCTION trol FROL ature	Total Tra 0 Speed L 35	AUTOMO Operating A ailers imit Emergency NOT APP Traffic Cont NO Road Grade	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing		
	Unit IN T Vehi (SP) Tota 1 Insul YES Most MAI Traff TWG Surfa BLA Truc NO	Status RANSIT cle Type ORT) UTILITY VEHICL I Occs rance? St Harmful Event: Collision VILBOX fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU k Bus or HazMat	Train/Bus # Injured Direction Of Travel WESTBOUND With	Total # Cita 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva	erating As Class utions Issued CrashTire Mark nation CIAL FUNCTION trol FROL ature	Total Tra 0 Speed L 35	AUTOMO Operating A ailers imit Emergency NOT APP Traffic Cont NO Road Grade	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing		
	Unit IN T Vehi (SP) Tota 1 Insul YES Most MAI Traff TWG Surfa BLA Truc NO	Status RANSIT cle Type ORT) UTILITY VEHICL I Occs rance? St Harmful Event: Collision Villebox ric Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU k Bus or HazMat	Train/Bus # Injured Direction Of Travel WESTBOUND With	Total # Cita 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva STRAIGH	erating As Class attions Issued CrashTire Mark action CIAL FUNCTIO trol FROL atture	Total Tra 0 Speed L 35	AUTOMO Operating A ailers imit Emergency NOT APP Traffic Cont NO Road Grade UPHILL	Total HazMat Types O Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing		
	Unit IN T Vehi (SP) Tota 1 Insul YES Most MAI Traff TWG Surfa BLA Truc NO	Status RANSIT cle Type ORT) UTILITY VEHICL I Occs rance? St Harmful Event: Collision V ILBOX ric Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU k Bus or HazMat Vehicle License Plate Number	Train/Bus # Injured Direction Of Travel WESTBOUND With	Total # Cita 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva STRAIGH	erating As Class titions Issued CrashTire Mark nction CIAL FUNCTIO TROL ature	Total Tra 0 Speed L 35	AUTOMO Operating A ailers imit Emergency NOT APP Traffic Cont NO Road Grade UPHILL	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing		
	Unit IN T Vehi (SP) Tota 1 Insul YES Most MAI Traff TWG Surfa BLA Truc NO	Status RANSIT cle Type ORT) UTILITY VEHICL I Occs rance? St Harmful Event: Collision Villebox fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU k Bus or HazMat Vehicle License Plate Number 363XPB	Train/Bus # Injured Direction Of Travel WESTBOUND With	Total # Cita 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva STRAIGH	erating As Class attions Issued CrashTire Mark action CIAL FUNCTIO trol FROL atture	Total Tra 0 Speed L 35 ON	AUTOMO Operating A ailers imit Emergency NOT APP Traffic Cont NO Road Grade UPHILL Country of Is UNITED S	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing		
	Unit IN T Vehi (SP) Tota 1 Insul YES Most MAI Traff TWG Surfa BLA Truc NO	Status RANSIT cle Type ORT) UTILITY VEHICL I Occs rance? St Harmful Event: Collision V ILBOX ric Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU k Bus or HazMat Vehicle License Plate Number	Train/Bus # Injured Direction Of Travel WESTBOUND With	Total # Cita 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva STRAIGH	erating As Class attions Issued CrashTire Mark Cital FUNCTIO TROL attire IT	Total Tra 0 Speed L 35	AUTOMO Operating A ailers imit Emergency NOT APP Traffic Cont NO Road Grade UPHILL	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing		
	Unit IN T Vehi (SP Tota 1 Insury YES MAI Traff TWC Surfa BLA Truc	Status RANSIT cle Type ORT) UTILITY VEHICL I Occs rance? St Harmful Event: Collision VILBOX fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU k Bus or HazMat Vehicle License Plate Number 363XPB Vehicle Identification Nur 2GNALPEC7B11774: Color	Train/Bus # Injured Direction Of Travel WESTBOUND With	Total # Cita 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva STRAIGH Plate Type AUT - AU Make CHEVRO Body Style	erating As Class ditions Issued CrashTire Mark notion CIAL FUNCTIO trol FROL ature IT JTOMOBILE DLET	Total Tra 0 Speed L 35 ON St WI Year 2011	AUTOMO Operating A ailers imit Emergency NOT APP Traffic Cont NO Road Grade UPHILL Country of Is UNITED S' Model EQUINOX Bus Use	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing		
	Unit IN T Vehi (SP Tota 1 Insur YES MAI Traff TWO Surfa BLA Truc NO	Status RANSIT cle Type ORT) UTILITY VEHICL I Occs rance? St Harmful Event: Collision V ILBOX fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU k Bus or HazMat Vehicle License Plate Number 363XPB Vehicle Identification Nur 2GNALPEC7B11774: Color GLD - GOLD	Train/Bus # Injured Direction Of Travel WESTBOUND With	Total # Cita 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva STRAIGH Plate Type AUT - AU Make CHEVRO Body Style UT - SPC	erating As Class crashTire Mark notion CIAL FUNCTION trol FROL ature IT JTOMOBILE DLET DET DET DET DET DET DET DET DET DET D	Total Tra 0 Speed L 35 ON St WI Year 2011	AUTOMO Operating A ailers imit Emergency NOT APP Traffic Cont NO Road Grade UPHILL Country of Is UNITED S' Model EQUINOX	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing		
	Unit IN T Vehi (SP Tota 1 Insur YES MAI Traff TWO Surfa BLA Truc NO	Status RANSIT cle Type ORT) UTILITY VEHICL I Occs rance? St Harmful Event: Collision VILBOX fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU k Bus or HazMat Vehicle License Plate Number 363XPB Vehicle Identification Nur 2GNALPEC7B11774: Color	Train/Bus # Injured Direction Of Travel WESTBOUND With S)	Total # Cita 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva STRAIGH Plate Type AUT - AU Make CHEVRO Body Style	erating As Class crashTire Mark notion CIAL FUNCTION trol FROL ature IT JTOMOBILE DLET DET DET DET DET DET DET DET DET DET D	Total Tra 0 Speed L 35 ON St WI Year 2011	AUTOMO Operating A ailers imit Emergency NOT APP Traffic Cont NO Road Grade UPHILL Country of Is UNITED S' Model EQUINOX Bus Use	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing		
	Unit IN T Vehi (SP Tota 1 Insury YES MAI Traff TWC Surfa BLA Truc	Status RANSIT cle Type ORT) UTILITY VEHICL I Occs rance? St Harmful Event: Collision VILBOX fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU k Bus or HazMat Vehicle License Plate Number 363XPB Vehicle Identification Nur 2GNALPEC7B11774: Color GLD - GOLD Initial Contact Point	Train/Bus # Injured Direction Of Travel WESTBOUND With S)	Total # Cita 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva STRAIGH Plate Type AUT - AU Make CHEVRO Body Style UT - SPO Vehicle Da	crating As Class distions Issued CrashTire Mark notion CIAL FUNCTION TROL ature IT JTOMOBILE DET DET DRT UTILITY	Sification Total Tra 0 Speed L 35 DN St WI Year 2011 VEHICLE	AUTOMO Operating A ailers imit Emergency NOT APP Traffic Cont NO Road Grade UPHILL Country of Is UNITED S Model EQUINOX Bus Use NOT A BU	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing	MIDDLE	

6TL09N3P4N

18-00598

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

		Towed Due To Dama NOT TOWED	ge	Vehicle Removed By					
		What Driver Was Doing		Vehicle Factors					
		GOING STRAIGHT							
		Driver Prior Action Other		NOT APPLICABLE					
LINO	VEHICLE	Driver Actions SPEED TOO FAST/COND, FAILURE TO CONTROL, RAN OFF ROADWAY							
		Driver Distractions NOT DISTRACTED							
5	2								
		Owner Name RONALD MUNNEKE (608) 963-0292		Owner Address					
				S3658 N BENT TREE DR BARABOO, WI 53913 , US					
		(****, **** *							
	(Sequence Of Events							
	٦	Event MAILBOX							
	Event								
	03	Event							
	40	Event							
		Policy Holder							
L		Insurance Company		Individual					
5		AMERICAN-FAMILY-INS-CO		RONALD MUNNEKE					
	1	Individual							
		Driver		Citations Issued	Sex				
	7	MELISSA MUNNEKE (608) 963-3690		0	FEMALE				
	INDIVIDUAL			Date of Birth	Race WHITE				
EN		Address S3658 N BENT TREE DR BARABOO, WI 53913 , US		Driver License Number					
_				STATE: WISCONSIN COUNTRY: UNITED STATES					
				OTATE. WIGOONOM GOOM IN TO SMITED OTATES					
		Equipment	On Duty Crash	Safety Equipment					
				SHOULDER & LAP BELT Helmet Compliance					
		Seat Position 1FRONT SEAT-LEFT SIDE (DRIVER/MOTORCY Helmet Use Eye Protection							
				Tint Compliance					
	_		Injury Severity	Airbag					
5	00	Injury NO APPARENT INJURY		NON DEPLOYED					
		Ejected		Ejection Path	Trapped/Extricated				
		NOT EJECTED		NOT EJECTED/NOT APPLICABL	NOT TRAPPED				

6TL09N3P4N 18-00598

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT **BARABOO, WI 53913** (608) 356-4895

		Medical Transport NOT TRANSPORTED			EMS Agency Identifier		EMS Run#			
		Hospital			Date of Death		Time of Death			
		Non Motoris	Striking Unit #	Prior Action		Location		To/From School		
UNIT	INDIVIDUAL	Action								
		Action Other								
	Drug & Alcohol Suspected Alcohol Use NO				Suspected Drug Use NO					
		Alcohol Test Giver TEST NOT GIV			Alcohol Test Type		Alcohol Test Results			
		Drug Test Given TEST NOT GIV	EN		Drug Test Type		Drug Test Results			
10	001	Drug Type								
		Individual Condition								
		APPEARED NO								
	Pro	roperty Owner								
PROP 01	(608	ridual CKY GIEBEL 3) 477-1213			Address E11411A GOERK BARABOO, WI 53	S RD 1913 , US				
	Fixe	ed Objects St	ruck							
	2		Struck Object MAILBOX				Structure Number	Damage Tag Number		