
6TL097RB1G

18-01280

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895



6TL097RB1G

18-01280

WISCONSIN MOTOR VEHICLE CRASH REPORT

-	2									
	UN	S8903A USH12 WB				Latitude		Longitud		
) MI N		43.322060261			-89.759	0105393		
		PRAIRIE RD			X Coordinate 276282.8125			Y Coord	linate	
	(HO	USE/BUILDING S8903						480027		
					Structure			4000211.5		
	IN 3	SAUK COUNTY		HOUSE/BUILDING						
(Cra	sh Scene 🛛 🗖								
1	First	Harmful Event				First Harm	nful Event Lo	ocation		
	DIT	СН			MEDIAN BARRIER					
		ner of Collision								
		COLLISION W/VEHIC								
	-				DAYLIGHT					
	Road	d Surface Condition(s)				Roadway	Factor(s)			
	SNO	OW, SLUSH, ICE								
	Envi	ronment Factor(s)								
		ronment Factor(s)			ROADS		CONDITION	WFT 10	CY, SNOW, SLUSH,	
	WE	ATHER CONDITIONS				ETC)		Comprision		
	W/02	ther Condition(s)				,				
		. ,								
	CLC	DUDY, BLOWING SNC)W							
	Anim	nal Type				Relation T	o Trafficway	V		
	Animal Type					Relation To Trafficway TRAFFICWAY - NOT ON ROAD				
	Crat	h Classification Lasting								
	Crash Classification - Location PUBLIC PROPERTY					Crash Classification - Jurisdiction				
						NO SPECIAL JURISDICTION				
	Iriba	al Land				Access Control Special Study		Special Study		
				Intersection		on Type				
	With	in Interchange Area	Junction Location							
	NO NON-JUNCTION			NOT AN INTERSEC				ION		
	110		NON-JONCTION		NOT AN	INTERSE	CTION			
	-	t Summary	NON-JONCTION		NOT AN	INTERSE	CTION			
	Uni	t Summary	NON-JUNCTION	Vehicle One						
	Uni t	Status	NON-JONC HON		erating As Cl					
	Unit Unit	Status RANSIT	NON-JONC HON	Vehicle Ope D CLASS	erating As Cl			AUTOMO		
	Unit Unit IN T Vehi	Status RANSIT cle Type	NON-JONC HON		erating As Cl					ments
01	Unit Unit IN T Vehi PAS	Status RANSIT cle Type SSENGER CAR			erating As Cl			AUTOMO Operating A	s Endorsei	
	Unit Unit IN T Vehi PAS	Status RANSIT cle Type	Train/Bus # Injured	D CLASS	erating As Cl	lassification		AUTOMO Operating A	s Endorsei	ments Mat Types
	Unit Unit IN T Vehi PAS	Status RANSIT cle Type SSENGER CAR		D CLASS	erating As C	lassification		AUTOMO Operating A	s Endorsei	
	Unit Unit IN T Vehi PAS Tota 1	Status RANSIT cle Type SSENGER CAR		D CLASS	erating As C	lassification	Total Trail	AUTOMO Operating A ers	s Endorsei Total Haz	Mat Types
01	Unit Unit IN T Vehi PAS Tota 1	Status RANSIT cle Type SSENGER CAR I Occs rance?	Train/Bus # Injured	D CLASS	erating As C	lassification	Total Trail	AUTOMO Operating A ers	s Endorsei Total Haz 0	Mat Types
01	Unit Unit IN T Vehi PAS Tota 1 Insu	Status RANSIT cle Type SSENGER CAR I Occs rance? S	Train/Bus # Injured Direction Of Travel NORTHBOUND	D CLASS	erating As Cl ations Issued CrashTire Mark	lassification	Total Trail 0 Speed Lin	AUTOMO Operating A ers	s Endorsei Total Haz 0 Total Lan 4	Mat Types es
	Unit Unit IN T Vehi PAS Tota 1 Insu	Status RANSIT cle Type SSENGER CAR I Occs rance? S t Harmful Event: Collision 1	Train/Bus # Injured Direction Of Travel NORTHBOUND	D CLASS	erating As Cl ations Issued CrashTire Mark	lassification	Total Trail 0 Speed Lin	AUTOMO Operating A ers	s Endorsel Total Haz 0 Total Lan 4 Motor Veh	Mat Types es icle Use
01	Unit Unit IN T Vehi PAS Tota 1 Insur YES Most	Status RANSIT cle Type SSENGER CAR I Occs rance? S t Harmful Event: Collision ' CH	Train/Bus # Injured Direction Of Travel NORTHBOUND	D CLASS	erating As Cl ations Issued CrashTire Mark CIAL FUNC	lassification	Total Trail 0 Speed Lin	AUTOMO Operating A ers hit Emergency NOT APP	s Endorser Total Haz 0 Total Lan 4 Motor Veh LICABLE	Mat Types es icle Use
01	Unit Unit IN T Vehi PAS Tota 1 Insur YES Most DIT Traff	Status RANSIT cle Type SSENGER CAR I Occs rance? S t Harmful Event: Collision ¹ CH ic Way	Train/Bus # Injured Direction Of Travel NORTHBOUND With	D CLASS	erating As Cl ations Issued CrashTire Mark CIAL FUNC trol	lassification	Total Trail 0 Speed Lin	AUTOMO Operating A ers nit Emergency NOT APP Traffic Cont	s Endorser Total Haz 0 Total Lan 4 Motor Veh LICABLE	Mat Types es icle Use
01	Unit Unit IN T Vehi PAS Tota 1 Insu YES Most DIT Traff	Status RANSIT cle Type SSENGER CAR I Occs rance? S t Harmful Event: Collision 1 CH ic Way D-WAY, DIVIDED, UNI	Train/Bus # Injured Direction Of Travel NORTHBOUND	D CLASS	erating As Cl tions Issued CrashTire Mark Inction CIAL FUNC trol	lassification	Total Trail 0 Speed Lin	AUTOMO Operating A ers nit Emergency NOT APP Traffic Cont NO	Total Haz 0 Total Lan 4 Motor Veh LICABLE rol Inopera	Mat Types es icle Use
01	Unit Unit IN T Vehi PAS Tota 1 Insuu YES DIT Traff TW(C Surfa	Status RANSIT cle Type SSENGER CAR I Occs rance? S t Harmful Event: Collision 1 CH ic Way D-WAY, DIVIDED, UNF ace Type	Train/Bus # Injured Direction Of Travel NORTHBOUND With	D CLASS	erating As Cl titions Issued CrashTire Mark Inction CIAL FUNC trol IROL ature	lassification	Total Trail 0 Speed Lin	AUTOMO Operating A ers nit Emergency NOT APP Traffic Cont NO Road Grade	Total Haz 0 Total Lan 4 Motor Veh LICABLE rol Inopera	Mat Types es icle Use
01	Unit Unit IN T Vehi PAS Tota 1 Insuu YES Most DIT Traff TWO Surfa	Status RANSIT cle Type SSENGER CAR I Occs rance? Harmful Event: Collision 1 CH ic Way D-WAY, DIVIDED, UNF ace Type NCRETE	Train/Bus # Injured Direction Of Travel NORTHBOUND With	D CLASS	erating As Cl titions Issued CrashTire Mark Inction CIAL FUNC trol IROL ature	lassification	Total Trail 0 Speed Lin	AUTOMO Operating A ers nit Emergency NOT APP Traffic Cont NO	Total Haz 0 Total Lan 4 Motor Veh LICABLE rol Inopera	Mat Types es icle Use
01	Unit Unit IN T Vehi PAS Tota 1 Insu YES Most DIT Traff Two Surfa COI Truc	Status RANSIT cle Type SSENGER CAR I Occs rance? S t Harmful Event: Collision 1 CH ic Way D-WAY, DIVIDED, UNF ace Type	Train/Bus # Injured Direction Of Travel NORTHBOUND With	D CLASS	erating As Cl titions Issued CrashTire Mark Inction CIAL FUNC trol IROL ature	lassification	Total Trail 0 Speed Lin	AUTOMO Operating A ers nit Emergency NOT APP Traffic Cont NO Road Grade	Total Haz 0 Total Lan 4 Motor Veh LICABLE rol Inopera	Mat Types es icle Use
01	Unit Unit IN T Vehi PAS Tota 1 Insuu YES Most DIT Traff TWO Surfa	Status RANSIT cle Type SSENGER CAR I Occs rance? Tharmful Event: Collision 1 CH CH Tic Way D-WAY, DIVIDED, UNF ace Type NCRETE	Train/Bus # Injured Direction Of Travel NORTHBOUND With	D CLASS	erating As Cl titions Issued CrashTire Mark Inction CIAL FUNC trol IROL ature	lassification	Total Trail 0 Speed Lin	AUTOMO Operating A ers nit Emergency NOT APP Traffic Cont NO Road Grade	Total Haz 0 Total Lan 4 Motor Veh LICABLE rol Inopera	Mat Types es icle Use
01	Unit Unit IN T Vehi PAS Tota 1 Insuu YES Most DIT Traff TWC Surfa COI Truc NO	Status RANSIT cle Type SSENGER CAR I Occs rance? Tharmful Event: Collision 1 CH CH Tic Way D-WAY, DIVIDED, UNF ace Type NCRETE	Train/Bus # Injured Direction Of Travel NORTHBOUND With	D CLASS	erating As Cl titions Issued CrashTire Mark Inction CIAL FUNC trol IROL ature	lassification	Total Trail 0 Speed Lin	AUTOMO Operating A ers nit Emergency NOT APP Traffic Cont NO Road Grade	Total Haz 0 Total Lan 4 Motor Veh LICABLE rol Inopera	Mat Types es icle Use
01	Unit Unit IN T Vehi PAS Tota 1 Insuu YES Most DIT Traff TWC Surfa COI Truc NO	Status RANSIT cle Type SSENGER CAR I Occs rance? S t Harmful Event: Collision 1 CH ic Way D-WAY, DIVIDED, UNF ace Type NCRETE k Bus or HazMat	Train/Bus # Injured Direction Of Travel NORTHBOUND With	D CLASS	erating As Cl titions Issued CrashTire Mark CIAL FUNC trol TROL ature IT	lassification	Total Trail 0 Speed Lin	AUTOMO Operating A ers nit Emergency NOT APP Traffic Cont NO Road Grade	Total Haz 0 Total Lan 4 Motor Veh LICABLE rol Inopera	Mat Types es icle Use
01	Unit Unit IN T Vehi PAS Tota 1 Insuu YES Most DIT Traff TWC Surfa COI Truc NO	Status RANSIT cle Type SSENGER CAR I Occs rance? S t Harmful Event: Collision 1 CH ic Way D-WAY, DIVIDED, UNF ace Type NCRETE k Bus or HazMat Vehicle	Train/Bus # Injured Direction Of Travel NORTHBOUND With	D CLASS	erating As Cl titions Issued CrashTire Mark CIAL FUNC trol TROL ature IT	TION	Total Trail 0 Speed Lin 55	AUTOMO Operating A ers nit Emergency NOT APP Traffic Cont NO Road Grade LEVEL	suance	Mat Types es icle Use
UNIT 01	Unit Unit IN T Vehi PAS Tota 1 Insuu YES Most DIT Traff TWC Surfa COI Truc NO	Status RANSIT cle Type SSENGER CAR I Occs rance? S t Harmful Event: Collision 1 CH fic Way D-WAY, DIVIDED, UNF ace Type NCRETE k Bus or HazMat Vehicle License Plate Number 740WZT	Train/Bus # Injured Direction Of Travel NORTHBOUND With PROTECTED (PAINTED >	D CLASS	erating As Cl titions Issued CrashTire Mark CIAL FUNC trol TROL ature IT	TION	Total Trail 0 Speed Lin 55 St WI	AUTOMO Operating A ers nit Emergency NOT APP Traffic Cont NO Road Grade LEVEL	suance	Mat Types es icle Use
UNIT 01	Unit Unit IN T Vehi PAS Tota 1 Insuu YES DIT Traff TWO Surfa COI Truc NO	Status RANSIT cle Type SSENGER CAR I Occs rance? S t Harmful Event: Collision 1 CH ic Way D-WAY, DIVIDED, UNF ace Type NCRETE k Bus or HazMat Vehicle License Plate Number 740WZT Vehicle Identification Nur	Train/Bus # Injured Direction Of Travel NORTHBOUND With PROTECTED (PAINTED >	D CLASS	erating As Cl titions Issued CrashTire Mark Inction CIAL FUNC trol IROL ature IT	TION	Total Trail 0 Speed Lin 55 St WI Year	AUTOMO Operating A ers nit Emergency NOT APP Traffic Cont NO Road Grade LEVEL	s Endorser Total Haz 0 Total Lan 4 Motor Veh LICABLE rol Inopera	Mat Types es icle Use
UNIT 01	Unit Unit IN T Vehi PAS Tota 1 Insuu YES Most DIT Traff TWC Surfa COI Truc NO	Status RANSIT cle Type SSENGER CAR I Occs rance? S t Harmful Event: Collision 1 CH fic Way D-WAY, DIVIDED, UNF ace Type NCRETE k Bus or HazMat Vehicle License Plate Number 740WZT Vehicle Identification Nur 2C3HD46R3YH42710	Train/Bus # Injured Direction Of Travel NORTHBOUND With PROTECTED (PAINTED >	D CLASS	erating As Cl tions Issued CrashTire Mark Diction CIAL FUNC trol TROL ature IT	TION	Total Trail 0 Speed Lin 55 St WI	AUTOMO Operating A ers nit Emergency NOT APP Traffic Cont NO Road Grade LEVEL Country of Is UNITED S ^T Model CONCORE	s Endorser Total Haz 0 Total Lan 4 Motor Veh LICABLE rol Inopera	Mat Types es icle Use
UNIT 01	Unit Unit IN T Vehi PAS Tota 1 Insuu YES DIT Traff TWO Surfa COI Truc NO	Status RANSIT cle Type SSENGER CAR I Occs rance? S t Harmful Event: Collision 1 CH ic Way D-WAY, DIVIDED, UNF ace Type NCRETE k Bus or HazMat Vehicle License Plate Number 740WZT Vehicle Identification Nur 2C3HD46R3YH42710 Color	Train/Bus # Injured Direction Of Travel NORTHBOUND With PROTECTED (PAINTED >	D CLASS	erating As Cl tions Issued CrashTire Mark Diction CIAL FUNC trol TROL ature IT	TION	Total Trail 0 Speed Lin 55 St WI Year	AUTOMO Operating A ers nit Emergency NOT APP Traffic Cont NO Road Grade LEVEL Country of Is UNITED S ^T Model CONCORE Bus Use	s Endorser Total Haz 0 Total Lan 4 Motor Veh LICABLE rol Inopera suance FATES	Mat Types es icle Use
UNIT 01	Jnii Unit INT Vehi PAS Tota 1 Insuu YES Most DIT COI Traff TWC Surfa COI Truc NO	Status RANSIT Cle Type SSENGER CAR I Occs I Occs t Harmful Event: Collision 1 CH Tic Way D-WAY, DIVIDED, UNF ace Type NCRETE k Bus or HazMat Vehicle License Plate Number 740WZT Vehicle Identification Nur 2C3HD46R3YH42710 Color SIL - SILVER (ALUM	Train/Bus # Injured Direction Of Travel NORTHBOUND With PROTECTED (PAINTED >	D CLASS Total # Cita 0 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva STRAIGH Plate Type AUT - AU Make CHRYSL Body Style SD - SED	erating As Cl erating As Cl trions Issued CrashTire Mark DIAL FUNC trol IT CROL ature IT JTOMOBIL ER DAN	TION	Total Trail 0 Speed Lin 55 St WI Year	AUTOMO Operating A ers nit Emergency NOT APP Traffic Cont NO Road Grade LEVEL Country of Is UNITED S ^T Model CONCORE	s Endorser Total Haz 0 Total Lan 4 Motor Veh LICABLE rol Inopera suance FATES	Mat Types es icle Use
01 UNIT 01	Jnii Unit Unit IN T Vehi PAS Tota 1 Insui YES Most DIT Traff TWO Surfa COI Truc NO	Status RANSIT Cle Type SSENGER CAR I Occs rance? t Harmful Event: Collision 1 CH fic Way D-WAY, DIVIDED, UNF ace Type NCRETE k Bus or HazMat Vehicle Identification Nur 2C3HD46R3YH42710 Color SIL - SILVER (ALUM Initial Contact Point	Train/Bus # Injured Direction Of Travel NORTHBOUND With PROTECTED (PAINTED >	D CLASS	erating As Cl erating As Cl trions Issued CrashTire Mark DIAL FUNC trol IT CROL ature IT JTOMOBIL ER DAN	TION	Total Trail 0 Speed Lin 55 St WI Year	AUTOMO Operating A ers nit Emergency NOT APP Traffic Cont NO Road Grade LEVEL Country of Is UNITED S ^T Model CONCORE Bus Use	s Endorser Total Haz 0 Total Lan 4 Motor Veh LICABLE rol Inopera suance FATES	Mat Types es icle Use
01 UNIT 01	Jnii Unit Unit IN T Vehi PAS Tota 1 Insui YES Most DIT Traff TWO Surfa COI Truc NO	Status RANSIT Cle Type SSENGER CAR I Occs rance? S t Harmful Event: Collision 1 CH Tic Way D-WAY, DIVIDED, UNF ace Type NCRETE k Bus or HazMat Vehicle License Plate Number 740WZT Vehicle Identification Nur 2C3HD46R3YH42710 Color SIL - SILVER (ALUM Initial Contact Point 12FRONT	Train/Bus # Injured Direction Of Travel NORTHBOUND With PROTECTED (PAINTED >	D CLASS Total # Cita 0 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva STRAIGH Plate Type AUT - AU Make CHRYSL Body Style SD - SED Vehicle Da	erating As Cl tions Issued CrashTire Mark notion ClAL FUNC trol TROL ature IT JTOMOBIL ER DAN amage	TION	Total Trail 0 Speed Lin 55 St WI Year	AUTOMO Operating A ers nit Emergency NOT APP Traffic Cont NO Road Grade LEVEL Country of Is UNITED S ^T Model CONCORE Bus Use	s Endorser Total Haz 0 Total Lan 4 Motor Veh LICABLE rol Inopera suance FATES	Mat Types es icle Use
UNIT 01	Jnii Unit INT Vehi PAS Tota 1 Insuu YES Most DIT COI Traff TWC Surfa COI Truc NO	Status RANSIT Cle Type SSENGER CAR I Occs rance? t Harmful Event: Collision 1 CH fic Way D-WAY, DIVIDED, UNF ace Type NCRETE k Bus or HazMat Vehicle Identification Nur 2C3HD46R3YH42710 Color SIL - SILVER (ALUM Initial Contact Point	Train/Bus # Injured Direction Of Travel NORTHBOUND With PROTECTED (PAINTED > nber D7	D CLASS Total # Cita 0 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva STRAIGH Plate Type AUT - AU Make CHRYSL Body Style SD - SED	erating As Cl tions Issued CrashTire Mark notion ClAL FUNC trol TROL ature IT JTOMOBIL ER DAN amage	TION	Total Trail 0 Speed Lin 55 St WI Year	AUTOMO Operating A ers nit Emergency NOT APP Traffic Cont NO Road Grade LEVEL Country of Is UNITED S ^T Model CONCORE Bus Use	s Endorser Total Haz 0 Total Lan 4 Motor Veh LICABLE rol Inopera suance FATES	Mat Types es icle Use



18-01280

WISCONSIN MOTOR VEHICLE **CRASH REPORT**

		Towed Due To Dama		Vehicle Re	moved By				
		TOWED DUE TO DISABLING DAMAGE							
		What Driver Was Doing		Vehicle Fa	ctors				
		GOING STRAIGHT Driver Prior Action Other							
				NOT APP	PLICABLE				
		Driver Actions							
	щ	SPEED TOO FAST/COND, FAILURE TO CONTROL, RAN OFF ROADWAY							
UNIT	CL								
S	H								
-	VEHICLE								
	-								
		Driver Distractions							
		UNKNOWN IF DISTRACTED							
_	_								
01	01								
		Owner Name		Owner	r Address				
		MEGAN WALLEN	1	823 E WOODLAND TRL					
		(608) 359-3440		PRAI	RIE DU SAC, WI 53578 ,US				
		Sequence Of E	vents						
	Sequence Of Events								
	0	5 RUN OFF ROADWAY LEFT							
	02	Event DITCH							
		Event							
	03	LVOIR							
	04	Event							
L		Policy Holder							
UNIT		Insurance Company Individual							
		AMERICAN-FAMI	LY-INS-CO	MEGA	MEGAN WALLEN				
		Individual							
		Driver		Citations	sissued	Sex			
		MEGAN WALLEN		0		FEMALE			
	AL			Date of I	Birth	Race			
_	DC			Date of	Bitti	WHITE			
UNIT	INDIVIDUA	Address		Driver Li	icense Number				
D	D	823 E WOODLAND TRL PRAIRIE DU SAC, WI 53578 , US							
	N			STATE: WISCONSIN COUNTRY: UNITED STATES					
		L	On Duty Crash	Safetv F	quipment				
		Equipment			-1F				
	1	Seat Position		SHOUL	_DER & LAP BELT				
		1FRONT SEAT-LEFT SIDE (DRIVER/MOTORCY							
		Helmet Use		Helmet (Compliance				
		Eye Protection		Tint Con	npliance				
-	3		Injury Severity	Airbag					
01	001	Injury	NO APPARENT INJURY	NON D	EPLOYED				
		Ejected		Ejection Path Trapped/Extricated					
		NOT EJECTED		NOT E	JECTED/NOT APPLICABL	NOT TRAPPED			
Wisco	nsin N	Notor Vehicle Crash	This rep	ort does not	include any CJIS data.	Crash Date	02/04/2018		

6TL097RB1G

18-01280

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

		Medical Transport NOT TRANSPOR	TED		EMS Agency Identifier		EMS Run #		
		Hospital			Date of Death		Time of Death		
		Non Motorist	Striking Unit #	Prior Action		Location		To/From School	
		Action							
UNIT	INDIVIDUAL								
	Z	Action Other							
	Ľ	Drug & Alcohol	Suspected Alcohol L NO	Jse	Suspected Drug Us	se			
		Alcohol Test Given TEST NOT GIVEN			Alcohol Test Type		Alcohol Test Results		
		Drug Test Given TEST NOT GIVEN	l		Drug Test Type		Drug Test Results		
6	001	Drug Type							
		Individual Condition							
		APPEARED NORI	MAL						