
6TL0B1714F 18-01112

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895



6TL0B1714F

18-01112

WISCONSIN MOTOR VEHICLE CRASH REPORT

Location							
ON N REEDSBURG RD 0.44 MI W	Latitude 43.539585825	Longitude -89.81925208					
OF DEER TRL IN THE TOWN OF DELTON IN SAUK COUNTY	X Coordinate 272223.59375	Y Coordinate 4824599.5					
	Structure Type NO STRUCTURE						
Crash Scene							
First Harmful Event	First Harmful Event Location	1					
TREE	SHOULDER LEFT	SHOULDER LEFT					
Manner of Collision	Light Condition	Light Condition					
NO COLLISION W/VEHICLE IN TRANSPORT	DARK/UNLIT	DARK/UNLIT					
Road Surface Condition(s)	Roadway Factor(s)						
DRY							
Environment Factor(s)		NONE					
NONE	NONE						
Weather Condition(s)							
CLEAR							

Within Interchange Area	Junction Location NON-JUNCTION	n Type INTERSECTION			
Tribal Land			Access Control NO CONTROL	Special Study	
Crash Classification - Location PUBLIC PROPERTY			Crash Classification - Jurisdiction NO SPECIAL JURISDICTION		
Animal Type			Relation To Trafficway TRAFFICWAY - NOT ON ROAD		
CLEAR					
Weather Condition(s)					

Unit	Summary	

Unit Status			Vehicle Operating As Classifica	Vehicle Operating As Classification		Unit Type	
IN TRANSIT			D CLASS	D CLASS		AUTOMOBILE	
Vehicle Type						Operating As Endorsements	
PAS	SENGER VAN						
Total Occs Train/Bus # Injured		Total # Citations Issued	Total # Citations Issued Total Traile		ers Total HazMat Types		
1			4	0		0	
Insurance? Direction Of Travel		Pre CrashTire	Speed Li	peed Limit Total Lanes			
UNKNOWN EASTBOUND		Mark	Mark 45		2		
Most Harmful Event: Collision With			Special Function			Emergency Motor Vehicle Use	
TREE			NO SPECIAL FUNCTION	NO SPECIAL FUNCTION		NOT APPLICABLE	
Traffic Way			Traffic Control	Traffic Control		Traffic Control Inoperative/Missing	
TWO-WAY, NOT DIVIDED			NO CONTROL	NO CONTROL		NO	
Surface Type			Road Curvature	Road Curvature		Road Grade	
BLACKTOP (BITUMINOUS)			CURVE RIGHT	CURVE RIGHT		LEVEL	
	Bus or HazMat						
NO							
Vehicle							
	License Plate Number		Plate Type	St	Country of Issuance		
928ZEV Vehicle Identification Number		AUT - AUTOMOBILE	WI	UNITED STATES			
		Make	Year	Model			
6	1P4GP44G5WB640559		PLYMOUTH	1998	GRAND VOYA		
	Color		Body Style	Body Style		Bus Use	
	PLE - PURPLE		VN - VAN	VN - VAN		NOTABUS	
Lu Initial Contact Point		Vehicle Damage	Vehicle Damage 8LEFT SIDE REAR, 9LEFT SIDE MIDDLE, 10LEFT SIDE FRONT				
9LEFT SIDE MIDDLE Extent Of Damage DISABLING DAMAGE							
							8LEFT SIDE REAR. 9L
<u></u>	DISABLING DAMAGE		, -		,		
	N T Vehic PAS Fotal I Insur JNK Most TRE Traffi Surfa SLA Fruck	N TRANSIT /ehicle Type PASSENGER VAN Total Occs Insurance? JNKNOWN Most Harmful Event: Collision With REE Traffic Way WO-WAY, NOT DIVIDED Surface Type BLACKTOP (BITUMINOUS) Truck Bus or HazMat NO Vehicle License Plate Number 928ZEV Vehicle Identification Numb 1P4GP44G5WB640555 Color PLE - PURPLE Initial Contact Point	N TRANSIT /ehicle Type PASSENGER VAN Total Occs Train/Bus # Injured Insurance? Direction Of Travel JNKNOWN EASTBOUND Most Harmful Event: Collision With EASTBOUND Most Harmful Event: Collision With TREE Traffic Way WO-WAY, NOT DIVIDED Surface Type BLACKTOP (BITUMINOUS) Truck Bus or HazMat NO Vehicle License Plate Number 928ZEV Vehicle Identification Number 1P4GP44G5WB640559 Color PLE - PURPLE Initial Contact Point	N TRANSIT D CLASS Vehicle Type PASSENGER VAN Fotal Occs Train/Bus # Injured Total # Citations Issued Insurance? Direction Of Travel Pre CrashTire JNKNOWN EASTBOUND Mark Most Harmful Event: Collision With Special Function TREE NO SPECIAL FUNCTION Traffic Way Traffic Control Traffic Way Traffic Control WO-WAY, NOT DIVIDED NO CONTROL Surface Type Road Curvature BLACKTOP (BITUMINOUS) CURVE RIGHT Truck Bus or HazMat NO NO Plate Type 28ZEV AUT - AUTOMOBILE Vehicle Identification Number Make 1P4GP44G5WB640559 PLYMOUTH Color Body Style VL Vehicle Damage	N TRANSIT D CLASS Vehicle Type PASSENGER VAN PASSENGER VAN Total # Citations Issued Total Tra Ionsurance? Direction Of Travel Pre CrashTire Speed Li JNKNOWN EASTBOUND Mark 45 Most Harmful Event: Collision With Special Function NO SPECIAL FUNCTION TREE NO CONTROL NO CONTROL Surface Type Road Curvature CURVE RIGHT StatackTOP (BITUMINOUS) CURVE RIGHT Wi Truck Bus or HazMat NO Vehicle Vehicle License Plate Number Plate Type St 928ZEV AUT - AUTOMOBILE Wi Vehicle Identification Number Make Year 1P4GP44G5WB640559 PLYMOUTH 1998 Color Body Style VN - VAN Initial Contact Point Vehicle Damage Vehicle Damage	N TRANSIT D CLASS AUTOM Vehicle Type Operating PASSENGER VAN Operating Fotal Occs Train/Bus # Injured Total # Citations Issued Total Trailers Insurance? Direction Of Travel Pre CrashTire Speed Limit JNKNOWN EASTBOUND Mark 45 Most Harmful Event: Collision With Special Function Emergend REE NO SPECIAL FUNCTION Not AP Traffic Way Traffic Control Not AP Traffic Way Traffic Control Not AP Surface Type Road Curvature Road Gra BLACKTOP (BITUMINOUS) CURVE RIGHT LEVEL Vehicle Vehicle Vehicle So Vehicle Vehicle Vi Uvehicle Identification Number Plate Type St Country of Yehicle Identification Number Make Year Model 1P4GP44G5WB640559 PLYMOUTH 1998 GRAND V Color Body Style Bus Use NOT A B Unit Id Contact Point Vehicle Damage NOT A B	N TRANSIT D CLASS AUTOMOBILE /ehicle Type Operating As Endorsements ASSENGER VAN Total # Citations Issued Total Trailers Operating As Endorsements /on 0 0 0 Imsurance? Direction Of Travel Pre CrashTire Speed Limit 1 JNKNOWN EASTBOUND Pre CrashTire Speed Limit 1 JNKNOWN EASTBOUND Special Function Emergency Motor Vehicle Use NO SPECIAL FUNCTION NO APPLICABLE NOT APPLICABLE rrafic Way Traffic Control NO WO-WAY, NOT DIVIDED NO CONTROL NO Surface Type Road Curvature Road Grade BLACKTOP (BITUMINOUS) CURVE RIGHT LEVEL Truck Bus or HazMat NO NO Vehicle Identification Number Make 9282EV AUT - AUTOMOBILE Wi Vehicle Identification Number Make Year 1P4GP44G5WB640559 PLYMOUTH 1998 GRAND VOYA Color NOT A BUS

6TL0B1714F

18-01112

WISCONSIN MOTOR VEHICLE CRASH REPORT

		Towed Due To Dama	^{ige} DISABLING DAMAGE	Vehicle Removed By CRAIGS TOWING					
		What Driver Was Doi		Vehicle Factors					
		NEGOTIATING CU							
		Driver Prior Action Ot	her	NOT APPLICABLE					
		Driver Actions							
	щ		FAILURE TO CONTROL						
F									
UNIT	Ξ								
	2								
		Driver Distractions							
		UNKNOWN IF DIS	STRACTED						
0	6								
0	0								
		Owner Name		Owner Address					
		BRITTANY NICOL (608) 477-1013	E LORD	S3726 W BENT TREE DR BARABOO, WI 53913 , US					
		Soguenee Of E	vente						
		Sequence Of Events Event							
	0	TREE							
	02	Event							
	03	Event							
	0	_							
	04	Event							
	l	Individual							
		Driver BRITTANY NICOLE LORD		Citations Issued	Sex				
	٦L	(608) 477-1013	ELORD	4	FEMALE				
_	DIVIDUAL			Date of Birth	Race WHITE				
UNIT	Ξ	Address		Driver License Number					
	IND	S3726 W BENT TH		STATE: WISCONSIN COUNTRY: UNITED STATES					
	=	BARABOO, WI 53913 , US		STATE. WISCONSIN COUNTRY. 0	NITED STATES				
			On Duty Crash	Safety Equipment					
		Equipment							
		Seat Position		RESTRAINT USE UNKNOWN					
		1FRONT SEAT-LEFT SIDE (DRIVER/MOTORCY							
		Helmet Use		Helmet Compliance					
		Eye Protection		Tint Compliance					
01	001	Injury							
	0	Ejected	SUSPECTED MINOR INJURY	DEPLOYED-FRONT Ejection Path	Trapped/Extricated				
		NOT EJECTED		NOT EJECTED/NOT APPLICABL	NOT TRAPPED				
		Medical Transport		EMS Agency Identifier	EMS Run #				
		NOT TRANSPORTED							

6TL0B1714F 18-01112

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

		Hospital		Date of Death		Time of Death	Time of Death		
		Non Motorist	Striking Unit #	Prior Action		Location		To/From School	
		Action							
	IAL								
UNIT	ם								
5	INDIVIDUAL								
	Ĭ								
		Action Other							
	r	rug 8 Alaahal	Suspected Alco	hol Use	Suspected I	Drug Use			
	Drug & Alcohol								
	Alcohol Test Given TEST NOT GIVEN			Alcohol Test Type		Alcohol Test Results	Alcohol Test Results		
		Drug Test Given			Drug Test T	VDe	Drug Test Results		
		TEST NOT GIVEN			5				
2	001	Drug Type							
•	0								
		Individual Condition							
		NOT OBSERVED							
		Violations			T - ··				
	6	UTC Number AI392334	Issue To? 001	Statute Number 343.44(1)(a)	Seq Num 001	Description OPERATING AFTER	SUSPENSION		
	02	UTC Number Al392335	Issue To? 001	Statute Number 344.62(1)	Seq Num 001	Description OPERATE MOTOR VI	EHICLE W/O INSURANC	E	
	03	UTC Number Al392336	Issue To? 001	Statute Number 346.70(2)	Seq Num 001	Description FAILURE TO FILE ACCIDENT REPORT			
	6	UTC Number AI392337	Issue To? 001	Statute Number 346.05(1)	Seq Num 001	Description OPERATING LEFT OI	F CENTER LINE		