6TL097RB1H

18-01352

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Document N	Document Number Override		Primary Crash Document # Crash Time		Agency Crash Number 18-01352		Investigating Officer/Deputy DEPUTY H. WEINKE		
					Date Arrived		Time Arrived		
Date Notified		07:33 AM Time Notified			02/06/2018 Total Units		12:00 AM Total Injured Total Killed		
02/06/2018	02/06/2018			01			00		
02/06/2018 Date Notified 02/06/2018	On Emergency		t and Run 🔄 Lane Clos		sure Work Zone		r or Towed	Reporting Threshold	
	overnment Property		hool Zone	School NO	Bus Related	Tags			
Repor	table	Crash Type DT4000 (STA	NDARD CRAS	6H)			ded	Secondary Crash	
Descript	tion 📃								
USH 12 NOT 1 SCAL	го 🗲						Photos By	ormation	

6TL097RB1H

18-01352

WISCONSIN MOTOR VEHICLE CRASH REPORT

ļ		ation								
	INTERSECTION				Latitude			Longitude		
	ON USH12 EB					43.351027933			-89.765068592	
	AT MOELY BRANCH RD IN THE TOWN OF SUMPTER IN SAUK COUNTY					X Coordinate			Y Coordinate	
						275905.9	90625		4803510.5	
	IN C	BAUK COUNT I				Structure Type				
L	^	ah Caana								
(sh Scene								
		Harmful Event				First Harm				
	DIT	СН				SHOULD	DER RIGI	HT		
	Man	ner of Collision				Light Condition				
	NO	COLLISION W/VEHIC	LE IN TRANSPORT			DAYLIGHT				
	Road	d Surface Condition(s)				Roadway	Factor(s)			
	SNC	OW, ICE								
	Envi	ronment Factor(s)				1				
	NO	NE				ETC)	URFACE	CONDITION	I (WET, ICY, SNOW, SLUSH,	
	Wea	ther Condition(s)								
	CLE	EAR								
	Anim	nal Type				Relation To Trafficway TRAFFICWAY - NOT ON ROAD				
								D		
		sh Classification - Location						 Jurisdiction 		
	PUBLIC PROPERTY Tribal Land					NO SPECIAL JURISDICTION				
					Access Control NO CONTROL		Special Study			
	Within Interchange Area Junction Location				Intersection Type					
	NO NON-JUNCTION				NOT AN	OT AN INTERSECTION				
						INTEROL	enen			
ļ	Jni	t Summary								
		t Summary		Vehicle Ope	_	lassification		Unit Type		
	Unit	Status RANSIT		Vehicle Ope	erating As C	-		Unit Type AUTOMO	BILE	
	Unit IN T Vehi	Status RANSIT icle Type			erating As C	-		AUTOMO	BILE s Endorsements	
	Unit IN T Vehi	Status RANSIT		D CLASS	erating As C	lassification		AUTOMO		
	Unit IN T Vehi PAS	Status RANSIT icle Type	Train/Bus # Injured	D CLASS	erating As C	lassification		AUTOMO		
	Unit IN T Vehi PAS	Status RANSIT icle Type SSENGER VAN	Train/Bus # Injured	D CLASS	erating As C	lassification		AUTOMO	s Endorsements	
	Unit IN T Vehi PAS Tota 2	Status RANSIT icle Type SSENGER VAN	Train/Bus # Injured	D CLASS	erating As C	lassification	Total Tra	AUTOMO Operating A	s Endorsements	
01	Unit IN T Vehi PAS Tota 2	Status RANSIT icle Type SSENGER VAN I Occs rance?		D CLASS	erating As C	lassification	Total Tra 0	AUTOMO Operating A	s Endorsements Total HazMat Types	
01	Unit IN T Vehi PAS Tota 2 Insur YES	Status RANSIT icle Type SSENGER VAN I Occs rance?	Direction Of Travel	D CLASS	erating As C tions Issued CrashTire Mark notion	lassification	Total Tra 0 Speed Li	AUTOMO Operating A illers mit Emergency	s Endorsements Total HazMat Types Total Lanes 4 Motor Vehicle Use	
UNIT 01	Unit IN T Vehi PAS Tota 2 Insur YES	Status RANSIT icle Type SSENGER VAN I Occs rance? S t Harmful Event: Collision 1	Direction Of Travel	D CLASS	erating As C tions Issued CrashTire Mark	lassification	Total Tra 0 Speed Li	AUTOMO Operating A illers mit	s Endorsements Total HazMat Types Total Lanes 4 Motor Vehicle Use	
01	Unit IN T Vehi PAS Tota 2 Insu YES Most DIT	Status RANSIT icle Type SSENGER VAN I Occs rance? S t Harmful Event: Collision 1	Direction Of Travel	D CLASS	erating As C tions Issued CrashTire Mark nction CIAL FUNC	lassification	Total Tra 0 Speed Li	AUTOMO Operating A illers mit Emergency NOT APP	s Endorsements Total HazMat Types Total Lanes 4 Motor Vehicle Use	
01	Unit IN T Vehi PAS Tota 2 Insur YES Most DIT Traff	Status RANSIT icle Type SSENGER VAN I Occs rance? S t Harmful Event: Collision ¹ CH fic Way	Direction Of Travel	D CLASS	erating As C tions Issued CrashTire Mark nction CIAL FUNC	lassification	Total Tra 0 Speed Li	AUTOMO Operating A illers mit Emergency NOT APP	s Endorsements Total HazMat Types Total Lanes 4 Motor Vehicle Use LICABLE	
01	Unit IN T Vehi PAS Tota 2 Insur YES DIT Traff	Status RANSIT icle Type SSENGER VAN I Occs rance? S t Harmful Event: Collision ¹ CH fic Way	Direction Of Travel EASTBOUND With	D CLASS	erating As C tions Issued CrashTire Mark IAL FUNC trol TROL	lassification	Total Tra 0 Speed Li	AUTOMO Operating A illers mit Emergency NOT APP Traffic Cont	s Endorsements Total HazMat Types Total Lanes 4 Motor Vehicle Use LICABLE rol Inoperative/Missing	
01	Unit IN T Vehi PAS Tota 2 Insu YES Most DIT Traff TW(Surfa	Status RANSIT icle Type SSENGER VAN I Occs rance? S t Harmful Event: Collision 1 CH fic Way D-WAY, DIVIDED, UNI	Direction Of Travel EASTBOUND With	D CLASS	erating As C tions Issued CrashTire Mark hotion CIAL FUNC trol ROL ature	lassification	Total Tra 0 Speed Li	AUTOMO Operating A illers mit Emergency NOT APP Traffic Cont NO	s Endorsements Total HazMat Types Total Lanes 4 Motor Vehicle Use LICABLE rol Inoperative/Missing	
01	Unit IN T Vehi PAS Tota 2 Insuu YES DIT Traff TWC COI Truc	Status RANSIT icle Type SSENGER VAN I Occs rance? S t Harmful Event: Collision ¹ CH fic Way D-WAY, DIVIDED, UNF ace Type	Direction Of Travel EASTBOUND With	D CLASS	erating As C tions Issued CrashTire Mark hotion CIAL FUNC trol ROL ature	lassification	Total Tra 0 Speed Li	AUTOMO Operating A iilers mit Emergency NOT APP Traffic Cont NO Road Grade	s Endorsements Total HazMat Types Total Lanes 4 Motor Vehicle Use LICABLE rol Inoperative/Missing	
01	Unit IN T Vehi PAS Tota 2 Insuu YES Moss DIT Traff TW(C Surfa COI Truc NO	Status RANSIT icle Type SSENGER VAN I Occs rance? S t Harmful Event: Collision 1 CH fic Way D-WAY, DIVIDED, UNF ace Type NCRETE k Bus or HazMat	Direction Of Travel EASTBOUND With	D CLASS	erating As C tions Issued CrashTire Mark hotion CIAL FUNC trol ROL ature	lassification	Total Tra 0 Speed Li	AUTOMO Operating A iilers mit Emergency NOT APP Traffic Cont NO Road Grade	s Endorsements Total HazMat Types Total Lanes 4 Motor Vehicle Use LICABLE rol Inoperative/Missing	
01	Unit IN T Vehi PAS Tota 2 Insuu YES Moss DIT Traff TW(C Surfa COI Truc NO	Status RANSIT icle Type SSENGER VAN I Occs rance? S t Harmful Event: Collision ¹ CH fic Way D-WAY, DIVIDED, UNF ace Type NCRETE ik Bus or HazMat Vehicle	Direction Of Travel EASTBOUND With	D CLASS	tions Issued CrashTire Mark CIAL FUNC Trol TROL ature EFT	lassification	Total Tra 0 Speed Li 55	AUTOMO Operating A illers mit Emergency NOT APP Traffic Cont NO Road Grade LEVEL	s Endorsements Total HazMat Types Total Lanes 4 Motor Vehicle Use LICABLE rol Inoperative/Missing	
01	Unit IN T Vehi PAS Tota 2 Insuu YES Moss DIT Traff TW(C Surfa COI Truc NO	Status RANSIT icle Type SSENGER VAN I Occs rance? S t Harmful Event: Collision ¹ CH fic Way D-WAY, DIVIDED, UNF ace Type NCRETE ik Bus or HazMat Vehicle License Plate Number	Direction Of Travel EASTBOUND With	D CLASS	tions Issued CrashTire Mark Cial FUNC trol TROL ature EFT	lassification	Total Tra 0 Speed Li 55	AUTOMO Operating A illers mit Emergency NOT APP Traffic Cont NO Road Grade LEVEL	s Endorsements Total HazMat Types Total Lanes 4 Motor Vehicle Use LICABLE rol Inoperative/Missing suance	
01	Unit IN T Vehi PAS Tota 2 Insuu YES Moss DIT Traff TW(C Surfa COI Truc NO	Status RANSIT icle Type SSENGER VAN I Occs rance? S t Harmful Event: Collision 1 CH fic Way D-WAY, DIVIDED, UNF ace Type NCRETE ik Bus or HazMat Vehicle License Plate Number GLT002	Direction Of Travel EASTBOUND With PROTECTED (PAINTED >	D CLASS	tions Issued CrashTire Mark Cial FUNC trol TROL ature EFT	lassification	Total Tra 0 Speed Li 55	AUTOMO Operating A iilers mit Emergency NOT APP Traffic Cont NO Road Grade LEVEL	s Endorsements Total HazMat Types Total Lanes 4 Motor Vehicle Use LICABLE rol Inoperative/Missing suance	
UNI 01	Unit IN T Vehi PAS Tota 2 Insuu YES Moss DIT Traff TW(C Surfa COI Truc NO	Status RANSIT icle Type SSENGER VAN I Occs rance? S t Harmful Event: Collision ¹ CH fic Way D-WAY, DIVIDED, UNF ace Type NCRETE ik Bus or HazMat Vehicle License Plate Number	Direction Of Travel EASTBOUND With PROTECTED (PAINTED >	D CLASS	erating As C tions Issued CrashTire Mark inction CiAL FUNC trol FROL ature EFT SABLED	lassification	Total Tra 0 Speed Li 55	AUTOMO Operating A illers mit Emergency NOT APP Traffic Cont NO Road Grade LEVEL	s Endorsements Total HazMat Types Total Lanes 4 Motor Vehicle Use LICABLE rol Inoperative/Missing suance	
UNI 01	Unit IN T Vehi PAS Tota 2 Insuu YES DIT Traff TWC Surfa COI Truc NO	Status RANSIT Icle Type SSENGER VAN I Occs rance? S t Harmful Event: Collision 1 CH fic Way D-WAY, DIVIDED, UNF ace Type NCRETE Ik Bus or HazMat Vehicle License Plate Number GLT002 Vehicle Identification Nur	Direction Of Travel EASTBOUND With PROTECTED (PAINTED >	D CLASS Total # Cita 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road CUTVA CURVE L Plate Type DIS - DIS Make	erating As C tions Issued CrashTire Mark Diction CIAL FUNC trol TROL ature EFT SABLED ER	lassification	Total Tra 0 Speed Li 55 St WI Year	AUTOMO Operating A illers mit Emergency NOT APP Traffic Cont NO Road Grade LEVEL Country of Is UNITED ST Model PACIFICA Bus Use	s Endorsements Total HazMat Types Total Lanes 4 Motor Vehicle Use LICABLE rol Inoperative/Missing suance rATES	
UNI 01	Unit IN T Vehi PAS Tota 2 Insuu YES DIT Traff TWC Surfa COI Truc NO	Status RANSIT Icle Type SSENGER VAN I Occs rance? S t Harmful Event: Collision 1 CH fic Way D-WAY, DIVIDED, UNF ace Type NCRETE Ik Bus or HazMat Vehicle License Plate Number GLT002 Vehicle Identification Nur 2C4RC1GG1HR6359	Direction Of Travel EASTBOUND With PROTECTED (PAINTED >	D CLASS	erating As C tions Issued CrashTire Mark Diction CIAL FUNC trol TROL ature EFT SABLED ER	lassification	Total Tra 0 Speed Li 55 St WI Year	AUTOMO Operating A illers mit Emergency NOT APP Traffic Cont NO Road Grade LEVEL Country of Is UNITED ST Model PACIFICA	s Endorsements Total HazMat Types Total Lanes 4 Motor Vehicle Use LICABLE rol Inoperative/Missing suance rATES	
UNI 01	Unit IN T Vehi PAS Tota 2 Insuu YES DIT Traff TWC Surfa COI Truc NO	Status RANSIT Cele Type SSENGER VAN I Occs rance? Tance? Tharmful Event: Collision 1 CH fic Way D-WAY, DIVIDED, UNF ace Type NCRETE k Bus or HazMat Vehicle License Plate Number GLT002 Vehicle Identification Nur 2C4RC1GG1HR6359 Color	Direction Of Travel EASTBOUND With PROTECTED (PAINTED >	D CLASS	erating As C tions Issued CrashTire Mark notion CROL ature EFT SABLED ER N	lassification	Total Tra 0 Speed Li 55 St WI Year	AUTOMO Operating A illers mit Emergency NOT APP Traffic Cont NO Road Grade LEVEL Country of Is UNITED ST Model PACIFICA Bus Use	s Endorsements Total HazMat Types Total Lanes 4 Motor Vehicle Use LICABLE rol Inoperative/Missing suance rATES	
01 UNIT 01	Unit IN T Vehi PAS Tota 2 Insuu YES DIT Traff TWC Surfa COI Truc NO	Status RANSIT Cele Type SSENGER VAN I Occs rance? Tance? Thermful Event: Collision 1 CH fic Way D-WAY, DIVIDED, UNF ace Type NCRETE k Bus or HazMat Vehicle License Plate Number GLT002 Vehicle Identification Nur 2C4RC1GG1HR6359 Color RED - RED	Direction Of Travel EASTBOUND With PROTECTED (PAINTED >	D CLASS	erating As C tions Issued CrashTire Mark notion CROL ature EFT SABLED ER N	lassification	Total Tra 0 Speed Li 55 St WI Year	AUTOMO Operating A illers mit Emergency NOT APP Traffic Cont NO Road Grade LEVEL Country of Is UNITED ST Model PACIFICA Bus Use	s Endorsements Total HazMat Types Total Lanes 4 Motor Vehicle Use LICABLE rol Inoperative/Missing suance rATES	
UNIT 01	Unit IN T Vehi PAS Tota 2 Insu YES Most DIT Traff TWO Surfa COI Trac NO	Status RANSIT Cele Type SSENGER VAN I Occs rance? Tance? Tharmful Event: Collision 1 CH fic Way D-WAY, DIVIDED, UNF ace Type NCRETE k Bus or HazMat Vehicle License Plate Number GLT002 Vehicle Identification Nur 2C4RC1GG1HR6359 Color RED - RED Initial Contact Point	Direction Of Travel EASTBOUND With PROTECTED (PAINTED >	D CLASS	erating As C tions Issued CrashTire Mark ction CIAL FUNC trol TROL ature EFT SABLED ER SABLED	lassification	Total Tra 0 Speed Li 55 St WI Year	AUTOMO Operating A illers mit Emergency NOT APP Traffic Cont NO Road Grade LEVEL Country of Is UNITED ST Model PACIFICA Bus Use	s Endorsements Total HazMat Types Total Lanes 4 Motor Vehicle Use LICABLE rol Inoperative/Missing suance rATES	



18-01352

WISCONSIN MOTOR VEHICLE CRASH REPORT

		Towed Due To Dama	ge	Vehicle Removed By				
				EVERETTS TOWING				
		What Driver Was Doing		Vehicle Factors				
		NEGOTIATING CURVE						
		Driver Prior Action Ot	her	NOT APPLICABLE				
UNIT	VEHICLE	Driver Actions SPEED TOO FAS	T/COND, FAILURE TO CONTROL	., RAN OFF ROADWAY				
		Driver Distractions UNKNOWN IF DIS	STRACTED					
01	01							
		Owner Name GERALD L TOUR (608) 402-5024	DOT SR	Owner Address 903 MOORE ST #200 BARABOO, WI 53913 , US				
		Sequence Of E	vents					
	01	Event RUN OFF ROADW						
	02	Event DITCH						
	03	Event						
	04 (Event						
Г		Policy Holder						
UNIT		Insurance Company	RP	Individual GERALD TOURDOT				
		Individual						
		Driver		Citations Issued	Sex			
	_	REGINA L COX		0	FEMALE			
	INDIVIDUAI	(608) 415-0598		Date of Birth	Race WHITE			
UNIT	IVIE	Address		Driver License Number				
	IND	629 LUCKY ST # 1 REEDSBURG, WI		STATE: WISCONSIN COUNTRY: UNITED STATES				
			On Duty Crash	Safety Equipment				
		Equipment						
		Seat Position 1FRONT SEAT-L	EFT SIDE (DRIVER/MOTORCY	SHOULDER & LAP BELT				
		Helmet Use		Helmet Compliance				
		Eye Protection		Tint Compliance				
01	001	Injury	Injury Severity NO APPARENT INJURY	Airbag NON DEPLOYED				
		Ejected NOT EJECTED		Ejection Path NOT EJECTED/NOT APPLICABL	Trapped/Extricated NOT TRAPPED			
Wisco	nsin N	L Motor Vehicle Crash	This rep	I ort does not include any CJIS data.	Crash Date 02/06/2018			

6TL097RB1H

18-01352

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

		Medical Transport			EMS Agency Identi	fier	EMS Run #			
		NOT TRANSPORT	ſED							
		Hospital			Date of Death		Time of Death			
	Hospital									
			Otriking Linit #	Prior Action		Location		To/From Cohool		
		Non Motorist	Striking Unit #	Prior Action		Location		To/From School		
		Action								
	INDIVIDUAL									
нI	Ŋ									
UNIT	6									
5	<u></u>									
	Ę									
	=									
		Action Other								
		Action Other								
	Г	Drug & Alcohol	Suspected Alcohol U	se	Suspected Drug Us	se				
	L	nug a Alconor	NO		NO					
		Alcohol Test Given			Alcohol Test Type		Alcohol Test Results			
		TEST NOT GIVEN								
		Drug Test Given			Drug Test Type		Drug Test Results			
		TEŠT NOT GIVEN					5			
	-	Drug Type								
2	001	Didg Type								
-	0									
		Individual Condition								
		APPEARED NORI	MAL							
		Individual								
					Citations Issued		0			
		Passenger GERALD L TOURDOT SR				ed Sex MALE				
	Ļ	(608) 402-5024	DOT SIX		0					
	INDIVIDUAL				Date of Birth	Date of Birth Race WHITE				
E										
LIND	2	Address			Driver License Nun	nber				
	₽	903 MOORE ST #2								
	2	BARABOO, WI 53	913 , US		STATE: WISCONSIN COUNTRY: UNITED STATES					
			On Duty Crash		Safety Equipment					
		Equipment			Caloty Equipmont					
		Seat Position			SHOULDER & L					
					SHOULDER & L	AF DELI				
			RIGHT SIDE (TRAII	NENGINEER						
		Helmet Use			Helmet Compliance					
		Eye Protection			Tint Compliance Airbag					
~	002									
2	8	Injury	NO APPARENT I	NJURY	NON DEPLOYED					
		Ejected			Ejection Path Trapped/Extricated					
		NOT EJECTED			NOT EJECTED/NOT APPLICABL NOT TRAPPED					
		Medical Transport					EMS Run #			
		NOT TRANSPORT	FD		Line Agency well					
					Data of Drath		Time of De-th			
		Hospital			Date of Death		Time of Death			
		Non Motorist	Striking Unit #	Prior Action		Location		To/From School		
		Non motorist								

6TL097RB1H 18-01352

WISCONSIN MOTOR VEHICLE CRASH REPORT

UNIT	INDIVIDUAL	Action Action Other			
	Ľ	Drug & Alcohol Suspected Alcohol Use	Suspected Drug Use		
		Alcohol Test Given TEST NOT GIVEN	Alcohol Test Type	Alcohol Test Results	
		Drug Test Given TEST NOT GIVEN	Drug Test Type	Drug Test Results	
9	002	Drug Type			
		Individual Condition			
		APPEARED NORMAL			