WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Document Number Overric	le Primary Cras	h Document #	Agency 18-017	Crash Number 714	Investigating Of DEPUTY S. S		1
Crash Date 02/16/2018	Crash Time 01:45 AM			rrived 2018	Time Arrived 01:59 AM		
Date Notified 02/16/2018				nits	Total Injured Total Kill 00 00		ed
On Emergency	Hit and Run	Lane Clo		Work Zone	Trailer or	Towed	Reporting Threshold
Government Property	Active	School Zone	School NO	Bus Related	Tags		
✓ Reportable	Crash Type DT4000 (ST	TANDARD CRAS	SH)		Amended	l	Secondar Crash
escription =					D	o o o o o tru o tio	n Dv
Piagram					K	econstructio	in By
	1						
					Pł	notos By	
					Ad	dditional Info	ormation
Hill	man Rd.	I					
				0			
			A.				
			R	7)			
		I		(
			~				
			[]				
				Not	to scale		
			u I N				
				I			
I. a sworn law enfo	rcement officer, ag	gree that I have	not added	d any CJIS data in t	his report.		

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 02/16/2018

Crash Time 01:45 AM

	Location —									
	ON HILLMAN RD				Latitude			Longitude		
	0.36 MI W		43.58275464			-89.753838988				
	OF CTHT EB		-							
	IN THE TOWN OF DELT			X Coordinate			Y Coordinate			
	IN SAUK COUNTY		_	277667.6875			4829217			
				Structure Type						
			NO STRUCTURE							
	Crash Scene									
	First Harmful Event				First Harm	ful Event I	ocation		_	
	DITCH				SHOULD					
	Manner of Collision			Light Condition					_	
	NO COLLISION W/VEH	CLE IN TRANSPORT			DARK/UI					
		CLE IN TRANSPORT							_	
	Road Surface Condition(s)				Roadway I	-actor(s)				
	DRY									
	Environment Factor(s)									
	ANIMAL (S) IN ROADW	AY			NONE					
	` ,									
	Weather Condition(s)									
	CLOUDY									
	Animal Type			Relation To Trafficway			/			
	DEER				TRAFFICWAY - ON ROAD					
	Crash Classification - Locati	on			Crash Classification - Jurisdiction					
	PUBLIC PROPERTY				NO SPE	CIAL JUF	JURISDICTION			
	Tribal Land			Access Control			Special Study			
						NO CONTROL				
	Within Interchange Area	Junction Location		Intersection	**					
	NO	NON-JUNCTION		NOT AN	INTERSECTION					
	Unit Summary									
	Unit Status		-	erating As Cla	Classification Unit Type					
	IN TRANSIT D CLASS				TRUCK					
			D CLASS							
-	Vehicle Type		D CLASS					s Endorsements		
5	Vehicle Type (SPORT) UTILITY VEHIC		D CLASS				Operating A			
5	Vehicle Type	CLE Train/Bus # Injured		tions Issued		Total Tra	Operating A	s Endorsements Total HazMat Types	_	
5	Vehicle Type (SPORT) UTILITY VEHIC			tions Issued		Total Tra	Operating A			
5	Vehicle Type (SPORT) UTILITY VEHIC Total Occs		Total # Cita	tions Issued			Operating A	Total HazMat Types	_	
5	Vehicle Type (SPORT) UTILITY VEHIC Total Occs 1	Train/Bus # Injured	Total # Cita			0	Operating A	Total HazMat Types 0	_	
	Vehicle Type (SPORT) UTILITY VEHIC Total Occs 1 Insurance? YES Most Harmful Event: Collision	Train/Bus # Injured Direction Of Travel EASTBOUND	Total # Cita 0 Pre Special Fun	CrashTire Mark	TION	0 Speed Lii	Operating A illers	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use		
	Vehicle Type (SPORT) UTILITY VEHIC Total Occs 1 Insurance? YES Most Harmful Event: Collision DITCH	Train/Bus # Injured Direction Of Travel EASTBOUND	Total # Cita 0 Pre Special Fun NO SPEC	CrashTire Mark oction	TION	0 Speed Lii	Operating A illers mit Emergency NOT APPI	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE		
	Vehicle Type (SPORT) UTILITY VEHIC Total Occs 1 Insurance? YES Most Harmful Event: Collision DITCH Traffic Way	Train/Bus # Injured Direction Of Travel EASTBOUND n With	Total # Cita 0 Pre Special Fun NO SPEC	CrashTire Mark action IAL FUNC	TION	0 Speed Lii	Operating A illers mit Emergency NOT APPI Traffic Cont	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use		
	Vehicle Type (SPORT) UTILITY VEHIC Total Occs 1 Insurance? YES Most Harmful Event: Collision DITCH Traffic Way TWO-WAY, NOT DIVIDE	Train/Bus # Injured Direction Of Travel EASTBOUND n With	Total # Cita 0 Pre Special Fun NO SPEC Traffic Cont	CrashTire Mark loction IAL FUNC	TION	0 Speed Lii	Operating A illers mit Emergency NOT APPI Traffic Conti	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing		
	Vehicle Type (SPORT) UTILITY VEHIC Total Occs 1 Insurance? YES Most Harmful Event: Collision DITCH Traffic Way TWO-WAY, NOT DIVIDE Surface Type	Train/Bus # Injured Direction Of Travel EASTBOUND n With	Total # Cita 0 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva	CrashTire Mark Inction IAL FUNCTOR	TION	0 Speed Lii	Operating A illers Emergency NOT APP Traffic Cont NO Road Grade	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing		
	Vehicle Type (SPORT) UTILITY VEHIC Total Occs 1 Insurance? YES Most Harmful Event: Collision DITCH Traffic Way TWO-WAY, NOT DIVIDE Surface Type BLACKTOP (BITUMING	Train/Bus # Injured Direction Of Travel EASTBOUND n With	Total # Cita 0 Pre Special Fun NO SPEC Traffic Cont	CrashTire Mark Inction IAL FUNCTOR	TION	0 Speed Lii	Operating A illers mit Emergency NOT APPI Traffic Conti	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing		
	Vehicle Type (SPORT) UTILITY VEHIC Total Occs 1 Insurance? YES Most Harmful Event: Collision DITCH Traffic Way TWO-WAY, NOT DIVIDE Surface Type BLACKTOP (BITUMING) Truck Bus or HazMat	Train/Bus # Injured Direction Of Travel EASTBOUND n With	Total # Cita 0 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva	CrashTire Mark Inction IAL FUNCTOR	TION	0 Speed Lii	Operating A illers Emergency NOT APP Traffic Cont NO Road Grade	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing		
	Vehicle Type (SPORT) UTILITY VEHIC Total Occs 1 Insurance? YES Most Harmful Event: Collision DITCH Traffic Way TWO-WAY, NOT DIVIDE Surface Type BLACKTOP (BITUMING) Truck Bus or HazMat NO	Train/Bus # Injured Direction Of Travel EASTBOUND n With	Total # Cita 0 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva	CrashTire Mark Inction IAL FUNCTOR	TION	0 Speed Lii	Operating A illers Emergency NOT APP Traffic Cont NO Road Grade	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing	_ _ _ _	
	Vehicle Type (SPORT) UTILITY VEHIC Total Occs 1 Insurance? YES Most Harmful Event: Collision DITCH Traffic Way TWO-WAY, NOT DIVIDE Surface Type BLACKTOP (BITUMING) Truck Bus or HazMat	Train/Bus # Injured Direction Of Travel EASTBOUND n With	Total # Cita 0 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva	CrashTire Mark Inction IAL FUNCTOR TOI TROL	TION	0 Speed Lii	Operating A illers mit Emergency NOT APP Traffic Cont NO Road Grade DOWNHIL	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing		
	Vehicle Type (SPORT) UTILITY VEHIC Total Occs 1 Insurance? YES Most Harmful Event: Collision DITCH Traffic Way TWO-WAY, NOT DIVIDE Surface Type BLACKTOP (BITUMINO) Truck Bus or HazMat NO Vehicle License Plate Number	Train/Bus # Injured Direction Of Travel EASTBOUND In With ED	Total # Cita 0 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva STRAIGH	CrashTire Mark Iction IIAL FUNC rol ROL hture T		Speed Lin 45	Operating A illers mit Emergency NOT APPI Traffic Cont NO Road Grade DOWNHIL	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing		
	Vehicle Type (SPORT) UTILITY VEHIC Total Occs 1 Insurance? YES Most Harmful Event: Collision DITCH Traffic Way TWO-WAY, NOT DIVIDE Surface Type BLACKTOP (BITUMINO) Truck Bus or HazMat NO Vehicle License Plate Number JA7786	Train/Bus # Injured Direction Of Travel EASTBOUND In With ED DUS)	Total # Cita 0 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva STRAIGH	CrashTire Mark Iction IIAL FUNC rol ROL hture T		Speed Lin 45 St WI	Operating A illers mit Emergency NOT APPI Traffic Cont NO Road Grade DOWNHIL Country of Is UNITED ST	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing		
	Vehicle Type (SPORT) UTILITY VEHIC Total Occs 1 Insurance? YES Most Harmful Event: Collision DITCH Traffic Way TWO-WAY, NOT DIVIDE Surface Type BLACKTOP (BITUMINO) Truck Bus or HazMat NO Vehicle License Plate Number JA7786 Vehicle Identification N	Train/Bus # Injured Direction Of Travel EASTBOUND IN With DUS)	Total # Cita 0 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva STRAIGH Plate Type LTK - LIC Make	CrashTire Mark Iction IIAL FUNC rol ROL hture T		Speed Lin 45 St WI Year	Operating A illers mit Emergency NOT APPI Traffic Contino NO Road Grade DOWNHIL Country of Is UNITED ST	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing		
	Vehicle Type (SPORT) UTILITY VEHIC Total Occs 1 Insurance? YES Most Harmful Event: Collision DITCH Traffic Way TWO-WAY, NOT DIVIDE Surface Type BLACKTOP (BITUMINO) Truck Bus or HazMat NO Vehicle License Plate Number JA7786 Vehicle Identification N 1FMCU9DG6BKB4	Train/Bus # Injured Direction Of Travel EASTBOUND IN With DUS)	Total # Cita 0 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva STRAIGH Plate Type LTK - LIC Make FORD	CrashTire Mark iction IAL FUNC rol ROL sture T		Speed Lin 45 St WI	Operating A illers mit Emergency NOT APPI Traffic Cont NO Road Grade DOWNHIL Country of Is UNITED ST Model ESCAPE X	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing		
	Vehicle Type (SPORT) UTILITY VEHIC Total Occs 1 Insurance? YES Most Harmful Event: Collision DITCH Traffic Way TWO-WAY, NOT DIVIDE Surface Type BLACKTOP (BITUMINO) Truck Bus or HazMat NO Vehicle License Plate Number JA7786 Vehicle Identification N 1FMCU9DG6BKB4 Color	Train/Bus # Injured Direction Of Travel EASTBOUND IN With DUS)	Total # Cita 0 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva STRAIGH Plate Type LTK - LIC Make FORD Body Style	CrashTire Mark Inction IAL FUNC* IROL Inture T	к	St WI Year 2011	Operating A illers mit Emergency NOT APPI Traffic Contino NO Road Grade DOWNHIL Country of Is UNITED ST	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing L Suance TATES LT		
	Vehicle Type (SPORT) UTILITY VEHIC Total Occs 1 Insurance? YES Most Harmful Event: Collision DITCH Traffic Way TWO-WAY, NOT DIVIDE Surface Type BLACKTOP (BITUMINO) Truck Bus or HazMat NO Vehicle License Plate Number JA7786 Vehicle Identification No 1FMCU9DG6BKB4 Color BLK - BLACK	Train/Bus # Injured Direction Of Travel EASTBOUND IN With DUS)	Total # Cita 0 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva STRAIGH Plate Type LTK - LIC Make FORD Body Style UT - SPC	CrashTire Mark Indiction IAL FUNC* IROL Inture T	к	St WI Year 2011	Operating A illers mit Emergency NOT APPI Traffic Cont NO Road Grade DOWNHIL Country of Is UNITED ST Model ESCAPE X Bus Use	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing L Suance TATES LT		
	Vehicle Type (SPORT) UTILITY VEHIC Total Occs 1 Insurance? YES Most Harmful Event: Collision DITCH Traffic Way TWO-WAY, NOT DIVIDE Surface Type BLACKTOP (BITUMINO) Truck Bus or HazMat NO Vehicle License Plate Number JA7786 Vehicle Identification No 1FMCU9DG6BKB4 Color BLK - BLACK	Train/Bus # Injured Direction Of Travel EASTBOUND In With DUS)	Total # Cita 0 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva STRAIGH Plate Type LTK - LIC Make FORD Body Style	CrashTire Mark Indiction IAL FUNC* IROL Inture T	к	St WI Year 2011	Operating A illers mit Emergency NOT APPI Traffic Cont NO Road Grade DOWNHIL Country of Is UNITED ST Model ESCAPE X Bus Use	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing L Suance TATES LT		
	Vehicle Type (SPORT) UTILITY VEHIC Total Occs 1 Insurance? YES Most Harmful Event: Collision DITCH Traffic Way TWO-WAY, NOT DIVIDE Surface Type BLACKTOP (BITUMINO) Truck Bus or HazMat NO Vehicle License Plate Number JA7786 Vehicle Identification No 1FMCU9DG6BKB4 Color BLK - BLACK	Train/Bus # Injured Direction Of Travel EASTBOUND In With DUS)	Plate Type LTK - LIG Make FORD Body Style UT - SPO Vehicle Da	CrashTire Mark Inction IAL FUNCTION INCTION IN	K Y VEHICI	St WI Year 2011	Operating A illers mit Emergency NOT APPI Traffic Conti NO Road Grade DOWNHIL Country of Is UNITED ST Model ESCAPE X Bus Use NOT A BUS	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing L suance TATES LT		
	Vehicle Type (SPORT) UTILITY VEHIC Total Occs 1 Insurance? YES Most Harmful Event: Collision DITCH Traffic Way TWO-WAY, NOT DIVIDE Surface Type BLACKTOP (BITUMINO) Truck Bus or HazMat NO Vehicle License Plate Number JA7786 Vehicle Identification N 1FMCU9DG6BKB4 Color BLK - BLACK Initial Contact Point	Train/Bus # Injured Direction Of Travel EASTBOUND IN With DUS) DUS) DUS)	Plate Type LTK - LIG Make FORD Body Style UT - SPO Vehicle Da	CrashTire Mark Inction IAL FUNCTION INCTION IN	K Y VEHICI	St WI Year 2011	Operating A illers mit Emergency NOT APPI Traffic Conti NO Road Grade DOWNHIL Country of Is UNITED ST Model ESCAPE X Bus Use NOT A BUS	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing L Suance TATES LT		

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

		Towed Due To Damage TOWED DUE TO DISABLING DAMAGE		Vehicle Removed By PLATTS WRECKER					
		What Driver Was Doing		Vehicle Factors					
		GOING STRAIGHT		VEHICLE I ACIOIS					
		Driver Prior Action Of		NOT APPLICABLE					
		Driver Actions	**************************************	1					
	쁴	OVER-CORRECT	ING/OVER-STEERING						
LINO	VEHICL								
5	픕								
	>								
		Driver Distractions							
		DISTRACTED BY	OUTSIDE PERSON, OBJECT, O	R EVENT					
01	5								
0	0								
		Owner Name		Owner Address					
		CHRISTOPHER J	FISHER	165 WHITETAIL BLVD					
		(608) 434-5875		BARABOO, WI 53913 , US					
	;	Sequence Of E	vents						
	2	Event NON DOMESTICA	ATED ANIMAL (ALIVE)						
	02	Event DITCH							
		Event							
	03	TREE							
	9	Event							
_	ı	Policy Holder							
UNIT		Insurance Company		Individual					
_		PROGRESSIVE-C	CLASSIC-INS-CO	CHRISTOPHER FISHER					
	ı	Individual							
		Driver CHRISTOPHER J FISHER (608) 434-5875 Address		Citations Issued	Sex				
	ᆜ			0	MALE				
_	INDIVIDUA			Date of Birth	Race WHITE				
	\exists			Driver License Number	<u> </u>				
5	≧	165 WHITETAIL BLVD BARABOO, WI 53913 , US							
	Z			STATE: WISCONSIN COUNTRY: UNITED STATES					
		Farringsont	On Duty Crash	Safety Equipment					
		Equipment							
		Seat Position		SHOULDER & LAP BELT					
		1FRONT SEAT-LEFT SIDE (DRIVER/MOTORCY Helmet Use							
				Helmet Compliance					
		Eye Protection		Tint Compliance					
5	90	Injury	Injury Severity	Airbag					
_	0	Ejected	NO APPARENT INJURY	NON DEPLOYED					
		NOT EJECTED		Ejection Path Trapped/Extricated NOT EJECTED/NOT APPLICABL NOT TRAPPED					
					•				

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 02/16/2018

Crash Time 01:45 AM

		Medical Transport			EMS Agency Identifier		EMS Run #	
		NOT TRANSPORTED						
		Hospital			Date of Death		Time of Death	
			Loca: 11.5.6	ID: 4.0		li e		T /F 0 1 1
		Non Motorist	Striking Unit #	Prior Action		Location		To/From School
		Action	•					
	7							
⊨	INDIVIDUAL							
UNIT	₹							
	S							
		Action Other						
	E	Drug & Alcohol	NO	Use	Suspected Drug Us	6 e		
		Alcohol Test Given			Alcohol Test Type		Alcohol Test Results	
		Drug Test Given			Drug Test Type		Drug Test Results	
		Drug Test Given TEST NOT GIVEN	I					
01	001	Drug Type			•			
	0							
		Individual Condition						
		APPEARED NOR	MAL					