6TL08S5WTD

18-02328

WISCONSIN MOTOR VEHICLE **CRASH REPORT**

SAUK COUNTY SHERIFFS DEPARTMEN **1300 LANGE COURT BARABOO, WI 53913** (608) 356-4895

Docume	ent Number Override	Primary Crash Document #	Agency Crash Number	Investigating Officer/Deputy				
			18-02328	DEPUTY S. SCHRAM				
Crash D 03/05/2	2018	Crash Time 06:21 PM	Date Arrived 03/05/2018	Time Arrived 06:40 PM				
Date No		Time Notified	Total Units	Total Injured Total Killed				
03/05/2	2018	06:21 PM	01	00 00				
	Emergency Hit	and Run		Trailer or Towed				
Crash D 03/05/2 Date No 03/05/2 0 0n	Government Property	Active School Zone	School Bus Related NO	Tags Crash				
🗸 Rej	portable	Crash Type DT4000 (STANDARD CRASH)					
Description								
Diegram								
UNIT 1 WAS TRAVELING EB ON HWY 33 WEST OF SCHUTTE ROAD. UNIT 1 OPERATOR LOST CONTROL OF THE VEHICLE CAUSING IT TO CROSS OVER THE WB LANE OF TRAFFIC AND ENTER INTO THE NORTH DITCH LINE. UNIT 1 STRUCK ROCKS AND OTHER DEBRIS IN THE DITCH, CAUSING DAMAGE TO THE FRONT AND FRONT DRIVERS SIDE OF THE VEHICLE. UNIT 1 OPERATOR THEN LEFT THE SCENE AND DID NOT REPORT THE CRASH TO LAW ENFORCEMENT. RUNNING THE PLATE AND R.O. OF THE VEHICLE THE R.O. SHOWED A SUSP WI DRIVING STATUS WITH PREVIOUS CONVICTIONS FOR NO PROOF OF INSURANCE. DISPATCH LOCATED A PHONE NUMBER FOR THE OPERATOR BUT HE HUNG UP ON LAW ENFORCEMENT ATTEMPTING CONTACT WITH HIM AND THEN REFUSED TO ANSWER PHONE. OPERATOR CITED FOR OPERATING WHILE SUSPENDED, NO								
		IM AND THEN REFUSED TO ANSV Y POLICE OF ACCIDENT AND SPI			ENDED, NO			

6TL08S5WTD

18-02328

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

	-	STH33 EB			Latitude		Longitude			
		151 FT W				43.566306021		-90.095776408		
	-	OF SCHUETTE RD IN THE TOWN OF LA VALLE				X Coordinate		Y Coordinate		
		SAUK COUNTY		249	9991.828125		4828362.5			
				Stru	Structure Type					
	Cra	ish Scene								
1		t Harmful Event			F :	st Harmful Event I				
	DIT					ADSIDE	Location			
		nner of Collision			_					
					0	ht Condition				
	NO COLLISION W/VEHICLE IN TRANSPORT Road Surface Condition(s)									
					Roa	adway Factor(s)				
	SNOW									
	Envi	ironment Factor(s)								
	WE	ATHER CONDITIONS					CONDITION	(WET, ICY, SNOW, SLUSH,		
					ET	C)				
	Wea	ather Condition(s)								
	SNC	OW, BLOWING SNOW								
	Anim	nal Type			Rela	Relation To Trafficway				
					TR	AFFICWAY - N	NOT ON ROA	D		
	Cras	sh Classification - Location	1		Cra	sh Classification	- Jurisdiction			
	PUE	PUBLIC PROPERTY Iribal Land			NO	NO SPECIAL JURISDICTION				
	Triba				Acc	Access Control Special Study				
						NO CONTROL				
	With NO	Within Interchange Area Junction Location Intersectio NO NON-JUNCTION NOT AN				on Type I INTERSECTION				
	-									
	l l en la		•							
		t Summary		Vahiela Ope	proting As Classif	fication	Linit Tuno			
1	Unit	Status			erating As Classif	fication		211 E		
	Unit IN T	Status		Vehicle Ope		fication	AUTOMO			
	Unit IN T Vehi	Status FRANSIT icle Type				fication	AUTOMO	BILE s Endorsements		
	Unit IN T Vehi PAS	Status IRANSIT icle Type SSENGER CAR	Train/Bus # Injured	D CLASS			AUTOMOE Operating A	s Endorsements		
	Unit IN T Vehi PAS Tota	Status FRANSIT icle Type	Train/Bus # Injured	D CLASS		Total Tra	AUTOMOE Operating A	s Endorsements Total HazMat Types		
	Unit IN T Vehi PAS Tota 01	Status TRANSIT icle Type SSENGER CAR al Occs		D CLASS	tions Issued	Total Tra 0	AUTOMOE Operating A	s Endorsements Total HazMat Types 0		
01	Unit IN T Vehi PAS Tota 01 Insur	Status TRANSIT icle Type SSENGER CAR al Occs irance?	Direction Of Travel	D CLASS	tions Issued	Total Tra 0 Speed Li	AUTOMOE Operating A	s Endorsements Total HazMat Types 0 Total Lanes		
01	Unit IN T Vehi PAS Tota 01 Insur NO	Status IRANSIT icle Type SSENGER CAR al Occs Irance?	Direction Of Travel	D CLASS	tions Issued CrashTire Mark	Total Tra 0	AUTOMOE Operating A illers mit	s Endorsements Total HazMat Types 0 Total Lanes 02		
01	Unit IN T Vehi PAS Tota 01 Insui NO	Status TRANSIT icle Type SSENGER CAR al Occs irance? it Harmful Event: Collision	Direction Of Travel	D CLASS	tions Issued CrashTire Mark	Total Tra 0 Speed Li 55	AUTOMOE Operating A illers mit	s Endorsements Total HazMat Types 0 Total Lanes 02 Motor Vehicle Use		
01	Unit IN T Vehi PAS Tota 01 Insui NO Most DIT	Status TRANSIT icle Type SSENGER CAR al Occs arrance? it Harmful Event: Collision	Direction Of Travel	D CLASS	tions Issued CrashTire Mark Iction IAL FUNCTIO	Total Tra 0 Speed Li 55	AUTOMOE Operating Au illers mit Emergency NOT APPL	s Endorsements Total HazMat Types 0 Total Lanes 02 Motor Vehicle Use ICABLE		
01	Unit IN T Vehi PAS Tota 01 Insut NO Most DIT Traff	Status TRANSIT icle Type SSENGER CAR al Occs irrance? it Harmful Event: Collision CH fic Way	Direction Of Travel EASTBOUND With	D CLASS	tions Issued CrashTire Mark Iction IAL FUNCTIO	Total Tra 0 Speed Li 55	AUTOMOE Operating Au iilers mit Emergency NOT APPL Traffic Contr	s Endorsements Total HazMat Types 0 Total Lanes 02 Motor Vehicle Use		
01	Unit IN T Vehi PAS Tota 01 Insur NO Most DIT Traff	Status IRANSIT icle Type SSENGER CAR al Occs irrance? it Harmful Event: Collision CH fic Way O-WAY, NOT DIVIDED	Direction Of Travel EASTBOUND With	D CLASS	tions Issued CrashTire Mark Iction IAL FUNCTION TOI	Total Tra 0 Speed Li 55	AUTOMOE Operating Au illers mit Emergency NOT APPL	s Endorsements Total HazMat Types 0 Total Lanes 02 Motor Vehicle Use ICABLE ol Inoperative/Missing		
01	Unit IN T Vehi PAS Tota 01 Insut NO Most DIT Traff TWC Surfa	Status IRANSIT icle Type SSENGER CAR al Occs irrance? it Harmful Event: Collision CH fic Way O-WAY, NOT DIVIDED iace Type	Direction Of Travel EASTBOUND With	D CLASS	tions Issued CrashTire Mark action HAL FUNCTION rol ROL ature	Total Tra 0 Speed Li 55	AUTOMOE Operating A illers mit Emergency NOT APPL Traffic Contr NO Road Grade	s Endorsements Total HazMat Types 0 Total Lanes 02 Motor Vehicle Use ICABLE ol Inoperative/Missing		
01	Unit IN T Vehi PAS Tota 01 Insut NO Most DIT Traff TW(C Surfa	Status TRANSIT icle Type SSENGER CAR al Occs irrance? it Harmful Event: Collision CH fic Way O-WAY, NOT DIVIDED iace Type ACKTOP (BITUMINOU	Direction Of Travel EASTBOUND With	D CLASS	tions Issued CrashTire Mark action HAL FUNCTION rol ROL ature	Total Tra 0 Speed Li 55	AUTOMOE Operating A illers mit Emergency NOT APPL Traffic Contr NO	s Endorsements Total HazMat Types 0 Total Lanes 02 Motor Vehicle Use ICABLE ol Inoperative/Missing		
01	Unit IN T Vehi PAS Tota 01 Insut NO Most DIT Traff TW(C Surfa	Status IRANSIT icle Type SSENGER CAR al Occs irrance? at Harmful Event: Collision CH fic Way O-WAY, NOT DIVIDED face Type ACKTOP (BITUMINOU ck Bus or HazMat	Direction Of Travel EASTBOUND With	D CLASS	tions Issued CrashTire Mark action HAL FUNCTION rol ROL ature	Total Tra 0 Speed Li 55	AUTOMOE Operating A illers mit Emergency NOT APPL Traffic Contr NO Road Grade	s Endorsements Total HazMat Types 0 Total Lanes 02 Motor Vehicle Use ICABLE ol Inoperative/Missing		
01	Unit IN T Vehi PAS Tota 01 Insuu NO Most DITO Traff TWO Surfa BLA Truc NO	Status TRANSIT icle Type SSENGER CAR al Occs irrance? it Harmful Event: Collision ' CH fic Way O-WAY, NOT DIVIDED iace Type ACKTOP (BITUMINOU ck Bus or HazMat Vehicle	Direction Of Travel EASTBOUND With	D CLASS	tions Issued CrashTire Mark action HAL FUNCTION rol ROL ature	Total Tra 0 Speed Li 55	AUTOMOE Operating Au illers mit Emergency NOT APPL Traffic Contr NO Road Grade LEVEL	s Endorsements Total HazMat Types 0 Total Lanes 02 Motor Vehicle Use ICABLE ol Inoperative/Missing		
01	Unit IN T Vehi PAS Tota 01 Insuu NO Most DITO Traff TWO Surfa BLA Truc NO	Status TRANSIT icle Type SSENGER CAR al Occs irrance? it Harmful Event: Collision CH fic Way O-WAY, NOT DIVIDED face Type ACKTOP (BITUMINOU ck Bus or HazMat Vehicle License Plate Number	Direction Of Travel EASTBOUND With	D CLASS	tions Issued CrashTire Mark Indian IAL FUNCTION IAL FUNCTION IROL Ature EFT	Total Tra 0 Speed Li 55 N	AUTOMOE Operating A iilers mit Emergency NOT APPL Traffic Contr NO Road Grade LEVEL	s Endorsements Total HazMat Types 0 Total Lanes 02 Motor Vehicle Use ICABLE ol Inoperative/Missing suance		
01	Unit IN T Vehi PAS Tota 01 Insuu NO Most DITO Traff TWO Surfa BLA Truc NO	Status TRANSIT icle Type SSENGER CAR al Occs irrance? it Harmful Event: Collision ' CH fic Way O-WAY, NOT DIVIDED iace Type ACKTOP (BITUMINOU ck Bus or HazMat Vehicle	Direction Of Travel EASTBOUND With	D CLASS	tions Issued CrashTire Mark ction IAL FUNCTION rol ROL ature EFT	Total Tra 0 Speed Li 55 N	AUTOMOE Operating Au illers mit Emergency NOT APPL Traffic Contr NO Road Grade LEVEL	s Endorsements Total HazMat Types 0 Total Lanes 02 Motor Vehicle Use ICABLE ol Inoperative/Missing suance		
UNIT 01	Unit IN T Vehi PAS Tota 01 Insuu NO Most DIT Traff TWC Surfa BLA Truc	Status TRANSIT icle Type SSENGER CAR al Occs irrance? it Harmful Event: Collision CH fic Way O-WAY, NOT DIVIDED face Type ACKTOP (BITUMINOU ck Bus or HazMat Vehicle License Plate Number 357ZWW Vehicle Identification Num	mber	D CLASS	tions Issued CrashTire Mark Indian IAL FUNCTION IAL FUNCTION IROL Ature EFT	Total Tra 0 Speed Li 55 N	AUTOMOE Operating A illers mit Emergency NOT APPL Traffic Contr NO Road Grade LEVEL	s Endorsements Total HazMat Types 0 Total Lanes 02 Motor Vehicle Use ICABLE ol Inoperative/Missing suance FATES		
UNIT 01	Unit IN T Vehi PAS Tota 01 Insuu NO Most DITO Traff TWO Surfa BLA Truc NO	Status TRANSIT icle Type SSENGER CAR al Occs irance? ACH fic Way O-WAY, NOT DIVIDED face Type ACKTOP (BITUMINOU ck Bus or HazMat Vehicle License Plate Number 357ZWW Vehicle Identification Nuu JM1BK34L58182778	mber	D CLASS	tions Issued CrashTire Mark Interion IAL FUNCTION IROL Ature EFT ITOMOBILE	Total Tra 0 Speed Li 55 N	AUTOMOE Operating A illers mit Emergency NOT APPL Traffic Contr NO Road Grade LEVEL	s Endorsements Total HazMat Types 0 Total Lanes 02 Motor Vehicle Use ICABLE ol Inoperative/Missing suance FATES		
UNIT 01	Unit IN T Vehi PAS Tota 01 Insuu NO Most DIT Traff TWC Surfa BLA Truc	Status TRANSIT icle Type SSENGER CAR al Occs irrance? ACH fic Way O-WAY, NOT DIVIDED face Type ACKTOP (BITUMINOU ck Bus or HazMat Vehicle License Plate Number 357ZWW Vehicle Identification Nuu JM1BK34L58182778 Color	mber	D CLASS	tions Issued CrashTire Mark Interion IAL FUNCTION IROL Ature EFT ITOMOBILE	Total Tra 0 Speed Li 55 N	AUTOMOE Operating A iilers mit Emergency NOT APPL Traffic Contr NO Road Grade LEVEL Country of Iss UNITED ST Model MAZDASPI Bus Use	s Endorsements Total HazMat Types 0 Total Lanes 02 Motor Vehicle Use ICABLE ol Inoperative/Missing suance ATES EED		
UNIT 01	Unit IN T Vehi PAS Tota 01 Insur NO Most DITC Traff TWC Surfa BLA NO	Status TRANSIT icle Type SSENGER CAR al Occs irance? it Harmful Event: Collision CH fic Way O-WAY, NOT DIVIDED face Type ACKTOP (BITUMINOU ck Bus or HazMat Vehicle License Plate Number 357ZWW Vehicle Identification Nur JM1BK34L58182778 Color RED - RED	mber	D CLASS	tions Issued CrashTire Mark Inction IAL FUNCTION IROL Ature EFT ITOMOBILE	Total Tra 0 Speed Li 55 N	AUTOMOE Operating A illers mit Emergency NOT APPL Traffic Contr NO Road Grade LEVEL	s Endorsements Total HazMat Types 0 Total Lanes 02 Motor Vehicle Use ICABLE ol Inoperative/Missing suance ATES EED		
01 UNIT 01	Unit IN T Vehi PAS Tota 01 Insut NO Most DITC Traff TWC Surfa BLA NO	Status TRANSIT icle Type SSENGER CAR al Occs irance? it Harmful Event: Collision CH fic Way O-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU ck Bus or HazMat Vehicle License Plate Number 357ZWW Vehicle Identification Nul JM1BK34L58182778 Color RED - RED Initial Contact Point	mber	D CLASS	tions Issued CrashTire Mark Inction IAL FUNCTION IROL Ature EFT ITOMOBILE	Total Tra 0 Speed Li 55 N	AUTOMOE Operating A iilers mit Emergency NOT APPL Traffic Contr NO Road Grade LEVEL Country of Iss UNITED ST Model MAZDASPI Bus Use	s Endorsements Total HazMat Types 0 Total Lanes 02 Motor Vehicle Use ICABLE ol Inoperative/Missing suance ATES EED		
UNIT 01	Unit IN T Vehi PAS Tota 01 Insur NO Most DITC Traff TWC Surfa BLA NO	Status TRANSIT icle Type SSENGER CAR al Occs irance? it Harmful Event: Collision CH fic Way O-WAY, NOT DIVIDED face Type ACKTOP (BITUMINOU ck Bus or HazMat Vehicle License Plate Number 357ZWW Vehicle Identification Nur JM1BK34L58182778 Color RED - RED	mber	D CLASS	tions Issued CrashTire Mark Interion IAL FUNCTION ITAL FUN	Total Tra 0 Speed Li 55 N	AUTOMOE Operating A illers mit Emergency NOT APPL Traffic Contr NO Road Grade LEVEL	s Endorsements Total HazMat Types 0 Total Lanes 02 Motor Vehicle Use ICABLE ol Inoperative/Missing suance ATES EED		



18-02328

WISCONSIN MOTOR VEHICLE CRASH REPORT

		Towed Due To Dama TOWED DUE TO	age DISABLING DAMAGE	Vehicle Removed By SHIELDS TOWING						
		What Driver Was Doing		Vehicle Factors						
		NEGOTIATING CURVE Driver Prior Action Other		NOT APPLICABLE						
		Driver Prior Action Ot	iner							
UNIT	VEHICLE	Driver Actions SPEED TOO FAST/COND, FAILURE TO CONTROL								
		Driver Distractions UNKNOWN IF DIS								
0	01									
		Owner Name		Owner Address						
		COLE WEISERT (608) 434-8183		1404 OLDE SAW MILL RD BARABOO, WI 53913 , US						
	ç	Sequence Of E	vents							
	01	Event DITCH								
	02	Event								
		Event								
	03	Event								
	04									
	I	ndividual								
		Driver COLE WEISERT (608) 434-8183		Citations Issued 04	Sex MALE					
	AL			Date of Birth	Race					
F	DIVIDUAL				WHITE					
UNIT	DIV			Driver License Number						
	I			STATE: WISCONSIN COUNTRY: UNITED STATES						
		Equipment	On Duty Crash	Safety Equipment						
		Seat Position		SHOULDER & LAP BELT						
		1FRONT SEAT-LEFT SIDE (DRIVER/MOTORCY		Halmot Compliance						
		Helmet Use		Helmet Compliance						
		Eye Protection		Tint Compliance						
-	Ξ		Injury Severity	Airbag						
01	001	Injury	NO APPARENT INJURY	NON DEPLOYED						
		Ejected NOT EJECTED		Ejection Path NOT EJECTED/NOT APPLICABL	Trapped/Extricated NOT TRAPPED					
		Medical Transport		EMS Agency Identifier						
		NOT TRANSPOR	TED							

6TL08S5WTD

18-02328

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

	Hospital				Date of Death		Time of Death			
		Non Motorist	Striking Unit #	Prior Action		Loca	tion		To/From School	
	1	Action				I				
	٩L									
⊑	INDIVIDUAL									
UNIT										
	IN									
		Action Other								
	Г	Drug & Alcohol	Suspected Alco	hol Use	Suspected Drug Use					
		Alcohol Test Given	NO					Alcohol Test Results		
		TEST NOT GIVEN			Alcohol Test Type			Alconol Test Results		
		Drug Test Given TEST NOT GIVEN			Drug Test T	уре		Drug Test Results		
2	001	Drug Type								
0	00									
		Individual Condition								
		NOT OBSERVED								
	Violations									
	01	UTC Number AE140919	Issue To? 001	Statute Number 344.62(1)	Seq Num 001	Description OPERATE		LE W/O INSURANCE	:	
	02	UTC Number AE140920	Issue To? 001	Statute Number 343.44(1)(a)	Seq Num 001	Description OPERATING AFTER SUSPENSION				
	03	UTC Number AE140921	Issue To? 001	Statute Number 346.70(1)	Seq Num 006	Description FAILURE OF OPERATOR TO NOTIFY POLICE OF ACCIDENT				
	04	UTC Number AE140922	Issue To? 001	Statute Number 346.57(3)	Seq Num 001	Description DRIVING	TOO FAST FOR	CONDITIONS		