
18-02247

#### WISCONSIN MOTOR VEHICLE CRASH REPORT



18-02247

#### WISCONSIN MOTOR VEHICLE CRASH REPORT

		ation							
-	ON TIMOTHY LN (2)					titude		Longitude	
		16 FT N				.55599577		-89.777995076	
	OF	OF TIMOTHY LN (1) IN THE TOWN OF DELTON				X Coordinate Y Co		Y Coordinate	
						275617.9375 4826310			
	IN SAUK COUNTY					ucture Type			
						Structure Type			
		· • —							
		sh Scene							
-	First	Harmful Event			Firs	st Harmful Event	_ocation		
	MO	TOR VEH IN TRANSP	ORT		-	N ROADWAY			
	Man	ner of Collision			Lig	ht Condition			
	05	SIDESWIPE/SAME DI	IRECTION		DA	ARK/LIGHTED			
	Road	d Surface Condition(s)			Ro	adway Factor(s)			
	DR	Y							
	Envi	ronment Factor(s)							
	NO	NE			NC	ONE			
	Wea	ther Condition(s)							
	CLE	EAR							
	Anim	nal Type					n To Trafficway		
	Cras	sh Classification - Location	1			AFFICWAY - C	ON ROAD		
		BLIC PROPERTY				O SPECIAL JU		l	
	Triba	al Land			-	cess Control		Special Study	
	With	in Interchange Area	Junction Location		Intersection Ty				
	YES	3	INTERSECTION		ROUNDABC	ABOUT			
	Uni	t Summary							
		t Summary Status		Vehicle Ope	erating As Classi	ification	Unit Type		
	Unit			Vehicle Ope	0	ification	Unit Type AUTOMOI	BILE	
	Unit IN T	Status			0	ification	AUTOMO	BILE s Endorsements	
01	Unit IN T Vehi	Status RANSIT			0	ification	AUTOMO		
	Unit IN T Vehi PAS	Status RANSIT icle Type	Train/Bus # Injured	D CLASS	0	ification	AUTOMOI Operating A		
	Unit IN T Vehi PAS	Status RANSIT icle Type SSENGER CAR	Train/Bus # Injured	D CLASS			AUTOMOI Operating A	s Endorsements	
	Unit IN T Vehi PAS Tota 1	Status RANSIT icle Type SSENGER CAR	Train/Bus # Injured	D CLASS Total # Cita 0	tions Issued	Total Tra	AUTOMOI Operating A ilers	s Endorsements Total HazMat Types	
01	Unit IN T Vehi PAS Tota 1	Status RANSIT icle Type SSENGER CAR I Occs rance?		D CLASS Total # Cita 0		Total Tra 0	AUTOMOI Operating A ilers	s Endorsements Total HazMat Types 0	
01	Unit IN T Vehi PAS Tota 1 Insur YES	Status RANSIT icle Type SSENGER CAR I Occs rance?	Direction Of Travel	D CLASS	tions Issued CrashTire Mark	Total Tra 0 Speed Li 15	AUTOMOI Operating A illers mit Emergency	s Endorsements Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use	
01	Unit IN T Vehi PAS Tota 1 Insul YES	Status RANSIT icle Type SSENGER CAR I Occs rance? S	Direction Of Travel WESTBOUND With	D CLASS	tions Issued CrashTire Mark	Total Tra 0 Speed Li 15	AUTOMOI Operating A illers mit Emergency NOT APPI	s Endorsements Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use ICABLE	
01	Unit IN T Vehi PAS Tota 1 Insur YES Most Traff	Status RANSIT icle Type SSENGER CAR I Occs rance? S t Harmful Event: Collision TOR VEH IN TRANSP fic Way	Direction Of Travel WESTBOUND With ORT	D CLASS	tions Issued CrashTire Mark Inction IIAL FUNCTIO	Total Tra 0 Speed Li 15	AUTOMOI Operating A illers mit Emergency NOT APPI Traffic Contr	s Endorsements Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use	
01	Unit IN T Vehi PAS Tota 1 Insut YES Most Traff	Status RANSIT icle Type SSENGER CAR I Occs rance? S t Harmful Event: Collision TOR VEH IN TRANSP fic Way D-WAY, NOT DIVIDED	Direction Of Travel WESTBOUND With ORT	D CLASS	tions Issued CrashTire Mark CIAL FUNCTIO	Total Tra 0 Speed Li 15	AUTOMOI Operating A illers mit Emergency NOT APPI Traffic Contr NO	s Endorsements Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use ICABLE fol Inoperative/Missing	
01	Unit IN T Vehi PAS Tota 1 Insur YES MOS Traff TWO Surfa	Status RANSIT icle Type SSENGER CAR I Occs rance? TOR VEH IN TRANSP fic Way D-WAY, NOT DIVIDED ace Type	Direction Of Travel WESTBOUND With ORT	D CLASS	tions Issued CrashTire Mark CIAL FUNCTIO Trol GN	Total Tra 0 Speed Li 15	AUTOMOI Operating A illers mit Emergency NOT APPI Traffic Contr NO Road Grade	s Endorsements Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use ICABLE fol Inoperative/Missing	
01	Unit IN T Vehi PAS Tota 1 Insuu YES MOSI Traff TWO Surfa BLA	Status RANSIT icle Type SSENGER CAR I Occs rance? S t Harmful Event: Collision TOR VEH IN TRANSP fic Way D-WAY, NOT DIVIDED	Direction Of Travel WESTBOUND With ORT	D CLASS	tions Issued CrashTire Mark CIAL FUNCTIO Trol GN	Total Tra 0 Speed Li 15	AUTOMOI Operating A illers mit Emergency NOT APPI Traffic Contr NO	s Endorsements Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use ICABLE fol Inoperative/Missing	
01	Unit IN T Vehi PAS Tota 1 Insuu YES MOSI Traff TWO Surfa BLA	Status RANSIT icle Type SSENGER CAR I Occs rance? TOR VEH IN TRANSP fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU	Direction Of Travel WESTBOUND With ORT	D CLASS	tions Issued CrashTire Mark CIAL FUNCTIO Trol GN	Total Tra 0 Speed Li 15	AUTOMOI Operating A illers mit Emergency NOT APPI Traffic Contr NO Road Grade	s Endorsements Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use ICABLE fol Inoperative/Missing	
01	Unit IN T Vehi PAS Tota 1 Insuur YES MOS Traff TWO Surfa BLA Truc NO	Status RANSIT icle Type SSENGER CAR I Occs rance? TOR VEH IN TRANSP fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU ik Bus or HazMat Vehicle	Direction Of Travel WESTBOUND With ORT	D CLASS	tions Issued CrashTire Mark ction ctiAL FUNCTIO crol GN ature T	Total Tra 0 Speed Li 15	AUTOMOI Operating A illers mit Emergency NOT APPI Traffic Contr NO Road Grade LEVEL	s Endorsements Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use ICABLE rol Inoperative/Missing	
01	Unit IN T Vehi PAS Tota 1 Insuur YES MOS Traff TWO Surfa BLA Truc NO	Status RANSIT icle Type SSENGER CAR I Occs rance? TOR VEH IN TRANSP icle Type ACKTOP (BITUMINOU ik Bus or HazMat Vehicle License Plate Number	Direction Of Travel WESTBOUND With ORT	D CLASS	tions Issued CrashTire Mark ction ct	Total Tra 0 Speed Li 15 DN	AUTOMOI Operating A illers mit Emergency NOT APPI Traffic Contu NO Road Grade LEVEL	s Endorsements Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use ICABLE Tol Inoperative/Missing	
UNIT 01	Unit IN T Vehi PAS Tota 1 Insuur YES MOS Traff TWO Surfa BLA Truc NO	Status RANSIT icle Type SSENGER CAR I Occs rance? S t Harmful Event: Collision TOR VEH IN TRANSP fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU ik Bus or HazMat Vehicle License Plate Number 600TNM	Direction Of Travel WESTBOUND With ORT	D CLASS	tions Issued CrashTire Mark ction ctiAL FUNCTIO crol GN ature T	Total Tra 0 Speed L 15 DN	AUTOMOI Operating A illers mit Emergency NOT APPI Traffic Conti NO Road Grade LEVEL	s Endorsements Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use ICABLE Tol Inoperative/Missing	
UNIT 01	Unit IN T Vehi PAS Tota 1 Insuur YES MOS Traff TWO Surfa BLA Truc NO	Status RANSIT icle Type SSENGER CAR I Occs rance? TOR VEH IN TRANSP icle Type ACKTOP (BITUMINOU ik Bus or HazMat Vehicle License Plate Number	Mith ORT JS)	D CLASS	tions Issued CrashTire Mark Inction CIAL FUNCTIO Irol SN Iture T JTOMOBILE	Total Tra 0 Speed Li 15 DN	AUTOMOI Operating A illers mit Emergency NOT APPI Traffic Contu NO Road Grade LEVEL	s Endorsements Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use ICABLE Tol Inoperative/Missing	
UNIT 01	Unit IN T Vehi PAS Tota 1 Insuu YES MO' Traff TWO Surfa BLA Truc	Status RANSIT Icle Type SSENGER CAR I Occs I Occs Tance? S t Harmful Event: Collision TOR VEH IN TRANSP fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU Ik Bus or HazMat Vehicle License Plate Number 600TNM Vehicle Identification Nu 2G1105S34H919491 Color	Mith ORT JS)	D CLASS	tions Issued CrashTire Mark Inction CIAL FUNCTIO Trol SN Ature T JTOMOBILE DLET	Total Tra 0 Speed Li 15 DN	AUTOMOI Operating A illers mit Emergency NOT APPI Traffic Conti NO Road Grade LEVEL Country of Is UNITED S1 Model IMPALA Bus Use	s Endorsements Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use ICABLE Tol Inoperative/Missing suance TATES	
UNIT 01	Unit IN T Vehi PAS Tota 1 Insuu YES MOS Traff TWO Surfa BLA Truc NO	Status TRANSIT Icle Type SSENGER CAR I Occs I Occs Tance? S t Harmful Event: Collision TOR VEH IN TRANSP fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU Ik Bus or HazMat Vehicle License Plate Number 600TNM Vehicle Identification Nu 2G1105S34H919491 Color RED - RED	Mith ORT JS)	D CLASS	tions Issued CrashTire Mark Inction IAL FUNCTIO TOI T JTOMOBILE DLET DAN	Total Tra 0 Speed Li 15 DN	AUTOMOI Operating A illers mit Emergency NOT APPI Traffic Contr NO Road Grade LEVEL	s Endorsements Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use ICABLE Tol Inoperative/Missing suance TATES	
01 UNIT 01	Unit IN T Vehi PAS Tota 1 Insu YES MOS Traff TWO Surfa BLA Truc NO	Status TRANSIT Icle Type SSENGER CAR I Occs Tance? S t Harmful Event: Collision TOR VEH IN TRANSP fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU k Bus or HazMat Vehicle Identification Nu 2G1105S34H919491 Color RED - RED Initial Contact Point	Mith ORT Direction Of Travel WeSTBOUND With ORT D JS) mber 0	D CLASS	tions Issued CrashTire Mark Inction IAL FUNCTIO TOI T JTOMOBILE DLET DAN	Total Tra 0 Speed Li 15 DN	AUTOMOI Operating A illers mit Emergency NOT APPI Traffic Conti NO Road Grade LEVEL Country of Is UNITED S1 Model IMPALA Bus Use	s Endorsements Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use ICABLE Tol Inoperative/Missing suance TATES	
UNIT 01	Unit IN T Vehi PAS Tota 1 Insuu YES MOS Traff TWO Surfa BLA Truc NO	Status TRANSIT Icle Type SSENGER CAR I Occs I Occs Tance? S t Harmful Event: Collision TOR VEH IN TRANSP fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU Ik Bus or HazMat Vehicle License Plate Number 600TNM Vehicle Identification Nu 2G1105S34H919491 Color RED - RED	Mith ORT Direction Of Travel WeSTBOUND With ORT D JS) mber 0	D CLASS	tions Issued CrashTire Mark Inction IAL FUNCTIO TOI T JTOMOBILE DLET DAN	Total Tra 0 Speed L1 15 DN St WI Year 2017	AUTOMOI Operating A illers mit Emergency NOT APPI Traffic Conti NO Road Grade LEVEL Country of Is UNITED S1 Model IMPALA Bus Use	s Endorsements Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use ICABLE Tol Inoperative/Missing suance TATES	

18-02247

## WISCONSIN MOTOR VEHICLE CRASH REPORT

		Towed Due To Dama NOT TOWED	ge	Vehicle Removed By OWNER					
		What Driver Was Doing		Vehicle Factors					
		GOING STRAIGHT							
		Driver Prior Action Ot	her	NOT APPLICABLE					
		Driver Actions							
	щ	FAILED TO YIELD	RIGHT-OF-WAY						
UNIT	VEHICLE								
5	ΈH								
	>								
		Driver Distractions NOT DISTRACTED							
01	1								
0	01								
		Owner Name		Owner Address					
		AUDREY A BOLZ (608) 356-6903		625 4TH AVE BARABOO, WI 53913 , US					
		(008) 330-0903		BARABOO, WI 33913 , 03					
	ļ	Sequence Of Ev	vents						
	01	Event MOTOR VEH IN T	RANSPORT						
	02	Event RIGHT TURN							
	03	Event							
	04	Event							
F	l	Policy Holder							
UNIT		Insurance Company WEST-BEND-MUT	TUAL-INS-CO	Individual AUDREY BOLZ					
		Individual							
		Driver		Citations Issued	Sex				
	_	AUDREY A BOLZ (608) 356-6903		0	FEMALE				
	JA			Date of Birth	Race				
₽	IDI				WHITE				
UNIT		Address 625 4TH AVE BARABOO, WI 53913 , US		Driver License Number					
	Z			STATE: WISCONSIN COUNTRY: UN	NITED STATES				
		Equipment	On Duty Crash	Safety Equipment					
	i	Seat Position		SHOULDER & LAP BELT					
		1FRONT SEAT-LEFT SIDE (DRIVER/MOTORCY							
		Helmet Use		Helmet Compliance					
		Eye Protection		Tint Compliance					
~	5		Injury Severity	Airbag					
01	00	Injury NO APPARENT INJURY		NON DEPLOYED					
		Ejected NOT EJECTED		Ejection Path NOT EJECTED/NOT APPLICABL	Trapped/Extricated NOT TRAPPED				
Wisco	nsin N	Motor Vehicle Crash	This repo	ort does not include any CJIS data.	Crash Date 03/03/2018				

18-02247

### WISCONSIN MOTOR VEHICLE CRASH REPORT

		Medical Transport NOT TRANSPORTED			EMS Agency Identifier			EMS Run #		
		Hospital			Date of Death			Time of Death		
		Non Motorist	Striking Unit #	Prior Action	Location			To/From School		
		Action								I
	Ļ									
F	INDIVIDUAL									
UNIT	Ξ									
	Q									
	-									
		Action Other								
	Ľ	Drug & Alcohol	Suspected Alcohol	Use	Suspected Drug Us	se				
		Alcohol Test Given TEST NOT GIVEN			Alcohol Test Type			Alcohol Test	Results	
		Drug Test Given			Drug Test Type			Drug Test R	esults	
		TEŠT NOT GIVEN								
9	001	Drug Type								
		Individual Condition								
		APPEARED NORM	AL							
' 		t Summary			/ehicle Operating As (	Classification		Linit Type		
	Unit	t Summary  Status TRANSIT			/ehicle Operating As ( D CLASS	Classification		Unit Type AUTOMOI	BILE	
	Unit IN T Vehi	Status <b>FRANSIT</b> icle Type				Classification				ients
02	Unit IN T Vehi PAS	Status RANSIT	Train/Bus # In	r			Total Trail	AUTOMOI Operating A		
	Unit IN T Vehi PAS Tota 1	Status IRANSIT icle Type SSENGER CAR Il Occs		jured	O CLASS	d	0	AUTOMOI Operating A ers	s Endorsem Total HazM <b>0</b>	lat Types
02	Unit IN T Vehi PAS Tota 1	Status TRANSIT icle Type SSENGER CAR il Occs rance?	Train/Bus # In Direction Of T NORTHBOL	jured T ravel	O CLASS	d		AUTOMOI Operating A ers	s Endorsem Total HazN	lat Types
	Unit IN 1 Vehi PAS Tota 1 Insu YES Mos	Status FRANSIT icle Type SSENGER CAR il Occs rance? S t Harmful Event: Collisior	Direction Of T NORTHBOU	jured T ravel JND [	O CLASS	d e	0 Speed Lim	AUTOMOE Operating A ers nit Emergency	s Endorsem Total HazM 0 Total Lane 2 Motor Vehic	Nat Types s
02	Unit IN T Vehi PAS Tota 1 Insu YES Mos MO	Status TRANSIT icle Type SSENGER CAR II Occs rance? S	Direction Of T NORTHBOU	jured T c ravel JND [ i	O CLASS	d e	0 Speed Lim	AUTOMON Operating A ers	s Endorsem Total HazM 0 Total Lane 2 Motor Vehic LICABLE	Nat Types s de Use
02	Unit IN T Vehi PAS Tota I Insu YES MOS Traff	Status TRANSIT icle Type SSENGER CAR il Occs rance? S t Harmful Event: Collisior TOR VEH IN TRANSI fic Way O-WAY, NOT DIVIDE	Direction Of T NORTHBOU With PORT	jured T ravel J JND [ I I I I	CLASS  Cotal # Citations Issue  Pre CrashTir Mark  Special Function NO SPECIAL FUNCT  Traffic Control NO CONTROL	d e	0 Speed Lim	AUTOMOS Operating A ers nit Emergency NOT APPI Traffic Contr NO	s Endorsem Total HazM 0 Total Lane 2 Motor Vehic ICABLE ol Inoperation	Nat Types s de Use
02	Unit IN T Vehi PAS Tota 1 Insu YES MOS Traff TWO Surf	Status TRANSIT icle Type SSENGER CAR il Occs rance? S t Harmful Event: Collision TOR VEH IN TRANSI fic Way O-WAY, NOT DIVIDE ace Type	Direction Of T NORTHBOU With PORT	jured 7 ravel 9 JND 9 1 F	O CLASS         Total # Citations Issue         Pre CrashTir         Mark         Special Function         NO SPECIAL FUNCTOR         Traffic Control         NO CONTROL         Road Curvature	d e	0 Speed Lim	AUTOMOS Operating A ers nit Emergency NOT APPI Traffic Contr NO Road Grade	s Endorsem Total HazM 0 Total Lane 2 Motor Vehic ICABLE ol Inoperation	Nat Types s de Use
02	Unit IN T Vehi PAS Tota 1 Insu YES MOS Traff TWO Surf: BLA	Status TRANSIT icle Type SSENGER CAR il Occs rance? S t Harmful Event: Collisior TOR VEH IN TRANSI fic Way O-WAY, NOT DIVIDE	Direction Of T NORTHBOU With PORT	jured 7 ravel 9 JND 9 1 F	CLASS  Cotal # Citations Issue  Pre CrashTir Mark  Special Function NO SPECIAL FUNCT  Traffic Control NO CONTROL	d e	0 Speed Lim	AUTOMOS Operating A ers nit Emergency NOT APPI Traffic Contr NO	s Endorsem Total HazM 0 Total Lane 2 Motor Vehic ICABLE ol Inoperation	Nat Types s de Use
02	Unit IN T Vehi PAS Tota 1 Insu YES Mos MO Traff Two Surf: BL/ Truc NO	Status TRANSIT icle Type SSENGER CAR II Occs rance? S t Harmful Event: Collision TOR VEH IN TRANSI fic Way O-WAY, NOT DIVIDE ace Type ACKTOP (BITUMINO) ik Bus or HazMat	Direction Of T NORTHBOU With PORT	jured 7 ravel 9 JND 9 1 F	O CLASS         Total # Citations Issue         Pre CrashTir         Mark         Special Function         NO SPECIAL FUNCTOR         Traffic Control         NO CONTROL         Road Curvature	d e	0 Speed Lim	AUTOMOS Operating A ers nit Emergency NOT APPI Traffic Contr NO Road Grade	s Endorsem Total HazM 0 Total Lane 2 Motor Vehic ICABLE ol Inoperation	Nat Types s de Use
02	Unit IN T Vehi PAS Tota 1 Insu YES Mos MO Traff Two Surf: BL/ Truc NO	Status TRANSIT icle Type SSENGER CAR I Occs rance? S t Harmful Event: Collision TOR VEH IN TRANSI fic Way O-WAY, NOT DIVIDE ace Type ACKTOP (BITUMINO) ick Bus or HazMat Vehicle	Direction Of T NORTHBOU With PORT	jured T ravel JND [ F F F S	CLASS  Total # Citations Issue  Pre CrashTir Mark  Special Function NO SPECIAL FUNCT  Traffic Control NO CONTROL  Road Curvature  STRAIGHT	d e CTION	0 Speed Lin 15	AUTOMOI Operating A ers hit Emergency NOT APPI Traffic Contr NO Road Grade LEVEL	s Endorsem Total HazN 0 Total Lane 2 Motor Vehic ICABLE rol Inoperati	Nat Types s de Use
02	Unit IN T Vehi PAS Tota 1 Insu YES Mos MO Traff Two Surf: BL/ Truc NO	Status TRANSIT icle Type SSENGER CAR II Occs rance? S t Harmful Event: Collision TOR VEH IN TRANSI fic Way O-WAY, NOT DIVIDE ace Type ACKTOP (BITUMINO) ik Bus or HazMat	Direction Of T NORTHBOU With PORT	jured T ravel JND [ F F S	O CLASS         Total # Citations Issue         Pre CrashTir         Mark         Special Function         NO SPECIAL FUNCTOR         Traffic Control         NO CONTROL         Road Curvature	d e CTION	0 Speed Lim	AUTOMOS Operating A ers nit Emergency NOT APPI Traffic Contr NO Road Grade	s Endorsem Total HazM 0 Total Lane 2 Motor Vehic ICABLE rol Inoperativ	Nat Types s de Use
UNIT 02	Unit IN T Vehi PAS Tota 1 Insu YES MOS Traff TWO Surf: BLA NO	Status TRANSIT icle Type SSENGER CAR I Occs rance? S t Harmful Event: Collision TOR VEH IN TRANSI fic Way O-WAY, NOT DIVIDE ace Type ACKTOP (BITUMINOU ick Bus or HazMat Vehicle License Plate Number MV4038 Vehicle Identification No	Direction Of T NORTHBOU With PORT D JS)	jured T ravel JND [ F F S	O CLASS         Total # Citations Issue         Pre CrashTir         Mark         Special Function         NO SPECIAL FUNCTION         Traffic Control         NO CONTROL         Road Curvature         STRAIGHT         Plate Type         AUT - AUTOMOBIL         Make	d e CTION	0 Speed Lin 15	AUTOMOI Operating A ers nit Emergency NOT APPI Traffic Contr NO Road Grade LEVEL Country of Is: UNITED ST Model	s Endorsem Total HazN 0 Total Lane 2 Motor Vehic LICABLE Tol Inoperativ	Nat Types s de Use
02	Unit IN T Vehi PAS Tota 1 Insu YES Mos MO Traff Two Surf: BL/ Truc NO	Status TRANSIT icle Type SSENGER CAR I Occs rance? S t Harmful Event: Collision TOR VEH IN TRANSI fic Way O-WAY, NOT DIVIDE ace Type ACKTOP (BITUMINOU Ik Bus or HazMat Vehicle License Plate Number MV4038	Direction Of T NORTHBOU With PORT D JS)	jured 7 ravel JND [ F F S	O CLASS         Fotal # Citations Issue         O         Pre CrashTir         Mark         Special Function         NO SPECIAL FUNCTION         Traffic Control         NO CONTROL         Road Curvature         STRAIGHT	d e CTION	0 Speed Lim 15	AUTOMOR Operating A ers nit Emergency NOT APPI Traffic Contr NO Road Grade LEVEL Country of Is: UNITED ST Model E3504M AV Bus Use	s Endorsem Total HazN 0 Total Lane 2 Motor Vehic ICABLE rol Inoperativ	Nat Types s de Use
UNIT 02	Unit IN T Vehi PAS Tota 1 Insu YES Mos MO Traff TWO Surf: BLA Truc NO	Status TRANSIT icle Type SSENGER CAR il Occs rance? S t Harmful Event: Collision TOR VEH IN TRANSI fic Way O-WAY, NOT DIVIDE ace Type ACKTOP (BITUMINOU ik Bus or HazMat Vehicle License Plate Number MV4038 Vehicle Identification Ni WDBUF87X28B206 Color BLK - BLACK	Direction Of T NORTHBOU With PORT D JS)	jured 7 ravel JND [ F S	O CLASS         Total # Citations Issue         Pre CrashTir         Mark         Special Function         NO SPECIAL FUNI         Traffic Control         NO CONTROL         Road Curvature         STRAIGHT         Plate Type         AUT - AUTOMOBI         Make         MERCEDES BENZ         Body Style         4D - 4DR	d e CTION	0 Speed Lin 15	AUTOMOR Operating A ers iit Emergency NOT APPI Traffic Contr NO Road Grade LEVEL Country of Is: UNITED ST Model E3504M AV	s Endorsem Total HazN 0 Total Lane 2 Motor Vehic ICABLE rol Inoperativ	Nat Types s de Use
02 UNIT 02	Unit IN T Vehi PAS Tota 1 Insu YES Mos MO Traff TWO Suff BL/ Truc NO	Status TRANSIT icle Type SSENGER CAR il Occs rance? S t Harmful Event: Collision TOR VEH IN TRANSI fic Way O-WAY, NOT DIVIDE ace Type ACKTOP (BITUMINOU ick Bus or HazMat Vehicle License Plate Number MV4038 Vehicle Identification Nu WDBUF87X28B206 Color BLK - BLACK Initial Contact Point	Jirection Of T NORTHBOU With PORT JS) JS)	jured 7 ravel JND [ F S	O CLASS         Total # Citations Issue         Pre CrashTir         Mark         Special Function         NO SPECIAL FUNI         Traffic Control         NO CONTROL         Road Curvature         STRAIGHT         Plate Type         AUT - AUTOMOBI         Make         MERCEDES BENZ         Body Style	d e CTION	0 Speed Lin 15	AUTOMOR Operating A ers nit Emergency NOT APPI Traffic Contr NO Road Grade LEVEL Country of Is: UNITED ST Model E3504M AV Bus Use	s Endorsem Total HazN 0 Total Lane 2 Motor Vehic ICABLE rol Inoperativ	Nat Types s de Use
UNIT 02	Unit IN T Vehi PAS Tota 1 Insu YES Mos MO Traff TWO Surf: BLA Truc NO	Status TRANSIT icle Type SSENGER CAR il Occs rance? S t Harmful Event: Collision TOR VEH IN TRANSI fic Way O-WAY, NOT DIVIDE ace Type ACKTOP (BITUMINOU ik Bus or HazMat Vehicle License Plate Number MV4038 Vehicle Identification Ni WDBUF87X28B206 Color BLK - BLACK	Jirection Of T NORTHBOU With PORT JS) JS)	jured 1 ravel JND [ F F	O CLASS         Total # Citations Issue         Pre CrashTir         Mark         Special Function         NO SPECIAL FUNI         Traffic Control         NO CONTROL         Road Curvature         STRAIGHT         Plate Type         AUT - AUTOMOBI         Make         MERCEDES BENZ         Body Style         4D - 4DR	d e CTION	0 Speed Lin 15	AUTOMOR Operating A ers nit Emergency NOT APPI Traffic Contr NO Road Grade LEVEL Country of Is: UNITED ST Model E3504M AV Bus Use	s Endorsem Total HazN 0 Total Lane 2 Motor Vehic ICABLE rol Inoperativ	Nat Types s de Use

18-02247

## WISCONSIN MOTOR VEHICLE CRASH REPORT

		Towed Due To Damage	Vehicle Removed By						
		NOT TOWED	OPERATOR						
		What Driver Was Doing	Vehicle Factors						
		GOING STRAIGHT							
		Driver Prior Action Other	NOT APPLICABLE						
		Driver Actions							
	щ	NO CONTRIBUTING ACTION							
E	С								
UNIT	Ŧ								
	VEHICLE								
	-								
		Driver Distractions							
		NOT DISTRACTED							
~	~								
02	02								
		Owner Name	Owner Address						
		HWY TWELVE AUTO SALES LLC	S4066 CTH BD						
		(608) 432-2434	BARABOO, WI 53913 , US						
	9	Sequence Of Events							
		Event							
	01	MOTOR VEH IN TRANSPORT							
	02	Event							
		Event							
	03	Lvent							
		Event							
	04								
Ц	l	Policy Holder							
UNIT		Insurance Company	Organization/Company						
		ALLIED GENERAL AGENCY	HWY TWELVE AUTO SALES LLC						
		Individual							
		Driver	Citations Issued	Sex					
		TARAS V ZHYDYK	0	MALE					
	AL	(608) 432-2434	Date of Birth	Race					
	INDIVIDUA		Date of Birth	WHITE					
UNIT		Address	Driver License Number						
5	D	1001 CHURCH ST	Driver License Number						
	N	WISCONSIN DELLS, WI 53965 , US	STATE: WISCONSIN COUNTRY: UNITED STATES						
		On Duty Crash	Safety Equipment						
		Equipment	Salety Equipment						
	1	Seat Position	SHOULDER & LAP BELT						
		1FRONT SEAT-LEFT SIDE (DRIVER/MOTORCY							
		Helmet Use	Helmet Compliance						
		Eye Protection	Tint Compliance						
		· · · · · ·							
	2	Injury Severity	Airbag						
02	002	Injury NO APPARENT INJURY	NON DEPLOYED						
		Ejected	Ejection Path	Trapped/Extricated					
		NOT EJECTED	NOT EJECTED/NOT APPLICABL	NOT TRAPPED					
	noin M		ort does not include any CJIS data.	Crash Date 03/03/2018					

18-02247

#### WISCONSIN MOTOR VEHICLE CRASH REPORT

		Medical Transport	ſED		EMS Agency Identifier		EMS Run #	
	Hospital				Date of Death		Time of Death	
		Non Motorist	Striking Unit #	Prior Action		Location		To/From School
		Action						
UNIT	INDIVIDUAL							
		Action Other						
	Ľ	Drug & Alcohol	Suspected Alcohol	Use	Suspected Drug Us	se		
		Alcohol Test Given TEST NOT GIVEN			Alcohol Test Type		Alcohol Test Results	
		Drug Test Given TEST NOT GIVEN			Drug Test Type		Drug Test Results	
02	002	Drug Type					·	
		Individual Condition APPEARED NORI	MAL					