

6TL09XQXXN

18-02354

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMENT
1300 LANGE COURT
BARABOO, WI 53913
(608) 356-4895

Location

ON STH23 WB 0.47 MI W OF COUNTY LAND FILL LN IN THE TOWN OF EXCELSIOR IN SAUK COUNTY	Latitude 43.533545647	Longitude -89.901012976
	X Coordinate 265594.15625	Y Coordinate 4824156
	Structure Type NO STRUCTURE	

Crash Scene

First Harmful Event DITCH	First Harmful Event Location SHOULDER RIGHT	
Manner of Collision NO COLLISION W/VEHICLE IN TRANSPORT	Light Condition DARK/UNLIT	
Road Surface Condition(s) SNOW, SLUSH	Roadway Factor(s) NONE	
Environment Factor(s) WEATHER CONDITIONS		
Weather Condition(s) SNOW, BLOWING SNOW		
Animal Type	Relation To Trafficway TRAFFICWAY - ON ROAD	
Crash Classification - Location PUBLIC PROPERTY	Crash Classification - Jurisdiction NO SPECIAL JURISDICTION	
Tribal Land	Access Control NO CONTROL	Special Study
Within Interchange Area NO	Junction Location NON-JUNCTION	Intersection Type NOT AN INTERSECTION

Unit Summary

01 UNIT	Unit Status IN TRANSIT		Vehicle Operating As Classification D CLASS		Unit Type AUTOMOBILE		
	Vehicle Type PASSENGER CAR				Operating As Endorsements		
	Total Occs 1	Train/Bus # Injured	Total # Citations Issued 0	Total Trailers 0	Total HazMat Types 0		
	Insurance? YES	Direction Of Travel WESTBOUND	<input type="checkbox"/> Pre Crash Tire Mark	Speed Limit 55	Total Lanes 2		
	Most Harmful Event: Collision With DITCH		Special Function NO SPECIAL FUNCTION		Emergency Motor Vehicle Use NOT APPLICABLE		
	Traffic Way TWO-WAY, NOT DIVIDED		Traffic Control NO CONTROL		Traffic Control Inoperative/Missing NO		
	Surface Type BLACKTOP (BITUMINOUS)		Road Curvature STRAIGHT		Road Grade LEVEL		
	Truck Bus or HazMat NO						
	01 VEHICLE	Vehicle					
		License Plate Number 377ZMT		Plate Type AUT - AUTOMOBILE	St WI	Country of Issuance UNITED STATES	
Vehicle Identification Number KM8SC73EX5U988111		Make HYUNDAI	Year 2005	Model SANTA FE G			
Color WHI - WHITE		Body Style UT - SPORT UTILITY VEHICLE		Bus Use NOT A BUS			
Initial Contact Point NON-COLLISION		Vehicle Damage					
Extent Of Damage MINOR DAMAGE		10--LEFT SIDE FRONT, 11--LEFT FRONT CORNER, 12--FRONT					

WISCONSIN MOTOR VEHICLE
CRASH REPORT

UNIT	Towed Due To Damage NOT TOWED		Vehicle Removed By OWNER		
	What Driver Was Doing GOING STRAIGHT		Vehicle Factors		
	Driver Prior Action Other		NOT APPLICABLE		
	Driver Actions NO CONTRIBUTING ACTION				
	Driver Distractions NOT DISTRACTED				
01	01	Owner Name JEAN RONDA CLARK (920) 412-6301		Owner Address S3042 AULT RD REEDSBURG, WI 53959 , US	
Sequence Of Events					
	01	Event DITCH			
	02	Event			
	03	Event			
	04	Event			
UNIT	Policy Holder				
	Insurance Company USAA-GENERAL-INDEMNITY-CO		Individual JEAN CLARK		
UNIT	INDIVIDUAL	Individual			
		Driver JEAN RONDA CLARK (920) 412-6301	Citations Issued 0	Sex FEMALE	
			Date of Birth [REDACTED]	Race INDIAN	
		Address S3042 AULT RD REEDSBURG, WI 53959 , US		Driver License Number [REDACTED] STATE: WISCONSIN COUNTRY: UNITED STATES	
		Equipment		Safety Equipment	
	On Duty Crash	SHOULDER & LAP BELT			
	Seat Position 1--FRONT SEAT-LEFT SIDE (DRIVER/MOTORCY	Helmet Compliance			
	Helmet Use	Tint Compliance			
	Eye Protection				
01	001	Injury		Airbag	
		Injury Severity NO APPARENT INJURY	NON DEPLOYED		
	Ejected NOT EJECTED	Ejection Path NOT EJECTED/NOT APPLICABL	Trapped/Extricated NOT TRAPPED		

6TL09XQXXN
18-02354

WISCONSIN MOTOR VEHICLE
CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN
1300 LANGE COURT
BARABOO, WI 53913
(608) 356-4895

UNIT	INDIVIDUAL	Medical Transport NOT TRANSPORTED		EMS Agency Identifier	EMS Run #	
		Hospital		Date of Death	Time of Death	
		Non Motorist	Striking Unit #	Prior Action	Location	To/From School
		Action				
		Action Other				
		Drug & Alcohol	Suspected Alcohol Use NO		Suspected Drug Use NO	
		Alcohol Test Given TEST NOT GIVEN		Alcohol Test Type	Alcohol Test Results	
		Drug Test Given TEST NOT GIVEN		Drug Test Type	Drug Test Results	
		Drug Type				
		Individual Condition APPEARED NORMAL				