
6TL0BC3B1H

18-03069

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895



6TL0BC3B1H

18-03069

WISCONSIN MOTOR VEHICLE **CRASH REPORT**

L	_OC	ation								
Ē		HORKAN RD				Latitude			Longitud	de
	-	5 MI W				43.574451593		•	-89.951338782	
		HORKAN LN								
	-	THE TOWN OF DELLO	NA			X Coordinate 261688.984375		Y Coordinate		
		SAUK COUNTY						4828842.5		12.5
						Structure	Туре			
					NO STRUCTURE					
(Cra	sh Scene								
T	First	Harmful Event				First Harm	nful Event L	ocation		
	DIT	СН			ON ROADWAY					
F	Manner of Collision						Light Condition			
	Manner of Collision NO COLLISION W/VEHICLE IN TRANSPORT						DARK/UNLIT			
-					Roadway Factor(s)					
	DR	Road Surface Condition(s)				Ruduway Factor(S)				
ŀ	Envi	ronment Factor(s)								
	NO	NE				NONE				
ŀ	Wea	ther Condition(s)								
	CLE	EAR								
╞	Anim	nal Type				Relation T	o Trafficwa	IV		
		21 -								
-	Crae	h Classification - Location						-		
	Crash Classification - Location PUBLIC PROPERTY							on - Jurisdiction JURISDICTION		
Ī	Triba	al Land				Access Co				Special Study
-	10/:46	in Interchange Area	lunction Logotion		Intersection Type					
	NO	in Interchange Area	Junction Location NON-JUNCTION			INTERSECTION				
	NО		NON-JUNCTION							
L						INTEROL	onion			
l		t Summary								
	Unit	Status			erating As C	Classification		Unit Type		
	Unit IN T	Status RANSIT		Vehicle Ope D CLASS	erating As C			TRUCK		
-	Unit IN T Vehi	Status RANSIT icle Type			erating As C				s Endorse	ments
-	Unit IN T Vehi	Status RANSIT	TRUCK		erating As C			TRUCK	s Endorse	ments
-	Unit IN T Vehi UTII	Status RANSIT icle Type	TRUCK		erating As C	Classification		TRUCK Operating A		ments Mat Types
-	Unit IN T Vehi UTII	Status TRANSIT icle Type LITY TRUCK/PICKUP ⁻		D CLASS	erating As C	Classification		TRUCK Operating A		
-	Unit IN T Vehi UTII Tota 1	Status TRANSIT icle Type LITY TRUCK/PICKUP ⁻		D CLASS	erating As C	Classification	Total Trai	TRUCK Operating A	Total Haz	Mat Types
10	Unit IN T Vehi UTII Tota 1	Status RANSIT icle Type LITY TRUCK/PICKUP ⁻ I Occs rance?	Train/Bus # Injured	D CLASS	erating As C	Classification	Total Tra	TRUCK Operating A	Total Haz 0	Mat Types
10	Unit IN T Vehi UTII Tota 1 Insur YES	Status RANSIT Icle Type LITY TRUCK/PICKUP ⁻ I Occs rance? S	Train/Bus # Injured Direction Of Travel SOUTHBOUND	D CLASS	erating As C tions Issued CrashTire Mark	Classification	Total Trai 0 Speed Lii	TRUCK Operating A illers mit	Total Haz 0 Total Lan 2	Mat Types es
10	Unit IN T Vehi UTII Tota 1 Insur YES Most	Status RANSIT icle Type LITY TRUCK/PICKUP ⁻ I Occs rance? S t Harmful Event: Collision V	Train/Bus # Injured Direction Of Travel SOUTHBOUND	D CLASS	erating As C tions Issued CrashTire Mark	Classification	Total Trai 0 Speed Lii	TRUCK Operating A	Total Haz 0 Total Lan 2 Motor Veh	Mat Types es icle Use
10	Unit IN T Vehi Tota 1 Insu YES Most	Status RANSIT icle Type LITY TRUCK/PICKUP ⁻ I Occs rance? S t Harmful Event: Collision V EE	Train/Bus # Injured Direction Of Travel SOUTHBOUND	D CLASS	tions Issued CrashTire Mark Diction CIAL FUNC	Classification	Total Trai 0 Speed Lii	TRUCK Operating A ilers mit Emergency NOT APP	Total Haz 0 Total Lan 2 Motor Veh LICABLE	Mat Types es icle Use
	Unit IN T Vehi Tota 1 Insur YES Most TRE	Status RANSIT icle Type LITY TRUCK/PICKUP ⁻ I Occs rance? 5 t Harmful Event: Collision V EE fic Way	Train/Bus # Injured Direction Of Travel SOUTHBOUND	D CLASS	tions Issued CrashTire Mark CIAL FUNC	Classification	Total Trai 0 Speed Lii	TRUCK Operating A illers mit Emergency NOT APP Traffic Cont	Total Haz 0 Total Lan 2 Motor Veh LICABLE	Mat Types es icle Use
	Unit IN T Vehi UTII Tota 1 Insu YES Most TRE Traff	Status RANSIT icle Type LITY TRUCK/PICKUP I Occs rance? S t Harmful Event: Collision V EE fic Way D-WAY, NOT DIVIDED	Train/Bus # Injured Direction Of Travel SOUTHBOUND	D CLASS	tions Issued CrashTire Mark Diction CIAL FUNC	Classification	Total Trai 0 Speed Lii	TRUCK Operating A illers mit Emergency NOT APP Traffic Cont NO	Total Haz 0 Total Lan 2 Motor Veh LICABLE rol Inopera	Mat Types es icle Use
	Unit IN T Vehi UTII Tota 1 Insur YES Most TRE Traff TWC Surfa	Status TRANSIT icle Type LITY TRUCK/PICKUP I Occs rance? S t Harmful Event: Collision V EE fic Way D-WAY, NOT DIVIDED ace Type	Train/Bus # Injured Direction Of Travel SOUTHBOUND Vith	D CLASS	tions Issued CrashTire Mark Inction CIAL FUNC trol FROL ature	Classification	Total Trai 0 Speed Lii	TRUCK Operating A illers mit Emergency NOT APP Traffic Cont NO Road Grade	Total Haz 0 Total Lan 2 Motor Veh LICABLE rol Inopera	Mat Types es icle Use
	Unit IN T Vehi Tota 1 Insur YES TRE Traff TWC Surfa	Status TRANSIT icle Type LITY TRUCK/PICKUP I Occs rance? S t Harmful Event: Collision V EE fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS	Train/Bus # Injured Direction Of Travel SOUTHBOUND Vith	D CLASS	tions Issued CrashTire Mark Inction CIAL FUNC trol FROL ature	Classification	Total Trai 0 Speed Lii	TRUCK Operating A illers mit Emergency NOT APP Traffic Cont NO	Total Haz 0 Total Lan 2 Motor Veh LICABLE rol Inopera	Mat Types es icle Use
	Unit IN T Vehi Tota 1 Insur YES TRE Traff TWC Surfa	Status TRANSIT icle Type LITY TRUCK/PICKUP I Occs rance? S t Harmful Event: Collision V EE fic Way D-WAY, NOT DIVIDED ace Type	Train/Bus # Injured Direction Of Travel SOUTHBOUND Vith	D CLASS	tions Issued CrashTire Mark Inction CIAL FUNC trol FROL ature	Classification	Total Trai 0 Speed Lii	TRUCK Operating A illers mit Emergency NOT APP Traffic Cont NO Road Grade	Total Haz 0 Total Lan 2 Motor Veh LICABLE rol Inopera	Mat Types es icle Use
	Unit IN T Vehi Tota 1 Insur YES Most TRE Traff TWC Surfa BLA Truc NO	Status TRANSIT icle Type LITY TRUCK/PICKUP I Occs rance? S t Harmful Event: Collision V EE fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS	Train/Bus # Injured Direction Of Travel SOUTHBOUND Vith	D CLASS	tions Issued CrashTire Mark Inction CIAL FUNC trol FROL ature	Classification	Total Trai 0 Speed Lii	TRUCK Operating A illers mit Emergency NOT APP Traffic Cont NO Road Grade	Total Haz 0 Total Lan 2 Motor Veh LICABLE rol Inopera	Mat Types es icle Use
	Unit IN T Vehi Tota 1 Insur YES Most TRE Traff TWC Surfa BLA Truc NO	Status RANSIT Icle Type LITY TRUCK/PICKUP ⁻ I Occs rance? S t Harmful Event: Collision V EE fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS k Bus or HazMat	Train/Bus # Injured Direction Of Travel SOUTHBOUND Vith	D CLASS	tions Issued CrashTire Mark CiAL FUNC TROL ature EFT	Classification	Total Trai 0 Speed Lii	TRUCK Operating A illers mit Emergency NOT APP Traffic Cont NO Road Grade	Total Haz 0 Total Lan 2 Motor Veh LICABLE rol Inopera	Mat Types es icle Use
	Unit IN T Vehi Tota 1 Insur YES Most TRE Traff TWC Surfa BLA Truc NO	Status TRANSIT icle Type LITY TRUCK/PICKUP T I Occs rance? S t Harmful Event: Collision V EE fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS ik Bus or HazMat Vehicle	Train/Bus # Injured Direction Of Travel SOUTHBOUND Vith	D CLASS	tions Issued CrashTire Mark CiAL FUNC TROL ature EFT	Classification	Total Trai 0 Speed Liu 45	TRUCK Operating A illers mit Emergency NOT APP Traffic Cont NO Road Grade DOWNHIL	Total Haz 0 Total Lan 2 Motor Veh LICABLE rol Inopera -L suance	Mat Types es icle Use
	Unit IN T Vehi Tota 1 Insur YES Most TRE Traff TWC Surfa BLA Truc NO	Status RANSIT icle Type LITY TRUCK/PICKUP I Occs rance? S t Harmful Event: Collision V EE ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS k Bus or HazMat Vehicle License Plate Number LD2337	Train/Bus # Injured Direction Of Travel SOUTHBOUND Vith	D CLASS	tions Issued CrashTire Mark Cial FUNC trol TROL ature EFT	Classification	Total Tra 0 Speed Lin 45	TRUCK Operating A illers mit Emergency NOT APP Traffic Cont NO Road Grade DOWNHIL Country of Is UNITED S	Total Haz 0 Total Lan 2 Motor Veh LICABLE rol Inopera -L suance	Mat Types es icle Use
	Unit IN T Vehi Tota 1 Insur YES Most TRE Traff TWC Surfa BLA Truc NO	Status TRANSIT icle Type LITY TRUCK/PICKUP T I Occs rance? S t Harmful Event: Collision V EE ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS ik Bus or HazMat Vehicle License Plate Number	Train/Bus # Injured Direction Of Travel SOUTHBOUND Vith S)	D CLASS	tions Issued CrashTire Mark Inction CrashTire Mark IAL FUNC trol FROL ature EFT GHT TRUC	Classification	Total Trai 0 Speed Liu 45 St WI	TRUCK Operating A illers mit Emergency NOT APP Traffic Cont NO Road Grade DOWNHIL	Total Haz 0 Total Lan 2 Motor Veh LICABLE rol Inopera 2 L suance FATES	Mat Types es icle Use
	Unit IN T Vehi Tota 1 Insur YES Most TRE Traff TRE Traff Truc NO	Status TRANSIT Cicle Type LITY TRUCK/PICKUP I Occs Trance? Contemporate Status Trance? Contemporate Status Thermful Event: Collision V EE Cicle Way Co-WAY, NOT DIVIDED Contemporate Status Contemporate Statu	Train/Bus # Injured Direction Of Travel SOUTHBOUND Vith S)	D CLASS	tions Issued CrashTire Mark Diction CrashTire Mark Diction Crol Trol TROL DIAL FUNC Trol CROL CROL CROL CROL CROL CROL CROL CROL	Classification	Total Trai 0 Speed Liu 45 St WI Year	TRUCK Operating A illers mit Emergency NOT APP Traffic Cont NO Road Grade DOWNHIL Country of Is UNITED ST Model SILVERAD	Total Haz 0 Total Lan 2 Motor Veh LICABLE rol Inopera 2 L suance FATES	Mat Types es icle Use
	Unit IN T Vehi Tota 1 Insur YES Most TRE Traff TRE Traff Truc NO	Status Status RANSIT Cole Type LITY TRUCK/PICKUP OCCS Trance? Trance? Thermful Event: Collision V EE Tic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS k Bus or HazMat Vehicle License Plate Number LD2337 Vehicle Identification Num 3GCPKSE74CG16298 Color	Train/Bus # Injured Direction Of Travel SOUTHBOUND Vith S)	D CLASS	tions Issued CrashTire Mark IAL FUNC trol TROL ature EFT BHT TRUC DLET	Classification	Total Trai 0 Speed Liu 45 St WI Year	TRUCK Operating A Operating A illers mit Emergency NOT APP Traffic Cont NO Road Grade DOWNHIL Country of Is UNITED S ⁻ Model	Total Haz 0 Total Lan 2 Motor Veh LICABLE rol Inopera 3 L suance TATES 00	Mat Types es icle Use
	Unit IN T Vehi Tota 1 Insu YES Most TRE Traff TWC Surfa BLA NO	Status TRANSIT Cicle Type LITY TRUCK/PICKUP I Occs Trance? Trance? Tharmful Event: Collision V EE Tic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS k Bus or HazMat Vehicle License Plate Number LD2337 Vehicle Identification Num 3GCPKSE74CG16295 Color SIL - SILVER (ALUMI	Train/Bus # Injured Direction Of Travel SOUTHBOUND Vith S)	D CLASS	tions Issued CrashTire Mark notion CRAL FUNC trol FROL ature EFT BHT TRUC	Classification	Total Trai 0 Speed Liu 45 St WI Year	TRUCK Operating A ilers mit Emergency NOT APP Traffic Cont NO Road Grade DOWNHIL Country of Is UNITED S Model SILVERAD Bus Use	Total Haz 0 Total Lan 2 Motor Veh LICABLE rol Inopera 3 L suance TATES 00	Mat Types es icle Use
01 01	Unit IN T Vehi UTII Tota 1 Insuu YES Most TRE Traff TWC Surfa BLA Truc NO	Status TRANSIT Cele Type LITY TRUCK/PICKUP I Occs Trance? Trance? Tharmful Event: Collision V EE fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS k Bus or HazMat Vehicle License Plate Number LD2337 Vehicle Identification Num 3GCPKSE74CG16295 Color SIL - SILVER (ALUMI Initial Contact Point	Train/Bus # Injured Direction Of Travel SOUTHBOUND Vith S) nber 52 NUM)	D CLASS	tions Issued CrashTire Mark notion CRAL FUNC trol FROL ature EFT BHT TRUC	Classification	Total Trai 0 Speed Liu 45 St WI Year	TRUCK Operating A ilers mit Emergency NOT APP Traffic Cont NO Road Grade DOWNHIL Country of Is UNITED S Model SILVERAD Bus Use	Total Haz 0 Total Lan 2 Motor Veh LICABLE rol Inopera 3 L suance TATES 00	Mat Types es icle Use
01 01	Unit IN T Vehi UTII Tota 1 Insuu YES Most TRE Traff TWC Surfa BLA Truc NO	Status TRANSIT CICLE Type LITY TRUCK/PICKUP I OCCS Tance? Tance? The tharmful Event: Collision V EE Tic Way D-WAY, NOT DIVIDED Tic Way CO-WAY, NOT DIVIDED ACKTOP (BITUMINOUS ACKTOP (BITUMINOUS ACKTOP (BITUMINOUS ACKTOP (BITUMINOUS COLOR SIL - SILVER (ALUMI Initial Contact Point 1RIGHT FRONT CO	Train/Bus # Injured Direction Of Travel SOUTHBOUND Vith S) nber 52 NUM)	D CLASS	tions Issued TrashTire Mark CrashTire CrashTire Mark CrashTire CrashTi	Classification	Total Tra 0 Speed Lin 45 St WI Year 2012 2RIGHT	TRUCK Operating A ilers mit Emergency NOT APP Traffic Cont NO Road Grade DOWNHIL Country of Is UNITED S Model SILVERAD Bus Use NOT A BU SIDE FROM	Total Haz 0 Total Lan 2 Motor Veh LICABLE rol Inopera 3 LL Suance TATES 00 S IT, 9LEI	Mat Types es icle Use tive/Missing FT SIDE MIDDLE, 10
	Unit IN T Vehi Tota 1 Insu YES Most TRE Traff TWC Surfa BLA NO	Status TRANSIT Cele Type LITY TRUCK/PICKUP I Occs Trance? Trance? Tharmful Event: Collision V EE Tic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS k Bus or HazMat Vehicle License Plate Number LD2337 Vehicle Identification Num 3GCPKSE74CG16295 Color SIL - SILVER (ALUMI Initial Contact Point	Train/Bus # Injured Direction Of Travel SOUTHBOUND Vith S) Ther S2 NUM) RNER	D CLASS	tions Issued TrashTire Mark CrashTire CrashTire Mark CrashTire CrashTi	Classification	Total Tra 0 Speed Lin 45 St WI Year 2012 2RIGHT	TRUCK Operating A ilers mit Emergency NOT APP Traffic Cont NO Road Grade DOWNHIL Country of Is UNITED S ^T Model SILVERAD Bus Use NOT A BU	Total Haz 0 Total Lan 2 Motor Veh LICABLE rol Inopera 3 LL Suance TATES 00 S IT, 9LEI	Mat Types es icle Use tive/Missing FT SIDE MIDDLE, 10

UNIT



18-03069

WISCONSIN MOTOR VEHICLE **CRASH REPORT**

		TOWED BUT NOT DUE TO DISABLING DAMAG What Driver Was Doing	STEVES AUTO SERVICE Vehicle Factors					
		NEGOTIATING CURVE						
		Driver Prior Action Other	NOT APPLICABLE					
UNIT	VEHICLE	Driver Actions FAILURE TO CONTROL, RAN OFF ROADWAY, FA	AILED TO KEEP IN DESIGNATED LANE	, OVER-CORRECTING/OVER-STEERING				
		Driver Distractions NOT DISTRACTED						
6	01	2						
		Owner Name LOGAN COY (608) 963-8868	Owner Address 414 CRESTVIEW DR REEDSBURG, WI 53959, US					
		Sequence Of Events	•					
	01	Event RUN OFF ROADWAY RIGHT						
	02	Event CROSS CENTERLINE						
	03	Event TREE						
	04	Event OVERTURN/ROLLOVER						
ъ	I	Policy Holder						
UNIT		Insurance Company AMERICAN-FAMILY-INS-CO	Individual LOGAN COY					
	I	ndividual						
		Driver LOGAN COY	Citations Issued	Sex				
	AL	(608) 963-8868	1 Date of Birth	MALE Race				
ы	DO			WHITE				
UNIT	NDIVIDUA	Address 414 CRESTVIEW DR	Driver License Number					
	Z	REEDSBURG, WI 53959, US	STATE: WISCONSIN COUNTRY: UNITED STATES					
	l	On Duty Crash	Safety Equipment					
		Seat Position	SHOULDER & LAP BELT					
		1FRONT SEAT-LEFT SIDE (DRIVER/MOTORCY						
		Helmet Use	Helmet Compliance					
		Eye Protection	Tint Compliance					
5	001	Injury Severity SUSPECTED MINOR INJURY	Airbag DEPLOYED-COMBINATION					
Nicco	ncin M	NOT EJECTED Autor Vehicle Crash This rep	NOT EJECTED/NOT APPLICABL	NOT TRAPPED Crash Date 03/25/2018				

6TL0BC3B1H

18-03069

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

		Medical Transport NOT TRANSPORTED			EMS Agenc	cy Identifier	EMS Run #			
		Hospital			Date of Dea	ath	Time of Death			
		Non Motorist	Striking Unit #	Prior Action	•	Location		To/From School		
		Action	- -	·						
⊢	UAL									
	INDIVIDUAL									
	IN									
		Action Other								
	Ľ	Drug & Alcohol Suspected Alcohol Use YES			Suspected Drug Use NO					
		Alcohol Test Given	•		Alcohol Tes	••	Alcohol Test Results			
		TEST GIVEN				ARY BREATH TEST (P	13			
		Drug Test Given TEST NOT GIVE	N		Drug Test T	уре	Drug Test Results			
5	001	Drug Type								
Individual Condition										
	UNDER THE INFLUENCE OF MEDICATIONS/DRUGS/ ALCOHOL									
Violations										
	_	UTC Number	Issue To?	Statute Number	Seq Num 006					
	5	AE138228	001	346.70(1)	000	FAILURE OF OPERATOR				
		perty Owner								
е ^н 01		ernment WNSHIP OF DELLONA 8) 524-0800			Address E8062 CTH H REEDSBURG, WI 53959, US					
PROP OWNER	NNO									
	Fixe	ed Objects Str	uck							
	0	U U	truck Object				Structure Number	Damage Tag Number N/A		