
18-03725

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895



18-03725

WISCONSIN MOTOR VEHICLE CRASH REPORT

	Loc									
ſ	-	CTHS EB			Latitude			Longituc		
		5 FT W		4	43.460187681			-90.107	120312	
		NARROWS VALLEY R IDGE)			X Coordinate 248635.15625			Y Coord 481661		
		IN THE TOWN OF WASHINGTON IN SAUK COUNTY				Structure Type BRIDGE				
		sh Scene								
Ţ		Harmful Event			F	First Harmful Event Location				
		DITCH						DF-WAY (TF	RAFFICW	AY)
ŀ	Man	ner of Collision		ight Cond		•	_	,		
	NO	NO COLLISION W/VEHICLE IN TRANSPORT					IT			
ŀ	Road	d Surface Condition(s)		R	Roadway Factor(s)					
	SLU	JSH								
ŀ	Envi	ronment Factor(s)								
	WE	ATHER CONDITIONS				ROAD SU ETC)	JRFACE (CONDITION	(WET, IC	CY, SNOW, SLUSH,
ŀ	Wea	ther Condition(s)				-,				
	RAI	N, SLEET/HAIL								
ŀ	Anim	nal Type			R	Relation To	o Trafficway	,		
					TRAFFICWAY - NOT ON ROAD					
ľ	Cras	h Classification - Location		C	Crash Classification - Jurisdiction					
		PUBLIC PROPERTY						SDICTION		
	Triba	Tribal Land					Access Control Special Study NO CONTROL		Special Study	
		•				tion Type				
	NO		NON-JUNCTION		NOT AN IN	OT AN INTERSECTION				
	Ini	t Summary 🛛 💻								
	Unit	Status			erating As Clas	ssification		Unit Type		
	Unit IN T	Status RANSIT		Vehicle Ope	0	ssification		AUTOMO		nonte
	Unit IN T Vehi	Status RANSIT cle Type	F		0	ssification				nents
	Unit IN T Vehi (SP	Status TRANSIT cle Type ORT) UTILITY VEHICL		D CLASS		ssification	Total Traile	AUTOMOI Operating A	s Endorser	
	Unit IN T Vehi (SP	Status RANSIT cle Type	E Train/Bus # Injured	D CLASS	0	ssification	Total Traile 0	AUTOMOI Operating A	s Endorser	nents Mat Types
	Unit IN T Vehi (SP Tota 1	Status TRANSIT cle Type ORT) UTILITY VEHICL		D CLASS	tions Issued	ssification		AUTOMON Operating A	s Endorser Total Haz	Mat Types
10	Unit IN T Vehi (SP Tota 1	Status RANSIT cle Type ORT) UTILITY VEHICL I Occs rance?	Train/Bus # Injured	D CLASS		ssification	0	AUTOMON Operating A	s Endorser Total Haz 0	Mat Types
10	Unit IN T Vehi (SP Tota 1 Insu YES	Status RANSIT cle Type ORT) UTILITY VEHICL I Occs rance? S t Harmful Event: Collision V	Train/Bus # Injured Direction Of Travel EASTBOUND	D CLASS	tions Issued CrashTire Mark		0 Speed Lim	AUTOMOE Operating A ers it Emergency	s Endorser Total Haz 0 Total Lan 2 Motor Vehi	Mat Types es icle Use
10	Unit IN T Vehi (SP Tota 1 Insu YES Most DIT	Status RANSIT cle Type ORT) UTILITY VEHICL I Occs rance? S t Harmful Event: Collision V CH	Train/Bus # Injured Direction Of Travel EASTBOUND	D CLASS	tions Issued CrashTire Mark iction CIAL FUNCTI		0 Speed Lim	AUTOMOI Operating A ers it Emergency NOT APPI	s Endorser Total Haz 0 Total Land 2 Motor Vehi LICABLE	Mat Types es icle Use
	Unit IN T Vehi (SP) Tota 1 Insu YES Most DIT Traff	Status RANSIT cle Type ORT) UTILITY VEHICL I Occs rance? S t Harmful Event: Collision V CH ic Way	Train/Bus # Injured Direction Of Travel EASTBOUND With	D CLASS	tions Issued CrashTire Mark Inction CIAL FUNCTION		0 Speed Lim	AUTOMOI Operating A ors it Emergency NOT APPI Traffic Contr	s Endorser Total Haz 0 Total Land 2 Motor Vehi LICABLE	Mat Types es icle Use
	Unit IN T Vehi (SP Tota 1 Insut YES DIT Traff	Status RANSIT cle Type ORT) UTILITY VEHICL I Occs rance? S t Harmful Event: Collision V CH ic Way D-WAY, NOT DIVIDED	Train/Bus # Injured Direction Of Travel EASTBOUND With	D CLASS	tions Issued CrashTire Mark Inction IAL FUNCTION ITOI IROL		0 Speed Lim	AUTOMON Operating A ers it Emergency NOT APPI Traffic Contr NO	s Endorser Total Haz 0 Total Land 2 Motor Vehi LICABLE ol Inoperal	Mat Types es icle Use
	Unit IN T Vehi (SP Tota 1 Insu YES DIT Traff TW(Surfa	Status RANSIT cle Type ORT) UTILITY VEHICL I Occs rance? S t Harmful Event: Collision V CH ic Way D-WAY, NOT DIVIDED ace Type	Train/Bus # Injured Direction Of Travel EASTBOUND With	D CLASS	tions Issued CrashTire Mark action CIAL FUNCTION TROL ature		0 Speed Lim	AUTOMOI Operating A ers it Emergency NOT APPI Traffic Contr NO Road Grade	s Endorser Total Haz 0 Total Land 2 Motor Vehi LICABLE	Mat Types es icle Use
	Unit IN T Vehi (SP Tota 1 Insuu YES Most DIT Traff Two Surfa BLA	Status RANSIT cle Type ORT) UTILITY VEHICL I Occs rance? S t Harmful Event: Collision V CH ic Way D-WAY, NOT DIVIDED	Train/Bus # Injured Direction Of Travel EASTBOUND With	D CLASS	tions Issued CrashTire Mark action CIAL FUNCTION Trol ROL ature		0 Speed Lim	AUTOMON Operating A ers it Emergency NOT APPI Traffic Contr NO	s Endorser Total Haz 0 Total Land 2 Motor Vehi LICABLE	Mat Types es icle Use
	Unit IN T Vehi (SP Tota 1 Insuu YES Most DIT Traff Two Surfa BLA	Status RANSIT Cle Type ORT) UTILITY VEHICL I Occs rance? S t Harmful Event: Collision V CH fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS	Train/Bus # Injured Direction Of Travel EASTBOUND With	D CLASS	tions Issued CrashTire Mark action CIAL FUNCTION Trol ROL ature		0 Speed Lim	AUTOMOI Operating A operating A ers it Emergency NOT APPI Traffic Contr NO Road Grade	s Endorser Total Haz 0 Total Land 2 Motor Vehi LICABLE	Mat Types es icle Use
	Unit IN T Vehi (SP Tota 1 Insuu YES Moss DIT Traff Surfa BLA Truc NO	Status RANSIT cle Type ORT) UTILITY VEHICL I Occs rance? S t Harmful Event: Collision W CH ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS k Bus or HazMat Vehicle	Train/Bus # Injured Direction Of Travel EASTBOUND With	D CLASS	tions Issued CrashTire Mark action SIAL FUNCTION TROL ature T	ION	0 Speed Lim 55	AUTOMOI Operating A ors it Emergency NOT APPI Traffic Contr NO Road Grade DOWNHIL	s Endorser Total Haz 0 Total Land 2 Motor Vehi LICABLE rol Inoperat	Mat Types es icle Use
	Unit IN T Vehi (SP Tota 1 Insuu YES Moss DIT Traff Surfa BLA Truc NO	Status RANSIT Cle Type ORT) UTILITY VEHICL I Occs rance? S t Harmful Event: Collision W CH ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS k Bus or HazMat Vehicle License Plate Number	Train/Bus # Injured Direction Of Travel EASTBOUND With	D CLASS	tions Issued CrashTire Mark action SIAL FUNCTION TOL ature T		0 Speed Lim 55	AUTOMOI Operating A operating A ers it Emergency NOT APPI Traffic Contr NO Road Grade DOWNHIL	s Endorser Total Haz 0 Total Land 2 Motor Vehi LICABLE rol Inoperat	Mat Types es icle Use
	Unit IN T Vehi (SP Tota 1 Insuu YES Moss DIT Traff Surfa BLA Truc NO	Status RANSIT cle Type ORT) UTILITY VEHICL I Occs rance? S t Harmful Event: Collision W CH ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS k Bus or HazMat Vehicle License Plate Number 122YRC	Train/Bus # Injured Direction Of Travel EASTBOUND With S)	D CLASS	tions Issued CrashTire Mark action SIAL FUNCTION TROL ature T		0 Speed Lim 55	AUTOMOI Operating A Operating A ers it Emergency NOT APPI Traffic Contr NO Road Grade DOWNHIL	s Endorser Total Haz 0 Total Land 2 Motor Vehi LICABLE rol Inoperat	Mat Types es icle Use
	Unit IN T Vehi (SP Tota 1 Insuu YES Moss DIT Traff Surfa BLA Truc NO	Status RANSIT cle Type ORT) UTILITY VEHICL I Occs rance? S t Harmful Event: Collision W CH ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS k Bus or HazMat Vehicle License Plate Number 122YRC Vehicle Identification Num	Train/Bus # Injured Direction Of Travel EASTBOUND With S)	D CLASS	tions Issued CrashTire Mark Inction CIAL FUNCTION TOI TOI TOI TUTUTE T JTOMOBILE		0 Speed Lim 55	AUTOMOI Operating A Operating A ers it Emergency NOT APPI Traffic Contr NO Road Grade DOWNHIL Country of Is: UNITED ST Model	s Endorser Total Haz 0 Total Land 2 Motor Vehi LICABLE fol Inoperat	Mat Types es icle Use
	Unit IN T Vehi (SP Tota 1 Insuu YES DIT Traff Two Surfa BLA Truc NO	Status RANSIT cle Type ORT) UTILITY VEHICL I Occs rance? S t Harmful Event: Collision W CH ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS k Bus or HazMat Vehicle License Plate Number 122YRC	Train/Bus # Injured Direction Of Travel EASTBOUND With S)	D CLASS	tions Issued CrashTire Mark Inction CIAL FUNCTIN TROL Ature T JTOMOBILE DLET		0 Speed Lim 55 St WI Year 2003	AUTOMOI Operating A Operating A ers it Emergency NOT APPI Traffic Contr NO Road Grade DOWNHIL Country of Is: UNITED ST Model TRAILBLA. Bus Use	s Endorser Total Haz 0 Total Land 2 Motor Vehi LICABLE rol Inoperat	Mat Types es icle Use
	Unit IN T Vehi (SP Tota 1 Insuu YES DIT Traff Two Surfa BLA Truc NO	Status RANSIT cle Type ORT) UTILITY VEHICL I Occs rance? S t Harmful Event: Collision V CH ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS k Bus or HazMat Vehicle License Plate Number 122YRC Vehicle Identification Num 1GNDT13SX3227644	Train/Bus # Injured Direction Of Travel EASTBOUND With S)	D CLASS	tions Issued CrashTire Mark Inction CIAL FUNCTIN TROL Ature T JTOMOBILE DLET		0 Speed Lim 55 St WI Year 2003	AUTOMOI Operating A Pers it Emergency NOT APPI Traffic Contr NO Road Grade DOWNHIL Country of Ist UNITED ST Model TRAILBLA	s Endorser Total Haz 0 Total Land 2 Motor Vehi LICABLE rol Inoperat	Mat Types es icle Use
	Unit Unit IN T Vehi (SP) Tota 1 Insur YES DITO Traff TWO Surfa BLA Truc NO	Status Status RANSIT Cle Type ORT) UTILITY VEHICL OCCS rance? Tance? Tharmful Event: Collision V CH Tic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS k Bus or HazMat Vehicle License Plate Number 122YRC Vehicle Identification Num 1GNDT13SX3227644 Color TAN - TAN Initial Contact Point	Train/Bus # Injured Direction Of Travel EASTBOUND With S) nber 1	D CLASS	tions Issued CrashTire Mark Inction IAL FUNCTIN TROL Ature T JTOMOBILE DLET DRT UTILITY		0 Speed Lim 55 St WI Year 2003	AUTOMOI Operating A Operating A ers it Emergency NOT APPI Traffic Contr NO Road Grade DOWNHIL Country of Is: UNITED ST Model TRAILBLA. Bus Use	s Endorser Total Haz 0 Total Land 2 Motor Vehi LICABLE rol Inoperat	Mat Types es icle Use
UNI 01	Unit IN T Vehi (SP Tota 1 Insu YES DIT Surfa BLA NO	Status RANSIT cle Type ORT) UTILITY VEHICL I Occs rance? S t Harmful Event: Collision V CH ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS k Bus or HazMat Vehicle License Plate Number 122YRC Vehicle Identification Num 1GNDT13SX3227644 Color TAN - TAN	Train/Bus # Injured Direction Of Travel EASTBOUND With S) nber 1	D CLASS	tions Issued CrashTire Mark Inction IAL FUNCTIN TROL Ature T JTOMOBILE DLET DRT UTILITY		0 Speed Lim 55 St WI Year 2003	AUTOMOI Operating A Operating A ers it Emergency NOT APPI Traffic Contr NO Road Grade DOWNHIL Country of Is: UNITED ST Model TRAILBLA. Bus Use	s Endorser Total Haz 0 Total Land 2 Motor Vehi LICABLE rol Inoperat	Mat Types es icle Use

18-03725

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

		Towed Due To Damage Vehicle Removed By							
	TOWED BUT NOT DUE TO DISABLING DAMAG		STEVES AUTO SERVICE						
		What Driver Was Doing GOING STRAIGHT		Vehicle Factors					
		Driver Prior Action Other			NOT APPLICABLE				
UNIT	VEHICLE	Driver Actions SPEED TOO FAST/COND, FAILURE TO CONTROL, FAILED TO KEEP IN DESIGNATED LANE, SWERVED OR AVOIDED DUE TO WIND, SLIPPERY SURFACE, MOTOR VEHICLE, OBJECT, NON-MOTORIST IN ROADWAY, ETC., OVER-CORRECTING/OVER- STEERING							
		Driver Distractions NOT DISTRACTED							
01	01	5							
		Owner Name ROXANN R DEMA (608) 547-4478			Owner Address E889 COUNTY ROAD EE WONEWOC, WI 53968, US				
		Sequence Of Ev	vents						
	01	5 DITCH							
	02	Event							
	03	Event							
	04	Event							
н	l l	Policy Holder							
UNIT		Insurance Company GERMANTOWN-MUTUAL-INS-CO							
		Individual							
		Driver			Citations Issued	Sex			
	Ļ	ROXANN R DEMA	SKE	0	0	FEMALE			
ь	DUA			1	Date of Birth	Race WHITE			
UNIT	INDIVIDUA	Address E889 COUNTY ROAD EE WONEWOC, WI 53968 , US		Driver License Number STATE: WISCONSIN COUNTRY: UNITED STATES					
		On Duty Crash		Safety Equipment					
	1	Seat Position 1FRONT SEAT-LEFT SIDE (DRIVER/MOTORCY		SHOULDER & LAP BELT					
		Helmet Use		ł	Helmet Compliance				
		Eye Protection			Tint Compliance				
6	001	Indune	Injury Severity NO APPARENT INJURY		Airbag NON DEPLOYED				
		Ejected NOT EJECTED			Ejection Path Trapped/Extricated NOT EJECTED/NOT APPLICABL NOT TRAPPED				
Visco	nsin N	Notor Vehicle Crash	This rep		loes not include any CJIS data.	Crash Date	04/13/2018		

18-03725

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Medical Transport					EMS Agency Ident	fier	EMS Run #			
		NOT TRANSPORT	TED							
Hospital				Date of Death		Time of Death				
	l	Non Motorist	Striking Unit #	Prior Action		Location		To/From School		
		Action								
	AL									
UNIT	INDIVIDUAL									
5										
	IN									
		Action Other								
	_		Suspected Alcohol U	lse	Suspected Drug Us	se				
	L	Drug & Alcohol NO			NO					
		Alcohol Test Given TEST NOT GIVEN	L		Alcohol Test Type		Alcohol Test Results			
		Drug Test Given				Drug Test Type		Drug Test Results		
		TEST NOT GIVEN								
6	001	Drug Type								
	•									
		Individual Condition								
		APPEARED NORMAL								