6TL09B7D8N

18-03921

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

	Document Number Override	Primary Crash Document #		Agency Crash Number 18-03921		Investigating Officer/Deputy DEPUTY A. MEEKER		
	Crash Date 04/18/2018	Crash Time 05:29 PM		Date Arrived 04/18/2018		Time Arrived 05:58 PM		
O I LUSD / DOIN	Date Notified 04/18/2018	Time Notified 06:07 PM		Total Units 01		Total Injured 00	· · · · · · · · · · · · · · · · · · ·	
-03I	On Emergency Him	t and Run	Lane Closu	ure	☐ Work Zone	Trailer	or Towed	Reporting Threshold
0 I L	Government Property	School NO	Bus Related	Tags				
	Reportable	Crash Type DT4000 (STA	ANDARD CRASH	l)		Amend	ed	Secondary Crash
	Description				_			
	s. golfcourse rd			fire I	number	(Photos By Additional Info	
					drawing not to scale			
	I, a sworn law enforceme							OVER CORRECTED
	SPINNING AROUND BEFORE EN OF UNIT 1 DID NOT HAVE A VAL VALID LICENSE.	ITERING THE EA	AST SIDE DITCH S	TRIKING	A FIRE NUMBER SIGN	AND COMING T	O A REST FAC	CING NORTH. OPERATOR

6TL09B7D8N 18-03921

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN **1300 LANGE COURT BARABOO, WI 53913** (608) 356-4895

Crash Time 05:29 PM

L	OC	ation								
		ERSECTION			Latitude			Longitude		
	ON	GOLF COURSE RD				43.523936574		-89.964544041		
		.T JUNCTION RD N THE TOWN OF REEDSBURG				X Coordinate		Y Coordinate		
						260422.46875		4823270		
	IN S	SAUK COUNTY						4023270		
					Structure Type NO STRUCTURE					
(ra	sh Scene								
T	First	Harmful Event			First Harm	nful Event I	ocation			
	DIT				ON ROA		200411011			
		ner of Collision			Light Cond	Light Condition				
		NO COLLISION W/VEHICLE IN TRANSPORT				HT				
_		d Surface Condition(s)			Roadway					
		T, SNOW, SLUSH			, todanay	. acto.(0)				
-	Envi	ronment Factor(s)								
		ATHER CONDITIONS			ROAD S ETC)	URFACE	CONDITION	(WET, ICY, SNOW, SLUSH,		
F	Wea	ther Condition(s)								
	CLOUDY, SNOW, FOG									
İ	Anim	nal Type	уре				Relation To Trafficway TRAFFICWAY - ON ROAD			
F	Crash Classification - Location PUBLIC PROPERTY									
						Crash Classification - Jurisdiction NO SPECIAL JURISDICTION				
		al Land				Access Control Special Study				
						NO CONTROL				
-	With	Vithin Interchange Area Junction Location Intersection				on Type				
	- I					INTERSECTION				
ī	Ini	t Summary								
		Status		I Vahiala On anatina Aa			•			
				venicle Operating As	Classification	1	Unit Type			
				Vehicle Operating As D CLASS	Classification	l	Unit Type AUTOMO	BILE		
	IN T	FRANSIT icle Type		D CLASS	Classification	1	AUTOMO	BILE s Endorsements		
_	IN T Vehi	RANSIT			Classification		AUTOMO			
10	IN T Vehi	TRANSIT icle Type	Train/Bus # Injured			Total Tra	AUTOMOI Operating A			
6	IN T Vehi	TRANSIT icle Type SSENGER CAR	Train/Bus # Injured	D CLASS			AUTOMOI Operating A	s Endorsements		
5	Vehi PAS Tota	TRANSIT icle Type SSENGER CAR	Train/Bus # Injured Direction Of Travel	D CLASS Total # Citations Issu 1	ed	Total Tra	AUTOMOI Operating A	s Endorsements		
5	Vehi PAS Tota	TRANSIT icle Type SSENGER CAR Il Occs	ŕ	D CLASS Total # Citations Issu	ed	Total Tra	AUTOMOI Operating A	s Endorsements Total HazMat Types		
5	IN T Vehi PAS Tota 1 Insur	TRANSIT icle Type SSENGER CAR Il Occs	Direction Of Travel SOUTHBOUND	Total # Citations Issu 1 Pre CrashTi	ed	Total Tra 0 Speed Li	AUTOMOI Operating A iilers	s Endorsements Total HazMat Types Total Lanes 2 Motor Vehicle Use		
	IN T Vehi PAS Tota 1 Insur	RANSIT icle Type SSENGER CAR Il Occs rance? S t Harmful Event: Collision V	Direction Of Travel SOUTHBOUND	Total # Citations Issu 1 Pre CrashTi Mark	ed re	Total Tra 0 Speed Li	AUTOMOI Operating A	s Endorsements Total HazMat Types Total Lanes 2 Motor Vehicle Use		
	IN T Vehi PAS Tota 1 Insui YES Most	RANSIT icle Type SSENGER CAR Il Occs rance? S t Harmful Event: Collision V	Direction Of Travel SOUTHBOUND	Total # Citations Issu 1 Pre CrashTi Mark Special Function	ed re	Total Tra 0 Speed Li	AUTOMOI Operating A iilers mit Emergency NOT APPI	s Endorsements Total HazMat Types Total Lanes 2 Motor Vehicle Use		
	IN T Vehi PAS Tota 1 Insur YES Most DIT	TRANSIT icle Type SSENGER CAR Il Occs rance? S t Harmful Event: Collision V	Direction Of Travel SOUTHBOUND With	Total # Citations Issu 1 Pre CrashTi Mark Special Function NO SPECIAL FUN	ed re	Total Tra 0 Speed Li	AUTOMOI Operating A iilers mit Emergency NOT APPI	s Endorsements Total HazMat Types Total Lanes 2 Motor Vehicle Use LICABLE		
	IN T Vehi PAS Tota 1 Insur YES Most DIT Traff	TRANSIT icle Type SSENGER CAR Il Occs rance? S It Harmful Event: Collision V CH fic Way	Direction Of Travel SOUTHBOUND With	Total # Citations Issu 1 Pre CrashTi Mark Special Function NO SPECIAL FUN Traffic Control	ed re	Total Tra 0 Speed Li	AUTOMOI Operating A iilers mit Emergency NOT APPI Traffic Cont	Total HazMat Types Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing		
LO IIIO	PAS Tota 1 Insur YES Most DIT(Traff TWC)	TRANSIT icle Type SSENGER CAR Il Occs rance? S It Harmful Event: Collision V CH fic Way D-WAY, NOT DIVIDED	Direction Of Travel SOUTHBOUND With	Total # Citations Issu 1 Pre CrashTi Mark Special Function NO SPECIAL FUN Traffic Control NO CONTROL	ed re	Total Tra 0 Speed Li	AUTOMOI Operating A iilers mit Emergency NOT APPI Traffic Conti	Total HazMat Types Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing		
TO IND	IN T Vehi PAS Tota 1 Insuit YES Most DIT(Traff TW(Surfa BLA	TRANSIT Icle Type SSENGER CAR Il Occs rance? S It Harmful Event: Collision W CH fic Way D-WAY, NOT DIVIDED ace Type	Direction Of Travel SOUTHBOUND With	Total # Citations Issu 1 Pre CrashTi Mark Special Function NO SPECIAL FUN Traffic Control NO CONTROL Road Curvature	ed re	Total Tra 0 Speed Li	AUTOMOI Operating A iilers mit Emergency NOT APP Traffic Cont NO Road Grade	Total HazMat Types Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing		
ONII OI	IN T Vehi PAS Tota 1 Insuit YES Most DIT(Traff TW(Surfa BLA	TRANSIT Icle Type SSENGER CAR II Occs rance? St Harmful Event: Collision W CH fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS ik Bus or HazMat	Direction Of Travel SOUTHBOUND With	Total # Citations Issu 1 Pre CrashTi Mark Special Function NO SPECIAL FUN Traffic Control NO CONTROL Road Curvature	ed re	Total Tra 0 Speed Li	AUTOMOI Operating A iilers mit Emergency NOT APP Traffic Cont NO Road Grade	Total HazMat Types Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing		
ONII OI	IN T Vehi PAS Tota 1 Insur YES Most DIT Traff TWC Surfa BLA Truc NO	TRANSIT icle Type SSENGER CAR Il Occs rance? S t Harmful Event: Collision V CH fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS ick Bus or HazMat	Direction Of Travel SOUTHBOUND With	Total # Citations Issu 1 Pre CrashTi Mark Special Function NO SPECIAL FUN Traffic Control NO CONTROL Road Curvature	ed re	Total Tra 0 Speed Li	AUTOMOI Operating A iilers mit Emergency NOT APP Traffic Cont NO Road Grade	Total HazMat Types Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing		
ONII OI	IN T Vehi PAS Tota 1 Insur YES Most DIT Traff TWC Surfa BLA Truc NO	TRANSIT Icle Type SSENGER CAR II Occs rance? St Harmful Event: Collision W CH fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS ik Bus or HazMat	Direction Of Travel SOUTHBOUND With	Total # Citations Issu 1 Pre CrashTi Mark Special Function NO SPECIAL FUN Traffic Control NO CONTROL Road Curvature STRAIGHT	ed re	Total Tra 0 Speed Li	AUTOMOI Operating A iilers mit Emergency NOT APP Traffic Cont NO Road Grade	Total HazMat Types Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing		
ONII OI	IN T Vehi PAS Tota 1 Insur YES Most DIT Traff TWC Surfa BLA Truc NO	RANSIT Icle Type SSENGER CAR Il Occs rance? S It Harmful Event: Collision W CH Ific Way O-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS Ick Bus or HazMat	Direction Of Travel SOUTHBOUND With	Total # Citations Issu 1 Pre CrashTi Mark Special Function NO SPECIAL FUN Traffic Control NO CONTROL Road Curvature	ed re NCTION	Total Tra 0 Speed Li 45	AUTOMOI Operating A illers mit Emergency NOT APPI Traffic Cont NO Road Grade LEVEL	Total HazMat Types Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing		
	IN T Vehi PAS Tota 1 Insur YES Most DIT Traff TWC Surfa BLA Truc NO	TRANSIT Icle Type SSENGER CAR II Occs rance? St Harmful Event: Collision W CH Ific Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS Ick Bus or HazMat Vehicle License Plate Number 767UGP	Direction Of Travel SOUTHBOUND With	Total # Citations Issu 1 Pre CrashTi Mark Special Function NO SPECIAL FUN Traffic Control NO CONTROL Road Curvature STRAIGHT	ed re NCTION	Total Tra 0 Speed Li 45	AUTOMOI Operating A iilers mit Emergency NOT APPI Traffic Cont NO Road Grade LEVEL Country of Is UNITED ST	Total HazMat Types Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing		
	IN T Vehi PAS Tota 1 Insur YES Most DIT Traff TWC Surfa BLA Truc NO	TRANSIT Icle Type SSENGER CAR II Occs Trance? St Harmful Event: Collision N CH Icle Icle Icle Icle Icle Icle Icle Icle	Direction Of Travel SOUTHBOUND With	Total # Citations Issu 1 Pre CrashTi Mark Special Function NO SPECIAL FUN Traffic Control NO CONTROL Road Curvature STRAIGHT Plate Type AUT - AUTOMOE Make	ed re NCTION	Total Tra 0 Speed Li 45	AUTOMOI Operating A iilers mit Emergency NOT APPI Traffic Cont NO Road Grade LEVEL	Total HazMat Types Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing		
	IN T Vehi PAS Tota 1 Insur YES Most DIT(Traff TW(Surfa BLA Truc	TRANSIT Icle Type SSENGER CAR ICOCCS Trance? St ACKTOP (BITUMINOUS ICK Bus or HazMat Vehicle License Plate Number 767UGP Vehicle Identification Nun 2G1WH55K41913883	Direction Of Travel SOUTHBOUND With	Total # Citations Issu 1 Pre CrashTi Mark Special Function NO SPECIAL FUN Traffic Control NO CONTROL Road Curvature STRAIGHT Plate Type AUT - AUTOMOE Make CHEVROLET	ed re NCTION	Total Tra 0 Speed Li 45 St WI Year	AUTOMOI Operating A iilers mit Emergency NOT APPI Traffic Cont NO Road Grade LEVEL Country of Is UNITED S1 Model	Total HazMat Types Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing		
	IN T Vehi PAS Tota 1 Insur YES Most DIT(Traff TW(Surfa BLA Truc	TRANSIT Icle Type SSENGER CAR II Occs rance? St Harmful Event: Collision W CH fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS Ick Bus or HazMat Vehicle License Plate Number 767UGP Vehicle Identification Num	Direction Of Travel SOUTHBOUND With	Total # Citations Issu 1 Pre CrashTi Mark Special Function NO SPECIAL FUN Traffic Control NO CONTROL Road Curvature STRAIGHT Plate Type AUT - AUTOMOE Make	ed re NCTION	Total Tra 0 Speed Li 45 St WI Year	AUTOMOI Operating A iilers mit Emergency NOT APPI Traffic Cont NO Road Grade LEVEL Country of Is UNITED ST Model IMPALA LS	Total HazMat Types Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing		
	IN T Vehi PAS Tota 1 Insur YES Most DIT Traff TWO Surfa BLA	TRANSIT Icle Type SSENGER CAR II Occs rance? St Harmful Event: Collision V CH fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS ik Bus or HazMat Vehicle License Plate Number 767UGP Vehicle Identification Nun 2G1WH55K41913883 Color	Direction Of Travel SOUTHBOUND With	Total # Citations Issu 1 Pre CrashTi Mark Special Function NO SPECIAL FUN Traffic Control NO CONTROL Road Curvature STRAIGHT Plate Type AUT - AUTOMOE Make CHEVROLET Body Style	ed re NCTION	Total Tra 0 Speed Li 45 St WI Year	AUTOMOI Operating A iilers mit Emergency NOT APPI Traffic Cont NO Road Grade LEVEL Country of Is UNITED ST Model IMPALA LS Bus Use	Total HazMat Types Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing		
	IN T Vehi PAS Tota 1 Insur YES Most DIT Traff TWO Surfa BLA	TRANSIT Icle Type SSENGER CAR ICOCCS Trance? St Harmful Event: Collision V CH fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS Ick Bus or HazMat Vehicle License Plate Number 767UGP Vehicle Identification Num 2G1WH55K41913883 Color RED - RED	Direction Of Travel SOUTHBOUND With S)	Total # Citations Issu 1 Pre CrashTi Mark Special Function NO SPECIAL FUN Traffic Control NO CONTROL Road Curvature STRAIGHT Plate Type AUT - AUTOMOE Make CHEVROLET Body Style 4D - 4DR	ed re NCTION	Total Tra 0 Speed Li 45 St WI Year	AUTOMOI Operating A iilers mit Emergency NOT APPI Traffic Cont NO Road Grade LEVEL Country of Is UNITED ST Model IMPALA LS Bus Use	Total HazMat Types Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing		
	IN T Vehi PAS Tota 1 Insur YES Most DIT Traff TWO Surfa BLA	TRANSIT Icle Type SSENGER CAR ICOCCS Trance? St Harmful Event: Collision V CH fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS Ik Bus or HazMat Vehicle License Plate Number 767UGP Vehicle Identification Num 2G1WH55K41913883 Color RED - RED Initial Contact Point	Direction Of Travel SOUTHBOUND With S)	Total # Citations Issu 1 Pre CrashTi Mark Special Function NO SPECIAL FUN Traffic Control NO CONTROL Road Curvature STRAIGHT Plate Type AUT - AUTOMOE Make CHEVROLET Body Style 4D - 4DR	ed re NCTION	Total Tra 0 Speed Li 45 St WI Year	AUTOMOI Operating A iilers mit Emergency NOT APPI Traffic Cont NO Road Grade LEVEL Country of Is UNITED ST Model IMPALA LS Bus Use	Total HazMat Types Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing		
	IN T Vehi PAS Tota 1 Ilnsui YES Most DIT Traff TW(Surfa BLA Truc	TRANSIT Icle Type SSENGER CAR II Occs Trance? Stat Harmful Event: Collision V CH fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS Ick Bus or HazMat Vehicle License Plate Number 767UGP Vehicle Identification Num 2G1WH55K41913883 Color RED - RED Initial Contact Point 5RIGHT REAR COR	Direction Of Travel SOUTHBOUND With S)	Total # Citations Issu 1 Pre CrashTi Mark Special Function NO SPECIAL FUN Traffic Control NO CONTROL Road Curvature STRAIGHT Plate Type AUT - AUTOMOE Make CHEVROLET Body Style 4D - 4DR	ed re NCTION	Total Tra 0 Speed Li 45 St WI Year	AUTOMOI Operating A iilers mit Emergency NOT APPI Traffic Cont NO Road Grade LEVEL Country of Is UNITED ST Model IMPALA LS Bus Use	Total HazMat Types Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing		
	IN T Vehi PAS Tota 1 Insur YES Most DIT Traff TWO Surfa BLA	TRANSIT Icle Type SSENGER CAR II Occs Trance? Stat Harmful Event: Collision V CH fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS Ick Bus or HazMat Vehicle License Plate Number 767UGP Vehicle Identification Num 2G1WH55K41913883 Color RED - RED Initial Contact Point 5RIGHT REAR COR Extent Of Damage	Direction Of Travel SOUTHBOUND With S)	Total # Citations Issu 1 Pre CrashTi Mark Special Function NO SPECIAL FUN Traffic Control NO CONTROL Road Curvature STRAIGHT Plate Type AUT - AUTOMOE Make CHEVROLET Body Style 4D - 4DR	ed re NCTION	Total Tra 0 Speed Li 45 St WI Year	AUTOMOI Operating A illers mit Emergency NOT APPI Traffic Conti NO Road Grade LEVEL Country of Is UNITED ST Model IMPALA LS Bus Use NOT A BUS	Total HazMat Types Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing		

6TL09B7D8N

18-03921

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

	-			Vehicle Removed By						
		NOT TOWED		STEVES AUTO SERVICE						
		What Driver Was Doing		Vehicle Factors						
		GOING STRAIGH		NOT APPLICABLE	NOT ARRIGARIE					
		Driver Prior Action Of	her	NOT AFFLICABLE	NOT APPLICABLE					
		Driver Actions								
	ш	SPEED TOO FAS	T/COND							
\vdash	긋									
L	¥									
-	VEHICL									
		Driver Distractions NOT DISTRACTED								
		NOIDISTRACTE	Ь							
2	5									
	J									
		- N								
		Owner Name LOUIS LOPEZ FI	I IO	Owner Address S4303 BUCKEYE RD ROCKSPRINGS, WI 53961, US						
		(608) 415-9735								
		()								
	,	Sequence Of Events								
		Event Events								
	5	DITCH								
	02	Event CALLED BOOK BOLLE OR SUPPORT								
	0	OTHER POST, POLE OR SUPPORT								
	03	Event								
	₩.	Event Event								
	04									
╘	ı	Policy Holder								
FIN		Insurance Company		Individual						
_		ALLSTATE-INS-CO		GARCIA MARTIN						
		Individual								
		Driver LOUIS LOPEZ FILIO (608) 415-9735		Citations Issued	Sex					
	7			1	MALE					
	INDIVIDUAL			Date of Birth	Race HISPANIC					
L N	₹	Address		Driver License Number						
5		S4303 BUCKEYE	RD	Diver License Number						
	Z	ROCKSPRINGS,								
			On Duty Crash	Safety Equipment						
		Equipment								
		Seat Position		SHOULDER & LAP BELT Helmet Compliance						
		1FRONT SEAT-LEFT SIDE (DRIVER/MOTORCY Helmet Use								
				Tipt Compliance						
		Eye Protection		Tint Compliance						
	_		Injury Severity	Airbag						
2	00	Injury NO APPARENT INJURY		NON DEPLOYED						
		Ejected		Ejection Path	Trapped/Extricated					
		NOT EJECTED		NOT EJECTED/NOT APPLICABL	NOT TRAPPED					

6TL09B7D8N

18-03921

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

		Medical Transport			EMS Agency Identifier		EMS Run #		
		NOT TRANSPORT	TED						
		Hospital			Date of Death		Time of Death	Time of Death	
		Christian Haite H. Drive Action							
		Non Motorist	Striking Unit #	Prior Action		Location		To/From School	
		Action							
	ب								
_	INDIVIDUAL								
UNIT	=								
)	₫								
	Z								
		Action Other							
			Suspected Alco	hol I Isa	Suspected I	Drug Hse			
	L	Drug & Alcohol	NO	1101 030	NO	Drug OSC			
		Alcohol Test Given			Alcohol Tes	t Type	Alcohol Test Results		
		TEST NOT GIVEN			Drug Test T	Vne	Drug Test Results		
		Drug Test Given TEST NOT GIVEN	I		Diug rest i	уре	Drug Test Results		
01	001	Drug Type					<u>.</u>		
	J								
		Individual Condition							
	,	Violetiana							
		Violations UTC Number	Issue To?	Statute Number	Sea Num Description				
	5	AE141833	001	343.05(3)(a)	Seq Num 002	Description OPERATE W/O VALI	ID LICENSE		