6TL0B8M7T2

18-03849

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT **BARABOO, WI 53913** (608) 356-4895

Document Number Override	Primary Crash Document # Crash Time 07:10 AM Time Notified 07:37 AM		Agency Crash Number 18-03849		Investigating Officer/Deputy DEPUTY B. MEARS				
Crash Date 04/17/2018			Date Arrived 04/17/2018			Time Arrived 07:57 AM			
Date Notified 04/17/2018 On Emergency Hit Government Property			Total Units 01		Total Injured Total Kille 00 00		Total Kille	ed	
On Emergency Hit	and Run	Lane Clos		Work Zon	е	ш	ailer or	Towed	Reporting Threshold
Government Property		chool Zone	NO School	Bus Related		Tags			
Reportable	Crash Type DT4000 (STA	NDARD CRASH	I)			Am	nended	l	Secondary Crash
Diagram Diagram							R	econstruction	n Bv
									,
<u></u>							PI	hotos By	
								dditional Info	rmation
unit on passe	nger side	(لِلْجِيدِيلِ)							
		cth hh			cth	h			
					1				
not to scale									
✓ I, a sworn law enforceme	nt officer, agr	ee that I have no	ot added	l any CJIS data	in this	report.			
UNIT WAS EB ON GAVIN RD APP SLIDE ON ICY SNOW COVERED OVERTURNING ONTO THE PASS PASSENGER SIDE. UNIT WAS RI	ROADWAY. UNI SENGER SIDE A	T SLID ACROSS V ND BECAME STU	VB LANE	INTO THE NORT	HSIDE DI	ITCH , TE	RAVELL	ED ABOUT 2	20 FEET, SLOWLY

6TL0B8M7T2 18-03849

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

	LOC	ation									
	_	GAVIN RD			Latitude			Longitude	e		
	313 FT W					43.620057994		_	-89.944382615		
		СТННН ЕВ									
	IN T	HE TOWN OF DELLO	NA		X Coordinate			Y Coordii 483388			
	IN S	SAUK COUNTY				262430.375			0		
					Structure	Structure Type					
	Cra	sh Scene									
					le:	() =					
		Harmful Event			mful Event						
	_	ERTURN/ROLLOVER				SHOULDER LEFT					
		ner of Collision			Light Condition						
		COLLISION W/VEHIC	LE IN TRANSPORT			DAYLIGHT					
	Road	d Surface Condition(s)			Roadway	Roadway Factor(s)					
	SNO	DW, ICE									
	Envi	ronment Factor(s)									
	NOI	NE			ROAD S	SURFACE	CONDITION	I (WET, IC	Y, SNOW, SLUSH,		
	Wea	ther Condition(s)									
	CLE	AR									
	Anim	nal Type			Dalation						
	AIIII	іаі туре				Relation To Trafficway TRAFFICWAY - NOT ON ROAD					
	Cras	sh Classification - Location			Crash Cla	Crash Classification - Jurisdiction					
		BLIC PROPERTY				NO SPECIAL JURISDICTION					
	Triba	al Land				Access Control			Special Study		
						NO CONTROL					
	NO NO	in Interchange Area	Junction Location INTERSECTION-RELA	TED	Intersection Type T-INTERSECTION						
		. ~				•					
		t Summary Status		L Vahiala Ona	rating As Classificatio	n	11-2 T				
	Unit	Status		-	rating As Classificatio	n	Unit Type	DII E			
	Unit IN T	Status RANSIT		Vehicle Oper	rating As Classificatio	n	AUTOMO		pente		
_	Unit IN T Vehi	Status RANSIT cle Type	E	-	rating As Classificatio	n	AUTOMO	BILE as Endorsem	nents		
	Unit IN T Vehi (SP	Status RANSIT cle Type ORT) UTILITY VEHICL		D CLASS		n Total Tra	AUTOMO Operating A	s Endorsem			
	Unit IN T Vehi (SP	Status RANSIT cle Type	E Train/Bus # Injured	-			AUTOMO Operating A				
	Unit IN T Vehi (SP Tota 01	Status RANSIT cle Type ORT) UTILITY VEHICL		D CLASS Total # Citati 00	ons Issued	Total Tra	AUTOMO Operating A	s Endorsem	Mat Types		
	Unit IN T Vehi (SP Tota 01	Status RANSIT cle Type ORT) UTILITY VEHICL I Occs	Train/Bus # Injured	Total # Citati	ons Issued CrashTire Mark	Total Tra	AUTOMO Operating A	Total Lane 02	Mat Types		
	Unit IN T Vehi (SP) Tota 01 Insul YES	Status RANSIT cle Type ORT) UTILITY VEHICL I Occs rance? 6 t Harmful Event: Collision \	Train/Bus # Injured Direction Of Travel EASTBOUND	Total # Citati 00 Pre C	ons Issued CrashTire Mark etion	Total Tra 0 Speed L	AUTOMO Operating A iilers imit Emergency	Total Hazh Total Lane 02 Motor Vehic	Mat Types		
	Unit IN T Vehi (SP Tota 01 Insu YES Most	Status RANSIT cle Type ORT) UTILITY VEHICL I Occs rance? St Harmful Event: Collision NERTURN/ROLLOVER	Train/Bus # Injured Direction Of Travel EASTBOUND	Total # Citati 00 Pre C Special Func NO SPECI	ons Issued CrashTire Mark stion AL FUNCTION	Total Tra 0 Speed L	AUTOMO Operating A stillers imit Emergency NOT APP	Total Hazi	Mat Types es cle Use		
	Unit IN T Vehi (SP Tota 01 Insu YES Most OVE	Status RANSIT cle Type ORT) UTILITY VEHICL I Occs rance? St Harmful Event: Collision Ne ERTURN/ROLLOVER iic Way	Train/Bus # Injured Direction Of Travel EASTBOUND With	Total # Citati 00 Pre (Special Func NO SPECI Traffic Contro	ons Issued CrashTire Mark Stion AL FUNCTION	Total Tra 0 Speed L	AUTOMO Operating A iilers imit Emergency NOT APP Traffic Cont	Total Hazh Total Lane 02 Motor Vehic	Mat Types es cle Use		
	Unit IN T Vehi (SP) Tota 01 Insui YES Mosi OVE Traff	Status RANSIT cle Type ORT) UTILITY VEHICL I Occs rance? St Harmful Event: Collision VERTURN/ROLLOVER fic Way D-WAY, NOT DIVIDED	Train/Bus # Injured Direction Of Travel EASTBOUND With	D CLASS Total # Citati 00 Pre (Special Func NO SPECI Traffic Contre NO CONTE	ons Issued CrashTire Mark Stion AL FUNCTION OI ROL	Total Tra 0 Speed L	AUTOMO Operating A sillers imit Emergency NOT APP Traffic Cont	Total Hazi	Mat Types es cle Use		
	Unit IN T Vehi (SP Tota 01 Insure YES OVE Traff TWG	Status TRANSIT cle Type ORT) UTILITY VEHICL I Occs rance? St Harmful Event: Collision Nerthandler ERTURN/ROLLOVER fic Way D-WAY, NOT DIVIDED ace Type	Train/Bus # Injured Direction Of Travel EASTBOUND With	Total # Citati 00 Pre (Special Func NO SPECI Traffic Contro	ons Issued CrashTire Mark etion AL FUNCTION ol ROL ure	Total Tra 0 Speed L	AUTOMO Operating A iilers imit Emergency NOT APP Traffic Cont	Total Hazi	Mat Types es cle Use		
	Unit IN T Vehi (SP Tota 01 Insur YES Most OVE Traff TWC Surfa BLA	Status RANSIT cle Type ORT) UTILITY VEHICL I Occs rance? St Harmful Event: Collision VERTURN/ROLLOVER fic Way D-WAY, NOT DIVIDED	Train/Bus # Injured Direction Of Travel EASTBOUND With	D CLASS Total # Citati 00 Pre C Special Func NO SPECI Traffic Contr NO CONTE	ons Issued CrashTire Mark etion AL FUNCTION ol ROL ure	Total Tra 0 Speed L	AUTOMO Operating A sillers Emergency NOT APP Traffic Cont NO Road Grade	Total Hazi	Mat Types es cle Use		
	Unit IN T Vehi (SP Tota 01 Insur YES Most OVE Traff TWC Surfa BLA	Status TRANSIT Cle Type ORT) UTILITY VEHICL I Occs Trance? St Harmful Event: Collision Nerturn/ROLLOVER Tic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS)	Train/Bus # Injured Direction Of Travel EASTBOUND With	D CLASS Total # Citati 00 Pre C Special Func NO SPECI Traffic Contr NO CONTE	ons Issued CrashTire Mark etion AL FUNCTION ol ROL ure	Total Tra 0 Speed L	AUTOMO Operating A sillers Emergency NOT APP Traffic Cont NO Road Grade	Total Hazi	Mat Types es cle Use		
	Unit IN T Vehi (SP) Tota 01 Insul YES Most OVE Traff TWO Surfa BLA Truc	Status TRANSIT Cle Type ORT) UTILITY VEHICL I Occs Trance? St Harmful Event: Collision Nerturn/ROLLOVER Tic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS)	Train/Bus # Injured Direction Of Travel EASTBOUND With	D CLASS Total # Citati 00 Pre C Special Func NO SPECI Traffic Contr NO CONTE	ons Issued CrashTire Mark etion AL FUNCTION ol ROL ure	Total Tra 0 Speed L 45	AUTOMO Operating A illers Emergency NOT APP Traffic Cont NO Road Grade UPHILL	Total Hazili Total Lane 02 Motor Vehic LICABLE rol Inoperati	Mat Types es cle Use		
	Unit IN T Vehi (SP) Tota 01 Insul YES Most OVE Traff TWO Surfa BLA Truc	Status RANSIT cle Type ORT) UTILITY VEHICL I Occs rance? St Harmful Event: Collision Network ERTURN/ROLLOVER ric Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS) k Bus or HazMat Vehicle License Plate Number	Train/Bus # Injured Direction Of Travel EASTBOUND With	D CLASS Total # Citati 00 Pre (Special Func NO SPECI Traffic Contre NO CONTE Road Curvat STRAIGHT	ons Issued CrashTire Mark stion AL FUNCTION ol ROL ure	Total Tra 0 Speed L 45	AUTOMO Operating A illers imit Emergency NOT APP Traffic Cont NO Road Grade UPHILL Country of Is	Total Hazili Total Lane 02 Motor Vehic LICABLE rol Inoperati	Mat Types es cle Use		
	Unit IN T Vehi (SP) Tota 01 Insul YES Most OVE Traff TWO Surfa BLA Truc	Status RANSIT cle Type ORT) UTILITY VEHICL I Occs rance? St Harmful Event: Collision Network ERTURN/ROLLOVER fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS k Bus or HazMat Vehicle License Plate Number ACJ4812	Train/Bus # Injured Direction Of Travel EASTBOUND With	Total # Citati 00 Pre C Special Func NO SPECI Traffic Contr NO CONTE Road Curvat STRAIGHT Plate Type AUT - AU'	ons Issued CrashTire Mark etion AL FUNCTION ol ROL ure	Total Tra 0 Speed L 45	AUTOMO Operating A sillers Imit Emergency NOT APP Traffic Cont NO Road Grade UPHILL Country of Is UNITED S	Total Hazili Total Lane 02 Motor Vehic LICABLE rol Inoperati	Mat Types es cle Use		
	Unit IN T Vehi (SP) Tota 01 Insul YES Most OVE Traff TWO Surfa BLA Truc	Status RANSIT cle Type ORT) UTILITY VEHICL I Occs rance? St Harmful Event: Collision Network ERTURN/ROLLOVER ric Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS) k Bus or HazMat Vehicle License Plate Number	Train/Bus # Injured Direction Of Travel EASTBOUND With	D CLASS Total # Citati 00 Pre (Special Func NO SPECI Traffic Contre NO CONTE Road Curvat STRAIGHT	ons Issued CrashTire Mark Etion AL FUNCTION ol ROL ure TOMOBILE	Total Tra 0 Speed L 45	AUTOMO Operating A illers imit Emergency NOT APP Traffic Cont NO Road Grade UPHILL Country of Is	Total Hazi	Mat Types es cle Use		
	Unit IN T Vehi (SP Tota 01 Insury YES OVE Traff TWC Surfa BLA Truc	Status RANSIT cle Type ORT) UTILITY VEHICL I Occs rance? St Harmful Event: Collision NERTURN/ROLLOVER fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS k Bus or HazMat Vehicle License Plate Number ACJ4812 Vehicle Identification Nur	Train/Bus # Injured Direction Of Travel EASTBOUND With	Total # Citati 00 Pre C Special Func NO SPECI Traffic Contre NO CONTE Road Curvat STRAIGHT Plate Type AUT - AU' Make	ons Issued CrashTire Mark Etion AL FUNCTION ol ROL ure TOMOBILE	Total Tra 0 Speed L 45 St WI Year	AUTOMO Operating A illers imit Emergency NOT APP Traffic Cont NO Road Grade UPHILL Country of Is UNITED S' Model MOUNTAII Bus Use	Total Hazili Total Lane 02 Motor Vehic LICABLE rol Inoperati	Mat Types es cle Use		
	Unit IN T Vehi (SP Tota 01 Insury YES OVE Traff TWC Surfa BLA Truc	Status RANSIT cle Type ORT) UTILITY VEHICL I Occs rance? St Harmful Event: Collision Network (Color of the Number ACJ4812 Vehicle Identification Nurus (March 1988)	Train/Bus # Injured Direction Of Travel EASTBOUND With	Total # Citati 00 Pre C Special Func NO SPECI Traffic Contre NO CONTF Road Curvat STRAIGHT Plate Type AUT - AU' Make MERCUR' Body Style UT - SPOI	ons Issued CrashTire Mark Stion AL FUNCTION OI ROL ure TOMOBILE Y	Total Tra 0 Speed L 45 St WI Year 2000	AUTOMO Operating A iilers imit Emergency NOT APP Traffic Cont NO Road Grade UPHILL Country of Is UNITED S' Model MOUNTAII	Total Hazili Total Lane 02 Motor Vehic LICABLE rol Inoperati	Mat Types es cle Use		
	Unit IN T Vehi (SP Tota 01 Insur YES Mosi OVE Traff TWO Surfa BLA Truc NO	Status RANSIT cle Type ORT) UTILITY VEHICL I Occs rance? St Harmful Event: Collision Net of the State o	Train/Bus # Injured Direction Of Travel EASTBOUND With S)	Total # Citati 00 Pre C Special Func NO SPECI Traffic Contre NO CONTF Road Curvat STRAIGHT Plate Type AUT - AU' Make MERCUR' Body Style	ons Issued CrashTire Mark Stion AL FUNCTION OI ROL ure TOMOBILE Y	Total Tra 0 Speed L 45 St WI Year 2000	AUTOMO Operating A illers imit Emergency NOT APP Traffic Cont NO Road Grade UPHILL Country of Is UNITED S' Model MOUNTAII Bus Use	Total Hazili Total Lane 02 Motor Vehic LICABLE rol Inoperati	Mat Types es cle Use		
	Unit IN T Vehi (SP Tota 01 Insur YES Mosi OVE Traff TWO Surfa BLA Truc NO	Status RANSIT Cle Type ORT) UTILITY VEHICL I Occs rance? St Harmful Event: Collision Note ERTURN/ROLLOVER Tic Way D-WAY, NOT DIVIDED Tace Type ACKTOP (BITUMINOUS Ik Bus or HazMat Vehicle License Plate Number ACJ4812 Vehicle Identification Nur 4M2ZU86P2YUJ2415 Color RED - RED Initial Contact Point 1RIGHT FRONT CO	Train/Bus # Injured Direction Of Travel EASTBOUND With S)	Total # Citati 00 Pre C Special Func NO SPECI Traffic Contre NO CONTE Road Curvat STRAIGHT Plate Type AUT - AU' Make MERCUR' Body Style UT - SPOI Vehicle Dar	ons Issued CrashTire Mark Stion AL FUNCTION OI ROL ure	Total Tra 0 Speed L 45 St WI Year 2000	AUTOMO Operating A illers imit Emergency NOT APP Traffic Cont NO Road Grade UPHILL Country of Is UNITED S' Model MOUNTAII Bus Use	Total Hazili Total Lane 02 Motor Vehic LICABLE rol Inoperati	Mat Types es cle Use		
	Unit IN T Vehi (SP Tota 01 Insury YES OVE Traff TWC Surfa BLA Truc	Status RANSIT cle Type ORT) UTILITY VEHICL I Occs rance? St Harmful Event: Collision Net of the State o	Train/Bus # Injured Direction Of Travel EASTBOUND With S)	Total # Citati 00 Pre C Special Func NO SPECI Traffic Contre NO CONTE Road Curvat STRAIGHT Plate Type AUT - AU' Make MERCUR' Body Style UT - SPOI Vehicle Dar	ons Issued CrashTire Mark Stion AL FUNCTION OI ROL ure TOMOBILE Y	Total Tra 0 Speed L 45 St WI Year 2000	AUTOMO Operating A illers imit Emergency NOT APP Traffic Cont NO Road Grade UPHILL Country of Is UNITED S' Model MOUNTAII Bus Use	Total Hazili Total Lane 02 Motor Vehic LICABLE rol Inoperati	Mat Types es cle Use		

Crash Time 07:10 AM

6TL0B8M7T2

18-03849

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

	Towed Due To Damage TOWED BUT NOT DUE TO DISABLING DAMAG			Vehicle Removed By STEVES AUTO SERVICE						
		What Driver Was Doing		Vehicle Factors						
		SLOW/STOPPING		NOT	ADDI ICADI E					
		Driver Prior Action Other			APPLICABLE					
		Driver Actions								
	ш	FAILURE TO CON	ITROL							
╘										
LIND	Ĭ									
ا ر	VEHICL									
		Driver Distractions	<u> </u>							
		NOT DISTRACTE	5							
5	6									
		Owner Name		Ιo	wner Address					
		ASHLEY NICOLE DILLEY			S935 KELLEY DR					
		(608) 415-2869			LYNDON STATION, WI 53944 , US					
	(Sequence Of E	vents							
		Event								
	Б рітсн									
	S Event OVERTURN/ROLLOVER									
	03	Event								
	_	Event								
	04									
_	ı	Policy Holder								
L		Insurance Company		Indi	vidual					
_	PROGRESSIVE-CASUALTY-INS-CO			TEI	RRY COLSON					
	ı	Individual								
		Driver		Cita	ations Issued	Sex				
	ب	ASHLEY NICOLE DILLEY (608) 415-2869		0		FEMALE				
	INDIVIDUA			Date	e of Birth	Race WHITE				
╘╵	₽					WHITE				
EN I	\leq	Address S935 KELLEY DR LYNDON STATION, WI 53944 , US			Driver License Number					
	Ż				STATE: WISCONSIN COUNTRY: UNITED STATES					
	_		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,							
			On Duty Crash	Safe	ety Equipment					
		Equipment		Sucry Equipment						
		Seat Position		SHOULDER & LAP BELT						
		1FRONT SEAT-LEFT SIDE (DRIVER/MOTORCY								
		Helmet Use			Helmet Compliance					
		Fue Drobestian		Tint Orang Kanan						
		Eye Protection		Tint	Compliance					
	_		Injury Severity	Airb	pag					
2	5 Injury NO APPARENT INJURY			NON DEPLOYED						
		Ejected			ction Path	Trapped/Extricated				
		NOT EJECTED		NO	T EJECTED/NOT APPLICABL	NOT TRAPPED				

6TL0B8M7T2

18-03849

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

		Medical Transport NOT TRANSPORTED Hospital			EMS Agency Identifier		EMS Run #	
					Date of Death		Time of Death	
		Non Motorist	Striking Unit #	Prior Action		Location		To/From School
		Action						
	JAL							
UNIT	INDIVIDUAL							
	N							
		Action Other						
	L	Drug & Alcohol	Suspected Alcohol NO	Use	Suspected Drug U NO	se		
		Alcohol Test Given TEST NOT GIVEN	l		Alcohol Test Type		Alcohol Test Results	
		Drug Test Given TEST NOT GIVEN	I		Drug Test Type		Drug Test Results	
10	001	Drug Type						
		Individual Condition						
		APPEARED NOR	MAL					