# 6TL092T5LQ

18-04672

### WISCONSIN MOTOR VEHICLE CRASH REPORT

#### SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

	Document Number Override	Primary Crash Document #				nvestigating Officer/Deputy DEPUTY J. KIRKENG		
g	Crash Date 05/07/2018	Crash Time 06:30 PM		e Arrived 07/2018	Time Arrived 06:37 PM	Time Arrived 06:37 PM		
6TL092T5LQ	Date Notified 05/07/2018	Time Notified 06:30 PM		al Units	Total Injured <b>00</b>	Total Kille <b>00</b>	al Killed	
600-	On Emergency	t and Run	Lane Closure	Work Zone	✓ Trailer	or Towed	Reporting Threshold	
6T	Government Property	Active Scho	ol Zone NO	ool Bus Related	Tags			
	Reportable	Crash Type PRIVATE PROP	ERTY/PARKING I	_OT	Amend	ed	Secondary Crash	
	Description							
	Diagram					Reconstruction	ву	
						Photos By		
						Additional Info NONE	rmation	
	✔ I, a sworn law enforceme							
	UNIT 1 WAS UNLOADING IT'S PF	RODUCT WHEN IT B	BECAME UNLEVEL A	ND TIPPED ONTO THE	DRIVERS SIDE.			

18-04672

### WISCONSIN MOTOR VEHICLE CRASH REPORT

1		ocation PRIVATE PROPERTY					Latitude			
	SAN	ND HILL RD		43.461814486			-90.06071414			
		IN THE TOWN OF WESTFIELD IN SAUK COUNTY					X Coordinate 252396.25		Y Coordinate <b>4816652</b>	
				Structure Type						
				NO STRUCTURE						
(	Cra	sh Scene								
Ī		Harmful Event		First Harmful Event Location						
	-	ERTURN/ROLLOVER		OFF ROADWAY, LOCATION UNKNOWN						
		ner of Collision		Light Condition						
ŀ		COLLISION W/VEHIC	LE IN TRANSPORT	DAYLIGH Roadway F						
		Road Surface Condition(s) MUD/DIRT Environment Factor(s) NONE								
ŀ	Envi									
	NO									
ŀ	Wea	ther Condition(s)								
	CLE	EAR								
ĺ	Anim	nal Type			Relation To Trafficway NON TRAFFICWAY -					
ŀ		sh Classification - Location	1		(	Crash Clas	sification	- Jurisdiction		
ļ		VATE PROPERTY								
	THUC		Access Control NO CONTROL			Special Study				
	With NO	Within Interchange Area         Junction Location         Intersection           NO         NON-JUNCTION         NOT AN					tion Type N INTERSECTION			
Ī	Uni	t Summary								
T	Unit Status Vehicle Operating As C									
						assification		Unit Type		
		GALLY PARKED		Vehicle Ope		assification		TRUCK		
	Vehi		ATTACHED)			assification		TRUCK Operating A	s Endorsements	
•	Vehi TRL Tota	GALLY PARKED	ATTACHED) Train/Bus # Injured	A CLASS		assification	Total Tra	TRUCK Operating A F - FARM	SERVICE CDL Total HazMat Types	
•	Vehi TRL Tota 0	GALLY PARKED icle Type JCK TRACTOR (SEMI I Occs	Train/Bus # Injured	A CLASS		assification	Total Tra 1	TRUCK Operating A F - FARM illers	SERVICE CDL Total HazMat Types 0	
	Vehi TRL Tota 0	GALLY PARKED icle Type JCK TRACTOR (SEMI I Occs rance?	-	A CLASS		assification	Total Tra	TRUCK Operating A F - FARM illers	SERVICE CDL Total HazMat Types	
	Vehi TRL Tota 0 Insur YES	GALLY PARKED icle Type JCK TRACTOR (SEMI I Occs rance? S t Harmful Event: Collision	Train/Bus # Injured Direction Of Travel NOT ON ROADWAY	A CLASS	tions Issued CrashTire Mark		Total Tra 1 Speed Li	TRUCK Operating A F - FARM illers mit	SERVICE CDL Total HazMat Types 0 Total Lanes 1 Motor Vehicle Use	
•	Vehi TRL Tota 0 Insur YES Most	GALLY PARKED icle Type JCK TRACTOR (SEMI I Occs rance? S t Harmful Event: Collision ERTURN/ROLLOVER	Train/Bus # Injured Direction Of Travel NOT ON ROADWAY	A CLASS	tions Issued CrashTire Mark iction iIAL FUNCT		Total Tra 1 Speed Li	TRUCK Operating A F - FARM illers mit Emergency NOT APP	SERVICE CDL Total HazMat Types 0 Total Lanes 1 Motor Vehicle Use LICABLE	
	Vehi TRL Tota 0 Insur YES Most OVE	GALLY PARKED icle Type JCK TRACTOR (SEMI I Occs rance? S t Harmful Event: Collision	Train/Bus # Injured Direction Of Travel NOT ON ROADWAY With	A CLASS	tions Issued CrashTire Mark Iction IAL FUNCT		Total Tra 1 Speed Li	TRUCK Operating A F - FARM illers mit Emergency NOT APP	SERVICE CDL Total HazMat Types 0 Total Lanes 1 Motor Vehicle Use	
•	Vehi TRL Tota 0 Insur YES Most OVE Traff	GALLY PARKED icle Type JCK TRACTOR (SEMI I Occs rance? S t Harmful Event: Collision ERTURN/ROLLOVER fic Way RKING LOT OR PRIVA ace Type	Train/Bus # Injured Direction Of Travel NOT ON ROADWAY With	A CLASS	tions Issued CrashTire Mark cition CIAL FUNCT rol ROL ature		Total Tra 1 Speed Li	TRUCK Operating A F - FARM illers mit Emergency NOT APP Traffic Cont	SERVICE CDL Total HazMat Types 0 Total Lanes 1 Motor Vehicle Use LICABLE rol Inoperative/Missing	
	Vehi TRL Tota 0 Insur YES Most OVE Traff PAR Surfa DIR Truc	GALLY PARKED icle Type JCK TRACTOR (SEMI I Occs rance? S t Harmful Event: Collision ERTURN/ROLLOVER fic Way RKING LOT OR PRIVA ace Type T tk Bus or HazMat	Train/Bus # Injured Direction Of Travel NOT ON ROADWAY With TE PROPERTY	A CLASS	tions Issued CrashTire Mark cition CIAL FUNCT rol ROL ature		Total Tra 1 Speed Li	TRUCK Operating A F - FARM illers mit Emergency NOT APP Traffic Cont NO Road Grade	SERVICE CDL Total HazMat Types 0 Total Lanes 1 Motor Vehicle Use LICABLE rol Inoperative/Missing	
	Vehi TRL Tota 0 Insur YES Most OVE Traff PAR Surfa DIR Truc TRL	GALLY PARKED icicle Type JCK TRACTOR (SEMI il Occs rance? S t Harmful Event: Collision ERTURN/ROLLOVER fic Way RKING LOT OR PRIVA ace Type T kk Bus or HazMat JCK OR TRUCK COM	Train/Bus # Injured Direction Of Travel NOT ON ROADWAY With	A CLASS	tions Issued CrashTire Mark cition CIAL FUNCT rol ROL ature		Total Tra 1 Speed Li	TRUCK Operating A F - FARM illers mit Emergency NOT APP Traffic Cont NO Road Grade	SERVICE CDL Total HazMat Types 0 Total Lanes 1 Motor Vehicle Use LICABLE rol Inoperative/Missing	
•	Vehi TRL Tota 0 Insur YES Most OVE Traff PAR Surfa DIR Truc TRL	GALLY PARKED icle Type JCK TRACTOR (SEMI I Occs rance? S t Harmful Event: Collision ERTURN/ROLLOVER fic Way RKING LOT OR PRIVA ace Type T tk Bus or HazMat	Train/Bus # Injured Direction Of Travel NOT ON ROADWAY With TE PROPERTY	A CLASS	tions Issued CrashTire Mark action FIAL FUNCT rol ROL ature	ΓΙΟΝ	Total Tra 1 Speed Li	TRUCK Operating A F - FARM illers mit Emergency NOT APP Traffic Cont NO Road Grade	SERVICE CDL Total HazMat Types 0 Total Lanes 1 Motor Vehicle Use LICABLE rol Inoperative/Missing	
	Vehi TRL Tota 0 Insur YES Most OVE Traff PAR Surfa DIR Truc TRL	GALLY PARKED icle Type JCK TRACTOR (SEMI I Occs rance? S t Harmful Event: Collision ERTURN/ROLLOVER fic Way RKING LOT OR PRIVA ace Type T k Bus or HazMat JCK OR TRUCK COM Vehicle	Train/Bus # Injured Direction Of Travel NOT ON ROADWAY With TE PROPERTY	A CLASS	tions Issued CrashTire Mark Intion IAL FUNCT rol ROL ature	rion	Total Tra 1 Speed Li N/A	TRUCK Operating A F - FARM illers mit Emergency NOT APP Traffic Cont NO Road Grade UNKNOW	SERVICE CDL Total HazMat Types 0 Total Lanes 1 Motor Vehicle Use LICABLE rol Inoperative/Missing N Suance	
-	Vehi TRL Tota 0 Insur YES Most OVE Traff PAR Surfa DIR Truc TRL	GALLY PARKED icle Type JCK TRACTOR (SEMI I Occs rance? 5 t Harmful Event: Collision ERTURN/ROLLOVER fic Way RKING LOT OR PRIVA ace Type T k Bus or HazMat JCK OR TRUCK COM Vehicle License Plate Number	Train/Bus # Injured Direction Of Travel NOT ON ROADWAY With TE PROPERTY BINATION > 10,000LBS G	A CLASS	tions Issued CrashTire Mark Intion IAL FUNCT rol ROL ature	FION	Total Tra 1 Speed Li N/A	TRUCK Operating A F - FARM illers mit Emergency NOT APP Traffic Cont NO Road Grade UNKNOW	SERVICE CDL Total HazMat Types 0 Total Lanes 1 Motor Vehicle Use LICABLE rol Inoperative/Missing N suance FATES	
	Vehi TRL Tota 0 Insuu YES OVE Traff PAR Surfa DIR Truc TRL	GALLY PARKED ICIE Type JCK TRACTOR (SEMI I Occs rance? S t Harmful Event: Collision ERTURN/ROLLOVER fic Way KING LOT OR PRIVA ace Type T Ik Bus or HazMat JCK OR TRUCK COM Vehicle License Plate Number TS45325 Vehicle Identification Nu 1FUPDWEB7XDB12 Color	Train/Bus # Injured Direction Of Travel NOT ON ROADWAY With TE PROPERTY BINATION > 10,000LBS G	A CLASS	tions Issued CrashTire Mark Interion IAL FUNCT rol ROL Ature N ACTOR CLINER COF	FION	Total Tra 1 Speed Li N/A St WI Year	TRUCK Operating A F - FARM illers mit Emergency NOT APP Traffic Cont NO Road Grade UNKNOW Country of Is UNITED S Model CONVENT Bus Use	SERVICE CDL Total HazMat Types 0 Total Lanes 1 Motor Vehicle Use LICABLE rol Inoperative/Missing N suance TATES ION	
	Vehi TRL Tota 0 Insu YES Most OVE DIR Traff PAR Surfa Truc TRL	GALLY PARKED icle Type JCK TRACTOR (SEMI JCK TRACTOR (SEMI I Occs rance? T t Harmful Event: Collision ERTURN/ROLLOVER fic Way RKING LOT OR PRIVA ace Type T ik Bus or HazMat JCK OR TRUCK COM Vehicle License Plate Number TS45325 Vehicle Identification Nu 1FUPDWEB7XDB12 Color BLK - BLACK	Train/Bus # Injured Direction Of Travel NOT ON ROADWAY With TE PROPERTY BINATION > 10,000LBS G	A CLASS	tions Issued CrashTire Mark Iction IAL FUNCT rol ROL ature /N	FION	Total Tra 1 Speed Li N/A St WI Year	TRUCK         Operating A         F - FARM         illers         mit         Emergency         NOT APP         Traffic Cont         NO         Road Grade         UNKNOW         Country of Is         UNITED S         Model         CONVENT	SERVICE CDL Total HazMat Types 0 Total Lanes 1 Motor Vehicle Use LICABLE rol Inoperative/Missing N suance TATES ION	
	Vehi TRL Tota 0 Insur YES OVE DIR Traff PAR Surfa Truc TRL	GALLY PARKED ICIE Type JCK TRACTOR (SEMI I Occs rance? S t Harmful Event: Collision ERTURN/ROLLOVER fic Way KING LOT OR PRIVA ace Type T Ik Bus or HazMat JCK OR TRUCK COM Vehicle License Plate Number TS45325 Vehicle Identification Nu 1FUPDWEB7XDB12 Color	Train/Bus # Injured Direction Of Travel NOT ON ROADWAY With TE PROPERTY BINATION > 10,000LBS G mber 440	A CLASS Total # Cita 0 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva UNKNOW /WR/GCWR Plate Type TOR - TR Make FREIGHT Body Style TC - TRA Vehicle Da	tions Issued CrashTire Mark Inction IAL FUNCT IN AUTOR IAL ACTOR ILINER COP	FION RP	Total Tra 1 Speed Li N/A St WI Year 1999	TRUCK Operating A F - FARM illers mit Emergency NOT APP Traffic Cont NO Road Grade UNKNOW Country of Is UNITED S Model CONVENT Bus Use NOT A BU	SERVICE CDL Total HazMat Types 0 Total Lanes 1 Motor Vehicle Use LICABLE rol Inoperative/Missing suance FATES ION S	
)	Vehi TRL Tota 0 Insu YES Most OVE DIR Traff PAR Surfa Truc TRL	GALLY PARKED icle Type JCK TRACTOR (SEMI I Occs rance? S t Harmful Event: Collision ERTURN/ROLLOVER fic Way KING LOT OR PRIVA ace Type T k Bus or HazMat JCK OR TRUCK COM Vehicle License Plate Number TS45325 Vehicle Identification Nu 1FUPDWEB7XDB12 Color BLK - BLACK Initial Contact Point	Train/Bus # Injured Direction Of Travel NOT ON ROADWAY With TE PROPERTY BINATION > 10,000LBS G mber 440	A CLASS	tions Issued CrashTire Mark Inction IAL FUNCT IN AUTOR IAL ACTOR ILINER COP	rion RP ORNER, 2	Total Tra 1 Speed Li N/A St WI Year 1999 2RIGH <sup>-</sup>	TRUCK Operating A F - FARM illers mit Emergency NOT APP Traffic Cont NO Road Grade UNKNOW Country of Is UNITED S <sup>T</sup> Model CONVENT Bus Use NOT A BU SIDE FROM	SERVICE CDL Total HazMat Types 0 Total Lanes 1 Motor Vehicle Use LICABLE rol Inoperative/Missing N suance TATES ION	

# 6TL092T5LQ

18-04672

## WISCONSIN MOTOR VEHICLE CRASH REPORT

#### SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

		Towed Due To Damage			Vehicle Removed By OWNER					
		What Driver Was Doing			Vehicle F					
		LEGALLY PARKED								
		Driver Prior Action Other		NOT APPLICABLE						
		Driver Actions								
	щ	NO CONTRIBUTING ACTION								
UNIT	VEHICLE									
Б										
	-									
		Driver Distractions NOT DISTRACTED								
4	-									
01	01									
		Owner Name				er Address 61 WILDCA1				
		APPLIED SEALCOATING AND SNOWPLOWING (414) 852-4883			IRON RIDGE, WI 53035 , US			i de la construcción de la constru		
		Sequence Of Events								
	01	Event OVERTURN/ROLLOVE	vent							
	02	Event								
	03	Event								
		Event								
	04	LVent								
E	I	Policy Holder			-					
UNIT		Insurance Company WEST-BEND-MUTUAL-	INS-CO		U U	Organization/Company APPLIED SEALCOATING AND SNOWPLOWING				
Trailer/Towed										
0			ate Type	Make		State		Country of Issuance		
	_	Unit Type	TL - SEMI	EAST DUMP		WI		UNITED STATES Address		
⊑ I	KAILEK/ TOWED	FULL TRAILER	Α	PPLIED SEALCOA	TING A	ING AND SNOWPLOWING		W3061 WILDCAT RD		
UNIT	<b>TOWED</b>	Vehicle Identification Number (414) 852-4883 1E1D1S281CRB47558						IRON RIDGE, WI 53035 , US		
	-	arrier								
		Source								
	01	Use Vehicle Owner Same as Carrier           Name				VEHICLE-SIDE Address				
0		APPLIED SEALCOATING AND SNOWPLOWING				W3061 WILDCAT RD IRON RIDGE, WI 53035, US				
								, US		
	s	GVWR Vehicle Configuration						Cargo Body Type		
Е	BUS	MORE THAN 26,000 LB TRUCK TRACTOR/SEM			I-TRAILER			OTHER		
UNIT		US DOT #		-			Permitted Load			
	TRUCK	1371639 INTRASTATE CARRIER WI Permit Number Perm				itted Vehicle On Escort		NOT APPLICABLE		
	TR	OS/OW Load			ermitted			By Permit Escort Vehicle Present		

#### 6TL092T5LQ 18-04672

### WISCONSIN MOTOR VEHICLE CRASH REPORT

#### SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Measured Height	Measured Length	Measured Width	Measured Weight