6TL0B655M8

18-05404

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT **BARABOO, WI 53913**

Document Number Override	e Primary Crash	Document #	18-05		Investigating Of DEPUTY W. I		
Crash Date 05/26/2018	Crash Time 03:30 AM		Date A 05/26		Time Arrived 08:37 AM		
Date Notified 05/26/2018	Time Notified 08:03 AM		Total U 02	Jnits	Total Injured 00	Total Kill	ed
On Emergency	Hit and Run	Lane Clo	sure	☐ Work Zone	Trailer or	Towed	Reporting Threshold
Government Property	Active So	chool Zone	Schoo NO	Bus Related	Tags		
✓ Reportable	Crash Type PRIVATE PR	OPERTY/PAR	KING LO	т	Amended		Secondar Crash
escription =							
Unit 67/68	U2 U1			Not		notos By	ormation

6TL0B655M8 18-05404

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

L	_oc	ation 									
Ī		CHRISTMAS MOUNTA	AIN RD			Latitude			Longitud	de	
	527 FT S				43.615949676			-89.862	216268		
	OF CTHH SB IN THE TOWN OF DELLONA IN SAUK COUNTY					X Coordin	ate		Y Coord	linate	
						269048.875 4833199.5			99.5		
						Structure NO STR	Type UCTURE				
(Cra	sh Scene									
		Harmful Event				First Harm	nful Event Lo	ocation			
	PAF	KED MOTOR VEHICL	E			IN PARK	(ING LAN	OR ZONE			
		ner of Collision				Light Cond					
L		REAR TO SIDE				DARK/UNLIT					
	Road DRY	Surface Condition(s)				Roadway	Factor(s)				
ŀ	Envii	onment Factor(s)									
	ЮИ					NONE					
F	Wea	ther Condition(s)				1					
	CLC	DUDY									
	Anim	al Type					o Trafficway	/ Y - PARKIN	G LOT		
F	Cras	h Classification - Location				_	ssification -				
	PRIVATE PROPERTY					PRIVATI	E PROPER	RTY			
	Triba	I Land				Access Co				Special Study	
	Within Interchange Area Junction Location					ction Type					
L	NO		NON-JUNCTION		NOT AN	INTERSE	CTION				
		Summary =		1,,,,,				T			
		Status RANSIT		D CLASS	erating As C	lassification	1	Unit Type	DII E		
-		cle Type		D CLASS				AUTOMOBILE Operating As Endorsements			
- 1		SENGER CAR						oporating /			
f	Total	Occs	Train/Bus # Injured	Total # Cita	tions Issued	ı	Total Trail	ers	Total Haz	:Mat Types	
L	1			0			0		0		
		ance?	Direction Of Travel	Pre CrashTire						nes	
L	YES		NOT ON ROADWAY	Special Fur	Mark	N/A CTION		Emergency Motor Vehicle Use NOT APPLICABLE		iolo I loo	
١ ١		Harmful Event: Collision V			CIAL FUNC						
		c Way		Traffic Cont				Traffic Cont	rol Inopera	tive/Missing	
		D-WAY, NOT DIVIDED		NO CONT				NO			
	Surface Type			Road Curvature STRAIGHT				Road Grade UPHILL			
		.CKTOP (BITUMINOUS Bus or HazMat	P)	STRAIGH				OFFILL			
	NO	C Dus of Flaziviat									
	'	/ehicle									
		License Plate Number		Plate Type		_	St	Country of Is			
		D319432			JTOMOBII	_E	IL Year	UNITED ST	TATES		
	01	Vehicle Identification Num 5TDYK3DC3B514566		Make TOYOTA			Year 2011	Model SIENNA			
	•	Color	<u> </u>	Body Style			2011		SIENNA Bus Use		
		SIL - SILVER (ALUMI	NUM)	MV - MIN				NOT A BUS			
	щ	Initial Contact Point		Vehicle Da							
		5RIGHT REAR COR	NER	5 510117 5545 665115							
5RIGHT REAR CORNER Extent Of Damage MINOR DAMAGE			5RIGHT REAR CORNER								

6TL0B655M8

18-05404

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

		Towed Due To Dama	ge	Vehicle Rem				
		NOT TOWED What Driver Was Doi	200	OPERATO Vehicle Fact				
		BACKING	ng	venicie Fact	ors			
		Driver Prior Action Ot	ther	NOT APPL	ICABLE			
		Driver Actions						
	Щ	NO CONTRIBUTI	NG ACTION, UNSAFE BACKING					
LINO	딜							
5	VEHICL							
	>							
		Driver Distractions						
		UNKNOWN IF DIS	STRACTED					
2	5							
0	0							
		Owner Name		Owner /				
		ADIS MUSIC		1221 N DEARBORN ST APT 209S CHICAGO, IL 60610 , US				
		(773) 350-5998		Спіся	190, 12 00010 , 03			
	•	Sequence Of E	vents					
	5	PARKED MOTOR	VEHICLE					
	~ I	Event						
	02							
	03	Event						
		Event						
	04	Event						
		Policy Holder						
HNO		Insurance Company		Individual				
–		ALLSTATE-INS-C	0	ADIS MU				
	1	Individual						
		Driver		Citations	Issued	Sex		
	بِ	ADIS MUSIC (773) 350-5998		0		MALE		
	INDIVIDUA	(113) 330-3330		Date of Bi	irth	Race WHITE		
	₹	Address		Driver Lie	anaa Numbar	William 2		
5	₫	1221 N DEARBOR	RN ST APT 209S	Driver License Number STATE: ILLINOIS COUNTRY: UNITED STATES				
	Z	CHICAGO, IL 606	10 , US					
		Equipment	On Duty Crash	Safety Eq	uipment			
		Equipment						
		Seat Position		SHOULDER & LAP BELT				
		1FRONT SEAT-LEFT SIDE (DRIVER/MOTORCY Helmet Use		Helmet Compliance				
		Tielinet Ose		Tiennet O	ompilance			
		Eye Protection		Tint Compliance				
2	001	Injury	Injury Severity	Airbag	IDLOVED.			
	0	Ejected	NO APPARENT INJURY	NON DE	EPLOYED Path	Trapped/Extricated		
		NOT EJECTED		-	ECTED/NOT APPLICABL	NOT TRAPPED		
		i		_		1		

6TL0B655M8 18-05404

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT **BARABOO, WI 53913** (608) 356-4895

	Medical Transport		- I			EMS Agency Identifier			EMS Run #		
		NOT TRANSPORTED									
		Hospital			Date of Death	Date of Death			Time of Death		
		Non Motorist	Striking Unit #	Prior Action	Location					To/From School	
		Action									
	_										
	INDIVIDUAL										
LIND	₫										
5	\geq										
	불										
		Action Other									
			Suspected Alcohol U	laa	Suspected Drug U						
	L	Orug & Alcohol	NO	Jse	NO	se					
		Alcohol Test Given			Alcohol Test Type			Alcohol Test	t Posults		
		TEST NOT GIVEN			Alcohol Test Type			AICOHOI 165	i ivesuits		
		Drug Test Given			Drug Test Type			Drug Test R	esults		
		TEST NOT GIVEN			,,						
_	Ξ	Drug Type						1			
6	001										
		Individual Condition									
		Individual Condition									
		APPEARED NORMAL									
		APPEARED NORM	1AL								
			1AL								
		 t Summary ■	IAL								
	Unit	t Summary Status	IAL		Vehicle Operating As (Classification		Unit Type			
	Unit LEG	t Summary Status GALLY PARKED	IAL		Vehicle Operating As 0	Classification		AUTOMO		onto	
02	Unit LEG Vehi	t Summary Status GALLY PARKED ICID Type	IAL			Classification				ents	
	Vehi	t Summary Status GALLY PARKED icle Type SSENGER CAR			D CLASS			AUTOMOR Operating A	s Endorsem		
	Vehi	t Summary Status GALLY PARKED ICID Type	Train/Bus # Inji	ured	Total # Citations Issue		Total Trail	AUTOMOR Operating A			
	Vehi PAS Tota 0	t Summary Status GALLY PARKED icle Type SSENGER CAR		ured -	D CLASS Total # Citations Issue 0	d	Total Trail	AUTOMOI Operating A ers	s Endorsem Total HazN	flat Types	
02	Vehi PAS Tota 0	t Summary Status GALLY PARKED icle Type SSENGER CAR Il Occs	Train/Bus # Inji	ured	Total # Citations Issue	d	Total Trail	AUTOMOI Operating A ers	s Endorsem Total HazN 0	flat Types	
02	Vehi PAS Tota O Insu YES	t Summary Status GALLY PARKED icle Type SSENGER CAR Il Occs	Train/Bus # Inji Direction Of Tr. NOT ON RO.	ured	Total # Citations Issue O Pre CrashTir Mark Special Function	d e	Total Trail O Speed Lin	AUTOMOR Operating A ers nit	Total HazN Total Lane O Motor Vehic	Mat Types s	
	Vehi PAS Tota 0 Insu YES	t Summary Status GALLY PARKED icle Type SSENGER CAR I Occs rance?	Train/Bus # Inj	ured	Total # Citations Issue O Pre CrashTir Mark	d e	Total Trail O Speed Lin	AUTOMOR Operating A ers	Total HazN Total Lane O Motor Vehic	Mat Types s	
02	Vehi PAS Tota 0 Insu YES MOS Traff	Status GALLY PARKED icicle Type SSENGER CAR II Occs rance? St Harmful Event: Collision TOR VEH IN TRANS fic Way	Train/Bus # Injudice in the In	ured (avel ADWAY)	Total # Citations Issue Pre CrashTir Mark Special Function NO SPECIAL FUNCTION	d e	Total Trail O Speed Lin	AUTOMOI Operating A ers nit Emergency NOT APPI Traffic Contr	s Endorsem Total HazM 0 Total Lane 0 Motor Vehic	Mat Types s	
02	Unit LEG Vehi PAS Tota 0 Insur YES MOS Traff	Status GALLY PARKED icice Type SSENGER CAR II Occs rance? S It Harmful Event: Collision TOR VEH IN TRANS fic Way RKING LOT OR PRIN	Train/Bus # Injudice in the In	avel ADWAY	Total # Citations Issue Pre CrashTir Mark Special Function NO SPECIAL FUNCT Traffic Control NO CONTROL	d e	Total Trail O Speed Lin	AUTOMOR Operating A ers nit Emergency NOT APPR Traffic Contr	Total HazM 0 Total Lane 0 Motor Vehic LICABLE rol Inoperation	Mat Types s	
02	Unit LEG Vehi PAS Tota 0 Insur YES Most MO Traff PAR Surfa	Status GALLY PARKED ICICE Type SSENGER CAR II Occs Tance? Status It Harmful Event: Collision TOR VEH IN TRANS Ific Way RKING LOT OR PRIMACE Type	Train/Bus # Injudice Direction Of Train/On RO. On With SPORT	avel ADWAY	Total # Citations Issue Pre CrashTir Mark Special Function NO SPECIAL FUNCT Traffic Control NO CONTROL Road Curvature	d e	Total Trail O Speed Lin	AUTOMOR Operating A eers nit Emergency NOT APPI Traffic Contr NO Road Grade	Total HazM 0 Total Lane 0 Motor Vehic LICABLE rol Inoperation	Mat Types s	
02	Vehi PAS Tota 0 Insul YES MOS Traff PAR Surfa	t Summary Status SALLY PARKED Icle Type SSENGER CAR I Occs TOR VEH IN TRANS IIC Way RKING LOT OR PRIVACE ACKTOP (BITUMING	Train/Bus # Injudice Direction Of Train/On RO. On With SPORT	avel ADWAY	Total # Citations Issue Pre CrashTir Mark Special Function NO SPECIAL FUNCT Traffic Control NO CONTROL	d e	Total Trail O Speed Lin	AUTOMOR Operating A ers nit Emergency NOT APPR Traffic Contr	Total HazM 0 Total Lane 0 Motor Vehic LICABLE rol Inoperation	Mat Types s	
02	Unit LECO Vehi PAS Tota 0 Insur YES MOS Traff PAR Surfa BLA Truc	t Summary Status SALLY PARKED icle Type SSENGER CAR I Occs rance? S It Harmful Event: Collision TOR VEH IN TRANS fic Way RKING LOT OR PRIVA ace Type ACKTOP (BITUMING ik Bus or HazMat	Train/Bus # Injudice Direction Of Train/On RO. On With SPORT	avel ADWAY	Total # Citations Issue Pre CrashTir Mark Special Function NO SPECIAL FUNCT Traffic Control NO CONTROL Road Curvature	d e	Total Trail O Speed Lin	AUTOMOR Operating A eers nit Emergency NOT APPI Traffic Contr NO Road Grade	Total HazM 0 Total Lane 0 Motor Vehic LICABLE rol Inoperation	Mat Types s	
02	Unit LEC Vehi PAS Tota 0 Insul YES Most MO Traff PAR Surfa BLA Truc NO	Status SALLY PARKED icle Type SSENGER CAR Il Occs rance? Status Harmful Event: Collision TOR VEH IN TRANS fic Way RKING LOT OR PRIV ace Type ACKTOP (BITUMING	Train/Bus # Injudice Direction Of Train/On RO. On With SPORT	avel ADWAY	Total # Citations Issue Pre CrashTir Mark Special Function NO SPECIAL FUNCT Traffic Control NO CONTROL Road Curvature	d e	Total Trail O Speed Lin	AUTOMOR Operating A eers nit Emergency NOT APPI Traffic Contr NO Road Grade	Total HazM 0 Total Lane 0 Motor Vehic LICABLE rol Inoperation	Mat Types s	
02	Unit LEC Vehi PAS Tota 0 Insul YES MOSI MO Traff PAR Surfa BLA Truc NO	Status GALLY PARKED icice Type SSENGER CAR II Occs rance? S It Harmful Event: Collision TOR VEH IN TRANS fic Way RKING LOT OR PRIV ace Type ACKTOP (BITUMING ik Bus or HazMat	Train/Bus # Inju Direction Of Tr NOT ON RO On With SPORT /ATE PROPERTY DUS)	avel ADWAY	Total # Citations Issue O Pre CrashTir Mark Special Function NO SPECIAL FUNCT Traffic Control NO CONTROL Road Curvature STRAIGHT	d e	Total Trail O Speed Lin N/A	AUTOMOLI Operating A ers nit Emergency NOT APPI Traffic Conti NO Road Grade LEVEL	Total HazM 0 Total Lane 0 Motor Vehic LICABLE rol Inoperation	Mat Types s	
02	Unit LEC Vehi PAS Tota 0 Insul YES MOSI MO Traff PAR Surfa BLA Truc NO	Status GALLY PARKED Icice Type SSENGER CAR II Occs Trance? Status TOR VEH IN TRANS Ific Way RKING LOT OR PRIVACE ACKTOP (BITUMING Ik Bus or HazMat Vehicle License Plate Number	Train/Bus # Inju Direction Of Tr NOT ON RO On With SPORT /ATE PROPERTY DUS)	avel ADWAY	Total # Citations Issue Total # Citations Issue Pre CrashTir Mark Special Function NO SPECIAL FUNCTION Traffic Control NO CONTROL Road Curvature STRAIGHT	e CTION	Total Trail O Speed Lin N/A	AUTOMOI Operating A ers nit Emergency NOT APPI Traffic Conti NO Road Grade LEVEL Country of Is:	Total HazM Total Lane Motor Vehic LICABLE rol Inoperation	Mat Types s	
UNIT 02	Unit LEG Vehi PAS Tota 0 Insury PAS MOO Traff PAR Suffa BLA Truc	Status GALLY PARKED Icle Type SSENGER CAR I Occs TOR VEH IN TRANS II Way RKING LOT OR PRIVA ACKTOP (BITUMING ICK Bus or HazMat Vehicle License Plate Number 104APL	Train/Bus # Injuiction Of Train/Bus # Injuiction Of Train/Bus # Injuiction Of Train NOT ON ROOM With SPORT /ATE PROPERTY	avel ADWAY	Total # Citations Issue O Pre CrashTir Mark Special Function NO SPECIAL FUNCT Traffic Control NO CONTROL Road Curvature STRAIGHT	e CTION	Total Trail 0 Speed Lin N/A St	AUTOMORI Operating A ers nit Emergency NOT APPI Traffic Contr NO Road Grade LEVEL Country of Is: UNITED ST	Total HazM Total Lane Motor Vehic LICABLE rol Inoperation	Mat Types s	
02	Unit LEC Vehi PAS Tota 0 Insul YES MOSI MO Traff PAR Surfa BLA Truc NO	Status GALLY PARKED Icice Type SSENGER CAR II Occs Trance? Status TOR VEH IN TRANS Ific Way RKING LOT OR PRIVACE ACKTOP (BITUMING Ik Bus or HazMat Vehicle License Plate Number	Train/Bus # Inju Direction Of Tr NOT ON RO ON With SPORT /ATE PROPERTY DUS)	avel ADWAY	Total # Citations Issue O Pre CrashTir Mark Special Function NO SPECIAL FUNCT Traffic Control NO CONTROL Road Curvature STRAIGHT Plate Type AUT - AUTOMOBI	e CTION	Total Trail O Speed Lin N/A	AUTOMOI Operating A ers nit Emergency NOT APPI Traffic Conti NO Road Grade LEVEL Country of Is:	Total HazM Total Lane Motor Vehic LICABLE rol Inoperation	Mat Types s	
UNIT 02	Unit LEG Vehi PAS Tota 0 Insury PAS MOO Traff PAR Suffa BLA Truc	Status GALLY PARKED ICIC Type SSENGER CAR I OCCS TOR VEH IN TRANS IIIC WAY RKING LOT OR PRIVATE ACKTOP (BITUMING ICK BUS OF HAZMAT Vehicle License Plate Number 104APL Vehicle Identification N	Train/Bus # Inju Direction Of Tr NOT ON RO ON With SPORT /ATE PROPERTY DUS)	avel ADWAY	Total # Citations Issue Total # Citations Issue Pre CrashTir Mark Special Function NO SPECIAL FUNCTIVE Traffic Control NO CONTROL Road Curvature STRAIGHT Plate Type AUT - AUTOMOBIL Make	e CTION	Total Trail 0 Speed Lin N/A St WI Year	AUTOMOI Operating A ers iit Emergency NOT APPI Traffic Conti NO Road Grade LEVEL Country of Is: UNITED ST Model HHR Bus Use	Total HazM Total Lane Total Lane Motor Vehic LICABLE rol Inoperation suance TATES	Mat Types s	
UNIT 02	Unit LEG Vehi PAS Tota 0 Insury PAS MOO Traff PAR Suffa BLA Truc	t Summary Status SALLY PARKED Icle Type SSENGER CAR I Occs TOR VEH IN TRANS Icle Type RKING LOT OR PRIVACE ICLE Type ACKTOP (BITUMING Ick Bus or HazMat Vehicle License Plate Number 104APL Vehicle Identification Icl	Train/Bus # Inji Direction Of Tr. NOT ON RO. On With SPORT /ATE PROPERTY DUS)	avel ADWAY	Total # Citations Issue O Pre CrashTir Mark Special Function NO SPECIAL FUNC Traffic Control NO CONTROL Road Curvature STRAIGHT Plate Type AUT - AUTOMOBI Make CHEVROLET	d e CTION	Total Trail 0 Speed Lin N/A St WI Year	AUTOMOR Operating A Bers Init Emergency NOT APPI Traffic Contr NO Road Grade LEVEL Country of Is: UNITED ST Model HHR	Total HazM Total Lane Total Lane Motor Vehic LICABLE rol Inoperation suance TATES	Mat Types s	
02 UNIT 02	Unit LEG Vehi PAS Tota 0 Insur YES MOS Traff PAF Surfa BLA Truc NO	t Summary Status SALLY PARKED Icle Type SSENGER CAR I Occs Tance? It Harmful Event: Collision TOR VEH IN TRANS Iclic Way RKING LOT OR PRIVATE ACKTOP (BITUMING Ick Bus or HazMat Vehicle License Plate Number 104APL Vehicle Identification It 3GNCA53V49S638 Color SIL - SILVER (ALU Initial Contact Point	Train/Bus # Inji Direction Of Tr. NOT ON RO. On With SPORT /ATE PROPERTY DUS)	avel ADWAY	Total # Citations Issue O Pre CrashTir Mark Special Function NO SPECIAL FUNCT Traffic Control NO CONTROL Road Curvature STRAIGHT Plate Type AUT - AUTOMOBI Make CHEVROLET Body Style	d e CTION	Total Trail 0 Speed Lin N/A St WI Year	AUTOMOI Operating A ers iit Emergency NOT APPI Traffic Conti NO Road Grade LEVEL Country of Is: UNITED ST Model HHR Bus Use	Total HazM Total Lane Total Lane Motor Vehic LICABLE rol Inoperation suance TATES	Mat Types s	
02 UNIT 02	Unit LEG Vehi PAS Tota 0 Insur YES MOS Traff PAF Surfa BLA Truc NO	t Summary Status GALLY PARKED Icle Type SSENGER CAR I Occs Tance? It Harmful Event: Collision TOR VEH IN TRANS Icle Way RKING LOT OR PRIVA ICLE License Plate Number 104APL Vehicle Identification In 3GNCA53V49S638 Color SIL - SILVER (ALL Initial Contact Point 7LEFT REAR CO	Train/Bus # Inji Direction Of Tr. NOT ON RO. On With SPORT /ATE PROPERTY DUS)	avel ADWAY	Total # Citations Issue Total # Citations Issue Pre CrashTir Mark Special Function NO SPECIAL FUNC Traffic Control NO CONTROL Road Curvature STRAIGHT Plate Type AUT - AUTOMOBI Make CHEVROLET Body Style 4H - HATCHBACK Vehicle Damage	d e CTION	Total Trail 0 Speed Lin N/A St WI Year 2009	AUTOMOS Operating A Ders Der	Total HazM 0 Total Lane 0 Motor Vehic LICABLE rol Inoperation	Mat Types s ile Use ve/Missing	
UNIT 02	Unit LEG Vehi PAS Tota 0 Insur YES MOO Traff PAR Surfa BLA Truc NO	t Summary Status SALLY PARKED Icle Type SSENGER CAR I Occs Tance? It Harmful Event: Collision TOR VEH IN TRANS Iclic Way RKING LOT OR PRIVATE ACKTOP (BITUMING Ick Bus or HazMat Vehicle License Plate Number 104APL Vehicle Identification It 3GNCA53V49S638 Color SIL - SILVER (ALU Initial Contact Point	Train/Bus # Inji Direction Of Tr. NOT ON RO. On With SPORT /ATE PROPERTY DUS)	avel ADWAY	Total # Citations Issue Total # Citations Issue Pre CrashTir Mark Special Function NO SPECIAL FUNCTION Traffic Control NO CONTROL Road Curvature STRAIGHT Plate Type AUT - AUTOMOBI Make CHEVROLET Body Style 4H - HATCHBACK	d e CTION	Total Trail 0 Speed Lin N/A St WI Year 2009	AUTOMOS Operating A Ders Der	Total HazM 0 Total Lane 0 Motor Vehic LICABLE rol Inoperation	Mat Types s ile Use ve/Missing	

6TL0B655M8

18-05404

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 05/26/2018

Crash Time 03:30 AM

		Towed Due To Damage	ehicle Removed By
		NOT TOWED C	PERATOR
		What Driver Was Doing	ehicle Factors
		LEGALLY PARKED	
		Driver Prior Action Other	IOT APPLICABLE
		Driver Actions NO CONTRIBUTING ACTION	
_	۳	ING CONTRIBOTING ACTION	
UNIT	을		
n	VEHICLE		
	>		
		Driver Distractions	
02	02		
0	0		
		Owner Name WAYNE B HOFFMAN JR	Owner Address 1025 HATHAWAY ST
		(608) 732-7393	PLATTEVILLE, WI 53818 , US
	9	Sequence Of Events	
		Event	
	5	MOTOR VEH IN TRANSPORT	
	02	Event	
	0		
	03	Event	
	0		
	9	Event	
		Dalias Haldan	
UNIT		Policy Holder	
5		Insurance Company STATE-FARM-GENERAL-INS-CO	Individual WAYNE HOFFMAN
		STATE-FARIVI-GENERAL-INS-CO	WATNE HOFFINAN