6TL0B4X4HS

18-06366

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT **BARABOO, WI 53913** (608) 356-4895

Document Number Override	Primary Crash Document #		0 ,	0 0	Investigating Officer/Deputy DEPUTY E. KNULL		
Crash Date 06/17/2018	Crash Time 01:01 PM			Time Arrived 01:10 PM			
Date Notified 06/17/2018	Time Notified 01:01 PM		- 10 1	Total Injured 00	· · · · · · · · · · · · · · · · · · ·		
On Emergency Hi	and Run Lane Closu		☐ Work Zone	Trailer or 1	Towed Reporting Threshold		
Government Property	Active School Z	ol Zone School Bus Related NO		Tags			
✓ Reportable	Crash Type DT4000 (STANDARD C			Amended	Secondary Crash		
	Crash Date 06/17/2018 Date Notified 06/17/2018 On Emergency Hi Government Property	Crash Date 06/17/2018 Date Notified 06/17/2018 On Emergency Government Property Reportable Crash Time 01:01 PM Time Notified 01:01 PM Active School Z	Crash Date	18-06366	Crash Date 06/17/2018 Crash Time 01:01 PM Date Arrived 06/17/2018 Time Arrived 01:10 PM Date Notified 06/17/2018 Time Notified 01:01 PM Total Units 01 Total Injured 00 On Emergency Hit and Run Lane Closure Work Zone Trailer or Tags Government Property Active School Zone NO School Bus Related NO Tags ✓ Reportable Crash Type DT4000 (STANDARD CRASH) Amended		

Description



✓ I, a sworn law enforcement officer, agree that I have not added any CJIS data in this report.

OPERATOR WAS TRAVELING WB ON CHURCHILL RD AND THE RIGHT SIDE TIRES WENT OFF THE ROAD. OPERATOR OVER CORRECTED AND CAME ACROSS THE ROAD ENTERING THE DITCH AND OVERTURNING. DURING THE ROLLOVER SHE STRUCK 2 FENCE POSTS. OWNER OF FENCE WAS NOTIFIED. NO INJURIES REPORTED. VEHICLE SUSTAINED DISABLING DAMAGE AND WAS REMOVED BY INTERSTATE BP.

6TL0B4X4HS 18-06366

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT **BARABOO, WI 53913** (608) 356-4895

Crash Time 01:01 PM

Lo	oc	ation								
0	N	CHURCHILL RD			Latitude			Longitude		
0	0.76 MI E					02954		-90.028111752		
_		CTHV WB			X Coordin	ato		Y Coordinate		
		HE TOWN OF WINFIEL	_D		255498.			4829304.5		
IN	N S	SAUK COUNTY						102000 110		
					Structure Type NO STRUCTURE					
Ļ					INO OTK	OOTOIL	-			
		sh Scene								
F	irst	Harmful Event			First Harn	nful Event	Location			
D)TI	CH			ROADS	IDE				
M	1anr	ner of Collision			Light Con	dition				
N	10	COLLISION W/VEHICL	E IN TRANSPORT		DAYLIG	HT				
R	loac	d Surface Condition(s)			Roadway	Factor(s)				
D	RY	(
F	n di	ronment Factor(s)								
		, ,								
N	101	NE			NONE					
W	Vea	ther Condition(s)								
		AR								
-										
Α	nim	nal Type				To Trafficw	•			
					TRAFFICWAY - NO					
		h Classification - Location				Crash Classification - Jurisdiction				
	-	BLIC PROPERTY					RISDICTION			
T	riba	al Land			Access C			Special Study		
					NO CONTROL					
		· ·	Junction Location		ection Type	**				
N	Ю		NON-JUNCTION	AN INTERSE	INTERSECTION					
U	nit	t Summary								
		t Summary Status		Vehicle Operating A			Unit Type			
U	Init			Vehicle Operating A			Unit Type AUTOMOI	BILE		
U II	Init :	Status					AUTOMOI	BILE s Endorsements		
U IN V	Init N T 'ehic	Status RANSIT	E				AUTOMOI			
∪ /II ∨ (\$	Init N T 'ehid SP(Status 'RANSIT cle Type	E Train/Bus # Injured		s Classification		AUTOMOI Operating A			
∪ /II ∨ (\$	Init N T 'ehic SP(otal	Status RANSIT cle Type ORT) UTILITY VEHICLE		D CLASS	s Classification	1	AUTOMOI Operating A	s Endorsements		
∪ N 	Init N T Gehic SPC otal	Status RANSIT cle Type ORT) UTILITY VEHICLE		D CLASS Total # Citations Iss 0	s Classification	Total Tra	Operating A	s Endorsements Total HazMat Types		
U	Init N T Gehic SPC otal	Status RANSIT cle Type ORT) UTILITY VEHICLE I Occs	Train/Bus # Injured	D CLASS Total # Citations Iss	s Classification	Total Tra	Operating A	s Endorsements Total HazMat Types 0		
U	nit Yehid SPO otal	Status RANSIT cle Type ORT) UTILITY VEHICLE I Occs	Train/Bus # Injured Direction Of Travel WESTBOUND	Total # Citations Iss 0 Pre Crash Mark Special Function	ued	Total Tra 0 Speed L	AUTOMOI Operating A sillers imit Emergency	Total HazMat Types O Total Lanes 2 Motor Vehicle Use		
U	Init in Init Init	Status RANSIT cle Type ORT) UTILITY VEHICLE I Occs rance?	Train/Bus # Injured Direction Of Travel WESTBOUND	Total # Citations Iss 0 Pre Crash Mark	ued	Total Tra 0 Speed L	AUTOMOI Operating A ailers	Total HazMat Types O Total Lanes 2 Motor Vehicle Use		
U	Init SP(Cotal	Status RANSIT cle Type ORT) UTILITY VEHICLE I Occs rance? 6 t Harmful Event: Collision W	Train/Bus # Injured Direction Of Travel WESTBOUND	Total # Citations Iss 0 Pre Crash Mark Special Function	ued	Total Tra 0 Speed L	AUTOMOI Operating A sillers imit Emergency NOT APPI	Total HazMat Types O Total Lanes 2 Motor Vehicle Use		
U	Init : N T 'ehid SP(otal	Status RANSIT cle Type ORT) UTILITY VEHICLE I Occs rance? It Harmful Event: Collision WERTURN/ROLLOVER	Train/Bus # Injured Direction Of Travel WESTBOUND	Total # Citations Iss O Pre Crash Mark Special Function NO SPECIAL FU	ued	Total Tra 0 Speed L	AUTOMOI Operating A sillers imit Emergency NOT APPI	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE		
U IN V (S) To 1 In Y M O To T'	Init: N T Yehid SPC Total TOTA	Status RANSIT cle Type ORT) UTILITY VEHICLE I Occs rance? It Harmful Event: Collision WERTURN/ROLLOVER ic Way	Train/Bus # Injured Direction Of Travel WESTBOUND	Total # Citations Iss O Pre Crash Mark Special Function NO SPECIAL FU Traffic Control	ued	Total Tra 0 Speed L	AUTOMOI Operating A sillers imit Emergency NOT APPI Traffic Contri	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE ol Inoperative/Missing		
	SP(fotal fo	Status RANSIT cle Type ORT) UTILITY VEHICLE I Occs rance? It Harmful Event: Collision WERTURN/ROLLOVER ic Way D-WAY, NOT DIVIDED	Train/Bus # Injured Direction Of Travel WESTBOUND //ith	Total # Citations Iss 0 Pre Crash Mark Special Function NO SPECIAL FU Traffic Control NO CONTROL	ued	Total Tra 0 Speed L	AUTOMOI Operating A sillers imit Emergency NOT APPI Traffic Contr	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE ol Inoperative/Missing		
U	Property of the control of the contr	Status RANSIT cle Type ORT) UTILITY VEHICLE I Occs rance? I Harmful Event: Collision W ERTURN/ROLLOVER ic Way D-WAY, NOT DIVIDED ace Type	Train/Bus # Injured Direction Of Travel WESTBOUND //ith	D CLASS Total # Citations Iss 0 Pre Crash Mark Special Function NO SPECIAL FU Traffic Control NO CONTROL Road Curvature	ued	Total Tra 0 Speed L	AUTOMOI Operating A sillers imit Emergency NOT APPI Traffic Contr NO Road Grade	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE ol Inoperative/Missing		
U	Property of the control of the contr	Status TRANSIT Cle Type ORT) UTILITY VEHICLE TOCCS Trance? St Harmful Event: Collision WERTURN/ROLLOVER TIC Way D-WAY, NOT DIVIDED TAKEN TYPE ACKTOP (BITUMINOUS	Train/Bus # Injured Direction Of Travel WESTBOUND //ith	D CLASS Total # Citations Iss 0 Pre Crash Mark Special Function NO SPECIAL FU Traffic Control NO CONTROL Road Curvature	ued	Total Tra 0 Speed L	AUTOMOI Operating A sillers imit Emergency NOT APPI Traffic Contr NO Road Grade	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE ol Inoperative/Missing		
U	Init: N T Yehid SP(Total Tota	Status TRANSIT Cle Type ORT) UTILITY VEHICLE I Occs rance? St Harmful Event: Collision WERTURN/ROLLOVER Tic Way D-WAY, NOT DIVIDED ACKTOP (BITUMINOUS k Bus or HazMat	Train/Bus # Injured Direction Of Travel WESTBOUND //ith	D CLASS Total # Citations Iss 0 Pre Crash Mark Special Function NO SPECIAL FU Traffic Control NO CONTROL Road Curvature	ued	Total Tra 0 Speed L	AUTOMOI Operating A sillers imit Emergency NOT APPI Traffic Contr NO Road Grade	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE ol Inoperative/Missing		
U	Init: N T Yehid SP(Total Tota	Status RANSIT cle Type ORT) UTILITY VEHICLE I Occs rance? St Harmful Event: Collision WERTURN/ROLLOVER ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS k Bus or HazMat	Train/Bus # Injured Direction Of Travel WESTBOUND //ith	D CLASS Total # Citations Iss 0 Pre Crash Mark Special Function NO SPECIAL FU Traffic Control NO CONTROL Road Curvature STRAIGHT	ued	Total Tra 0 Speed L	AUTOMOI Operating A silers imit Emergency NOT APPI Traffic Contr NO Road Grade LEVEL	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE Total Inoperative/Missing		
U	Init: N T Yehid SP(Total Tota	Status RANSIT cle Type ORT) UTILITY VEHICLE I Occs rance? St Harmful Event: Collision WERTURN/ROLLOVER ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS k Bus or HazMat Vehicle License Plate Number	Train/Bus # Injured Direction Of Travel WESTBOUND //ith	D CLASS Total # Citations Iss 0 Pre Crash Mark Special Function NO SPECIAL FU Traffic Control NO CONTROL Road Curvature	ued Fire	Total Tra 0 Speed L 45	AUTOMOI Operating A sillers imit Emergency NOT APPI Traffic Contr NO Road Grade LEVEL Country of Is:	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE Total Inoperative/Missing		
U	Init: N T Yehid SP(Total Tota	Status RANSIT cle Type ORT) UTILITY VEHICLE I Occs rance? St Harmful Event: Collision WERTURN/ROLLOVER fic Way D-WAY, NOT DIVIDED face Type ACKTOP (BITUMINOUS Ik Bus or HazMat Vehicle License Plate Number JV3780	Train/Bus # Injured Direction Of Travel WESTBOUND Jith	Total # Citations Iss 0 Pre Crash Mark Special Function NO SPECIAL FU Traffic Control NO CONTROL Road Curvature STRAIGHT Plate Type LTK - LIGHT TR	ued Fire	Total Tra 0 Speed L 45	AUTOMOI Operating A sillers imit Emergency NOT APPI Traffic Conti NO Road Grade LEVEL Country of Is: UNITED ST	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE Total Inoperative/Missing		
U N V (\$\frac{1}{3} \text{Tr} \text{Tr} \text{Tr} \text{Tr} \text{Tr} S B Tr N N Tr S B Tr N Tr S S S Tr N Tr S S S Tr N S S S Tr N S S S S S S S S S	Init: N T Yehid SP(Total Tota	Status RANSIT cle Type ORT) UTILITY VEHICLE I Occs rance? St Harmful Event: Collision WERTURN/ROLLOVER ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS k Bus or HazMat Vehicle License Plate Number	Train/Bus # Injured Direction Of Travel WESTBOUND Jith	D CLASS Total # Citations Iss 0 Pre Crash Mark Special Function NO SPECIAL FU Traffic Control NO CONTROL Road Curvature STRAIGHT	ued Fire	Total Tra 0 Speed L 45	AUTOMOI Operating A sillers imit Emergency NOT APPI Traffic Contr NO Road Grade LEVEL Country of Is:	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE Total Inoperative/Missing		
UIN V (S) TO 1 In Y M O T T S B T N	Init : N T Tehio SP(Total Tehio Tehio SP(Total Tehio	Status RANSIT cle Type ORT) UTILITY VEHICLE I Occs rance? St Harmful Event: Collision WERTURN/ROLLOVER ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS Ik Bus or HazMat Vehicle License Plate Number JV3780 Vehicle Identification Num 1FMEU15H7TLA52566	Train/Bus # Injured Direction Of Travel WESTBOUND Jith	Total # Citations Iss 0 Pre Crash Mark Special Function NO SPECIAL FU Traffic Control NO CONTROL Road Curvature STRAIGHT Plate Type LTK - LIGHT TR Make FORD	ued Fire	Total Tra 0 Speed L 45 St WI Year	AUTOMOI Operating A sillers imit Emergency NOT APPI Traffic Contr NO Road Grade LEVEL Country of Is: UNITED ST Model BRONCO	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE Tol Inoperative/Missing		
UIN V (S) Tr 1 In Y M CO Tr T' S B Tr N	Init : N T Tehio SP(Total Tehio Tehio SP(Total Tehio	Status RANSIT cle Type ORT) UTILITY VEHICLE I Occs rance? I Harmful Event: Collision WERTURN/ROLLOVER ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS k Bus or HazMat Vehicle License Plate Number JV3780 Vehicle Identification Num 1FMEU15H7TLA52562	Train/Bus # Injured Direction Of Travel WESTBOUND Jith	Total # Citations Iss 0 Pre Crash Mark Special Function NO SPECIAL FU Traffic Control NO CONTROL Road Curvature STRAIGHT Plate Type LTK - LIGHT TR Make FORD Body Style	ued Fire INCTION	Total Tra 0 Speed L 45 St WI Year 1996	AUTOMOI Operating A sailers Emergency NOT APPI Traffic Conti NO Road Grade LEVEL Country of Is: UNITED ST	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE ol Inoperative/Missing		
U IN V (S) TO 1 IN Y M O TO TO S B TO N	Init in Init Init	Status RANSIT cle Type ORT) UTILITY VEHICLE I Occs rance? St Harmful Event: Collision WERTURN/ROLLOVER ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS Ik Bus or HazMat Vehicle License Plate Number JV3780 Vehicle Identification Num 1FMEU15H7TLA52562 Color WHI - WHITE	Train/Bus # Injured Direction Of Travel WESTBOUND Jith	Total # Citations Iss 0 Pre Crash Mark Special Function NO SPECIAL FU Traffic Control NO CONTROL Road Curvature STRAIGHT Plate Type LTK - LIGHT TR Make FORD Body Style UT - SPORT UT	ued Fire INCTION	Total Tra 0 Speed L 45 St WI Year 1996	AUTOMOI Operating A sillers imit Emergency NOT APPI Traffic Conti NO Road Grade LEVEL Country of Is: UNITED ST Model BRONCO Bus Use	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE ol Inoperative/Missing		
U IN V (S) THE IN N	Init in Init Init	Status RANSIT cle Type ORT) UTILITY VEHICLE I Occs rance? St Harmful Event: Collision WERTURN/ROLLOVER ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS Ik Bus or HazMat Vehicle License Plate Number JV3780 Vehicle Identification Num 1FMEU15H7TLA52562 Color WHI - WHITE Initial Contact Point	Train/Bus # Injured Direction Of Travel WESTBOUND Jith	Total # Citations Iss 0 Pre Crash Mark Special Function NO SPECIAL FU Traffic Control NO CONTROL Road Curvature STRAIGHT Plate Type LTK - LIGHT TR Make FORD Body Style	ued Fire INCTION	Total Tra 0 Speed L 45 St WI Year 1996	AUTOMOI Operating A sillers imit Emergency NOT APPI Traffic Conti NO Road Grade LEVEL Country of Is: UNITED ST Model BRONCO Bus Use	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE ol Inoperative/Missing		
U IN V (S) THE IN N	Init in Init Init	Status RANSIT cle Type ORT) UTILITY VEHICLE I Occs rance? St Harmful Event: Collision WERTURN/ROLLOVER ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS Ik Bus or HazMat Vehicle License Plate Number JV3780 Vehicle Identification Num 1FMEU15H7TLA52562 Color WHI - WHITE Initial Contact Point 11LEFT FRONT COF	Train/Bus # Injured Direction Of Travel WESTBOUND Jith	D CLASS Total # Citations Iss 0 Pre Crash Mark Special Function NO SPECIAL FU Traffic Control NO CONTROL Road Curvature STRAIGHT Plate Type LTK - LIGHT TR Make FORD Body Style UT - SPORT UT Vehicle Damage	ued Fire INCTION	Total Tra 0 Speed L 45 St WI Year 1996	AUTOMOI Operating A sillers imit Emergency NOT APPI Traffic Conti NO Road Grade LEVEL Country of Is: UNITED ST Model BRONCO Bus Use	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE ol Inoperative/Missing		
U IN V (S) THE IN N	Init in Init Init	Status RANSIT cle Type ORT) UTILITY VEHICLE I Occs rance? St Harmful Event: Collision WERTURN/ROLLOVER ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS Ik Bus or HazMat Vehicle License Plate Number JV3780 Vehicle Identification Num 1FMEU15H7TLA52562 Color WHI - WHITE Initial Contact Point 11LEFT FRONT COF Extent Of Damage	Train/Bus # Injured Direction Of Travel WESTBOUND //tth	Total # Citations Iss 0 Pre Crash Mark Special Function NO SPECIAL FU Traffic Control NO CONTROL Road Curvature STRAIGHT Plate Type LTK - LIGHT TR Make FORD Body Style UT - SPORT UT	ued Fire INCTION	Total Tra 0 Speed L 45 St WI Year 1996	AUTOMOI Operating A sillers imit Emergency NOT APPI Traffic Conti NO Road Grade LEVEL Country of Is: UNITED ST Model BRONCO Bus Use	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE ol Inoperative/Missing		
UIN V (S To 1 Inn Y M C C T T S B T N	Init in Init Init	Status RANSIT cle Type ORT) UTILITY VEHICLE I Occs rance? St Harmful Event: Collision WERTURN/ROLLOVER ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS Ik Bus or HazMat Vehicle License Plate Number JV3780 Vehicle Identification Num 1FMEU15H7TLA52562 Color WHI - WHITE Initial Contact Point 11LEFT FRONT COF	Train/Bus # Injured Direction Of Travel WESTBOUND //tth	D CLASS Total # Citations Iss 0 Pre Crash Mark Special Function NO SPECIAL FU Traffic Control NO CONTROL Road Curvature STRAIGHT Plate Type LTK - LIGHT TR Make FORD Body Style UT - SPORT UT Vehicle Damage	ued Fire INCTION	Total Tra 0 Speed L 45 St WI Year 1996	AUTOMOI Operating A sillers imit Emergency NOT APPI Traffic Conti NO Road Grade LEVEL Country of Is: UNITED ST Model BRONCO Bus Use	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE ol Inoperative/Missing		

6TL0B4X4HS

18-06366

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

		Towed Due To Dama			cle Removed By				
					ERSTATE BP				
		What Driver Was Doi GOING STRAIGH		veni	cle Factors				
		Driver Prior Action Ot		ПОЛ	APPLICABLE				
		Driver Actions							
	Щ	FAILURE TO CON	NTROL						
LINO	VEHICL								
5	ᇤ								
	>								
		Driver Distractions							
		NOT DISTRACTE	D						
_	1								
5	01								
		Owner Name		- 1	Owner Address				
		JAMES M SHEAR	t		S780 MEFFERT RD				
		(608) 415-1399			WONEWOC, WI 53968, US				
		Sequence Of E	vents						
	01	Event DITCH							
		Event							
	02	OVERTURN/ROLI	LOVER						
	Event								
	03	FENCE							
	04	Event							
LIND		Policy Holder		.					
5		Insurance Company PEKIN-INS-CO			dividual ARY SHEAR				
		Individual		1					
		Driver		Ci	tations Issued	Sex			
	T	MARY BETH SHEAR		0		FEMALE			
				Da	ate of Birth	Race			
╘	INDIVIDUA					WHITE			
)IV	Address S780 MEFFERT RD			Driver License Number				
	Z	WONEWOC, WI 53968, US		S	STATE: WISCONSIN COUNTRY: UNITED STATES				
			On Duty Crash	Sa	afety Equipment				
		Equipment	,						
		Seat Position			SHOULDER & LAP BELT				
		1FRONT SEAT-LEFT SIDE (DRIVER/MOTORCY							
		Helmet Use			Helmet Compliance				
		Eye Protection			Tint Compliance				
		2,011000001			This Compilation				
_	7		Injury Severity	Ai	rbag				
5	00	Injury	NO APPARENT INJURY		ON DEPLOYED				
		Ejected			ection Path	Trapped/Extricated			
		NOT EJECTED		IN.	OT EJECTED/NOT APPLICABL	NOT TRAPPED			

6TL0B4X4HS

18-06366

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

		Medical Transport NOT TRANSPORTED			EMS Agency Identifier		EMS Run #			
		Hospital			Date of Death		Time of Death			
		Non Motoris	Striking Unit #	Prior Action		Location		To/From School		
LIND	INDIVIDUAL	Action								
		Action Other								
	Drug & Alcohol No				Suspected Drug Use NO					
		Alcohol Test Giver TEST NOT GIV			Alcohol Test Type		Alcohol Test Results			
		Drug Test Given TEST NOT GIV	EN		Drug Test Type		Drug Test Results			
10	00	Drug Type								
		Individual Condition								
		APPEARED NO								
		perty Owne								
PROP OWNER 01		ridual DRGE R CLEME 3) 524-3101	NT		Address E5816 CHURCHII REEDSBURG, W					
	Fixe	ed Objects St	ruck							
	2		Struck Object FENCE				Structure Number	Damage Tag Number		