

6TL0B8M7TB
18-06678

WISCONSIN MOTOR VEHICLE
CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMENT
1300 LANGE COURT
BARABOO, WI 53913
(608) 356-4895

6TL0B8M7TB

Document Number Override		Primary Crash Document #	Agency Crash Number 18-06678	Investigating Officer/Deputy DEPUTY B. MEARS	
Crash Date 07/01/2018		Crash Time 02:32 PM	Date Arrived 06/25/2018	Time Arrived 12:28 PM	
Date Notified 06/25/2018		Time Notified 12:13 PM	Total Units 01	Total Injured 00	Total Killed 00
<input type="checkbox"/> On Emergency	<input checked="" type="checkbox"/> Hit and Run	<input type="checkbox"/> Lane Closure	<input type="checkbox"/> Work Zone	<input type="checkbox"/> Trailer or Towed	<input type="checkbox"/> Reporting Threshold
<input type="checkbox"/> Government Property	<input type="checkbox"/> Active School Zone	School Bus Related NO		Tags	
<input type="checkbox"/> Reportable	Crash Type DT4000 (STANDARD CRASH)		<input type="checkbox"/> Amended	<input type="checkbox"/> Secondary Crash	

Description

<p>Diagram</p>	Reconstruction By
	Photos By DEPUTY MEARS
	Additional Information PHOTOS

I, a sworn law enforcement officer, agree that I have not added any CJIS data in this report.

UNKNOWN UNIT WAS NB ON KELLEY RD. UNIT WENT LEFT OF CENTER. DRIVER TRIED TO CORRECT UNITS PATH, CAUSING UNIT TO SKID. UNIT THEN TRAVELLED ABOUT 35 FT THEN OFF OF THE LEFT SIDE OF THE ROAD WHERE IT STRUCK A BARBED WIRE FENCE. UNIT CONTINUE ABOUT 25-30 MORE FEET TO THE NW, WHERE IT STOPPED FACING NE. UNIT WAS THEN DRIVEN THROUGH THE FIELD TO A GATE AT THE INTERSECTION OF GAVIN AND KELLEY ROADS. SOMEONE OPENED THE GATE AND THE CAR WAS DRIVEN ONTO THE ROAD. THE FENCE/POSTS WERE DAMAGED. THE OPERATOR AND VEHICLE INVOLVED HAVE NOT BEEN IDENTIFIED.

6TL0B8M7TB
18-06678

WISCONSIN MOTOR VEHICLE
CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMENT
1300 LANGE COURT
BARABOO, WI 53913
(608) 356-4895

Location

ON KELLY DR 386 FT S OF GAVIN RD IN THE TOWN OF WINFIELD IN SAUK COUNTY	Latitude 43.618404724	Longitude -89.979592389
	X Coordinate 259582.71875	Y Coordinate 4833806
	Structure Type	

Crash Scene

First Harmful Event FENCE	First Harmful Event Location SHOULDER LEFT	
Manner of Collision NO COLLISION W/VEHICLE IN TRANSPORT	Light Condition UNKNOWN	
Road Surface Condition(s) DRY	Roadway Factor(s) NONE	
Environment Factor(s) NONE		
Weather Condition(s) UNKNOWN		
Animal Type	Relation To Trafficway TRAFFICWAY - NOT ON ROAD	
Crash Classification - Location PUBLIC PROPERTY	Crash Classification - Jurisdiction NO SPECIAL JURISDICTION	
Tribal Land	Access Control NO CONTROL	Special Study
Within Interchange Area NO	Junction Location NON-JUNCTION	Intersection Type NOT AN INTERSECTION

Unit Summary

UNIT 01	Unit Status IN TRANSIT	Vehicle Operating As Classification D CLASS	Unit Type		
	Vehicle Type			Operating As Endorsements	
	Total Occs	Train/Bus # Injured	Total # Citations Issued	Total Trailers 0	Total HazMat Types
	Insurance? UNKNOWN	Direction Of Travel NORTHBOUND	<input checked="" type="checkbox"/> Pre Crash Tire Mark	Speed Limit 45	Total Lanes 02
	Most Harmful Event: Collision With FENCE		Special Function NO SPECIAL FUNCTION	Emergency Motor Vehicle Use NOT APPLICABLE	
	Traffic Way TWO-WAY, NOT DIVIDED		Traffic Control NO CONTROL	Traffic Control Inoperative/Missing NO	
	Surface Type BLACKTOP (BITUMINOUS)		Road Curvature CURVE RIGHT	Road Grade LEVEL	
	Truck Bus or HazMat				

Property Owner

PROP OWNER 01	Individual KAREN R MEICHUS (608) 524-4917	Address E6619 GAVIN RD LYNDON STATION, WI 53944 , US

Fixed Objects Struck

01	Striking Unit 01	Struck Object FENCE	Structure Number	Damage Tag Number