6TL0BJ1GH1

18-08996

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Document Number Overrid	e Primary Crash	Document #	Agency 18-089	Crash Number 96	DEPUTY J.		
Crash Date 08/16/2018	Crash Time 10:00 PM			Date Arrived 08/16/2018		Time Arrived 10:46 PM	
Date Notified	Time Notified		Total Un		Total Injured	Total Kille	 ed
08/16/2018	10:12 PM				00	00	
On Emergency	Hit and Run	Lane Closu		Work Zone	Trailer o	r Towed	Reporting Threshold
Government Property		chool Zone	NO School E	Bus Related	Tags		
Reportable	Crash Type DT4000 (STA	ANDARD CRASH)		Amende	d	Secondary Crash
Description Diagram						Reconstructio	
	Ui		Unit 1			Photos By Additional Info	ormation
, a sworn law enfo	rcement officer, agr	ee that I have no	t added	any CJIS data in th	nis report.		
ON 8/16/18 AT APPROXIN 1 STATED HE WAS NOT A STRAIGHT OFF THE ROA ONLY DRIVING 45 MPH. E DRIVING MUCH FASTER	ABLE TO SLOW DOWN DWAY APPROXIMATLE BASED ON MY OBSER\	SOON ENOUGH D EY 100 FT THROUG ATIONS AND HOW	UE TO THE	HE WET ROADS AND TREES COMING TO F	GRAVEL ON THE I	ROAD WAY. I RN FIELD. UN	UNIT 1 THEN WENT IIT 1 STATED HE WAS

6TL0BJ1GH1 18-08996

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

	Loc	ation ====										
	ON	SPARKS HILL RD				Latitude			Longitude			
		9 MI N			43.503570049			-90.188538379				
	-	PETIT RD			X Coordinate			Y Coordinate				
		THE TOWN OF IRONT(SAUK COUNTY	ON		242232.8125			4821678				
	IIN 3	SAUK COUNTT		Structure Type								
	Cra	sh Scene										
1	_	Harmful Event				First Harm	oful Event	Location				
	DIT					ON ROA		Location				
		ner of Collision										
		COLLISION W/VEHIC	I F IN TRANSPORT			Light Condition DARK/UNLIT						
		d Surface Condition(s)	LL III TRAITOT ORT			Roadway						
		` '				Roddway	r actor(3)					
	WE	T, GRAVEL										
	Envi	ronment Factor(s)										
	WE	ATHER CONDITIONS				NONE						
	Wea	ather Condition(s)				_						
	RAI	N.										
	Anim	nal Type			Relation To Trafficway TRAFFICWAY - ON RO							
	Cras	sh Classification - Location						- Jurisdiction				
		BLIC PROPERTY						RISDICTION				
	Triba	al Land				Access Control Special Study						
						NO CONTROL						
		in Interchange Area	Junction Location		Intersection	**						
	NO		NON-JUNCTION		NO NON-JUNCTION NOT AN I							
					l							
	Uni	t Summary 👅										
İ		t Summary Status		Vehicle Ope	erating As C	lassification		Unit Type				
ĺ	Unit IN T	Status FRANSIT		Vehicle Ope	erating As C	classification	l	TRUCK				
	Unit IN T Vehi	Status FRANSIT icle Type			erating As C	lassification		TRUCK	is Endorsements			
	Unit IN T Vehi UTII	Status FRANSIT icle Type LITY TRUCK/PICKUP		D CLASS				TRUCK Operating A				
10	Unit IN T Vehi UTII Tota	Status FRANSIT icle Type	TRUCK Train/Bus # Injured	D CLASS			Total Tra	TRUCK Operating A	Total HazMat Types			
	Unit IN T Vehi UTII Tota 1	Status TRANSIT icle Type LITY TRUCK/PICKUP	Train/Bus # Injured	D CLASS			Total Tra	TRUCK Operating A	Total HazMat Types			
	Unit IN T Vehi UTII Tota 1	Status TRANSIT icle Type LITY TRUCK/PICKUP II Occs rance?	Train/Bus # Injured Direction Of Travel	Total # Cital 1	tions Issued	I	Total Tra 0 Speed L	TRUCK Operating A	Total HazMat Types 0 Total Lanes			
	Unit IN T Vehi UTII Tota 1 Insur YES	Status FRANSIT icle Type LITY TRUCK/PICKUP II Occs rance?	Train/Bus # Injured Direction Of Travel NORTHBOUND	Total # Cital 1 Pre	tions Issuec CrashTire Mark	I	Total Tra	TRUCK Operating A ailers	Total HazMat Types 0 Total Lanes 2			
	Unit IN T Vehi UTII Tota 1 Insui YES	Status FRANSIT icle Type LITY TRUCK/PICKUP II Occs rance? S t Harmful Event: Collision	Train/Bus # Injured Direction Of Travel NORTHBOUND	Total # Cital 1	tions Issued CrashTire Mark Inction	1	Total Tra 0 Speed L	TRUCK Operating A ailers	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use			
	Unit IN T Vehi UTII Tota 1 Insui YES Most	Status FRANSIT icle Type LITY TRUCK/PICKUP II Occs rance? S t Harmful Event: Collision	Train/Bus # Injured Direction Of Travel NORTHBOUND	Total # Citat 1 Pre Special Fun NO SPEC	CrashTire Mark Iction	1	Total Tra 0 Speed L	TRUCK Operating A ailers imit Emergency NOT APP	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use			
	Unit IN T Vehi UTII Tota 1 Insui YES Most TRE	Status FRANSIT icle Type LITY TRUCK/PICKUP II Occs rance? St t Harmful Event: Collision	Train/Bus # Injured Direction Of Travel NORTHBOUND With	Total # Cital 1 Pre	CrashTire Mark ICTION IJAL FUNC	1	Total Tra 0 Speed L	TRUCK Operating A ailers imit Emergency NOT APP	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE			
	Unit IN T Vehi UTII Tota 1 Insur YES Most TRE	Status FRANSIT icle Type LITY TRUCK/PICKUP II Occs rance? St t Harmful Event: Collision of the collision of	Train/Bus # Injured Direction Of Travel NORTHBOUND With	Total # Citat 1 Pre Special Fun NO SPEC Traffic Cont	CrashTire Mark Iction IAL FUNC	1	Total Tra 0 Speed L	TRUCK Operating A ailers imit Emergency NOT APP Traffic Cont	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing			
	Unit IN T Vehi UTII Tota 1 Insur YES Most TRE Traff TWO	Status FRANSIT icle Type LITY TRUCK/PICKUP al Occs rance? St t Harmful Event: Collision of the Collision of	Train/Bus # Injured Direction Of Travel NORTHBOUND With	Total # Citat Pre Special Fun NO SPEC Traffic Cont NO CONT	CrashTire Mark Iction IAL FUNC	1	Total Tra 0 Speed L	TRUCK Operating A ailers imit Emergency NOT APP Traffic Cont NO	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing			
	Unit IN T Vehi UTIII Tota 1 Insur YES Most TRE TWO Surfa BLA	Status TRANSIT icle Type LITY TRUCK/PICKUP Il Occs rance? S t Harmful Event: Collision of the collisio	Train/Bus # Injured Direction Of Travel NORTHBOUND With	Total # Citat Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva	CrashTire Mark Iction IAL FUNC	1	Total Tra 0 Speed L	TRUCK Operating A ailers imit Emergency NOT APP Traffic Cont NO Road Grade	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing			
	Unit IN T Vehi UTII Tota 1 Insui YES Most TRE Traff TWO Surfa	Status TRANSIT icle Type LITY TRUCK/PICKUP Il Occs rance? S t Harmful Event: Collision of the collisio	Train/Bus # Injured Direction Of Travel NORTHBOUND With	Total # Citat Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva	CrashTire Mark Iction IAL FUNC	1	Total Tra 0 Speed L	TRUCK Operating A ailers imit Emergency NOT APP Traffic Cont NO Road Grade	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing			
	Unit IN T Vehi UTII Tota 1 Insur YES Most TREE Traff TWO Surfa BLA	Status TRANSIT icle Type LITY TRUCK/PICKUP Il Occs rance? S t Harmful Event: Collision of the collisio	Train/Bus # Injured Direction Of Travel NORTHBOUND With	Total # Citat Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva	CrashTire Mark Iction IAL FUNC	1	Total Tra 0 Speed L	TRUCK Operating A ailers imit Emergency NOT APP Traffic Cont NO Road Grade	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing			
	Unit IN T Vehi UTII Tota 1 Insur YES Most TREE Traff TWO Surfa BLA	Status FRANSIT icle Type LITY TRUCK/PICKUP II Occs rance? S t Harmful Event: Collision of the collision of	Train/Bus # Injured Direction Of Travel NORTHBOUND With	Total # Citat 1 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva CURVE LI	CrashTire Mark ction IIAL FUNC rol ROL ature	CTION	Total Tra 0 Speed L 45	TRUCK Operating A ailers imit Emergency NOT APP Traffic Cont NO Road Grade LEVEL	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing			
	Unit IN T Vehi UTII Tota 1 Insur YES Most TREE Traff TWO Surfa BLA	Status FRANSIT icle Type LITY TRUCK/PICKUP II Occs rance? St Harmful Event: Collision EE fic Way O-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU ck Bus or HazMat Vehicle License Plate Number PF8100	Train/Bus # Injured Direction Of Travel NORTHBOUND With	Total # Citat 1 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva CURVE LI	CrashTire Mark ction IIAL FUNC rol ROL ature	CTION	Total Tra 0 Speed L 45 St WI	TRUCK Operating A ailers imit Emergency NOT APP Traffic Cont NO Road Grade LEVEL Country of Is UNITED S	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing			
	Unit IN T Vehi UTIII Tota 1 InsuryES Most TRE Truck BLA	Status FRANSIT icle Type LITY TRUCK/PICKUP II Occs rance? St Harmful Event: Collision EE fic Way O-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU ck Bus or HazMat Vehicle License Plate Number PF8100 Vehicle Identification Nur	Train/Bus # Injured Direction Of Travel NORTHBOUND With S)	Total # Citat 1 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva CURVE LI Plate Type LTK - LIG Make	CrashTire Mark Iction IIAL FUNC IO INITIAL FUNC INITIAL F	CTION	Total Tra 0 Speed L 45 St WI Year	TRUCK Operating A ailers imit Emergency NOT APP Traffic Cont NO Road Grade LEVEL Country of Is UNITED S' Model	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing			
	Unit IN T Vehi UTII Tota 1 Insur YES Most TREE Traff TWO Surfa BLA	Status TRANSIT icle Type LITY TRUCK/PICKUP II Occs Trance? Status TRANSIT ICLE TRANSIT ICLE TRANSIT ICLE TRANSIT TRA	Train/Bus # Injured Direction Of Travel NORTHBOUND With S)	Total # Citat 1 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva CURVE LI Plate Type LTK - LIG Make CHEVRO	CrashTire Mark loction IAL FUNC rol ROL lature EFT	CTION	Total Tra 0 Speed L 45 St WI	TRUCK Operating A ailers imit Emergency NOT APP Traffic Cont NO Road Grade LEVEL Country of Is UNITED S' Model SILVERAD	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing			
	Unit IN T Vehi UTIII Tota 1 InsuryES Most TRE Truck BLA	Status TRANSIT icle Type LITY TRUCK/PICKUP II Occs Trance? Status TRANSIT TRA	Train/Bus # Injured Direction Of Travel NORTHBOUND With S)	Total # Citat 1 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva CURVE LI Plate Type LTK - LIG Make CHEVRO Body Style	CrashTire Mark loction IAL FUNC rol ROL lature EFT	CTION	Total Tra 0 Speed L 45 St WI Year	TRUCK Operating A ailers imit Emergency NOT APP Traffic Cont NO Road Grade LEVEL Country of Is UNITED S' Model	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing			
	Unit IN T Vehi UTIII Tota 1 Insur YES Most TRE TWO Surface BLA Truc NO	Status TRANSIT icle Type LITY TRUCK/PICKUP II Occs Trance? St Harmful Event: Collision EE fic Way O-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU ok Bus or HazMat Vehicle License Plate Number PF8100 Vehicle Identification Nur 2GCEK19T31132741 Color BLU - BLUE	Train/Bus # Injured Direction Of Travel NORTHBOUND With S)	Total # Cital 1 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva CURVE LI Plate Type LTK - LIG Make CHEVRO Body Style PK - PICI	CrashTire Mark Loction IAL FUNC TOI ROL LATE SHIT TRUC DLET	CTION	Total Tra 0 Speed L 45 St WI Year	TRUCK Operating A ailers imit Emergency NOT APP Traffic Cont NO Road Grade LEVEL Country of Is UNITED S' Model SILVERAD Bus Use	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing			
	Unit IN T Vehi UTIII Tota 1 InsuryES Most TREE TWO Surfa BLA	Status TRANSIT icle Type LITY TRUCK/PICKUP II Occs Trance? Status TRANSIT TRA	Train/Bus # Injured Direction Of Travel NORTHBOUND With S)	Total # Citat 1 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva CURVE LI Plate Type LTK - LIG Make CHEVRO Body Style	CrashTire Mark Loction IAL FUNC TOI ROL LATE SHIT TRUC DLET	CTION	Total Tra 0 Speed L 45 St WI Year	TRUCK Operating A ailers imit Emergency NOT APP Traffic Cont NO Road Grade LEVEL Country of Is UNITED S' Model SILVERAD Bus Use	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing			
	Unit IN T Vehi UTIII Tota 1 InsuryES Most TREE TWO Surfa BLA	Status TRANSIT icle Type LITY TRUCK/PICKUP II Occs Trance? St Harmful Event: Collision of the collision	Train/Bus # Injured Direction Of Travel NORTHBOUND With S)	Total # Cital 1 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva CURVE LI Plate Type LTK - LIG Make CHEVRO Body Style PK - PICI	CrashTire Mark lection IAL FUNC TOI ROL SHUTE SHITT TRUC PLET KUP Image	CTION	Total Tra 0 Speed L 45 St WI Year	TRUCK Operating A ailers imit Emergency NOT APP Traffic Cont NO Road Grade LEVEL Country of Is UNITED S' Model SILVERAD Bus Use	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing			
	Unit IN T Vehi UTIII Tota 1 Insur YES Most TRE TWO Surface BLA Truc NO	Status TRANSIT icle Type LITY TRUCK/PICKUP II Occs rance? S t Harmful Event: Collision of the collision of	Train/Bus # Injured Direction Of Travel NORTHBOUND With S)	Total # Cital Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva CURVE LI Plate Type LTK - LIG Make CHEVRO Body Style PK - PICI Vehicle Da	CrashTire Mark lection IAL FUNC TOI ROL SHUTE SHITT TRUC PLET KUP Image	CTION	Total Tra 0 Speed L 45 St WI Year	TRUCK Operating A ailers imit Emergency NOT APP Traffic Cont NO Road Grade LEVEL Country of Is UNITED S' Model SILVERAD Bus Use	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing			

2 of 4

6TL0BJ1GH1

18-08996

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

		Towed Due To Dama	nge DISABLING DAMAGE		le Removed By LDS TOWING				
	What Driver Was Doing			Vehic	le Factors				
		NEGOTIATING CURVE							
		Driver Prior Action Of	ther	NOT	APPLICABLE				
TIND	VEHICLE	Driver Actions EXCEED SPEED	LIMIT, SPEED TOO FAST/COND,	, FAILU	JRE TO CONTROL, RAN OFF RO	ADWAY			
		Driver Distractions NOT DISTRACTE	D						
			_						
5	01								
		Owner Name RILEY ANTHONY	ASTLE	-	Owner Address 2104 SAINT BRIDGETS RD				
		(608) 495-9133			CAZENOVIA, WI 53924 , US				
	5	Sequence Of E	vents						
	6	RUN OFF ROADV	VAY RIGHT						
	05	Event DITCH							
	03	Event TREE							
	04	Event							
	, F	Policy Holder							
	-	Insurance Company		Ind	ividual				
7		AMERICAN-FAMI	LY-INS-CO	RII	LEY ASTLE				
	I	ndividual							
		Driver RILEY ANTHONY	ASTLE	Cita 1	ations Issued	Sex MALE			
	₽	(608) 495-9133			te of Birth	Race			
⊨ ا	_ □					WHITE			
	INDIVIDUA	Address 32104 SAINT BRIDGETS RD CAZENOVIA, WI 53924 , US			Driver License Number				
	Ĭ				STATE: WISCONSIN COUNTRY: UNITED STATES				
	ı	Equipment On Duty Crash Seat Position			Safety Equipment SHOULDER & LAP BELT				
	Ī								
		1FRONT SEAT-LEFT SIDE (DRIVER/MOTORCY							
		Helmet Use			Helmet Compliance				
		Eye Protection			Tint Compliance				
	_		Injury Severity	Airl	pag				
2		Injury			-				
- 1	00	Ejected	NO APPARENT INJURY		ON DEPLOYED ction Path	Trapped/Extricated			

6TL0BJ1GH1 18-08996

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT **BARABOO, WI 53913** (608) 356-4895

		Medical Transport			EMS Agend	y Identifier	EMS Run#		
		NOT TRANSPORT	ΓED						
	Hospital				Date of Death		Time of Death		
		Non Motorist	Striking Unit #	Prior Action		Location		To/From School	
		Action							
	_								
	INDIVIDUAL								
UNIT	₫								
5	\geq								
	Ĭ								
		Action Other							
		Action Other							
			Suspected Alco	hol Use	Suspected	Orug Use			
		Orug & Alcohol	NO		NO				
		Alcohol Test Given			Alcohol Tes	t Type	Alcohol Test Results		
		TEST NOT GIVEN							
		Drug Test Given TEST NOT GIVEN			Drug Test T	ype	Drug Test Results		
	_	Drug Type							
10	00	Brug Type							
		Individual Condition							
		APPEARED NOR	MAL						
		Violations	1 T-0	Otatuta Number	L Com Nova	Di-ti			
	2	UTC Number AE140331	Issue To? 001	Statute Number 346.57(3)	Seq Num 001	Description DRIVING TOO FAST	FOR CONDITIONS		