## 6TL0BC3B21

18-09171

# WISCONSIN MOTOR VEHICLE CRASH REPORT

Document Number Override	Primary Crash	Primary Crash Document #		/ Crash Number 171	Investigating Officer/Deputy DEPUTY W. VERTEIN			
Crash Date <b>08/20/2018</b>			Date A 08/21/		Time Arrived 07:37 AM			
Date Notified 08/21/2018  On Emergency  Government Property	Time Notified 07:37 AM			Inits	Total Injured Total Kille		ed	
On Emergency	Hit and Run	Lane Closu		☐ Work Zone		or Towed	Reporting Threshold	
Government Property		Active School Zone		Bus Related	Tags			
Reportable	Crash Type DT4000 (ST	ANDARD CRASH	1)		Amended		Secondary Crash	
Description  Diagram						Reconstruction	- D.	
		on-Reportable				Additional Info	rmation	
□ La sworn law onforcer	ment officer co	ree that I have no	ot addo	d any CIIS data in th	nis renort			
I, a sworn law enforcer ON THE DESCRIBED DATE, T	IME, AND LOCATI	ON, THE OPERATO	OR OF U	NIT 1 WAS ATTEMPTIN	G TO BACK OUT	INTO THE RO	ADWAY. THE OPERATOR	
TURNED THE WHEELS TOO S RAINING AND DARK OUTSIDE	SOON CAUSING U	NIT 1 TO BACK OF	F A CUL	VERT AND GET STUCK	IN THE DITCH.	THE OPERATO	OR STATED IT WAS	

### 6TL0BC3B21 18-09171

### **WISCONSIN MOTOR VEHICLE CRASH REPORT**

		ation								
		S1473 COON BLUFF	RD		Latitude			Longitud	le	
	442	FT N			43.591	43.591989694			423881	
	OF	CTHP NB			X Coord	X Coordinate			inate	
	(FIR	E S1473)				268532.40625 4830553				
	IN T	HE TOWN OF DELLO	NΔ	Structur	e Type					
		AUK COUNTY	NA .		FIRE					
	C=-	oh Coone								
,	-	sh Scene								
		Harmful Event				rmful Event	Location			
	DIT				ON ROADWAY					
		ner of Collision		"	Light Condition					
		COLLISION W/VEHIC	DARK							
	Road	d Surface Condition(s)		Roadwa	y Factor(s)					
	WE	Γ								
	Envii	ronment Factor(s)								
	МОИ	` ,			NONE					
	Wea	ther Condition(s)								
	RAI	N								
	Anim	nal Type			Relation	Relation To Trafficway				
						TRAFFICWAY - ON ROAD				
	Cras	h Classification - Location			Crash C	Crash Classification - Jurisdiction				
	PUE	BLIC PROPERTY			NO SP	NO SPECIAL JURISDICTION				
	Triba	al Land			Access				Special Study	
					NO CO	NO CONTROL				
	With	in Interchange Area	Junction Location		Intersection Type					
	NO		NON-JUNCTION		NOT AN INTERS	ECTION				
į	Unit	t Summary =								
	Unit	Status		Vehicle Ope	erating As Classificati	on	Unit Type			
				Vehicle Ope		on	Unit Type TRUCK			
	IN T	Status				on		s Endorser	ments	
-	IN T	Status RANSIT	TRUCK			on	TRUCK			
-	Vehicutili Vehicutili Total	Status 'RANSIT cle Type	TRUCK Train/Bus # Injured	D CLASS  Total # Cita		Total Tra	TRUCK Operating A	Total Hazi	ments Mat Types	
-	Vehi	Status RANSIT cle Type LITY TRUCK/PICKUP	Train/Bus # Injured	D CLASS		Total Tra	TRUCK Operating A	Total Hazi	Mat Types	
5	Vehice UTII Total 1	Status RANSIT cle Type LITY TRUCK/PICKUP Occs rance?	Train/Bus # Injured  Direction Of Travel	Total # Cital 0	tions Issued  CrashTire	Total Tra  0  Speed L	TRUCK Operating A	Total Hazi	Mat Types	
	Vehicutiii Total 1 Insur	Status RANSIT cle Type LITY TRUCK/PICKUP I Occs rance?	Train/Bus # Injured  Direction Of Travel  NORTHBOUND	Total # Cital 0	tions Issued  CrashTire  Mark	Total Tra	TRUCK Operating A ailers	Total Hazi  0  Total Lane 2	Mat Types es	
	IN T Vehice UTII Total 1 Insur YES	Status RANSIT Cle Type LITY TRUCK/PICKUP I Occs rance? 6 Harmful Event: Collision \	Train/Bus # Injured  Direction Of Travel  NORTHBOUND	Total # Citar 0 Pre Special Fun	tions Issued  CrashTire  Mark Iction	Total Tra  0  Speed L	TRUCK Operating A sillers imit Emergency	Total Hazi  0 Total Lane 2 Motor Vehi	Mat Types es icle Use	
	IN T Vehice UTII Total 1 Insur YES Most CUL	Status RANSIT Cle Type LITY TRUCK/PICKUP I Occs rance? St Harmful Event: Collision \ LVERT	Train/Bus # Injured  Direction Of Travel  NORTHBOUND	Total # Cital 0 Pre Special Fun NO SPEC	crashTire Mark action	Total Tra  0  Speed L	TRUCK Operating A silers imit Emergency NOT APP	Total Hazi  0 Total Lane 2 Motor Vehi	Mat Types es icle Use	
	IN T Vehic UTII Total 1 Insur YES Most CUL	Status RANSIT Cle Type LITY TRUCK/PICKUP I Occs rance? 6 Harmful Event: Collision \ VERT ic Way	Train/Bus # Injured  Direction Of Travel  NORTHBOUND  With	Total # Citat  O  Pre  Special Fun  NO SPEC  Traffic Cont	CrashTire Mark action IIAL FUNCTION	Total Tra  0  Speed L	TRUCK Operating A sillers imit  Emergency NOT APP Traffic Cont	Total Hazi  0 Total Lane 2 Motor Vehi	Mat Types es icle Use	
	IN T Vehice UTII Total 1 Insur YES Most CUL Traff	Status RANSIT Cle Type LITY TRUCK/PICKUP I Occs rance? B Harmful Event: Collision Novertic Way D-WAY, NOT DIVIDED	Train/Bus # Injured  Direction Of Travel  NORTHBOUND  With	Total # Citar 0 Pre Special Fun NO SPEC Traffic Cont	tions Issued  CrashTire Mark ction IAL FUNCTION rol	Total Tra  0  Speed L	TRUCK Operating A sillers imit Emergency NOT APP Traffic Cont NO	Total Hazi  0 Total Lane 2 Motor Vehi LICABLE	Mat Types es icle Use	
	IN T Vehic UTII Total 1 Insur YES Most CUL Traff TWC	Status RANSIT Cle Type LITY TRUCK/PICKUP I Occs  rance? B Harmful Event: Collision V LVERT ic Way D-WAY, NOT DIVIDED ace Type	Train/Bus # Injured  Direction Of Travel  NORTHBOUND  With	Total # Citar 0 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva	crashTire Mark ICTION ITAL FUNCTION ITAL FUNCTION ITAL FUNCTION ITAL FUNCTION	Total Tra  0  Speed L	TRUCK Operating A sillers imit Emergency NOT APP Traffic Cont NO Road Grade	Total Hazi  0 Total Lane 2 Motor Vehi LICABLE	Mat Types es icle Use	
	Vehicutiii Total 1 Insur YES Most CUL Traff TWC Surfa	Status  RANSIT  cle Type  LITY TRUCK/PICKUP  Cocs  rance?  Harmful Event: Collision V  VERT  ic Way  D-WAY, NOT DIVIDED  ace Type  ACKTOP (BITUMINOU)	Train/Bus # Injured  Direction Of Travel  NORTHBOUND  With	Total # Citar 0 Pre Special Fun NO SPEC Traffic Cont	crashTire Mark ICTION ITAL FUNCTION ITAL FUNCTION ITAL FUNCTION ITAL FUNCTION	Total Tra  0  Speed L	TRUCK Operating A sillers imit Emergency NOT APP Traffic Cont NO	Total Hazi  0 Total Lane 2 Motor Vehi LICABLE	Mat Types es icle Use	
	IN T Vehic UTII Total 1 Insur YES Most CUL Traff TWC Surfa	Status RANSIT Cle Type LITY TRUCK/PICKUP I Occs  rance? B Harmful Event: Collision V LVERT ic Way D-WAY, NOT DIVIDED ace Type	Train/Bus # Injured  Direction Of Travel  NORTHBOUND  With	Total # Citar 0 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva	crashTire Mark ICTION ITAL FUNCTION ITAL FUNCTION ITAL FUNCTION ITAL FUNCTION	Total Tra  0  Speed L	TRUCK Operating A sillers imit Emergency NOT APP Traffic Cont NO Road Grade	Total Hazi  0 Total Lane 2 Motor Vehi LICABLE	Mat Types es icle Use	
	IN T Vehicutility Total 1 Insur YES Most CUL Traff TWC Surfa BLA Truck	Status RANSIT cle Type LITY TRUCK/PICKUP I Occs rance? B Harmful Event: Collision No. VERT ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS) k Bus or HazMat	Train/Bus # Injured  Direction Of Travel  NORTHBOUND  With	Total # Citar 0 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva	crashTire Mark ICTION ITAL FUNCTION ITAL FUNCTION ITAL FUNCTION ITAL FUNCTION	Total Tra  0  Speed L	TRUCK Operating A sillers imit Emergency NOT APP Traffic Cont NO Road Grade	Total Hazi  0 Total Lane 2 Motor Vehi LICABLE	Mat Types es icle Use	
	IN T Vehicutility Total 1 Insur YES Most CUL Traff TWC Surfa BLA Truck	Status RANSIT Cle Type LITY TRUCK/PICKUP I Occs rance? Status Harmful Event: Collision Navent LVERT Ic Way D-WAY, NOT DIVIDED RACKTOP (BITUMINOUS) R Bus or HazMat	Train/Bus # Injured  Direction Of Travel  NORTHBOUND  With	Total # Cital 0 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva STRAIGH	crashTire Mark ction IIAL FUNCTION rol ROL ature	Total Tra 0 Speed L 45	TRUCK Operating A silers imit  Emergency NOT APP Traffic Cont NO Road Grade UPHILL	Total Hazi  Total Lane  2  Motor Vehi LICABLE  rol Inoperat	Mat Types es icle Use	
	IN T Vehicutility Total 1 Insur YES Most CUL Traff TWC Surfa BLA Truck	Status RANSIT Cle Type LITY TRUCK/PICKUP I Occs France? Status Harmful Event: Collision Note of the collision	Train/Bus # Injured  Direction Of Travel  NORTHBOUND  With	Total # Cital 0 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva STRAIGH	CrashTire Mark ction IIAL FUNCTION rol ROL ature	Total Tra 0 Speed L 45	TRUCK Operating A silers  imit  Emergency NOT APP Traffic Cont NO Road Grade UPHILL  Country of Is	Total Hazi  Total Lane  2  Motor Vehi LICABLE  rol Inoperat	Mat Types es icle Use	
	IN T Vehicutility Total 1 Insur YES Most CUL Traff TWC Surfa BLA Truck	Status RANSIT Cle Type LITY TRUCK/PICKUP I Occs  rance? B Harmful Event: Collision Note of the collision of	Train/Bus # Injured  Direction Of Travel  NORTHBOUND  With	Total # Citar 0 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva STRAIGH	crashTire Mark ction IIAL FUNCTION rol ROL ature	Total Tra 0 Speed L 45	TRUCK Operating A  illers  imit  Emergency NOT APP Traffic Cont NO Road Grade UPHILL  Country of Is UNITED S	Total Hazi  Total Lane  2  Motor Vehi LICABLE  rol Inoperat	Mat Types es icle Use	
	IN T Vehicution Vehicution Vehicution Vehicution Vehicution Total 1 Insur YES Most CUL Traff TWC Surfa BLA Truck NO	Status RANSIT Cle Type LITY TRUCK/PICKUP I Occs  rance? 6 Harmful Event: Collision Noverther to the collision of the collisio	Train/Bus # Injured  Direction Of Travel NORTHBOUND  With	Total # Citat 0 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva STRAIGH	CrashTire Mark ICTION ITAL FUNCTION ITAL ITAL ITAL ITAL ITAL ITAL ITAL ITAL	Total Tra 0 Speed L 45	TRUCK Operating A  illers  imit  Emergency NOT APP Traffic Cont NO Road Grade UPHILL  Country of Is UNITED ST Model	Total Hazi  Total Lane  2  Motor Vehi LICABLE  rol Inoperat	Mat Types es icle Use	
	IN T Vehicutility Total 1 Insur YES Most CUL Traff TWC Surfa BLA Truck	Status RANSIT cle Type LITY TRUCK/PICKUP LOCCS rance? Status Harmful Event: Collision Note: LVERT ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS) Ik Bus or HazMat Vehicle License Plate Number 576894 Vehicle Identification Nur 3GNEK13T82G12102	Train/Bus # Injured  Direction Of Travel NORTHBOUND  With	Total # Citar 0 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva STRAIGH  Plate Type LTK - LIG Make CHEVRO	CrashTire Mark Interior IAL FUNCTION TOI ROL INTERIOR TOI	Total Tra 0 Speed L 45	TRUCK Operating A  ailers  imit  Emergency NOT APP  Traffic Cont NO  Road Grade UPHILL  Country of Is UNITED ST  Model AVALANC	Total Hazi  Total Lane  2  Motor Vehi LICABLE  rol Inoperat	Mat Types es icle Use	
	IN T Vehicution Vehicution Vehicution Vehicution Vehicution Total 1 Insur YES Most CUL Traff TWC Surfa BLA Truck NO	Status RANSIT Cle Type LITY TRUCK/PICKUP I Occs  rance? 6 Harmful Event: Collision Noverther to the collision of the collisio	Train/Bus # Injured  Direction Of Travel NORTHBOUND  With	Total # Citat 0 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva STRAIGH	CrashTire Mark Inction IAL FUNCTION TOI ROL INTURE T	Total Tra 0 Speed L 45	TRUCK Operating A  illers  imit  Emergency NOT APP Traffic Cont NO Road Grade UPHILL  Country of Is UNITED ST Model	Total Hazi  Total Lane  2  Motor Vehi LICABLE rol Inoperat	Mat Types es icle Use	
	IN T Vehicution Vehicu	Status RANSIT Cle Type LITY TRUCK/PICKUP LOCCS  Tance? Status Harmful Event: Collision Note: LVERT Ic Way D-WAY, NOT DIVIDED ACKTOP (BITUMINOUS) It Bus or HazMat  Vehicle License Plate Number 576894  Vehicle Identification Nur 3GNEK13T82G12102  Color	Train/Bus # Injured  Direction Of Travel NORTHBOUND  With	Total # Citar 0 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva STRAIGH  Plate Type LTK - LIG Make CHEVRO Body Style	CrashTire Mark Interest of the second of the	Total Tra 0 Speed L 45	TRUCK Operating A silers  imit  Emergency NOT APP Traffic Cont NO Road Grade UPHILL  Country of Is UNITED ST Model AVALANC Bus Use	Total Hazi  Total Lane  2  Motor Vehi LICABLE rol Inoperat	Mat Types es icle Use	
	IN T Vehicution Vehicu	Status RANSIT Cle Type LITY TRUCK/PICKUP LOCCS  Fance?  Harmful Event: Collision National States Colorum Park States LOCKTOP (BITUMINOUS & Bus or HazMat  Vehicle License Plate Number 576894  Vehicle Identification Num 3GNEK13T82G12102  Colorum BLK - BLACK	Train/Bus # Injured  Direction Of Travel NORTHBOUND  With  S)	Total # Citar 0 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva STRAIGH  Plate Type LTK - LIG Make CHEVRO Body Style PK - PICI	CrashTire Mark Interest of the second of the	Total Tra 0 Speed L 45	TRUCK Operating A silers  imit  Emergency NOT APP Traffic Cont NO Road Grade UPHILL  Country of Is UNITED ST Model AVALANC Bus Use	Total Hazi  Total Lane  2  Motor Vehi LICABLE rol Inoperat	Mat Types es icle Use	
	IN T Vehicution Vehicution Vehicution Vehicution Vehicution Total 1 Insur YES Most CUL Traff TWC Surfa BLA Truck NO	Status RANSIT cle Type LITY TRUCK/PICKUP LOCCS rance? B Harmful Event: Collision Name LVERT ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS) k Bus or HazMat Vehicle License Plate Number 576894 Vehicle Identification Num 3GNEK13T82G12102 Color BLK - BLACK Initial Contact Point	Train/Bus # Injured  Direction Of Travel NORTHBOUND  With  S)	Total # Citar 0 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva STRAIGH  Plate Type LTK - LIG Make CHEVRO Body Style PK - PICI	CrashTire Mark Interest of the second of the	Total Tra 0 Speed L 45	TRUCK Operating A silers  imit  Emergency NOT APP Traffic Cont NO Road Grade UPHILL  Country of Is UNITED ST Model AVALANC Bus Use	Total Hazi  Total Lane  2  Motor Vehi LICABLE rol Inoperat	Mat Types es icle Use	

#### 6TL0BC3B21

18-09171

# WISCONSIN MOTOR VEHICLE CRASH REPORT

	Towed Due To Damage TOWED BUT NOT DUE TO DISABLING DAMAG		Vehicle Removed By OPERATOR						
		What Driver Was Doing BACKING		Vehicle Factors					
		Driver Prior Action Other		NO	NOT APPLICABLE				
		Diver Filor Action Other							
		Driver Actions							
	щ	UNSAFE BACKING							
╘	VEHICL								
	ᇁ								
	7								
		Driver Distractions NOT DISTRACTE	D						
5	6								
		Owner Name			Owner Address				
		PAUL GORCHELS (608) 347-6990			E9303 PEBBLEBEACH DR WISCONSIN DELLS, WI 53965, US				
		` ,			,				
	9	L Sequence Of E	vents						
		Event	Ventes						
	2	RIGHT TURN							
	7	Event							
	8 DITCH								
	03	Event CULVERT							
	_	Event							
	04								
-	1	Policy Holder							
		Insurance Company			ndividual				
ا د		BRISTOL-WEST-I	NS-CO	PAUL GORCHELS					
	ı	Individual							
		Driver	6		Citations Issued	Sex			
	7	PAUL GORCHELS (608) 347-6990		0		MALE			
	INDIVIDUA				Date of Birth	Race WHITE			
	=	Address			Driver License Number				
5	≧	E9303 PEBBLEBEACH DR							
	Z	WISCONSIN DELLS, WI 53965 , US		STATE: WISCONSIN COUNTRY: UNITED STATES					
		Farringsont	On Duty Crash	S	Safety Equipment				
		Equipment							
		Seat Position		SHOULDER & LAP BELT					
		Helmet Use  Eye Protection							
				Helmet Compliance					
				Tint Compliance					
		l i							
0	001	Injury Severity			Nirbag				
0	ō	Injury NO APPARENT INJURY			NON DEPLOYED				
		Ejected			jection Path	Trapped/Extricated			
		NOT EJECTED		יון	NOT EJECTED/NOT APPLICABL	NOT TRAPPED			

## 6TL0BC3B21

18-09171

# WISCONSIN MOTOR VEHICLE CRASH REPORT

		Medical Transport NOT TRANSPORTED			EMS Agency Identifier		EMS Run #				
		Hospital			Date of Death		Time of Death				
		Non Motorist	Striking Unit #	Prior Action		Location		To/From School			
TINO	INDIVIDUAL	Action									
		Action Other									
	Ľ	Drug & Alcohol	ug & Alcohol NO		Suspected Drug Us	se					
		Alcohol Test Given TEST NOT GIVEN			Alcohol Test Type		Alcohol Test Results				
		Drug Test Given TEST NOT GIVEN			Drug Test Type		Drug Test Results				
10	001	Drug Type					,				
		Individual Condition									
		APPEARED NOR									
	Pro	perty Owner									
PROP OWNER 01	Government TOWNSHIP OF DELLONA (608) 524-0800			Address E8062 CTH H REEDSBURG, W	53959 , US						
	Fixe	ed Objects Stru									
	٦		ruck Object ITCH					Damage Tag Number N/A			
	05		ruck Object ULVERT					Damage Tag Number <b>N/A</b>			