WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT **BARABOO, WI 53913** (608) 356-4895

Government Property Active School Zone No	Document Number Override	Primary Crash Do	_	ncy Crash Number 1 9345	Investigating Off DEPUTY E. K		
Mulbern Mulb							
Government Property Active School Zone No				Units			d
Reportable DT4000 (STANDARD CRASH) Amended Secondic Crash Types Bescription Reconstruction By Photos By NOTTO SCALE WLOCUST ST MULBERRY MULBERRY NO Meanded Secondic Crash Additional Information NONE	On Emergency Hi	it and Run	Lane Closure	☐ Work Zone	☐ Trailer or	Towed	Reporting Threshold
Reconstruction By Photos By NOT TO SCALE WLOCUST ST MULBERR Additional Information WLOCUST ST MULBERR Amended Crash Crash Reconstruction By Reconstruction By		Active Sch	a a l 7 a m a	ol Bus Related	Tags		
NOTTO SCALE W LOCUST ST WULDERRY MULBERRY Reconstruction By Photos By Additional Information NONE	Reportable	Crash Type DT4000 (STAN	IDARD CRASH)		Amended		Secondary Crash
NOT TO SCALE WLOCUST ST MULBERR Photos By Additional Information NONE	<u>-</u>				1-		
NOT TO SCALE Additional Information NONE W LOCUST ST 11 MULBERRY Additional Information NONE	Jiagram				Re	construction	n Ву
NOT TO SCALE Additional Information NONE WLOCUST ST WLOCUST ST MULBERRY Additional Information NONE	*						
Additional Information NONE W LOCUST ST MULBERRY Additional Information NONE		I	1		Ph	otos By	
Additional Information NONE W LOCUST ST MULBERRY Additional Information NONE	~						
W LOCUST ST W LOCUST ST MULBERRY MULBERRY	NOT TO SCALE						
WLOCUST ST MULBERRY MULBERRY							rmation
1 MULBERRY STOP		40TS			14	JNE	
1 MULBERRY 2 STOP							
MULBERRY 2		<u> </u>)	WLOCUSTST			
1 MULBERRY		11					
1 MULBERRY							
1 MULBERRY			J				
MULBERRY 2							
1 MULBERRY			1				
1 MULBERRY							
MULBERRY			\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	СТОР			
		13 ' 14	9-20				
			MULBERRY				
		I	I				
↓ I, a sworn law enforcement officer, agree that I have not added any CJIS data in this report.	□ La sworn law enforceme	ent officer sares	that I have not add	lad anni C IIC data in ti	nis report		

AND UNIT 2 TOWED FROM SCENE BY MIKES TOWING

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT **BARABOO, WI 53913** (608) 356-4895

Crash Time 12:09 PM

	LOC	ation						
		ERSECTION			Latitude		Longitude	
	ON	LOCUST ST			43.47193755		-89.767053211	
		MULBERRY ST			X Coordinate		Y Coordinate	
		HE VILLAGE OF WES	T BARABOO		276191.09375 4816944.5			
	IN 3	SAUK COUNTY			Structure Type		L	
					NO STRUCTUR	E		
(Cra	sh Scene						
		Harmful Event			First Harmful Even	t Location		
	МО	TOR VEH IN TRANSPO	ORT		ON ROADWAY			
	Manı	ner of Collision			Light Condition			
	08	FRONT TO SIDE			DAYLIGHT			
	Road	d Surface Condition(s)			Roadway Factor(s)			
	DRY	1						
	Envi	ronment Factor(s)			_			
		, ,			NONE			
	МОИ	NE			NONE			
	Wea	ther Condition(s)						
	CLE	AR						
	Anim	nal Type			Relation To Traffic	way		
						TRAFFICWAY - ON ROAD		
	Cras	h Classification - Location			Crash Classification	n - Jurisdiction		
	PUE	BLIC PROPERTY			NO SPECIAL JU			
	Triba	al Land			Access Control		Special Study	
					NO CONTROL			
		•	Junction Location	Intersection				
	NO		INTERSECTION	FOUR-V	VAY INTERSECTION	ON		
- 1	Unit	t Summary 💳						
,		· · · · · · · · · · · · · · · · · · ·						
		Status		Vehicle Operating As C	Classification	Unit Type		
	Unit IN T	Status RANSIT		Vehicle Operating As C	Classification	TRUCK		
	Unit IN T Vehi	Status 'RANSIT cle Type		· -	Classification	TRUCK	s Endorsements	
	Unit IN T Vehic UTII	Status RANSIT cle Type LITY TRUCK/PICKUP 1		D CLASS		TRUCK Operating A		
	Unit IN T Vehic UTII Total	Status 'RANSIT cle Type	FRUCK Train/Bus # Injured	D CLASS Total # Citations Issued	d Total Ti	TRUCK Operating A	Total HazMat Types	
	Unit IN T Vehic UTII Total 2	Status RANSIT cle Type LITY TRUCK/PICKUP T	Train/Bus # Injured	D CLASS Total # Citations Issued 0	d Total Ti	TRUCK Operating A	Total HazMat Types 0	
	Unit IN T Vehic UTII Total 2 Insur	Status RANSIT cle Type LITY TRUCK/PICKUP T I Occs rance?	Train/Bus # Injured Direction Of Travel	Total # Citations Issued O Pre CrashTire	d Total Ti	TRUCK Operating A	Total HazMat Types 0 Total Lanes	
	Unit IN T Vehic UTII Total 2 Insur YES	Status RANSIT cle Type LITY TRUCK/PICKUP T I Occs rance?	Train/Bus # Injured Direction Of Travel SOUTHBOUND	Total # Citations Issued 0 Pre CrashTire Mark	d Total Ti	TRUCK Operating A	Total HazMat Types 0 Total Lanes 2	
	Unit IN T Vehic UTII Total 2 Insur YES	Status RANSIT cle Type LITY TRUCK/PICKUP T I Occs rance?	Train/Bus # Injured Direction Of Travel SOUTHBOUND Vith	Total # Citations Issued O Pre CrashTire	d Total To 0 e Speed 25	TRUCK Operating A	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use	
	Unit IN T Vehic UTII Total 2 Insur YES Most	Status RANSIT cle Type LITY TRUCK/PICKUP 1 I Occs rance? S t Harmful Event: Collision W	Train/Bus # Injured Direction Of Travel SOUTHBOUND Vith	Total # Citations Issued O Pre CrashTire Mark Special Function	d Total To 0 e Speed 25	TRUCK Operating Astrailers Limit Emergency NOT APPL	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use	
	Unit IN T Vehic UTII Total 2 Insur YES Most MO Traff TWO	Status RANSIT cle Type LITY TRUCK/PICKUP T I Occs rance? St Harmful Event: Collision W TOR VEH IN TRANSPO ic Way D-WAY, NOT DIVIDED	Train/Bus # Injured Direction Of Travel SOUTHBOUND Vith	Total # Citations Issued O Pre CrashTire Mark Special Function NO SPECIAL FUNC	d Total To 0 e Speed 25	TRUCK Operating Astrailers Limit Emergency NOT APPL	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE	
	Unit IN T Vehic UTII Total 2 Insur YES Most MO Traff TWC	Status RANSIT cle Type LITY TRUCK/PICKUP T I Occs rance? I Harmful Event: Collision W TOR VEH IN TRANSPO ic Way D-WAY, NOT DIVIDED ace Type	Train/Bus # Injured Direction Of Travel SOUTHBOUND Vith DRT	Total # Citations Issued Pre CrashTire Mark Special Function NO SPECIAL FUNC Traffic Control STOP SIGN Road Curvature	d Total To 0 e Speed 25	TRUCK Operating Astrailers Limit Emergency NOT APPL Traffic Contr NO Road Grade	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE fol Inoperative/Missing	
	Unit IN T Vehic UTII Total 2 Insur YES Most MO Traff TWO Surfa	Status TRANSIT Cle Type LITY TRUCK/PICKUP T I Occs Trance? The Harmful Event: Collision W TOR VEH IN TRANSPO TIC Way D-WAY, NOT DIVIDED TAKE Type ACKTOP (BITUMINOUS	Train/Bus # Injured Direction Of Travel SOUTHBOUND Vith DRT	Total # Citations Issued O Pre CrashTire Mark Special Function NO SPECIAL FUNC Traffic Control STOP SIGN	d Total To 0 e Speed 25	TRUCK Operating Astrailers Limit Emergency NOT APPL Traffic Contr	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE fol Inoperative/Missing	
	Unit IN T Vehicut In Total 2 Insur YES Most MO Surfaff TWO Surfa BLA	Status RANSIT cle Type LITY TRUCK/PICKUP T I Occs rance? I Harmful Event: Collision W TOR VEH IN TRANSPO ic Way D-WAY, NOT DIVIDED ace Type	Train/Bus # Injured Direction Of Travel SOUTHBOUND Vith DRT	Total # Citations Issued Pre CrashTire Mark Special Function NO SPECIAL FUNC Traffic Control STOP SIGN Road Curvature	d Total To 0 e Speed 25	TRUCK Operating Astrailers Limit Emergency NOT APPL Traffic Contr NO Road Grade	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE fol Inoperative/Missing	
	Unit IN T Vehin Vehin UTIII Total 2 Insur YES Most MO Traff TWC Surfa BLA Truck	Status RANSIT cle Type LITY TRUCK/PICKUP T I Occs rance? St Harmful Event: Collision W TOR VEH IN TRANSPO ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS k Bus or HazMat	Train/Bus # Injured Direction Of Travel SOUTHBOUND Vith DRT	Total # Citations Issued Pre CrashTire Mark Special Function NO SPECIAL FUNC Traffic Control STOP SIGN Road Curvature	d Total To 0 e Speed 25	TRUCK Operating Astrailers Limit Emergency NOT APPL Traffic Contr NO Road Grade	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE fol Inoperative/Missing	
	Unit IN T Vehin Vehin UTIII Total 2 Insur YES Most MO Traff TWC Surfa BLA Truck	Status TRANSIT Cle Type LITY TRUCK/PICKUP T I Occs Trance? The Harmful Event: Collision W TOR VEH IN TRANSPO TIC Way D-WAY, NOT DIVIDED TAKE Type ACKTOP (BITUMINOUS	Train/Bus # Injured Direction Of Travel SOUTHBOUND Vith DRT	Total # Citations Issued 0 Pre CrashTire Mark Special Function NO SPECIAL FUNC Traffic Control STOP SIGN Road Curvature STRAIGHT	d Total Ti 0 e Speed 25 CTION	TRUCK Operating Astrailers Limit Emergency NOT APPL Traffic Contr NO Road Grade LEVEL	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE ol Inoperative/Missing	
	Unit IN T Vehin Vehin UTIII Total 2 Insur YES Most MO Traff TWC Surfa BLA Truck	Status RANSIT cle Type LITY TRUCK/PICKUP T I Occs rance? St Harmful Event: Collision W TOR VEH IN TRANSPO ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS k Bus or HazMat Vehicle License Plate Number	Train/Bus # Injured Direction Of Travel SOUTHBOUND Vith DRT	Total # Citations Issued 0 Pre CrashTire Mark Special Function NO SPECIAL FUNC Traffic Control STOP SIGN Road Curvature STRAIGHT	d Total Ti 0 e Speed 25 CTION	TRUCK Operating Astrailers Limit Emergency NOT APPL Traffic Contr NO Road Grade LEVEL Country of Iss	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE ol Inoperative/Missing	
	Unit IN T Vehin Vehin UTIII Total 2 Insur YES Most MO Traff TWC Surfa BLA Truck	Status RANSIT cle Type LITY TRUCK/PICKUP T I Occs rance? St Harmful Event: Collision W TOR VEH IN TRANSPO ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS k Bus or HazMat Vehicle License Plate Number EV9378	Train/Bus # Injured Direction Of Travel SOUTHBOUND With ORT	Total # Citations Issued O Pre CrashTire Mark Special Function NO SPECIAL FUNC Traffic Control STOP SIGN Road Curvature STRAIGHT Plate Type LTK - LIGHT TRUC	d Total Tota	TRUCK Operating Astrailers Limit Emergency NOT APPL Traffic Contr NO Road Grade LEVEL Country of Iss UNITED ST	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE ol Inoperative/Missing	
	Unit IN T Vehicut IN T Vehicut IN T Vehicut IN T Vehicut IN	Status RANSIT cle Type LITY TRUCK/PICKUP T I Occs rance? St Harmful Event: Collision W TOR VEH IN TRANSPO ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS k Bus or HazMat Vehicle License Plate Number EV9378 Vehicle Identification Num	Train/Bus # Injured Direction Of Travel SOUTHBOUND With ORT	Total # Citations Issued O Pre CrashTire Mark Special Function NO SPECIAL FUNC Traffic Control STOP SIGN Road Curvature STRAIGHT Plate Type LTK - LIGHT TRUC Make	d Total Tota	TRUCK Operating Astrailers Limit Emergency NOT APPL Traffic Contr NO Road Grade LEVEL Country of Iss UNITED ST Model	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE ol Inoperative/Missing	
	Unit IN T Vehin Vehin UTIII Total 2 Insur YES Most MO Traff TWC Surfa BLA Truck	Status RANSIT cle Type LITY TRUCK/PICKUP T I Occs rance? St Harmful Event: Collision W TOR VEH IN TRANSPO ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS k Bus or HazMat Vehicle License Plate Number EV9378 Vehicle Identification Num 1FTFW1EV2AFA0531	Train/Bus # Injured Direction Of Travel SOUTHBOUND With ORT	Total # Citations Issued O Pre CrashTire Mark Special Function NO SPECIAL FUNC Traffic Control STOP SIGN Road Curvature STRAIGHT Plate Type LTK - LIGHT TRUC Make FORD	d Total Tota	TRUCK Operating Astrailers Limit Emergency NOT APPL Traffic Contr NO Road Grade LEVEL Country of Iss UNITED ST Model F150	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE ol Inoperative/Missing	
	Unit IN T Vehicut IN T Vehicut IN T Vehicut IN T Vehicut IN	Status RANSIT cle Type LITY TRUCK/PICKUP T I Occs rance? St Harmful Event: Collision W TOR VEH IN TRANSPO ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS k Bus or HazMat Vehicle License Plate Number EV9378 Vehicle Identification Num 1FTFW1EV2AFA0531 Color	Train/Bus # Injured Direction Of Travel SOUTHBOUND With ORT	Total # Citations Issued O Pre CrashTire Mark Special Function NO SPECIAL FUNC Traffic Control STOP SIGN Road Curvature STRAIGHT Plate Type LTK - LIGHT TRUC Make FORD Body Style	d Total Tota	TRUCK Operating Astrailers Limit Emergency NOT APPL Traffic Contr NO Road Grade LEVEL Country of Iss UNITED ST Model	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE ol Inoperative/Missing	
	Unit IN T Vehic UTIII Total 2 Insur YES MOOT Trafff TWO Surfa BLA Truck NO	Status RANSIT cle Type LITY TRUCK/PICKUP T I Occs rance? A Harmful Event: Collision W TOR VEH IN TRANSPO ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS k Bus or HazMat Vehicle License Plate Number EV9378 Vehicle Identification Num 1FTFW1EV2AFA0531 Color BLK - BLACK	Train/Bus # Injured Direction Of Travel SOUTHBOUND With ORT	Total # Citations Issued O Pre CrashTire Mark Special Function NO SPECIAL FUNC Traffic Control STOP SIGN Road Curvature STRAIGHT Plate Type LTK - LIGHT TRUC Make FORD Body Style PK - PICKUP	d Total Tota	TRUCK Operating Astraction of the control of the co	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE ol Inoperative/Missing	
	Unit IN T Vehicut IN T Vehicut IN T Vehicut IN T Vehicut IN	Status RANSIT cle Type LITY TRUCK/PICKUP T I Occs rance? St Harmful Event: Collision W TOR VEH IN TRANSPO ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS k Bus or HazMat Vehicle License Plate Number EV9378 Vehicle Identification Num 1FTFW1EV2AFA0531 Color	Train/Bus # Injured Direction Of Travel SOUTHBOUND With ORT	Total # Citations Issued O Pre CrashTire Mark Special Function NO SPECIAL FUNC Traffic Control STOP SIGN Road Curvature STRAIGHT Plate Type LTK - LIGHT TRUC Make FORD Body Style	d Total Tota	TRUCK Operating Astraction of the control of the co	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE ol Inoperative/Missing	
	Unit IN T Vehic UTIII Total 2 Insur YES MOOT Traff TWO Surfa BLA Truck NO	Status RANSIT cle Type LITY TRUCK/PICKUP T I Occs rance? St Harmful Event: Collision W TOR VEH IN TRANSPO ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS k Bus or HazMat Vehicle License Plate Number EV9378 Vehicle Identification Num 1FTFW1EV2AFA0531 Color BLK - BLACK Initial Contact Point	Train/Bus # Injured Direction Of Travel SOUTHBOUND With ORT	Total # Citations Issued O Pre CrashTire Mark Special Function NO SPECIAL FUNC Traffic Control STOP SIGN Road Curvature STRAIGHT Plate Type LTK - LIGHT TRUC Make FORD Body Style PK - PICKUP	d Total Tota	TRUCK Operating Astraction of the control of the co	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE ol Inoperative/Missing	
	Unit IN T Vehic UTIII Total 2 Insur YES MOOT Trafff TWO Surfa BLA Truck NO	Status RANSIT cle Type LITY TRUCK/PICKUP T I Occs rance? St Harmful Event: Collision W TOR VEH IN TRANSPO ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS k Bus or HazMat Vehicle License Plate Number EV9378 Vehicle Identification Num 1FTFW1EV2AFA0531 Color BLK - BLACK Initial Contact Point 12FRONT	Train/Bus # Injured Direction Of Travel SOUTHBOUND With DRT Sb)	Total # Citations Issued O Pre CrashTire Mark Special Function NO SPECIAL FUNC Traffic Control STOP SIGN Road Curvature STRAIGHT Plate Type LTK - LIGHT TRUC Make FORD Body Style PK - PICKUP Vehicle Damage	d Total Tota	TRUCK Operating Astraction of the control of the co	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE ol Inoperative/Missing	
	Unit IN T Vehicut Vehi	Status RANSIT cle Type LITY TRUCK/PICKUP T I Occs rance? St Harmful Event: Collision W TOR VEH IN TRANSPO ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS IK Bus or HazMat Vehicle License Plate Number EV9378 Vehicle Identification Num 1FTFW1EV2AFA0531 Color BLK - BLACK Initial Contact Point 12FRONT Extent Of Damage	Train/Bus # Injured Direction Of Travel SOUTHBOUND With DRT Sibber 5	Total # Citations Issued O Pre CrashTire Mark Special Function NO SPECIAL FUNC Traffic Control STOP SIGN Road Curvature STRAIGHT Plate Type LTK - LIGHT TRUC Make FORD Body Style PK - PICKUP Vehicle Damage	d Total Tota	TRUCK Operating Astrailers Limit Emergency NOT APPL Traffic Contract NO Road Grade LEVEL Country of Iss UNITED ST Model F150 Bus Use NOT A BUS	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE ol Inoperative/Missing	

6TL0B4X4J9

18-09345

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

		Towed Due To Dama	age		icle Removed By							
		NOT TOWED			ERATOR							
		What Driver Was Doing ENTERING TRAFFIC LANE		Vehicle Factors								
				NO	T ADDI ICADI E							
		Driver Prior Action Other			T APPLICABLE							
		Dairean Astisms										
		Driver Actions	RIGHT-OF-WAY									
_	LE	FAILED TO YIELD RIGHT-OF-WAY										
	2											
\supset	VEHICL											
	>											
		Driver Distractions										
		NOT DISTRACTE	Driver Distractions NOT DISTRACTED									
5	01											
		Owner Name			Owner Address							
		MICHAEL ANTHO	DNY SEIPP		743 FUR AVE	•						
		(920) 238-2001			WISCONSIN DELLS, WI 53965 , U	S						
		Sequence Of E	vents									
	01	Event	DANSDORT									
	0	MOTOR VEH IN T	RANSPORT									
	02	Event										
		T										
	03	Event										
		Event										
	04	270.11										
		Policy Holder										
		Insurance Company		1	ndividual							
5		PROGRESSIVE-C	CLASSIC-INS-CO	MICHAEL SEIPP								
		Individual										
		Driver		10	Citations Issued	Sex						
		MICHAEL ANTHO	NY SEIPP			MALE						
	AL	(920) 238-2001			Date of Birth	Race						
_	DO					WHITE						
	INDIVIDUA	Address		[Priver License Number							
⊃	ቯ	743 FUR AVE										
	=	WISCONSIN DELI	LS, WI 53965 , US	STATE: WISCONSIN COUNTRY: UNITED STATES								
	ļ	F	On Duty Crash	5	Safety Equipment							
		Equipment										
		Seat Position		5	SHOULDER & LAP BELT							
		1FRONT SEAT-LEFT SIDE (DRIVER/MOTORCY										
		Helmet Use			Helmet Compliance							
		Eye Protection		Ī	int Compliance							
			Linium, Soverity		irhaa							
5	90	Injury	Injury Severity NO APPARENT INJURY		irbag							
-	١	Ejected	INO AFFARENT INJUNT		ION DEPLOYED jection Path	Trapped/Extricated						
		NOT EJECTED			IOT EJECTED/NOT APPLICABL	NOT TRAPPED						
						1						

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

		Modical Transport			EMC A. III	'£'	EMO D "	
		Medical Transport			EMS Agency Identifier		EMS Run #	
		NOT TRANSPOR	TED					
		Hospital			Date of Death		Time of Death	
			Striking Unit #	Prior Action		Location		To/From School
		Non Motorist	Striking Onit #	Phoi Action		Location		TO/FIGHT SCHOOL
		Action						
	رِ							
	INDIVIDUAL							
LINO	7							
Z	Ħ							
\supset	\leq							
	爿							
	=							
		Action Other						
			Suspected Alcohol U	leo	Suspected Drug U	20		
	Г	Drug & Alcohol	NO	75E	NO	56		
		rug a rucciici	140		140			
		Alcohol Test Given			Alcohol Test Type		Alcohol Test Results	
		TEST NOT GIVEN	I					
			-		Drug Test Type		Drug Took Dooulto	
	Drug Test Given TEST NOT GIVEN	ı		Didg rest type		Drug Test Results		
	ILST NOT GIVEN	•						
_		Drug Type					•	
6	00							
	_							
		Individual Condition						
		marviadar Condition						
		APPEARED NOR	MAL					
		Individual						
		Passenger			Citations Issued		Sex	
		HEATHER LYNN	REBEDEW		0		FEMALE	
	₹	(000) 000 0750						
		(920) 602-2752			Date of Birth		Race	
_	Ž	(920) 602-2752			Date of Birth		Race WHITE	
╘	JIDU,						Race WHITE	
Ĭ	IVIDU,	Address			Date of Birth Driver License Nur	mber		
LINO	'NDINIDN'	Address 743 FUR AVE			Driver License Nur		WHITE	
LINO	INDIVIDUAL	Address 743 FUR AVE	LS, WI 53965 , US		Driver License Nur	nber NSIN COUNTRY: U	WHITE	
LIND	INDINIDN'	Address 743 FUR AVE			Driver License Nur		WHITE	
LIND	'NDINIDN'	Address 743 FUR AVE	LS, WI 53965 , US		Driver License Nur STATE: WISCO		WHITE	
LINO	'NDINIDN'	Address 743 FUR AVE WISCONSIN DEL			Driver License Nur		WHITE	
LIND	'NGINIQNI	Address 743 FUR AVE	LS, WI 53965 , US		Driver License Nur STATE: WISCO		WHITE	
LIND	UDIVIDU	Address 743 FUR AVE WISCONSIN DEL	LS, WI 53965 , US		Driver License Nur STATE: WISCO Safety Equipment	NSIN COUNTRY: U	WHITE	
LINO	NDINIDN	Address 743 FUR AVE WISCONSIN DEL Equipment Seat Position	LS, WI 53965 , US		Driver License Nur STATE: WISCO	NSIN COUNTRY: U	WHITE	
LINO	NDINIDNI	Address 743 FUR AVE WISCONSIN DEL Equipment Seat Position 3FRONT SEAT-	LS, WI 53965 , US		Driver License Nur STATE: WISCO Safety Equipment SHOULDER & I	NSIN COUNTRY: U	WHITE	
LIND	MOINIONI	Address 743 FUR AVE WISCONSIN DEL Equipment Seat Position	LS, WI 53965 , US		Driver License Nur STATE: WISCO Safety Equipment	NSIN COUNTRY: U	WHITE	
LIND	UDIVIDUI	Address 743 FUR AVE WISCONSIN DEL Equipment Seat Position 3FRONT SEAT-	LS, WI 53965 , US		Driver License Nur STATE: WISCO Safety Equipment SHOULDER & I	NSIN COUNTRY: U	WHITE	
LIND	NOINIONI	Address 743 FUR AVE WISCONSIN DEL Equipment Seat Position 3FRONT SEAT-I Helmet Use	LS, WI 53965 , US		Driver License Nur STATE: WISCO Safety Equipment SHOULDER & I Helmet Compliance	NSIN COUNTRY: U	WHITE	
LIND	MOINIONI	Address 743 FUR AVE WISCONSIN DEL Equipment Seat Position 3FRONT SEAT-	LS, WI 53965 , US		Driver License Nur STATE: WISCO Safety Equipment SHOULDER & I	NSIN COUNTRY: U	WHITE	
TINO		Address 743 FUR AVE WISCONSIN DEL Equipment Seat Position 3FRONT SEAT-I Helmet Use	LS, WI 53965 , US On Duty Crash RIGHT SIDE (TRAI		Driver License Nur STATE: WISCO Safety Equipment SHOULDER & I Helmet Compliance	NSIN COUNTRY: U	WHITE	
		Address 743 FUR AVE WISCONSIN DEL Equipment Seat Position 3FRONT SEAT-I Helmet Use Eye Protection	LS, WI 53965 , US On Duty Crash RIGHT SIDE (TRAIL	N ENGINEER	Driver License Nur STATE: WISCO Safety Equipment SHOULDER & I Helmet Compliance Tint Compliance	NSIN COUNTRY: U	WHITE	
UNIT UNIT	002 INDIVIDU	Address 743 FUR AVE WISCONSIN DEL Equipment Seat Position 3FRONT SEAT-I Helmet Use	LS, WI 53965 , US On Duty Crash RIGHT SIDE (TRAI	N ENGINEER	Driver License Nur STATE: WISCO Safety Equipment SHOULDER & I Helmet Compliance	NSIN COUNTRY: U	WHITE	
		Address 743 FUR AVE WISCONSIN DEL Equipment Seat Position 3FRONT SEAT-I Helmet Use Eye Protection	LS, WI 53965 , US On Duty Crash RIGHT SIDE (TRAIL	N ENGINEER	Driver License Nur STATE: WISCO Safety Equipment SHOULDER & I Helmet Compliance Tint Compliance Airbag NON DEPLOYE	NSIN COUNTRY: U	WHITE	
		Address 743 FUR AVE WISCONSIN DEL Equipment Seat Position 3FRONT SEAT-I Helmet Use Eye Protection Injury Ejected	LS, WI 53965 , US On Duty Crash RIGHT SIDE (TRAIL	N ENGINEER	Driver License Nur STATE: WISCO Safety Equipment SHOULDER & I Helmet Compliance Tint Compliance Airbag NON DEPLOYE Ejection Path	AP BELT	WHITE NITED STATES Trapped/Extricated	
		Address 743 FUR AVE WISCONSIN DEL Equipment Seat Position 3FRONT SEAT-I Helmet Use Eye Protection Injury Ejected NOT EJECTED	LS, WI 53965 , US On Duty Crash RIGHT SIDE (TRAIL	N ENGINEER	Driver License Nur STATE: WISCO Safety Equipment SHOULDER & I Helmet Compliance Tint Compliance Airbag NON DEPLOYE Ejection Path NOT EJECTED	AP BELT Country: U AP BELT Country: U	WHITE NITED STATES Trapped/Extricated NOT TRAPPED	
		Address 743 FUR AVE WISCONSIN DEL Equipment Seat Position 3FRONT SEAT-I Helmet Use Eye Protection Injury Ejected NOT EJECTED Medical Transport	LS, WI 53965 , US On Duty Crash RIGHT SIDE (TRAIL Injury Severity NO APPARENT II	N ENGINEER	Driver License Nur STATE: WISCO Safety Equipment SHOULDER & I Helmet Compliance Tint Compliance Airbag NON DEPLOYE Ejection Path	AP BELT Country: U AP BELT Country: U	WHITE NITED STATES Trapped/Extricated	
		Address 743 FUR AVE WISCONSIN DEL Equipment Seat Position 3FRONT SEAT-I Helmet Use Eye Protection Injury Ejected NOT EJECTED	LS, WI 53965 , US On Duty Crash RIGHT SIDE (TRAIL Injury Severity NO APPARENT II	N ENGINEER	Driver License Nur STATE: WISCO Safety Equipment SHOULDER & I Helmet Compliance Tint Compliance Airbag NON DEPLOYE Ejection Path NOT EJECTED	AP BELT Country: U AP BELT Country: U	WHITE NITED STATES Trapped/Extricated NOT TRAPPED	
		Address 743 FUR AVE WISCONSIN DEL Equipment Seat Position 3FRONT SEAT-I Helmet Use Eye Protection Injury Ejected NOT EJECTED Medical Transport	LS, WI 53965 , US On Duty Crash RIGHT SIDE (TRAIL Injury Severity NO APPARENT II	N ENGINEER	Driver License Nur STATE: WISCO Safety Equipment SHOULDER & I Helmet Compliance Tint Compliance Airbag NON DEPLOYE Ejection Path NOT EJECTED	AP BELT Country: U AP BELT Country: U	WHITE NITED STATES Trapped/Extricated NOT TRAPPED	
		Address 743 FUR AVE WISCONSIN DEL Equipment Seat Position 3FRONT SEAT-I Helmet Use Eye Protection Injury Ejected NOT EJECTED Medical Transport NOT TRANSPOR	LS, WI 53965 , US On Duty Crash RIGHT SIDE (TRAIL Injury Severity NO APPARENT II	N ENGINEER	Driver License Nur STATE: WISCO Safety Equipment SHOULDER & I Helmet Compliance Tint Compliance Airbag NON DEPLOYE Ejection Path NOT EJECTED/ EMS Agency Ident	AP BELT Country: U AP BELT Country: U	WHITE NITED STATES Trapped/Extricated NOT TRAPPED EMS Run #	
		Address 743 FUR AVE WISCONSIN DEL Equipment Seat Position 3FRONT SEAT-I Helmet Use Eye Protection Injury Ejected NOT EJECTED Medical Transport NOT TRANSPOR	LS, WI 53965 , US On Duty Crash RIGHT SIDE (TRAIL Injury Severity NO APPARENT II	N ENGINEER	Driver License Nur STATE: WISCO Safety Equipment SHOULDER & I Helmet Compliance Tint Compliance Airbag NON DEPLOYE Ejection Path NOT EJECTED/ EMS Agency Ident	AP BELT E NOT APPLICABL ifier	WHITE NITED STATES Trapped/Extricated NOT TRAPPED EMS Run #	To/Erom Coheat
	002	Address 743 FUR AVE WISCONSIN DEL Equipment Seat Position 3FRONT SEAT-I Helmet Use Eye Protection Injury Ejected NOT EJECTED Medical Transport NOT TRANSPOR	LS, WI 53965 , US On Duty Crash RIGHT SIDE (TRAIL Injury Severity NO APPARENT II	N ENGINEER	Driver License Nur STATE: WISCO Safety Equipment SHOULDER & I Helmet Compliance Tint Compliance Airbag NON DEPLOYE Ejection Path NOT EJECTED/ EMS Agency Ident	AP BELT Country: U AP BELT Country: U	WHITE NITED STATES Trapped/Extricated NOT TRAPPED EMS Run #	To/From School

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT **BARABOO, WI 53913** (608) 356-4895

LIND	INDIVIDUAL	Action							
		Action Other							
	L	Orug & Alcohol No	spected Alcohol Use		Suspected Drug Use				
		Alcohol Test Given TEST NOT GIVEN			Alcohol Test Type		Alcohol Tes	t Results	
		Drug Test Given TEST NOT GIVEN			Drug Test Type		Drug Test R	Results	
10	005	Drug Type							
		Individual Condition							
		APPEARED NORMA	L						
	Uni	t Summary =							
	Unit	Status			icle Operating As Classific	ation	Unit Type AUTOMO	DII E	
8		Cle Type			LASS			s Endorsements	
05		SSENGER CAR							
	Tota 1	Occs	Train/Bus # Injured	0	al # Citations Issued	Total Trail	ers Total HazMat Types 0		
–	Insu	ance?	Direction Of Travel EASTBOUND	Pre CrashTire Speed Lim Mark 25		nit Total Lanes 2			
LNO		Harmful Event: Collision V			Special Function NO SPECIAL FUNCTION			Motor Vehicle Use LICABLE	
		ic Way D-WAY, NOT DIVIDED			Traffic Control NO CONTROL Road Curvature STRAIGHT			rol Inoperative/Missing	
	Surfa	асе Туре		Roa)	
		CKTOP (BITUMINOU:	S)	ST					
	NO	N Bus of Flaziviat							
	,	Vehicle							
		License Plate Number 228YEZ			te Type JT - AUTOMOBILE	St WI	Country of Is UNITED ST		
05	05	Vehicle Identification Nun		Ma	ike AZDA	Year 2004	Model MAZDA6I		_
		1YVFP80C045N37744 Color		Во	dy Style	2004	Bus Use NOT A BUS		
	Щ	WHI - WHITE Initial Contact Point 11LEFT FRONT CORNER Extent Of Damage DISABLING DAMAGE			4D - 4DR Vehicle Damage				
LNO	VEHICL			11	11LEFT FRONT CORNER				
	>	Towed Due To Damage TOWED DUE TO DIS			hicle Removed By KES TOWING				
		What Driver Was Doing GOING STRAIGHT			hicle Factors				
		Driver Prior Action Other		NO	OT APPLICABLE				

Crash Date 08/25/2018

Crash Time 12:09 PM

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

=	ICLE	Driver Actions NO CONTRIBUTION	NG ACTION					
LINO	VEHICL							
		Driver Distractions NOT DISTRACTE	D					
05	02							
		Owner Name	NCER		Owner Address	et .		
		JOHN ARIN SPRII (608) 393-6304	NGER		513 LOCUST BARABOO, W			
	:	Sequence Of E	vents					
	6	Event MOTOR VEH IN T	RANSPORT					
	02	Event						
	03	Event						
	40	Event						
_		L Policy Holder						
LIND		Insurance Company ALLSTATE-INS-C	0		Individual JOHN SPRINGER			
	ı	Individual						
		Driver			Citations Issued		Sex	
	7	JOHN ARIN SPRII (608) 393-6304	NGER		0		MALE	
⊨	INDIVIDUAL	(000) 000 000 1			Date of Birth Race WHITE			
	\geq	Address 513 LOCUST ST			Driver License Number			
	Z	BARABOO, WI 53913 , US			STATE: WISCONSIN COUNTRY: UNITED STATES			
		Equipment	On Duty Crash		Safety Equipment			
		Seat Position 1FRONT SEAT-L	FET SIDE (DDIVE	P/MOTOPCY	SHOULDER & LAP BELT			
		Helmet Use	LI I SIDE (DRIVE	I SIMILOTOROT	Helmet Compliance			
		Eye Protection			Tint Compliance			
	က	Injury Severity			Airbag			
05	003	Injury	NO APPARENT I	NJURY	NON DEPLOYE	D		
		Ejected			Ejection Path Trapped/Extricated			
		NOT EJECTED Medical Transport				NOT APPLICABL	NOT TRAPPED EMS Run #	
		NOT TRANSPORT	ΓED		EMS Agency Ident	iiici	LIVIS KUII #	
		Hospital			Date of Death		Time of Death	
		Non Motorist	Striking Unit #	Prior Action	l	Location		To/From School

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 08/25/2018

Crash Time 12:09 PM

LIND	INDIVIDUAL	Action Action Other			
	L	Prug & Alcohol Use NO	Suspected Drug Use NO		
		Alcohol Test Given TEST NOT GIVEN	Alcohol Test Type	Alcohol Test Results	
		Drug Test Given TEST NOT GIVEN	Drug Test Type	Drug Test Results	
02	003	Drug Type			
		Individual Condition			
		APPEARED NORMAL			