18-09575

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT **BARABOO, WI 53913** (608) 356-4895

Document Number Override	Primary Crash I	Document #	Agency 18-095	Crash Number	Investigating Of DEPUTY S. F		
Crash Date 08/29/2018	Crash Time 07:35 PM		Date Arrived 08/29/2018		Time Arrived 07:43 PM		
Date Notified 08/29/2018	Time Notified 07:36 PM		Total U	nits	Total Injured 00	Total Kill	ed
On Emergency Hi	t and Run	Lane Clos	ure	☐ Work Zone	Trailer or	Towed	Reporting Threshold
Government Property	Active Sc	chool Zone	School NO	Bus Related	Tags		
▼ Reportable	Crash Type DT4000 (STA	NDARD CRASH	H)		Amended		Secondary Crash
Description Diagram					I n	econstructio	a Du
		If Course Rd	<u></u>		A	notos By dditional Info ONE	ormation
Ski Hill Rd				Not to Sca	le		
I, a sworn law enforcements on the control of the c	GOLF COURSE I	RD. NUMEROUS F	ROAD IN	THE AREA WERE BEIN	G COVERED BY W		

UP WITH THE OPERATOR DUE TO THE FLOOD. UPON LATER FOLLOWING UP WITH HIM HE STATED THAT HE HAD LEFT A TAVERN IN BARABOO, WI

AND WAS ON HIS WAY HOME. HE WAS ALSO UNABLE TO PROVIDE THE NAME OF HIS INSURANCE COMPANY.

6TL0B3P3DB 18-09575

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Loc	Janon								
_	GOLF COURSE RD				Latitude			Longitude	
701	701 FT N				43.505562105			-89.964151899	
	OF SKI HILL RD IN THE TOWN OF REEDSBURG IN SAUK COUNTY					X Coordinate		Y Coordinate	
						260381.40625		4821228	
IN 3						Туре			
					Oliuolaio	. , po			
Cra	sh Scene								
Firs	t Harmful Event				First Harm	ıful Event I	_ocation		
ОТ	HER NON-COLLISION				ON ROA	DWAY			
Mar	nner of Collision				Light Cond	dition			
NO	COLLISION W/VEHIC	LE IN TRANSPORT			DAYLIGI	HT			
Roa	ad Surface Condition(s)				Roadway	Factor(s)			
WE	:Τ								
Env	rironment Factor(s)								
ОТ	HER				NONE				
Wea	ather Condition(s)								
CL	OUDY								
Anir	mal Type				Relation T		=		
	1.01 '6' '						ON ROAD		
	sh Classification - Location BLIC PROPERTY						- Jurisdiction		
					NO SPECIAL JURISDICTION				
I rib	al Land				Access Control Special Study NO CONTROL				
With	nin Interchange Area	Junction Location		Intersection	ion Type				_
NO	=	=				N INTERSECTION			
				NOI AN	INTERSE	CHON			
Uni	it Summary			NOT AN	INTERSE	CHON			
	it Summary status		Vehicle Ope				Unit Type		
Unit			Vehicle Ope				Unit Type TRUCK		
Unit	t Status		·				TRUCK	s Endorsements	
Unit	t Status TRANSIT		·				TRUCK	s Endorsements	
Unit IN T Veh UTI	t Status TRANSIT sicle Type		·	erating As C	lassification		TRUCK Operating A	s Endorsements Total HazMat Types	
Unit IN T Veh UTI	t Status TRANSIT sicle Type ILITY TRUCK/PICKUP	TRUCK	D CLASS	erating As C	lassification		TRUCK Operating A		
Veh UTI Tota	t Status TRANSIT sicle Type ILITY TRUCK/PICKUP	TRUCK	D CLASS Total # Citat 0	erating As C	lassification	Total Tra	TRUCK Operating A	Total HazMat Types	
Unit IN 7 Veh UTI Tota 2 Insu	t Status TRANSIT sicle Type ILITY TRUCK/PICKUP al Occs	TRUCK Train/Bus # Injured	Total # Citat 0	erating As C	lassification	Total Tra	TRUCK Operating A	Total HazMat Types 0	
Unit IN 7 Veh UTI Tota 2 Insu UN	t Status TRANSIT sicle Type ILITY TRUCK/PICKUP al Occs urance?	TRUCK Train/Bus # Injured Direction Of Travel SOUTHBOUND	Total # Citat 0	erating As C tions Issued CrashTire Mark	lassification	Total Tra 0 Speed Li	TRUCK Operating A illers	Total HazMat Types 0 Total Lanes	
Unit IN 7 Veh UTI Tota 2 Insu UN	t Status TRANSIT iicle Type ILITY TRUCK/PICKUP al Occs urance? KNOWN	TRUCK Train/Bus # Injured Direction Of Travel SOUTHBOUND	Total # Citat 0 Pre	erating As C tions Issued CrashTire Mark ction	lassification	Total Tra 0 Speed Li	TRUCK Operating A illers	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use	
Unit IN 1 Veh UTI Tota 2 Insu UN Mos OTI	t Status TRANSIT iicle Type ILITY TRUCK/PICKUP al Occs urance? KNOWN st Harmful Event: Collision \	TRUCK Train/Bus # Injured Direction Of Travel SOUTHBOUND	Total # Citat 0 Pre	erating As C tions Issued CrashTire Mark ction IAL FUNC	lassification	Total Tra 0 Speed Li	TRUCK Operating A illers mit Emergency NOT APPI	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use	
Unit IN 7 Veh UTI Tota 2 Insu UN Mos OTI	t Status TRANSIT sicle Type ILITY TRUCK/PICKUP al Occs urance? KNOWN st Harmful Event: Collision \ HER NON-COLLISION	TRUCK Train/Bus # Injured Direction Of Travel SOUTHBOUND With	Total # Citat 0 Pre Special Fun NO SPEC	crating As C tions Issued CrashTire Mark ction IAL FUNC	lassification	Total Tra 0 Speed Li	TRUCK Operating A illers mit Emergency NOT APPI	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE	
Unit IN 7 Veh UTI Tota 2 Insu UN Mos OTI Traf	t Status TRANSIT sicle Type ILITY TRUCK/PICKUP al Occs urance? KNOWN st Harmful Event: Collision V HER NON-COLLISION Iffic Way	TRUCK Train/Bus # Injured Direction Of Travel SOUTHBOUND With	Total # Citat 0 Pre Special Fun NO SPEC Traffic Contr	crating As C tions Issued CrashTire Mark ction IAL FUNC	lassification	Total Tra 0 Speed Li	TRUCK Operating A iilers mit Emergency NOT APPI Traffic Control	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE fol Inoperative/Missing	
Unit IN Tota 2 Insu UN Mos OT Traf TW	t Status TRANSIT sicle Type ILITY TRUCK/PICKUP al Occs Jarance? KNOWN st Harmful Event: Collision of the	TRUCK Train/Bus # Injured Direction Of Travel SOUTHBOUND With	Total # Citat 0 Pre (Special Fun NO SPEC Traffic Contr	crating As C tions Issued CrashTire Mark ction IAL FUNC	lassification	Total Tra 0 Speed Li	TRUCK Operating A iilers mit Emergency NOT APPI Traffic Conti	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing	
Unit IN 7 Veh UTI Tota 2 Insu UN Mos OTI Traf TW Surl BL.	t Status TRANSIT iicle Type ILITY TRUCK/PICKUP al Occs Irrance? KNOWN St Harmful Event: Collision V HER NON-COLLISION Iffic Way O-WAY, NOT DIVIDED face Type ACKTOP (BITUMINOU ck Bus or HazMat	TRUCK Train/Bus # Injured Direction Of Travel SOUTHBOUND With	Total # Citat 0 Pre Special Fun NO SPEC Traffic Contr NO CONT Road Curva	crating As C tions Issued CrashTire Mark ction IAL FUNC	lassification	Total Tra 0 Speed Li	TRUCK Operating A iilers mit Emergency NOT APPI Traffic Conti NO Road Grade	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing	
Unit IN Total 2 Insu UN Mos OTI Traf TW Surl BL/	t Status TRANSIT icicle Type ILITY TRUCK/PICKUP al Occs urance? KNOWN St Harmful Event: Collision V HER NON-COLLISION iffic Way O-WAY, NOT DIVIDED face Type ACKTOP (BITUMINOU ck Bus or HazMat	TRUCK Train/Bus # Injured Direction Of Travel SOUTHBOUND With	Total # Citat 0 Pre Special Fun NO SPEC Traffic Contr NO CONT Road Curva	crating As C tions Issued CrashTire Mark ction IAL FUNC	lassification	Total Tra 0 Speed Li	TRUCK Operating A iilers mit Emergency NOT APPI Traffic Conti NO Road Grade	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing	<u> </u>
Unit IN 1 Veh UTI Tota 2 Insu UN Mos OTI Traf TW Surl BLA NO	t Status TRANSIT sicle Type ILITY TRUCK/PICKUP al Occs Jarance? KNOWN st Harmful Event: Collision of the	TRUCK Train/Bus # Injured Direction Of Travel SOUTHBOUND With	Total # Citat 0 Pre Special Fun NO SPEC Traffic Conti NO CONT Road Curva STRAIGH	crating As C CrashTire Mark Ction IAL FUNC rol ROL tture T	lassification	Total Tra 0 Speed Li 45	TRUCK Operating A illers mit Emergency NOT APPI Traffic Conti NO Road Grade DOWNHIL	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE ol Inoperative/Missing	
Unit IN Total 2 Insu UN Mos OTI Traf TW Surl BL/	t Status TRANSIT icle Type ILITY TRUCK/PICKUP al Occs Jarance? KNOWN St Harmful Event: Collision of the collision of t	TRUCK Train/Bus # Injured Direction Of Travel SOUTHBOUND With	Total # Citat 0 Pre Special Fun NO SPEC Traffic Conti NO CONT Road Curva STRAIGH	crating As C CrashTire Mark ction IAL FUNC rol ROL tture T	lassification	Total Tra 0 Speed Li 45	TRUCK Operating A illers mit Emergency NOT APPI Traffic Conti NO Road Grade DOWNHIL	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE Tol Inoperative/Missing	
Unit IN Tota 2 Insu UN Mos OTI Traf Truc NO	t Status TRANSIT sicle Type ILITY TRUCK/PICKUP al Occs Jarance? KNOWN st Harmful Event: Collision of the tenth of the te	TRUCK Train/Bus # Injured Direction Of Travel SOUTHBOUND With	Total # Citat 0 Pre Special Fun NO SPEC Traffic Conti NO CONT Road Curva STRAIGH	crating As C CrashTire Mark ction IAL FUNC rol ROL tture T	lassification	Total Tra 0 Speed Li 45 St WI	TRUCK Operating A illers mit Emergency NOT APPI Traffic Conti NO Road Grade DOWNHIL Country of Is: UNITED ST	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE Tol Inoperative/Missing	
Unit IN Total 2 Insu UN Mos OTI Traf TW Surf BLA	t Status TRANSIT sicle Type ILITY TRUCK/PICKUP al Occs Jarance? KNOWN St Harmful Event: Collision of the thermon-Collision of the thermon-Co	TRUCK Train/Bus # Injured Direction Of Travel SOUTHBOUND With S)	Total # Citat 0 Pre Special Fun NO SPEC Traffic Contr NO CONT Road Curva STRAIGH Plate Type LTK - LIG Make	crating As C crashTire Mark ction IAL FUNC rol ROL ture T	lassification	Total Tra 0 Speed Li 45 St WI Year	TRUCK Operating A illers mit Emergency NOT APPI Traffic Conti NO Road Grade DOWNHIL Country of Is UNITED ST	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing	
Unit IN Total 2 Insu UN Mos OTI Traf TW Surl BL/	t Status TRANSIT sicle Type ILITY TRUCK/PICKUP al Occs Irrance? KNOWN St Harmful Event: Collision V HER NON-COLLISION Iffic Way O-WAY, NOT DIVIDED face Type ACKTOP (BITUMINOU ck Bus or HazMat Vehicle License Plate Number 870175 Vehicle Identification Nur 2GCEK19T02141358	TRUCK Train/Bus # Injured Direction Of Travel SOUTHBOUND With S)	Total # Citat 0 Pre Special Fun NO SPEC Traffic Conti NO CONT Road Curva STRAIGH Plate Type LTK - LIG Make CHEVRO	crating As C tions Issued CrashTire Mark ction IAL FUNC rol ROL ture T	lassification	Total Tra 0 Speed Li 45 St WI	TRUCK Operating A illers mit Emergency NOT APPI Traffic Conte NO Road Grade DOWNHIL Country of Is UNITED ST Model SILVERAD	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing	
Unit IN Total 2 Insu UN Mos OT Traf TW Surf BLA	E Status TRANSIT sicle Type ILITY TRUCK/PICKUP al Occs Irrance? KNOWN St Harmful Event: Collision V HER NON-COLLISION Iffic Way O-WAY, NOT DIVIDED face Type ACKTOP (BITUMINOU ck Bus or HazMat Vehicle License Plate Number 870175 Vehicle Identification Nur 2GCEK19T02141358 Color	TRUCK Train/Bus # Injured Direction Of Travel SOUTHBOUND With S)	Total # Citat 0 Pre Special Fun NO SPEC Traffic Conti NO CONT Road Curva STRAIGH Plate Type LTK - LIG Make CHEVRO Body Style	crating As C tions Issued CrashTire Mark ction IAL FUNC rol ROL iture T	lassification	Total Tra 0 Speed Li 45 St WI Year	TRUCK Operating A illers mit Emergency NOT APPI Traffic Conti NO Road Grade DOWNHIL Country of Is UNITED ST	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing L suance ATES	
Unit IN Total 2 Insu UN Mos OTI Traf TW Surf BL. NO	E Status TRANSIT sicle Type ILITY TRUCK/PICKUP al Occs Jurance? KNOWN St Harmful Event: Collision V HER NON-COLLISION Iffic Way O-WAY, NOT DIVIDED face Type ACKTOP (BITUMINOU ck Bus or HazMat Vehicle License Plate Number 870175 Vehicle Identification Nur 2GCEK19T02141358 Color BLK - BLACK	TRUCK Train/Bus # Injured Direction Of Travel SOUTHBOUND With S)	Total # Citat 0 Pre (Special Fun NO SPEC Traffic Contr NO CONT Road Curva STRAIGH Plate Type LTK - LIG Make CHEVRO Body Style PK - PICK	crating As C tions Issued CrashTire Mark ction IAL FUNC rol ROL iture T	lassification	Total Tra 0 Speed Li 45 St WI Year	TRUCK Operating A illers mit Emergency NOT APPI Traffic Conti NO Road Grade DOWNHIL Country of Is: UNITED S1 Model SILVERAD Bus Use	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing L suance ATES	
Unit IN Tota 2 Insu UN Mos OTI Traf TW Surf BLA NO	t Status TRANSIT icicle Type ILITY TRUCK/PICKUP al Occs Jurance? KNOWN St Harmful Event: Collision Note: Type ACKTOP (BITUMINOU ock Bus or HazMat Vehicle License Plate Number 870175 Vehicle Identification Nur 2GCEK19T02141358 Color BLK - BLACK Initial Contact Point	TRUCK Train/Bus # Injured Direction Of Travel SOUTHBOUND With S)	Total # Citat 0 Pre Special Fun NO SPEC Traffic Conti NO CONT Road Curva STRAIGH Plate Type LTK - LIG Make CHEVRO Body Style	crating As C tions Issued CrashTire Mark ction IAL FUNC rol ROL iture T	lassification	Total Tra 0 Speed Li 45 St WI Year	TRUCK Operating A illers mit Emergency NOT APPI Traffic Conti NO Road Grade DOWNHIL Country of Is: UNITED S1 Model SILVERAD Bus Use	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing L suance ATES	
Unitin Tota 2 Insu UN Mos OTI Traf TW BLA NO	t Status TRANSIT icle Type ILITY TRUCK/PICKUP al Occs Trance? KNOWN St Harmful Event: Collision Not the collision of the	TRUCK Train/Bus # Injured Direction Of Travel SOUTHBOUND With S)	Total # Citat 0 Pre Special Fun NO SPEC Traffic Conti NO CONT Road Curva STRAIGH Plate Type LTK - LIG Make CHEVRO Body Style PK - PICH Vehicle Da	crating As C crashTire Mark ction IAL FUNC rol ROL ture T CHAPT TRUC LET KUP mage	lassification	Total Tra 0 Speed Li 45 St WI Year	TRUCK Operating A illers mit Emergency NOT APPI Traffic Conti NO Road Grade DOWNHIL Country of Is: UNITED S1 Model SILVERAD Bus Use	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing L suance ATES	
Unitin Tota 2 Insu UN Mos OTI Traf TW BLA NO	t Status TRANSIT icicle Type ILITY TRUCK/PICKUP al Occs Jurance? KNOWN St Harmful Event: Collision Note: Type ACKTOP (BITUMINOU ock Bus or HazMat Vehicle License Plate Number 870175 Vehicle Identification Nur 2GCEK19T02141358 Color BLK - BLACK Initial Contact Point	TRUCK Train/Bus # Injured Direction Of Travel SOUTHBOUND With S)	Total # Citat 0 Pre (Special Fun NO SPEC Traffic Contr NO CONT Road Curva STRAIGH Plate Type LTK - LIG Make CHEVRO Body Style PK - PICK	crating As C crashTire Mark ction IAL FUNC rol ROL ture T CHAPT TRUC LET KUP mage	lassification	Total Tra 0 Speed Li 45 St WI Year	TRUCK Operating A illers mit Emergency NOT APPI Traffic Conti NO Road Grade DOWNHIL Country of Is: UNITED S1 Model SILVERAD Bus Use	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing L suance ATES	

Crash Date **08/29/2018**Crash Time **07:35 PM**

18-09575

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT **BARABOO, WI 53913** (608) 356-4895

		Towed Due To Dama	rge FDUE TO DISABLING DAMAG		icle Removed By KES SALVAGE					
		What Driver Was Doi			Vehicle Factors					
		GOING STRAIGH	т							
		Driver Prior Action Other			NOT APPLICABLE					
		Driver Actions								
	щ	OPERATED MOTOR VEHICLE IN AGGRESSIVE/RECKLESS MANNER								
LIND	VEHICL									
5	E									
	>									
		Driver Distractions NOT DISTRACTE	D							
			_							
_	1									
6	01									
		Owner Name	DD CTANI EV		Owner Address					
		MICHAEL RICHAI (608) 525-9046	RD STANLET		E4315A THOMAS RD REEDSBURG, WI 53959, US					
	(33) 323 33 13				,					
		Sequence Of E	vents							
	5 Event OTHER NON-COLLISION									
	02	Event								
		Event								
	03									
	04	Event								
	i	Individual								
		Driver	DD STANI EV		Citations Issued	Sex				
	AL	MICHAEL RICHARD STANLEY (608) 525-9046			Date of Birth	MALE Race				
	DIVIDUAL				Date of Birth	WHITE				
	≥	Address E4315A THOMAS RD REEDSBURG, WI 53959, US			Driver License Number					
ا ر	IND			STATE: WISCONSIN COUNTRY: UNITED STATES						
	_				TATE. MOODHOM GOOMINT. ON	III D GIAILG				
			On Duty Crash	5	Safety Equipment					
		Equipment								
		Seat Position 1FRONT SEAT-LEFT SIDE (DRIVER/MOTORCY		RESTRAINT USE UNKNOWN						
		Helmet Use		Helmet Compliance						
		Eye Protection		Tint Compliance						
5	001	Injury	Injury Severity		Airbag					
٦	0		NO APPARENT INJURY	NON DEPLOYED Figetion Path Trapped/Extricated						
		Ejected NOT EJECTED			ejection Path	Trapped/Extricated NOT TRAPPED				
		Medical Transport			EMS Agency Identifier	EMS Run #				
		EMS GROUND			6001024					

3 of 5

18-09575

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT **BARABOO, WI 53913** (608) 356-4895

		Hospital			Date of Death		Time of Death			
		REEDSBURG ARE	EA MED CTR							
		Non Motorist	Striking Unit #	Prior Action		Location		To/From School		
		Action								
.	UAL									
	INDIVIDUAL									
_										
		Action Other								
	D	rug & Alcohol	Suspected Alcohol U YES	se	Suspected Drug Us NO	e				
		Alcohol Test Given TEST NOT GIVEN			Alcohol Test Type		Alcohol Test Results			
		Drug Test Given TEST NOT GIVEN			Drug Test Type		Drug Test Results			
2	00	Drug Type								
		Individual Condition								
		NOT OBSERVED								
	ا									
	ı	ndividual			Citations Issued		I o			
	إر	Passenger BLANCA LETICIA VILLA (608) 515-9046			Citations Issued 0		Sex FEMALE			
∟l	INDINIDUAL	(000) 313-9040			Date of Birth		Race HISPANIC			
	Ξ	Address E4315A THOMAS	RD		Driver License Number STATE: WISCONSIN COUNTRY: UNITED STATES					
	Z	REEDSBURG, WI								
	Į	Equipment	On Duty Crash		Safety Equipment					
		Seat Position			RESTRAINT USE UNKNOWN					
		2FRONT SEAT-MIDDLE Helmet Use			Helmet Compliance					
		Eye Protection			Tint Compliance					
5	005	Injury	Injury Severity NO APPARENT IN	NJURY	Airbag NON DEPLOYED					
		Ejected NOT EJECTED			Ejection Path NOT EJECTED/I	NOT APPLICABL	Trapped/Extricated NOT TRAPPED			
		Medical Transport EMS GROUND			EMS Agency Identif 6001024	fier	EMS Run #			
		Hospital REEDSBURG ARE	EA MED CTR		Date of Death		Time of Death			
		Non Motorist	Striking Unit #	Prior Action	I	Location		To/From School		

18-09575

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 08/29/2018

Crash Time 07:35 PM

		Action			
	_				
	JAI				
UNIT	ב				
5	\geq				
	INDIVIDUAL				
	_				
		Action Other			
				. 15 11	
	E	Orug & Alcohol NO	NO Suspen	cted Drug Use	
		Alcohol Test Given	Alcoho	l Test Type	Alcohol Test Results
		TEST NOT GIVEN			
		Drug Test Given TEST NOT GIVEN	Drug T	est Type	Drug Test Results
	~ 1				
01	002	Drug Type			
		Individual Condition			
		NOT OBSERVED			