# **6TL0BC3B25**

18-10588

# **WISCONSIN MOTOR VEHICLE CRASH REPORT**

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT **BARABOO, WI 53913** (608) 356-4895

	Document Number Override	Crash Time		Agency Crash Number 18-10588 Date Arrived 09/23/2018		Investigating Officer/Deputy DEPUTY W. VERTEIN  Time Arrived 01:49 PM		
N N	Crash Date <b>09/23/2018</b>							
	Date Notified <b>09/23/2018</b>	Time Notified 01:33 PM		Total Units 01		Total Injured Total Kille 00 00		ed
ם כ	On Emergency Hi	t and Run	Lane Closi		Work Zone		or Towed	Reporting Threshold
	Government Property		chool Zone	NO School	Bus Related	Tags		
	Reportable	Crash Type DT4000 (STANDARD CRASH)				Amend	ed	Secondary Crash
	Description Diagram						Reconstruction	n Bv
	J.a.g.a						T COOLIGIT GOLIO	. 2,
							Photos By	
							Additional Info	rmation
		_						
		N	on-reportable					
	, a sworn law enforcement	ent officer, agr	ee that I have no	ot added	d any CJIS data in th	is report.		
	ON THE DESCRIBED DATE, TIME, AND LOCATION, UNIT 1 WAS TRAVELING EASTBOUND. THE OPERATOR STATED A DEER RAN OUT IN FRONT OF HER AND SHE BRAKED. THE OPERATOR LOST CONTROL OF UNIT 1 AS IT BEGAN TO SLIDE SIDEWAYS. UNIT 1 ENTERED THE NORTHERNMOST DITCH LINE WHERE IT SPUN AROUND AND CAME TO REST IN A CORNFIELD. NO REPORTED INJURIES.							

# 6TL0BC3B25 18-10588

Location

# WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 09/23/2018

Crash Time 01:20 PM

	0.76 OF	LIME RIDGE RD/ CTHK 6 MI E THOMAS RD 7HE TOWN OF IRONTO			<b>43.5199</b> 2 X Coordin	Latitude 43.519921946  X Coordinate 251142.734375		Y Coord	<b>161886</b> inate
		AUK COUNTY						4823161	
					Structure	Гуре			
(	Cra	sh Scene							
1	First	Harmful Event			First Harn	nful Event	Location		
	DIT	CH			ON ROA	DWAY			
		ner of Collision			Light Con				
		COLLISION W/VEHICL	E IN TRANSPORT		DAYLIG				
	Road	d Surface Condition(s)			Roadway Factor(s)				
	DRY	DRY							
	Envi	ronment Factor(s)							
	МОМ	NE			NONE				
	Wea	ther Condition(s)			$\dashv$				
	CLE								
		nal Type			Dal-d- 3	Tac#:-	-		
							•		
		h Classification - Location					sification - Jurisdiction		
PUBLIC PROPERTY  Tribal Land						NO SPECIAL JURISDICTION		Chariel Study	
					Access Control NO CONTROL		Special Study		Special Study
		•	Junction Location		Intersection Type				
	NO		NON-JUNCTION	NOT A	AN INTERSE	CTION			
-	Unit	t Summary 🖚							
_'	Unit Status IN TRANSIT								
j	Unit			Vehicle Operating A	s Classification	1	Unit Type AUTOMO	BILE	
	Unit IN T Vehi	<b>RANSIT</b> cle Type			s Classification	1			ments
	Unit IN T Vehice PAS	RANSIT cle Type SSENGER CAR		D CLASS			AUTOMO Operating A	As Endorser	
	Unit IN T Vehice PAS Total	<b>RANSIT</b> cle Type	Train/Bus # Injured	D CLASS  Total # Citations Issue		Total Tra	AUTOMO Operating A	As Endorser	nents Mat Types
	Unit IN T Vehice PAS Total 2	CRANSIT CIE Type SSENGER CAR	,	D CLASS  Total # Citations Issue 0	ued	Total Tra	AUTOMO Operating A	As Endorser  Total Haz  0	Mat Types
	Unit IN T Vehice PAS Total 2 Insur	RANSIT cle Type SSENGER CAR I Occs rance?	Direction Of Travel	Total # Citations Issu  Pre CrashT	ued	Total Tra  0  Speed L	AUTOMO Operating A	Total Haz  O  Total Lane	Mat Types
_	Unit IN T Vehic PAS Total 2 Insur YES	RANSIT cle Type SSENGER CAR I Occs rance?	Direction Of Travel  EASTBOUND	D CLASS  Total # Citations Issue 0	ued	Total Tra	AUTOMO Operating A	Total Haz  Total Lane  2	Mat Types es
	Unit IN T Vehic PAS Total 2 Insur YES	RANSIT cle Type SSENGER CAR  Cocs rance?  Harmful Event: Collision W	Direction Of Travel  EASTBOUND	Total # Citations Issu 0  Pre CrashT  Mark	ued	Total Tra  0  Speed L	AUTOMO Operating A ailers	Total Haz  0 Total Land 2 Motor Vehi	Mat Types es
	Unit IN T Vehice PAS Total 2 Insur YES Most DIT(	RANSIT cle Type SSENGER CAR  Cocs rance?  Harmful Event: Collision W	Direction Of Travel  EASTBOUND	Total # Citations Isst 0  Pre CrashT  Mark  Special Function	ued	Total Tra  0  Speed L	AUTOMO Operating A ailers imit Emergency	Total Haz  0 Total Land 2 Motor Vehi	Mat Types es cle Use
	Unit IN T Vehic PAS Total 2 Insur YES Most DITC Traff	RANSIT cle Type SSENGER CAR I Occs rance? SHARMFULL EVENT: Collision W. CH ic Way D-WAY, NOT DIVIDED	Direction Of Travel  EASTBOUND	D CLASS  Total # Citations Issu 0  Pre CrashT  Mark  Special Function NO SPECIAL FU  Traffic Control NO CONTROL	ued	Total Tra  0  Speed L	AUTOMO Operating A ailers imit Emergency NOT APP Traffic Cont	Total Haz  0 Total Land 2 Motor Vehi LICABLE	Mat Types es cle Use
	Vehice PAS Total 2 Insur YES Most DITC Surfa	RANSIT  Cle Type  SSENGER CAR  I Occs  Tance?  Harmful Event: Collision W  CH  ic Way  D-WAY, NOT DIVIDED  ace Type	Direction Of Travel  EASTBOUND  //tth	D CLASS  Total # Citations Issu  Pre CrashT  Mark  Special Function NO SPECIAL FU  Traffic Control NO CONTROL  Road Curvature	ued	Total Tra  0  Speed L	AUTOMO Operating A ailers imit Emergency NOT APP Traffic Cont NO Road Grade	Total Haz  0 Total Lane 2 Motor Vehi LICABLE	Mat Types es cle Use
	Unit IN T Vehice PAS Total 2 Insur YES Most DITC Traff TWC Surfa BLA	RANSIT cle Type SSENGER CAR I Occs rance? SHarmful Event: Collision W CH ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS	Direction Of Travel  EASTBOUND  //tth	D CLASS  Total # Citations Issu 0  Pre CrashT  Mark  Special Function NO SPECIAL FU  Traffic Control NO CONTROL	ued	Total Tra  0  Speed L	AUTOMO Operating A ailers imit Emergency NOT APP Traffic Cont	Total Haz  0 Total Lane 2 Motor Vehi LICABLE	Mat Types es cle Use
	Unit IN T Vehice PAS Total 2 Insur YES Most DITC Traff TWC Surfa BLA	RANSIT  Cle Type  SSENGER CAR  I Occs  Tance?  Harmful Event: Collision W  CH  ic Way  D-WAY, NOT DIVIDED  ace Type	Direction Of Travel  EASTBOUND  //tth	D CLASS  Total # Citations Issu  Pre CrashT  Mark  Special Function NO SPECIAL FU  Traffic Control NO CONTROL  Road Curvature	ued	Total Tra  0  Speed L	AUTOMO Operating A ailers imit Emergency NOT APP Traffic Cont NO Road Grade	Total Haz  0 Total Lane 2 Motor Vehi LICABLE	Mat Types es cle Use
	Unit IN T Vehin PAS Total 2 Insur YES Most DITC Traff TWC Surfa BLA Truck	RANSIT cle Type SSENGER CAR  COCS  rance? S Harmful Event: Collision W CH ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS k Bus or HazMat	Direction Of Travel  EASTBOUND  //tth	D CLASS  Total # Citations Issue 0  Pre CrashT  Mark  Special Function  NO SPECIAL FU  Traffic Control  NO CONTROL  Road Curvature  STRAIGHT	ued	Total Tra  0 Speed L  55	AUTOMO Operating A ailers imit Emergency NOT APP Traffic Cont NO Road Grade DOWNHII	Total Haz 0 Total Land 2 Motor Vehi LICABLE crol Inoperat	Mat Types es cle Use
	Unit IN T Vehin PAS Total 2 Insur YES Most DITC Traff TWC Surfa BLA Truck	RANSIT cle Type SSENGER CAR  Cocs rance? Stance? Stance Type CH ic Way CH ic Way CH ace Type ACKTOP (BITUMINOUS Ik Bus or HazMat  Vehicle License Plate Number	Direction Of Travel  EASTBOUND  //tth	D CLASS  Total # Citations Issue 0  Pre CrashT  Mark  Special Function  NO SPECIAL FU  Traffic Control  NO CONTROL  Road Curvature  STRAIGHT	ued Tire NCTION	Total Tra 0 Speed L 55	AUTOMO Operating A silers imit  Emergency NOT APP Traffic Cont NO Road Grade DOWNHII	Total Haz  0 Total Lane 2 Motor Vehi LICABLE crol Inoperat	Mat Types es cle Use
	Unit IN T Vehin PAS Total 2 Insur YES Most DITC Traff TWC Surfa BLA Truck	RANSIT  cle Type  SSENGER CAR  I Occs  rance?  I Harmful Event: Collision W.  CH  ic Way  D-WAY, NOT DIVIDED  ace Type  ACKTOP (BITUMINOUS  k Bus or HazMat  Vehicle  License Plate Number  P7119G	Direction Of Travel EASTBOUND  //ith	D CLASS  Total # Citations Isst 0  Pre CrashT  Mark  Special Function  NO SPECIAL FU  Traffic Control  NO CONTROL  Road Curvature  STRAIGHT  Plate Type  AUT - AUTOMO	ued Tire NCTION	Total Tra 0 Speed L 55	AUTOMO Operating A ailers imit Emergency NOT APP Traffic Cont NO Road Grade DOWNHII  Country of Is UNITED S	Total Haz  0 Total Lane 2 Motor Vehi LICABLE crol Inoperat	Mat Types es cle Use
	Unit IN T Vehic PAS Total 2 Insur YES Most DITC Traff TWC Surfaß BLA Truck	RANSIT  cle Type  SSENGER CAR  l Occs  rance?  t Harmful Event: Collision W.  CH  ic Way  D-WAY, NOT DIVIDED  ace Type  ACKTOP (BITUMINOUS  k Bus or HazMat  Vehicle  License Plate Number  P7119G  Vehicle Identification Num	Direction Of Travel EASTBOUND  Jith	D CLASS  Total # Citations Isst 0  Pre CrashT  Mark  Special Function  NO SPECIAL FU  Traffic Control  NO CONTROL  Road Curvature  STRAIGHT  Plate Type  AUT - AUTOMO  Make	ued Tire NCTION	Total Tra 0 Speed L 55	AUTOMO Operating A ailers imit  Emergency NOT APP Traffic Cont NO Road Grade DOWNHII  Country of Is UNITED S	Total Haz  0 Total Lane 2 Motor Vehi LICABLE crol Inoperat	Mat Types es cle Use
	Unit IN T Vehin PAS Total 2 Insur YES Most DITC Traff TWC Surfa BLA Truck	RANSIT cle Type SSENGER CAR I Occs rance? CH ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS k Bus or HazMat  Vehicle License Plate Number P7119G Vehicle Identification Num 2G1FP32P7R2178574	Direction Of Travel EASTBOUND  Jith	Total # Citations Isst 0  Pre CrashT  Mark  Special Function  NO SPECIAL FU  Traffic Control  NO CONTROL  Road Curvature  STRAIGHT  Plate Type  AUT - AUTOMO  Make  CHEVROLET	ued Tire NCTION	Total Tra 0 Speed L 55	AUTOMO Operating A ailers imit Emergency NOT APP Traffic Cont NO Road Grade DOWNHII  Country of Is UNITED S	Total Haz  0 Total Lane 2 Motor Vehi LICABLE crol Inoperat	Mat Types es cle Use
	Unit IN T Vehic PAS Total 2 Insur YES Most DITC Traff TWC Surfaß BLA Truck	RANSIT  cle Type  SSENGER CAR  l Occs  rance?  t Harmful Event: Collision W.  CH  ic Way  D-WAY, NOT DIVIDED  ace Type  ACKTOP (BITUMINOUS  k Bus or HazMat  Vehicle  License Plate Number  P7119G  Vehicle Identification Num	Direction Of Travel EASTBOUND  Jith	D CLASS  Total # Citations Isst 0  Pre CrashT  Mark  Special Function  NO SPECIAL FU  Traffic Control  NO CONTROL  Road Curvature  STRAIGHT  Plate Type  AUT - AUTOMO  Make	ued  Tire  NCTION	Total Tra 0 Speed L 55	AUTOMO Operating A ailers imit Emergency NOT APP Traffic Cont NO Road Grade DOWNHII  Country of Is UNITED S' Model CAMARO	Total Haz  O Total Lane 2 Motor Vehi LICABLE  Include Inoperate  L  Ssuance TATES	Mat Types es cle Use
	Unit IN T Vehic PASS Total 2 Insur YES DITC Traff TWC Surfa BLA Truck NO	RANSIT cle Type SSENGER CAR I Occs rance? SHarmful Event: Collision W. CH ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS IK Bus or HazMat Vehicle License Plate Number P7119G Vehicle Identification Num 2G1FP32P7R2178574 Color	Direction Of Travel EASTBOUND  Jith	Total # Citations Isst 0  Pre CrashT  Mark  Special Function  NO SPECIAL FU  Traffic Control  NO CONTROL  Road Curvature  STRAIGHT  Plate Type  AUT - AUTOMO  Make  CHEVROLET  Body Style	ued  Tire  NCTION	Total Tra 0 Speed L 55	AUTOMO Operating A ailers imit  Emergency NOT APP Traffic Cont NO Road Grade DOWNHII  Country of Is UNITED S' Model CAMARO Bus Use	Total Haz  O Total Lane 2 Motor Vehi LICABLE  Include Inoperate  L  Ssuance TATES	Mat Types es cle Use
	Unit IN T Vehic PASS Total 2 Insur YES DITC Traff TWC Surfa BLA Truck NO	RANSIT  cle Type  SSENGER CAR  l Occs  rance?  the Harmful Event: Collision W  CH  ic Way  D-WAY, NOT DIVIDED  ace Type  ACKTOP (BITUMINOUS  k Bus or HazMat  Vehicle  License Plate Number  P7119G  Vehicle Identification Num  2G1FP32P7R2178574  Color  RED - RED  Initial Contact Point  6REAR	Direction Of Travel EASTBOUND  Jith	Total # Citations Isst 0  Pre CrashT  Mark  Special Function  NO SPECIAL FU  Traffic Control  NO CONTROL  Road Curvature  STRAIGHT   Plate Type  AUT - AUTOMO  Make  CHEVROLET  Body Style  CV - CONVERTI  Vehicle Damage	ued  Tire  NCTION	Total Tra 0 Speed L 55	AUTOMO Operating A ailers imit  Emergency NOT APP Traffic Cont NO Road Grade DOWNHII  Country of Is UNITED S' Model CAMARO Bus Use	Total Haz  O Total Lane 2 Motor Vehi LICABLE  Include Inoperate  L  Ssuance TATES	Mat Types es cle Use
	Unit IN T Vehice PAS Total 2 Insur YES Most DITC Traff TWC Surfa BLA Truck NO	RANSIT  cle Type  SSENGER CAR  l Occs  rance?  tharmful Event: Collision W  CH  ic Way  D-WAY, NOT DIVIDED  ace Type  ACKTOP (BITUMINOUS  k Bus or HazMat  Vehicle  License Plate Number  P7119G  Vehicle Identification Num  2G1FP32P7R2178574  Color  RED - RED  Initial Contact Point	Direction Of Travel EASTBOUND  Jith	Total # Citations Isst 0  Pre CrashT  Mark  Special Function  NO SPECIAL FU  Traffic Control  NO CONTROL  Road Curvature  STRAIGHT  Plate Type  AUT - AUTOMO  Make  CHEVROLET  Body Style  CV - CONVERTI	ued  Tire  NCTION	Total Tra 0 Speed L 55	AUTOMO Operating A ailers imit  Emergency NOT APP Traffic Cont NO Road Grade DOWNHII  Country of Is UNITED S' Model CAMARO Bus Use	Total Haz  O Total Lane 2 Motor Vehi LICABLE  Include Inoperate  L  Ssuance TATES	Mat Types es cle Use

#### **6TL0BC3B25**

18-10588

# WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

		Towed Due To Dama		Vehicle Removed By OPERATOR					
		TOWED BUT NOT DUE TO DISABLING DAMAG What Driver Was Doing		Vehicle Factors					
		GOING STRAIGHT		VOLIDO I GOLDIS					
		Driver Prior Action Of		NOT APPLICABLE					
		Driver Actions	ITROL DAN OFF DOADWAY	1					
.	LE	FAILURE TO COM	NTROL, RAN OFF ROADWAY						
E N	<u> </u>								
5	VEHICL								
	>								
		Driver Distractions							
		NOT DISTRACTE	D						
_	1								
2	01								
		Owner Name		Owner Address					
		DEBORAH ANN N	MEISTER	325 S GROVE ST # 31					
		(608) 434-1134		REEDSBURG, WI 53959 , US					
		Sequence Of E	vents						
	01	Event							
	0	CROSS CENTERI	IEKLINE						
	02	Event RUN OFF ROADWAY LEFT							
	Event								
	S Event DITCH								
	04	Event							
		Policy Holder							
LNO		Insurance Company							
⊃		PROGRESSIVE-A	ADVANCED-INSURANCE-CO	DEBORAH MEISTER					
	[	ndividual							
		Driver		Citations Issued	Sex				
	ب	DEBORAH ANN MEISTER (608) 434-1134		0	FEMALE				
	INDIVIDUA			Date of Birth	Race WHITE				
LNO	ΠD				WITTE				
5		Address 325 S GROVE ST	# 31	Driver License Number					
	Z	REEDSBURG, WI 53959 , US		STATE: WISCONSIN COUNTRY: UNITED STATES					
			On Duty Crash	Safety Equipment					
		Equipment							
		Seat Position		SHOULDER & LAP BELT					
		1FRONT SEAT-LEFT SIDE (DRIVER/MOTORCY							
		Helmet Use		Helmet Compliance					
		Eye Protection		Tint Compliance					
		,		Compiano					
_	001	la inserio	Injury Severity	Airbag					
6	ŏ	Injury	NO APPARENT INJURY	NON DEPLOYED					
		Ejected		Ejection Path Trapped/Extricated					
		NOT EJECTED		NOT EJECTED/NOT APPLICABL	NOT TRAPPED				

# 6TL0BC3B25 18-10588

# **WISCONSIN MOTOR VEHICLE CRASH REPORT**

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT **BARABOO, WI 53913** (608) 356-4895

		Medical Transport			EMS Agency Identifier		EMS Run #			
		NOT TRANSPOR	TED							
		Hospital			Date of Death		Time of Death			
			Striking Unit #	Prior Action		Location		To/From School		
		Non Motorist								
		Action								
		7.00011								
	_									
	INDIVIDUAL									
⊢∣	$\geq$									
LINO	Ħ									
⊃∣	$\leq$									
	Ħ									
	_									
		Action Other								
		/ totion other								
			I Commented Alaskall	1	I Commented Describ					
	Г	Drug & Alcohol NO			Suspected Drug U:	se				
			INO		NO Alcohol Test Type Alcohol Test Results					
		Alcohol Test Given			Alcohol Test Type					
		TEST NOT GIVEN	l							
		Drug Test Given			Drug Test Type		Drug Test Results			
		TEST NOT GIVEN	l							
	_	Drug Type								
6	00	Diag Type								
	J									
		Individual Condition								
		Individual Condition								
		APPEARED NOR	MAL							
		Individual								
		JOHN L CASTILE	:							
	7	(608) 434-1134			0 MALE					
	INDIVIDUAL	(000) 101 1101			Date of Birth Race WHITE					
╘	₽									
LNO	≥	Address			Driver License Nur	nber				
ر ر	무		N406 COUNTY ROAD N							
	=	WISCONSIN DELLS, WI 53965, US			STATE: WISCONSIN COUNTRY: UNITED STATES					
					STATE: WISCO	NSIN COUNTRY: U	NITED STATES			
			_0, 00000 , 00		STATE: WISCO	NSIN COUNTRY: U	NITED STATES			
						NSIN COUNTRY: U	NITED STATES			
		Equipment	On Duty Crash		Safety Equipment	NSIN COUNTRY: U	NITED STATES			
					Safety Equipment		NITED STATES			
		Seat Position	On Duty Crash				NITED STATES			
		Seat Position 3FRONT SEAT-I			Safety Equipment SHOULDER & L	AP BELT	NITED STATES			
		Seat Position	On Duty Crash		Safety Equipment	AP BELT	NITED STATES			
		Seat Position 3FRONT SEAT-I	On Duty Crash		Safety Equipment SHOULDER & L	AP BELT	NITED STATES			
		Seat Position 3FRONT SEAT-I	On Duty Crash		Safety Equipment SHOULDER & L	AP BELT	NITED STATES			
		Seat Position 3FRONT SEAT-I Helmet Use	On Duty Crash		Safety Equipment SHOULDER & L  Helmet Compliance	AP BELT	NITED STATES			
_	2	Seat Position 3FRONT SEAT-I Helmet Use Eye Protection	On Duty Crash		Safety Equipment SHOULDER & L  Helmet Compliance	AP BELT	NITED STATES			
01	002	Seat Position 3FRONT SEAT-I Helmet Use	On Duty Crash  RIGHT SIDE (TRAI	N ENGINEER	Safety Equipment  SHOULDER & L  Helmet Compliance  Tint Compliance	AP BELT	NITED STATES			
01	002	Seat Position 3FRONT SEAT-I Helmet Use Eye Protection	On Duty Crash  RIGHT SIDE (TRAI	N ENGINEER	Safety Equipment SHOULDER & L Helmet Compliance Tint Compliance Airbag NON DEPLOYE	AP BELT				
01	002	Seat Position 3FRONT SEAT-I Helmet Use Eye Protection  Injury Ejected	On Duty Crash  RIGHT SIDE (TRAI	N ENGINEER	Safety Equipment  SHOULDER & L  Helmet Compliance  Tint Compliance  Airbag  NON DEPLOYE  Ejection Path	AP BELT	Trapped/Extricated			
10	002	Seat Position 3FRONT SEAT-I Helmet Use Eye Protection  Injury  Ejected NOT EJECTED	On Duty Crash  RIGHT SIDE (TRAI	N ENGINEER	Safety Equipment SHOULDER & L Helmet Compliance Tint Compliance Airbag NON DEPLOYE Ejection Path NOT EJECTED/	AP BELT  D  NOT APPLICABL	Trapped/Extricated NOT TRAPPED			
01	000	Seat Position 3FRONT SEAT-I Helmet Use Eye Protection  Injury  Ejected NOT EJECTED  Medical Transport	On Duty Crash  RIGHT SIDE (TRAI	N ENGINEER	Safety Equipment  SHOULDER & L  Helmet Compliance  Tint Compliance  Airbag  NON DEPLOYE  Ejection Path	AP BELT  D  NOT APPLICABL	Trapped/Extricated			
10	002	Seat Position 3FRONT SEAT-I Helmet Use Eye Protection  Injury  Ejected NOT EJECTED	On Duty Crash  RIGHT SIDE (TRAI	N ENGINEER	Safety Equipment SHOULDER & L Helmet Compliance Tint Compliance Airbag NON DEPLOYE Ejection Path NOT EJECTED/	AP BELT  D  NOT APPLICABL	Trapped/Extricated NOT TRAPPED			
01	002	Seat Position 3FRONT SEAT-I Helmet Use Eye Protection  Injury  Ejected NOT EJECTED  Medical Transport	On Duty Crash  RIGHT SIDE (TRAI	N ENGINEER	Safety Equipment SHOULDER & L Helmet Compliance Tint Compliance Airbag NON DEPLOYE Ejection Path NOT EJECTED/	AP BELT  D  NOT APPLICABL	Trapped/Extricated NOT TRAPPED			
01	002	Seat Position 3FRONT SEAT-I Helmet Use Eye Protection  Injury  Ejected NOT EJECTED  Medical Transport NOT TRANSPOR	On Duty Crash  RIGHT SIDE (TRAI	N ENGINEER	Safety Equipment  SHOULDER & L  Helmet Compliance  Tint Compliance  Airbag  NON DEPLOYE  Ejection Path  NOT EJECTED/  EMS Agency Ident	AP BELT  D  NOT APPLICABL	Trapped/Extricated NOT TRAPPED EMS Run #			
01		Seat Position 3FRONT SEAT-I Helmet Use Eye Protection  Injury  Ejected NOT EJECTED  Medical Transport NOT TRANSPOR' Hospital	On Duty Crash  RIGHT SIDE (TRAI	N ENGINEER	Safety Equipment  SHOULDER & L  Helmet Compliance  Tint Compliance  Airbag  NON DEPLOYE  Ejection Path  NOT EJECTED/  EMS Agency Ident	AP BELT  D  NOT APPLICABL	Trapped/Extricated NOT TRAPPED EMS Run #	To/From School		
01		Seat Position 3FRONT SEAT-I Helmet Use Eye Protection  Injury  Ejected NOT EJECTED  Medical Transport NOT TRANSPOR	On Duty Crash  RIGHT SIDE (TRAI	N ENGINEER NJURY	Safety Equipment  SHOULDER & L  Helmet Compliance  Tint Compliance  Airbag  NON DEPLOYE  Ejection Path  NOT EJECTED/  EMS Agency Ident	AP BELT  D  NOT APPLICABL	Trapped/Extricated NOT TRAPPED EMS Run #	To/From School		

# **6TL0BC3B25**

18-10588

SAUK COUNTY SHERIFFS DEPARTMEN **WISCONSIN MOTOR VEHICLE** 1300 LANGE COURT **CRASH REPORT BARABOO, WI 53913** (608) 356-4895

						. ,		
		Action						
UNIT	JAI .							
		Action Other						
	E	Prug & Alcoh	Suspected Alcohol Use NO	Suspected Drug Use NO				
		Alcohol Test Given TEST NOT GIVEN		Alcohol Test Type	Alcohol Test Results			
		Drug Test Given TEST NOT GIVEN		Drug Test Type	Drug Test Results			
10	005	Drug Type						
		Individual Condition						
		APPEARED NORMAL						
		perty Owne	r					
PROP OWNER 01	Indiv GEF (608	idual RALD D WHITE ) 434-1995		Address S3175 WHITE RD REEDSBURG, WI 53959, US				
	Fixed Objects Struck							
	Striking Unit Struck Object OTHER FIXED OBJECT				Structure Number	Damage Tag Number N/A		
	Pro	roperty Owner						
PROP 02 OWNER	Government TOWNSHIP OF IRONTON Addit E46			Address E4685 PICKEL RD REEDSBURG, WI 53959, US				
	Fixe	d Objects St						
	05	Striking Unit  01	Struck Object DITCH		Structure Number	Damage Tag Number N/A		

Crash Date 09/23/2018

Crash Time 01:20 PM