
6TL096J8XL

18-12131

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895



Crash Date **10/31/2018** Crash Time **08:52 PM** 18-12131

WISCONSIN MOTOR VEHICLE CRASH REPORT

| | | ation | | | | _ | | | | | |
|---|---|--|--|---|--|---|---|--|---|--|--|
| | - | ON USH12 EB | | | | | Latitude Longitude | | | | |
| | | 323 FT W | | | | 43.435230869 -89. | | | -89.774689686 | | |
| | | OF SKILLET CREEK RD | | | | X Coordinate Y Coord | | | Y Coordinate | | |
| | | IN THE TOWN OF BARABOO IN SAUK COUNTY | | | | 275437.5 | | 4812888.5 | | | |
| | IN 3 | BAUK COUNTY | | | | Structure - | Туре | | | | |
| | | | | | | | Structure Type NO STRUCTURE | | | | |
| (| Cra | sh Scene | | | | | | | | | |
| Τ | First | Harmful Event | | | | First Harm | nful Event L | ocation | | | |
| | отн | HER TRAFFIC BARRIE | ER | | | ON ROA | DWAY | | | | |
| F | Man | ner of Collision | | | | Light Cond | dition | | | | |
| | NO | COLLISION W/VEHICI | LE IN TRANSPORT | | | DARK/U | NLIT | | | | |
| F | Road | d Surface Condition(s) | | | | Roadway | Factor(s) | | | | |
| | DR | | | | | | | | | | |
| - | Envi | ronment Factor(s) | | | | | | | | | |
| | NO | NE | | | | NONE | | | | | |
| F | Wea | ther Condition(s) | | | | | | | | | |
| | CLE | EAR | | | | | | | | | |
| - | Animal Type | | | | Relation To Trafficway | | | - | | | |
| - | Cras | sh Classification - Location | | | | | CWAY - C | | | | |
| | PUE | PUBLIC PROPERTY | | | | Crash Classification - Jurisdiction NO SPECIAL JURISDICTION | | | | | |
| | Tribal Land | | | | Access Control Special Study NO CONTROL | | | | | | |
| - | With | in Interchange Area | Junction Location | | Intersectio | | | | | | |
| | | in inclonange / iou | 5 | | | | INTERSECTION | | | | |
| | | | | | | | | | | | |
| l | Jni | t Summary 🛛 💻 | | | | | | | | | |
| | | t Summary Status | | Vehicle Ope | erating As Cl | lassification | | Unit Type | | | |
| | Unit | | | Vehicle Ope | erating As Cl | lassification | | Unit Type AUTOMOI | BILE | | |
| | Unit IN T | Status | | | erating As Cl | lassification | | AUTOMO | BILE s Endorsements | | |
| | Unit IN T Vehi | Status RANSIT | | | erating As Cl | lassification | | AUTOMO | | | |
| ; | Unit IN T Vehi PAS | Status RANSIT icle Type | Train/Bus # Injured | | | | Total Tra | AUTOMOI Operating A | | | |
| ; | Unit IN T Vehi PAS | Status RANSIT icle Type SSENGER VAN | Train/Bus # Injured | D CLASS | | | | AUTOMOI Operating A | s Endorsements | | |
| 5 | Unit IN T Vehi PAS Tota 1 | Status RANSIT icle Type SSENGER VAN | Train/Bus # Injured | D CLASS | tions Issued | | Total Tra | AUTOMOI Operating A lers | s Endorsements | | |
| ; | Unit IN T Vehi PAS Tota 1 Insu | Status RANSIT icle Type SSENGER VAN I Occs | | D CLASS | | | Total Tra | AUTOMOI Operating A lers | s Endorsements Total HazMat Types | | |
| ; | Unit IN T Vehi PAS Tota 1 Insur UNI | Status RANSIT icle Type SSENGER VAN I Occs rance? | Direction Of Travel | D CLASS | tions Issued CrashTire Mark ction | | Total Tra | AUTOMOI Operating A lers nit Emergency | s Endorsements Total HazMat Types Total Lanes 2 Motor Vehicle Use | | |
| | Unit IN T Vehi PAS Tota 1 Insur UNI Most | Status RANSIT Icle Type SSENGER VAN I Occs rance? KNOWN | Direction Of Travel SOUTHBOUND | D CLASS | tions Issued CrashTire Mark ction | | Total Tra | AUTOMOI Operating A lers nit | s Endorsements Total HazMat Types Total Lanes 2 Motor Vehicle Use | | |
| | Unit IN T Vehi PAS Tota 1 Insur UNP Most PAF | Status RANSIT Icle Type SSENGER VAN I Occs rance? KNOWN t Harmful Event: Collision N | Direction Of Travel SOUTHBOUND | D CLASS | tions Issued CrashTire Mark ction IAL FUNC | | Total Tra | AUTOMOI Operating A lers mit Emergency NOT APPI | s Endorsements Total HazMat Types Total Lanes 2 Motor Vehicle Use | | |
| | Unit IN T Vehi PAS Tota 1 Insui UNI Most PAF Traff | Status RANSIT icle Type SSENGER VAN I Occs rance? KNOWN t Harmful Event: Collision N RKED MOTOR VEHICL fic Way D-WAY, NOT DIVIDED | Direction Of Travel SOUTHBOUND With E | D CLASS | tions Issued CrashTire Mark ction IAL FUNC rol ROL | | Total Tra | AUTOMOI Operating A lers nit Emergency NOT APPI Traffic Contr NO | s Endorsements Total HazMat Types Total Lanes 2 Motor Vehicle Use ICABLE ol Inoperative/Missing | | |
| | Unit IN T Vehi PAS Tota 1 Insur UNP Most PAF Traff Two Surfa | Status RANSIT icle Type SSENGER VAN I Occs rance? KNOWN t Harmful Event: Collision V RKED MOTOR VEHICL fic Way D-WAY, NOT DIVIDED ace Type | Direction Of Travel SOUTHBOUND With E | D CLASS | tions Issued CrashTire Mark ction IAL FUNC rol ROL ture | | Total Tra | AUTOMOI Operating A lers nit Emergency NOT APPI Traffic Contr NO Road Grade | s Endorsements Total HazMat Types Total Lanes 2 Motor Vehicle Use ICABLE ol Inoperative/Missing | | |
| | Unit IN T Vehi PAS Tota 1 Insur UNP Traff Traff Surfa BLA | Status RANSIT icle Type SSENGER VAN I Occs rance? KNOWN t Harmful Event: Collision N RKED MOTOR VEHICL fic Way D-WAY, NOT DIVIDED | Direction Of Travel SOUTHBOUND With E | D CLASS | tions Issued CrashTire Mark ction IAL FUNC rol ROL ture | | Total Tra | AUTOMOI Operating A lers nit Emergency NOT APPI Traffic Contr NO | s Endorsements Total HazMat Types Total Lanes 2 Motor Vehicle Use ICABLE ol Inoperative/Missing | | |
| | Unit IN T Vehi PAS Tota 1 Insur UNH Most PAF Traff Surfa BLA Truc NO | Status RANSIT icle Type SSENGER VAN I Occs rance? KNOWN t Harmful Event: Collision N RKED MOTOR VEHICL fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS ik Bus or HazMat | Direction Of Travel SOUTHBOUND With E | D CLASS | tions Issued CrashTire Mark ction IAL FUNC rol ROL ture | | Total Tra | AUTOMOI Operating A lers nit Emergency NOT APPI Traffic Contr NO Road Grade | s Endorsements Total HazMat Types Total Lanes 2 Motor Vehicle Use ICABLE ol Inoperative/Missing | | |
| | Unit IN T Vehi PAS Tota 1 Insur UNH Most PAF Traff Surfa BLA Truc NO | Status RANSIT icle Type SSENGER VAN I Occs rance? KNOWN t Harmful Event: Collision N RKED MOTOR VEHICL fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS ik Bus or HazMat Vehicle | Direction Of Travel SOUTHBOUND With E | D CLASS | tions Issued CrashTire Mark ction IAL FUNC rol ROL iture T | | Total Trai 0 Speed Lii | AUTOMOI Operating A lers mit Emergency NOT APPI Traffic Contr NO Road Grade LEVEL | s Endorsements Total HazMat Types Total Lanes 2 Motor Vehicle Use ICABLE ol Inoperative/Missing | | |
| | Unit IN T Vehi PAS Tota 1 Insur UNH Most PAF Traff Surfa BLA Truc NO | Status RANSIT icle Type SSENGER VAN I Occs rance? KNOWN t Harmful Event: Collision N RKED MOTOR VEHICL fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS ik Bus or HazMat | Direction Of Travel SOUTHBOUND With E | D CLASS | tions Issued CrashTire Mark ction IAL FUNC rol ROL iture T | TION | Total Tra | AUTOMOI Operating A lers nit Emergency NOT APPI Traffic Contr NO Road Grade | s Endorsements Total HazMat Types Total Lanes 2 Motor Vehicle Use ICABLE ol Inoperative/Missing suance | | |
| | Unit IN T Vehi PAS Tota 1 Insui UNI Most Traff Traff Truc Surfa Surfa | Status RANSIT icle Type SSENGER VAN I Occs rance? KNOWN t Harmful Event: Collision V RED MOTOR VEHICL fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS ik Bus or HazMat Vehicle License Plate Number 593BEF Vehicle Identification Nur | birection Of Travel SOUTHBOUND With E S) | D CLASS | tions Issued CrashTire Mark ction IAL FUNC rol ROL ture T | TION | Total Tra 0 Speed Lin St WI Year | AUTOMOI Operating A lers nit Emergency NOT APPI Traffic Conti NO Road Grade LEVEL | s Endorsements Total HazMat Types Total Lanes 2 Motor Vehicle Use ICABLE ol Inoperative/Missing suance FATES | | |
| | Unit IN T Vehi PAS Tota 1 Insur UNH Most PAF Traff Surfa BLA Truc NO | Status RANSIT icle Type SSENGER VAN I Occs rance? KNOWN t Harmful Event: Collision N RKED MOTOR VEHICL fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS k Bus or HazMat Vehicle License Plate Number 593BEF Vehicle Identification Nur 1GHDX03E71D27368 | birection Of Travel SOUTHBOUND With E S) | D CLASS | tions Issued CrashTire Mark ction IAL FUNC rol ROL tture T | TION | Total Tra 0 Speed Lin St WI | AUTOMOI Operating A lers nit Emergency NOT APPI Traffic Contr NO Road Grade LEVEL Country of Is UNITED ST Model SILHOUET | s Endorsements Total HazMat Types Total Lanes 2 Motor Vehicle Use ICABLE ol Inoperative/Missing suance FATES | | |
| | Unit IN T Vehi PAS Tota 1 Insui UNI Most Traff Traff Truc Surfa Surfa | Status RANSIT icle Type SSENGER VAN I Occs rance? KNOWN t Harmful Event: Collision V RED MOTOR VEHICL fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS ik Bus or HazMat Vehicle License Plate Number 593BEF Vehicle Identification Nur | birection Of Travel SOUTHBOUND With E S) | D CLASS | tions Issued CrashTire Mark ction IAL FUNC rol ROL tture T | TION | Total Tra 0 Speed Lin St WI Year | AUTOMOI Operating A lers nit Emergency NOT APPI Traffic Conti NO Road Grade LEVEL | s Endorsements Total HazMat Types Total Lanes 2 Motor Vehicle Use ICABLE ol Inoperative/Missing suance ATES TE | | |
| | Unit IN T Vehi PAS Tota 1 Insur UNI Most PAF Traff TWC Surfa BLA Truc NO | Status RANSIT Cele Type SSENGER VAN I Occs rance? KNOWN t Harmful Event: Collision N RKED MOTOR VEHICL fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS k Bus or HazMat Vehicle License Plate Number 593BEF Vehicle Identification Nur 1GHDX03E71D27368 Color TAN - TAN Initial Contact Point | birection Of Travel SOUTHBOUND With E S) | D CLASS | tions Issued CrashTire Mark Ction IAL FUNC rol ROL Iture T ITOMOBIL DBILE I | TION | Total Tra 0 Speed Lin St WI Year | AUTOMOI Operating A lers nit Emergency NOT APPI Traffic Contu NO Road Grade LEVEL Country of Is UNITED S1 Model SILHOUET Bus Use | s Endorsements Total HazMat Types Total Lanes 2 Motor Vehicle Use ICABLE ol Inoperative/Missing suance ATES TE | | |
| | Unit IN T Vehi PAS Tota 1 Insu UNI Most PAF Traff TWC Surfa BLA NO | Status RANSIT Cele Type SSENGER VAN I Occs rance? KNOWN t Harmful Event: Collision N RKED MOTOR VEHICL fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS k Bus or HazMat Vehicle License Plate Number 593BEF Vehicle Identification Nur 1GHDX03E71D27368 Color TAN - TAN | birection Of Travel SOUTHBOUND With E S) | D CLASS Total # Citat 3 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva STRAIGH Plate Type AUT - AU Make OLDSMO Body Style VN - VAN | tions Issued CrashTire Mark ction IAL FUNC rol ROL ture T UTOMOBIL DBILE I mage | TION | Total Tra 0 Speed Lin St WI Year | AUTOMOI Operating A lers nit Emergency NOT APPI Traffic Contu NO Road Grade LEVEL Country of Is UNITED S1 Model SILHOUET Bus Use | s Endorsements Total HazMat Types Total Lanes 2 Motor Vehicle Use ICABLE ol Inoperative/Missing suance ATES TE | | |

18-12131

WISCONSIN MOTOR VEHICLE CRASH REPORT

| | | Towed Due To Dama NOT TOWED | age | Vehicle Removed By | | | | | | | | |
|------|----------|---|------------------------------|--|--------------------------------|--|--|--|--|--|--|--|
| | | What Driver Was Doi | | Vehicle Factors | | | | | | | | |
| | | GOING STRAIGH | | NOT APPLICABLE | | | | | | | | |
| | | Driver Prior Action Other NOT APPLICABLE | | | | | | | | | | |
| UNIT | VEHICLE | Driver Actions OPERATED MOT | OR VEHICLE IN INATTENTIVE, C | ARELESS OR ERRATIC MANNER | | | | | | | | |
| | | Driver Distractions UNKNOWN IF DISTRACTED | | | | | | | | | | |
| | | | | | | | | | | | | |
| 0 | 0 | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | Owner Name WILLIAM T KRUC | UTEN | Owner Address 7853 STATE ROAD 19 | | | | | | | | |
| | | (608) 798-3256 | | DANE, WI 53529 , US | | | | | | | | |
| | | | | | | | | | | | | |
| | ÷ | Sequence Of E | vents | | | | | | | | | |
| | 6 | Event OTHER TRAFFIC | BARRIER | | | | | | | | | |
| | 02 | Event | | | | | | | | | | |
| | 03 | Event | | | | | | | | | | |
| | | Event | | | | | | | | | | |
| | | 4 Event | | | | | | | | | | |
| | I | Individual Driver Citations Issued Sex | | | | | | | | | | |
| | _ | AARON J KRUCH | ITEN | 3 | Sex MALE | | | | | | | |
| | NAI | (608) 354-6757 | | Date of Birth | Race WHITE | | | | | | | |
| UNIT | DIVIDUAL | Address | | Driver License Number | | | | | | | | |
| Б | INDI | 7853 STATE ROAD 19 DANE, WI 53529 , US | | STATE: WISCONSIN COUNTRY: UNITED STATES | | | | | | | | |
| | = | | | | | | | | | | | |
| | | | On Duty Crash | Safety Equipment | | | | | | | | |
| | | Equipment | | | | | | | | | | |
| | | Seat Position 1FRONT SEAT-LEFT SIDE (DRIVER/MOTORCY | | RESTRAINT USE UNKNOWN | | | | | | | | |
| | | Helmet Use | | Helmet Compliance | | | | | | | | |
| | | Eye Protection | | Tint Compliance | | | | | | | | |
| - | 001 | les is sure s | Injury Severity | Airbag | | | | | | | | |
| 0 | õ | Injury | NO APPARENT INJURY | NON DEPLOYED | | | | | | | | |
| | | Ejected NOT EJECTED | | Ejection Path NOT EJECTED/NOT APPLICABL | Trapped/Extricated NOT TRAPPED | | | | | | | |
| | | Medical Transport | | EMS Agency Identifier | EMS Run # | | | | | | | |
| | | NOT TRANSPOR | TED | | | | | | | | | |

6TL096J8XL

18-12131

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

| | | Hospital | Date of Dea | Death Time of Death | | | | | | | |
|---|---|--|---|--|--|--|---|---------------------------------|---|----------------|--|
| | | Non Motorist | Striking Unit # | Prior Action | · | Location | | | | To/From School | |
| | | Action | | | | | | | | | |
| F | INDIVIDUAL | | | | | | | | | | |
| UNIT | IIVIO | | | | | | | | | | |
| | ≤ | | | | | | | | | | |
| | | Action Other | | | | | | | | | |
| | Ľ | . | Suspected Alco YES | spected Alcohol Use S | | Suspected Drug Use YES | | | | | |
| | | Alcohol Test Given TEST GIVEN | | | Alcohol Test Type BLOOD | | | Alcohol Test Results PENDING | | | |
| | | Drug Test Given TEST GIVEN | | | Drug Test T BLOOD | Гуре | | Drug Test R PENDING | esults | | |
| 01 | 001 | Drug Type | | | | | | | | | |
| | | Individual Condition | | | | | | | | | |
| UNDER THE INFLUENCE OF MEDICATIONS/DRUGS/ ALCOHOL | | | | | | | | | | | |
| | ' | Violations | T | 1 | | 1 | | | | | |
| | 6 | UTC Number AE757495 | Issue To? Statute Number 001 346.63(1)(a) | | Seq Num 003 | Description OPERATING V | scription PERATING WHILE UNDER THE INFLUENCE(3RD) | | | | |
| | 02 | UTC Number AE757496 | Issue To? 001 | Statute Number 346.935(2) | Seq Num 001 | Description POSSESS OPEN INTOXICANTS IN MV-DRIVER | | | | 2 | |
| | 03 | UTC NumberIssue To?Statute NumberAI387671001Statute Number | | | Seq Num Description HIT AND RUN-UNATTENDED VEHICLE | | | | | | |
| | | t Summary | | | | | | | | | |
| _ | | Status SALLY PARKED | | Vehicle Operating As Classification D CLASS | | | Unit Type TRUCK | | | | |
| 02 | | cle Type LITY TRUCK/PICKL | JP TRUCK | | | | Operating As Endorsements | | | | |
| | | | | Total # Citation 0 | I # Citations Issued Total Trail | | ers | Total HazM 0 | at Types | | |
| F | Insurance? Direction Of Travel YES NOT ON ROADWAY | | | Ma Ma | Pre CrashTire Speed Lin Mark | | | Total Lanes | 3 | | |
| UNIT | | t Harmful Event: Collisio TOR VEH IN TRANS | | Special Function NO SPECIAL FUNCTION | | | Emergency Motor Vehicle Use NOT APPLICABLE | | | | |
| | | | | | Traffic Control | Traffic Control NO CONTROL | | | Traffic Control Inoperative/Missing NO | | |
| | | | | | Road Curvature | Road Curvature STRAIGHT | | | Road Grade HILLCREST | | |
| | Truc NO | k Bus or HazMat | | | | | | | | | |
| | Y | Vehicle | | | | | | | | | |
| | | License Plate Number ML7895 | | | Plate Type LTK - LIGH | GHT TRUCK WI UNITED STATES | | | | | |
| 02 | 02 | Vehicle Identification Number 1FTRF14W85NA97534 | | Make FORD | | Year 2005 | Model F150 | | | | |

6TL096J8XL

18-12131

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

| | | | Body Style | Bus Use NOT A BUS | | | | | |
|------|---------|--|--|----------------------|--|--|--|--|--|
| | ш | | PK - PICKUP /ehicle Damage | | | | | | |
| ⊑ | С | 6REAR | 6REAR | | | | | | |
| UNIT | VEHICL | Extent Of Damage 6 MINOR DAMAGE | | | | | | | |
| | | | Vehicle Removed By | | | | | | |
| | | | OWNER | | | | | | |
| | | What Driver Was Doing V LEGALLY PARKED | Vehicle Factors | | | | | | |
| | | | NOT APPLICABLE | | | | | | |
| | | | | | | | | | |
| | ш | Driver Actions NO CONTRIBUTING ACTION | | | | | | | |
| UNIT | VEHICLE | | | | | | | | |
| 5 | H | | | | | | | | |
| | > | | | | | | | | |
| | | Driver Distractions NOT DISTRACTED | | | | | | | |
| | | | | | | | | | |
| ~ | 02 | | | | | | | | |
| 02 | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | Owner Name WILLIAM D WENZEL | Owner Address S5928 POINT OF ROCKS ROAD | | | | | | |
| | | (608) 477-0365 | BARABOO, WI 53913 , US | | | | | | |
| | | | | | | | | | |
| | ę | Sequence Of Events | | | | | | | |
| | 0 | | | | | | | | |
| | 02 | Event | | | | | | | |
| | 03 | Event | | | | | | | |
| | 04 | Event | | | | | | | |
| | | Policy Holder | | | | | | | |
| UNIT | | Insurance Company | Individual | | | | | | |
| ر ا | | OWNERS-INS-CO | WILLIAM WENZEL | | | | | | |