
18-12486

#### WISCONSIN MOTOR VEHICLE CRASH REPORT

#### SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895



#### 18-12486

### WISCONSIN MOTOR VEHICLE **CRASH REPORT**

1	_oc	ation								
ſ	ON USH12 EB 933 FT S				Latitude			Longitud	le	
						43.55887707			-89.779	362976
		MOON RD 1			X Coordinate 275518.15625			Y Coord	inate	
		THE TOWN OF DELTO						4826633.5		
	IN C					Structure Type			I	
						NO STRUCTURE				
(	Cra	sh Scene								
Ī	First	Harmful Event				First Harm	Iful Event L	ocation		
	CONCRETE TRAFFIC BARRIER Manner of Collision NO COLLISION W/VEHICLE IN TRANSPORT					ON ROADWAY				
					Light Condition					
						DAYLIGHT				
	Road	Road Surface Condition(s)				Roadway Factor(s)				
	WE	T, SNOW, SLUSH, ICE								
Ē	Envi	ronment Factor(s)								
	WE	ATHER CONDITIONS				ROAD S ETC)	URFACE	CONDITION	I (WET, IC	CY, SNOW, SLUSH,
-	Wea	ther Condition(s)								
		DUDY								
ŀ	Anim	nal Type				Relation To Trafficway				
	Animal Type					TRAFFICWAY - ON ROAD				
-	Cras	Crash Classification - Location <b>PUBLIC PROPERTY</b> Tribal Land				Crash Clas	ssification -	Jurisdiction		
						NO SPECIAL JURISDICTION				
	Triba					Access Control Special Study NO CONTROL				
		Ũ	Junction Location		Intersectio					
	NO NON-JUNCTION NOT AN				N INTERSECTION					
L	_				NUTAN	INTERSE	CHON			
l	Jni	t Summary						1		
l	<b>Jni</b> Unit	t Summary		-	erating As Cl			Unit Type		
l	Jni Unit IN T	t Summary		Vehicle Ope	erating As Cl			AUTOMO		nontr
01	Jni Unit IN T	t Summary Status RANSIT icicle Type		-	erating As Cl					nents
_	Jni Unit IN T Vehi PAS	t Summary Status RANSIT ICIE Type SSENGER CAR		D CLASS	erating As Cl	assification		AUTOMO Operating A	s Endorser	
_	Jni Unit IN T Vehi PAS	t Summary Status RANSIT icicle Type	Train/Bus # Injured	D CLASS	erating As Cl	assification		AUTOMO Operating A	s Endorser	nents Mat Types
_	Jni Unit IN T Vehi PAS Tota 1	t Summary Status RANSIT ICIE Type SSENGER CAR		D CLASS Total # Cita 0	erating As Cl	assification	Total Trai	AUTOMO Operating A	s Endorser Total Haz	Mat Types
01	Jni Unit IN T Vehi PAS Tota 1 Insu	t Summary Status RANSIT icle Type SSENGER CAR I Occs rance? S	Train/Bus # Injured Direction Of Travel EASTBOUND	D CLASS	erating As Cl tions Issued CrashTire Mark	assification	Total Trai <b>0</b>	AUTOMO Operating A lers	s Endorser Total Haz <b>0</b> Total Land	Mat Types es
01	Jni Unit IN T Vehi PAS Tota 1 Insu YES	t Summary Status RANSIT icle Type SSENGER CAR I Occs rance? S t Harmful Event: Collision V	Train/Bus # Injured Direction Of Travel <b>EASTBOUND</b> Vith	D CLASS	tions Issued CrashTire Mark	assification	Total Trai <b>0</b> Speed Lir	AUTOMO Operating A lers nit Emergency	s Endorser Total Haz <b>0</b> Total Lan <b>4</b> Motor Vehi	Mat Types es
_	Jni Unit IN T Vehi PAS Tota 1 Insu YES Most	t Summary Status RANSIT icle Type SSENGER CAR I Occs rance? t Harmful Event: Collision V NCRETE TRAFFIC BAB	Train/Bus # Injured Direction Of Travel <b>EASTBOUND</b> Vith	D CLASS	tions Issued CrashTire Mark CiAL FUNC	assification	Total Trai <b>0</b> Speed Lir	AUTOMO Operating A lers nit Emergency NOT APP	s Endorser Total Haz 0 Total Land 4 Motor Vehi LICABLE	Mat Types es cle Use
01	Jni Unit IN T Vehi PAS Tota 1 Insu YES Most COI Traff	t Summary Status RANSIT icle Type SSENGER CAR I Occs rance? t Harmful Event: Collision V NCRETE TRAFFIC BAB fic Way	Train/Bus # Injured Direction Of Travel EASTBOUND Vith RRIER	D CLASS	tions Issued CrashTire Mark CIAL FUNC	assification	Total Trai <b>0</b> Speed Lir	AUTOMO Operating A lers nit Emergency NOT APP Traffic Cont	s Endorser Total Haz 0 Total Land 4 Motor Vehi LICABLE	Mat Types es cle Use
01	Jnii Unit IN T Vehi PAS Tota 1 Insu YES COI Traff DIVI	t Summary Status RANSIT icle Type SSENGER CAR I Occs rance? t Harmful Event: Collision V NCRETE TRAFFIC BAB	Train/Bus # Injured Direction Of Travel EASTBOUND Vith RRIER	D CLASS	tions Issued CrashTire Mark Inction CIAL FUNC trol TROL	assification	Total Trai <b>0</b> Speed Lir	AUTOMO Operating A lers nit Emergency NOT APP	s Endorser Total Haz 0 Total Land 4 Motor Vehi LICABLE rol Inoperat	Mat Types es cle Use
01	Jnii Unit IN T Vehi PAS Tota 1 Insuu YES Most COI Traff DIVI Surfa	t Summary Status TRANSIT icle Type SSENGER CAR I Occs rance? THarmful Event: Collision V NCRETE TRAFFIC BAR fic Way IDED HWY MEDIAN W	Train/Bus # Injured Direction Of Travel EASTBOUND Vith RRIER	D CLASS	tions Issued CrashTire Mark Inction CIAL FUNC trol TROL ature	assification	Total Trai <b>0</b> Speed Lir	AUTOMO Operating A lers nit Emergency NOT APP Traffic Cont NO	s Endorser Total Haz 0 Total Land 4 Motor Vehi LICABLE rol Inoperat	Mat Types es cle Use
01	Jnii Unit IN T Vehi PAS Tota 1 Insuu YES Most COI Traff DIVI Surfa	t Summary Status TRANSIT Color Type SSENGER CAR Color Collision Collision CRETE TRAFFIC BAF Collision CRETE COLLIN CRETE C	Train/Bus # Injured Direction Of Travel EASTBOUND Vith RRIER	D CLASS	tions Issued CrashTire Mark Inction CIAL FUNC trol TROL ature	assification	Total Trai <b>0</b> Speed Lir	AUTOMO Operating A lers nit Emergency NOT APP Traffic Cont NO Road Grade	s Endorser Total Haz 0 Total Land 4 Motor Vehi LICABLE rol Inoperat	Mat Types es cle Use
01	Jni Unit IN T Vehi PAS Tota 1 Insuu YES Most COI Traff DIVI Surfa COI Trucc NO	t Summary Status TRANSIT Color Type SSENGER CAR Color Collision Collision CRETE TRAFFIC BAF Collision CRETE COLLIN CRETE C	Train/Bus # Injured Direction Of Travel EASTBOUND Vith RRIER	D CLASS	tions Issued CrashTire Mark Inction CIAL FUNC trol TROL ature	assification	Total Trai <b>0</b> Speed Lir	AUTOMO Operating A lers nit Emergency NOT APP Traffic Cont NO Road Grade	s Endorser Total Haz 0 Total Land 4 Motor Vehi LICABLE rol Inoperat	Mat Types es cle Use
01	Jni Unit IN T Vehi PAS Tota 1 Insuu YES Most COI Traff DIVI Surfa COI Trucc NO	t Summary Status TRANSIT Color Type SSENGER CAR COLOR	Train/Bus # Injured Direction Of Travel EASTBOUND Vith RRIER	D CLASS	tions Issued CrashTire Mark CiAL FUNC Trol TROL ature IGHT	TION	Total Trai 0 Speed Lir 65	AUTOMO Operating A lers nit Emergency NOT APP Traffic Cont NO Road Grade LEVEL	s Endorser Total Haz 0 Total Land 4 Motor Vehi LICABLE rol Inoperat	Mat Types es cle Use
01	Jni Unit IN T Vehi PAS Tota 1 Insuu YES Most COI Traff DIVI Surfa COI Trucc NO	t Summary Status Status RANSIT icle Type SSENGER CAR I Occs rance? CHarmful Event: Collision V NCRETE TRAFFIC BAR fic Way IDED HWY MEDIAN W/ ace Type NCRETE k Bus or HazMat Vehicle License Plate Number 392YJY	Train/Bus # Injured Direction Of Travel EASTBOUND Vith RRIER /BARRIER	D CLASS	tions Issued CrashTire Mark CiAL FUNC trol TROL ature IGHT	TION	Total Trai 0 Speed Lir 65 St WI	AUTOMO Operating A lers nit Emergency NOT APP Traffic Cont NO Road Grade LEVEL	s Endorser Total Haz 0 Total Land 4 Motor Vehi LICABLE rol Inoperat	Mat Types es cle Use
UNIT 01	Jni Unit IN T Vehi PAS Tota 1 Insuu YES Most COI Traff DIVI Surfa COI Trucc NO	t Summary Status TRANSIT Color Type SSENGER CAR COLOR	Train/Bus # Injured Direction Of Travel EASTBOUND Vith RRIER /BARRIER	D CLASS	tions Issued CrashTire Mark CiAL FUNC trol TROL ature IGHT	TION	Total Trai 0 Speed Lir 65	AUTOMO Operating A lers nit Emergency NOT APP Traffic Cont NO Road Grade LEVEL	s Endorser Total Haz 0 Total Land 4 Motor Vehi LICABLE rol Inoperat	Mat Types es cle Use
UNIT 01	Jnii Unit IN T Vehi PAS Tota 1 Insuu YES COI Traff DIVI Surfa COI Truc NO	t Summary Status Status RANSIT Color Type SSENGER CAR OCCS Trance? Trance? Thermful Event: Collision V NCRETE TRAFFIC BAF Color Colo	Train/Bus # Injured Direction Of Travel EASTBOUND Vith RRIER /BARRIER	D CLASS	tions Issued CrashTire Mark ctions ClAL FUNC trol TROL ature IGHT	TION	Total Trai 0 Speed Lir 65 St WI Year	AUTOMO Operating A lers nit Emergency NOT APP Traffic Cont NO Road Grade LEVEL Country of Is UNITED S <sup>-</sup> Model MALIBU L Bus Use	s Endorser Total Haz 0 Total Land 4 Motor Vehi LICABLE rol Inoperat suance FATES	Mat Types es cle Use
UNIT 01	Jnii Unit IN T Vehi PAS Tota 1 Insuu YES COI Traff DIVI Surfa COI Truc NO	t Summary Status Status TRANSIT Color Type SSENGER CAR OCCS Trance? Tr	Train/Bus # Injured Direction Of Travel EASTBOUND Vith RRIER /BARRIER	D CLASS	tions Issued CrashTire Mark Inction CrashTire Mark IGHT IGHT	TION	Total Trai 0 Speed Lir 65 St WI Year	AUTOMO Operating A lers nit Emergency NOT APP Traffic Cont NO Road Grade LEVEL	s Endorser Total Haz 0 Total Land 4 Motor Vehi LICABLE rol Inoperat suance FATES	Mat Types es cle Use
01 01 01	Jnii Unit IN T Vehi PAS Tota 1 Insur YES COI Traff DIVI Surfa COI Truc NO	t Summary Status Status FRANSIT Cicle Type SSENGER CAR I Occs I Occs I Occs I Harmful Event: Collision V NCRETE TRAFFIC BAF Cic Way IDED HWY MEDIAN W/ ace Type NCRETE Ik Bus or HazMat Vehicle License Plate Number 392YJY Vehicle Identification Num 1G1ZE5ST8GF197233 Color WHI - WHITE Initial Contact Point	Train/Bus # Injured Direction Of Travel EASTBOUND Vith RRIER /BARRIER	D CLASS	tions Issued CrashTire Mark Inction CrashTire Mark IGHT IGHT	TION	Total Trai 0 Speed Lir 65 St WI Year	AUTOMO Operating A lers nit Emergency NOT APP Traffic Cont NO Road Grade LEVEL Country of Is UNITED S <sup>-</sup> Model MALIBU L Bus Use	s Endorser Total Haz 0 Total Land 4 Motor Vehi LICABLE rol Inoperat suance FATES	Mat Types es cle Use
UNIT 01	Jni Unit INT Vehi PAS Tota 1 Insui YES Most COI Traff DIVI Surfa COI Truc NO	t Summary Status Status TRANSIT Cicle Type SSENGER CAR I Occs I Occs I docs I tharmful Event: Collision V NCRETE TRAFFIC BAF Cic Way IDED HWY MEDIAN W/ ace Type NCRETE Ik Bus or HazMat Vehicle License Plate Number 392YJY Vehicle Identification Num 1G1ZE5ST8GF197233 Color WHI - WHITE	Train/Bus # Injured Direction Of Travel EASTBOUND Vith RRIER /BARRIER	D CLASS	tions Issued CrashTire Mark Inction CrashTire Mark IGHT IGHT	TION	Total Trai 0 Speed Lir 65 St WI Year 2016	AUTOMO Operating A lers nit Emergency NOT APP Traffic Cont NO Road Grade LEVEL	s Endorser Total Haz 0 Total Land 4 Motor Vehi LICABLE rol Inoperat suance FATES	Mat Types es cle Use

UNIT

18-12486

# WISCONSIN MOTOR VEHICLE **CRASH REPORT**

		Towed Due To Damage TOWED DUE TO DISABLING DAMAGE		Vehicle Removed By CRAIGS TOWING					
		What Driver Was Doing		Vehicle Factors					
		NEGOTIATING CURVE							
		Driver Prior Action O	Other	NOT APPLICABLE					
		Driver Actions							
Ι.	Щ	SPEED TOO FAST/COND, FAILURE TO CONTROL							
UNIT	VEHICL								
	ΥĒ								
		Driver Distractions NOT DISTRACTED							
6	6								
	-								
		Owner Name		Owner Address					
		CORY ALAN JAC	COBSON	1065 HICKORY ST					
		(608) 698-6061		ONALASKA, WI 54650 , US					
		Sequence Of E	Events						
	2	Event CONCRETE TRA							
	-	Event							
	02	-							
	03	Event							
	04	Event							
⊢	I	Policy Holder							
UNIT		Insurance Company AMERICAN-FAMILY-INS-CO							
		Individual		CORY JACOBSON					
		Driver CORY ALAN JACOBSON (608) 698-6061		Citations Issued	Sex				
	Ļ			0	MALE				
	<b>⊿</b> ∩c			Date of Birth	Race WHITE				
UNIT	<u>I</u>	Address		Driver License					
	INDIVIDUA	1065 HICKORY ST ONALASKA, WI 54650 ,US		STATE: WISCONSIN COUNTRY: UNITED STATES					
		,	,						
		Equipment	On Duty Crash	Safety Equipment					
		Seat Position		SHOULDER & LAP BELT					
		1FRONT SEAT-LEFT SIDE (DRIVER/MOTORCY							
		Helmet Use		Helmet Compliance					
		Eye Protection		Tint Compliance					
	_		Injury Severity	Airbag					
0	00	Injury	NO APPARENT INJURY	DEPLOYED-FRONT					
		Ejected		Ejection Path	Trapped/Extricated				
		NOT EJECTED	<del></del>		NOT TRAPPED				
Wisco Form		Notor Vehicle Crash	This rep	ort does not include any CJIS data. 3 of 4	Crash Date 11/09/2018 Crash Time 08:19 AM				

18-12486

### WISCONSIN MOTOR VEHICLE CRASH REPORT

#### SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

		Medical Transport			EMS Agency Identi	fier	EMS Run #		
		NOT TRANSPORTED Hospital			Date of Death		Time of Death		
		Non Motoris	<i>t</i> Striking Unit #	Prior Action		Location		To/From School	
		Action						-	
	AL								
UNIT	INDIVIDUAL								
>									
	=								
		Action Other							
			Suspected Alcohol		Suspected Drug Use				
	Ľ	Drug & Alcoh		036	NO				
		Alcohol Test Giver			Alcohol Test Type		Alcohol Test Results		
		Drug Test Given TEST NOT GIV	EN		Drug Test Type		Drug Test Results		
2	001	Drug Type							
	Individual Condition								
		APPEARED NO	ORMAL						
Property Owner									
PROP OWNER 01		ernment JK COUNTY HW 3) 356-3855	Y DEPT		Address 620 STH 136 PO BOX 26 BARABOO, WI 53	913 , US			
	Fixe	ed Objects St	ruck						
	_	Striking Unit Struck Object					Structure Number	Damage Tag Number	
	0	01	CONCRETE TRAFF	IC BARRIER					