

WISCONSIN MOTOR VEHICLE
CRASH REPORT

Location

ON STH78 SB 871 FT S OF INSPIRATION DR (1) IN THE TOWN OF MERRIMAC IN SAUK COUNTY	Latitude 43.345267174	Longitude -89.701487109
	X Coordinate 281038.34375	Y Coordinate 4802702
	Structure Type	

Crash Scene

First Harmful Event DITCH	First Harmful Event Location ON ROADWAY	
Manner of Collision NO COLLISION W/VEHICLE IN TRANSPORT	Light Condition DAYLIGHT	
Road Surface Condition(s) WET, ICE	Roadway Factor(s) NONE	
Environment Factor(s) WEATHER CONDITIONS		
Weather Condition(s) CLOUDY		
Animal Type	Relation To Trafficway TRAFFICWAY - ON ROAD	
Crash Classification - Location PUBLIC PROPERTY	Crash Classification - Jurisdiction NO SPECIAL JURISDICTION	
Tribal Land	Access Control NO CONTROL	Special Study
Within Interchange Area NO	Junction Location NON-JUNCTION	Intersection Type NOT AN INTERSECTION

Unit Summary

UNIT	01	Unit Status IN TRANSIT	Vehicle Operating As Classification D CLASS		Unit Type AUTOMOBILE
		Vehicle Type PASSENGER VAN	Operating As Endorsements		
	Total Occs 1	Train/Bus # Injured	Total # Citations Issued 0	Total Trailers 0	Total HazMat Types
	Insurance? UNKNOWN	Direction Of Travel SOUTHBOUND	<input type="checkbox"/> Pre Crash Tire Mark	Speed Limit 55	Total Lanes 2
	Most Harmful Event: Collision With DITCH		Special Function NO SPECIAL FUNCTION	Emergency Motor Vehicle Use NOT APPLICABLE	
	Traffic Way TWO-WAY, NOT DIVIDED		Traffic Control NO CONTROL	Traffic Control Inoperative/Missing NO	
	Surface Type BLACKTOP (BITUMINOUS)		Road Curvature CURVE RIGHT	Road Grade LEVEL	
	Truck Bus or HazMat NO				

UNIT	01	Vehicle			
		License Plate Number 878ZEW	Plate Type AUT - AUTOMOBILE	St WI	Country of Issuance UNITED STATES
		Vehicle Identification Number 2FMZA514XXBB93197	Make FORD	Year 1999	Model WINDSTAR L
		Color	Body Style VN - VAN		Bus Use NOT A BUS
		Initial Contact Point NON-COLLISION	Vehicle Damage		
		Extent Of Damage NO DAMAGE	NO DAMAGE		

UNIT	Towed Due To Damage NOT TOWED		Vehicle Removed By OPERATOR		
	What Driver Was Doing NEGOTIATING CURVE		Vehicle Factors		
	Driver Prior Action Other		NOT APPLICABLE		
	Driver Actions SPEED TOO FAST/COND				
01	01	Driver Distractions UNKNOWN IF DISTRACTED			
		Owner Name RAFAEL NOYOLA (608) 493-2016	Owner Address 227 W MAIN ST MERRIMAC, WI 53561 , US		
Sequence Of Events					
UNIT	01	Event RUN OFF ROADWAY RIGHT			
		Event DITCH			
		Event			
		Event			
UNIT	001	Individual			
		Driver RAFAEL NOYOLA (608) 493-2016	Citations Issued 0	Sex MALE	
		Address 227 W MAIN ST MERRIMAC, WI 53561 , US	Date of Birth [REDACTED]	Race HISPANIC	
			Driver License Number [REDACTED]	STATE: WISCONSIN COUNTRY: UNITED STATES	
UNIT	001	Equipment	On Duty Crash	Safety Equipment	
		Seat Position 1--FRONT SEAT-LEFT SIDE (DRIVER/MOTORCY		RESTRAINT USE UNKNOWN	
		Helmet Use		Helmet Compliance	
		Eye Protection		Tint Compliance	
		Injury	Injury Severity NO APPARENT INJURY	Airbag NON DEPLOYED	
		Ejected NOT EJECTED		Ejection Path NOT EJECTED/NOT APPLICABL	Trapped/Extricated NOT TRAPPED
		Medical Transport NOT TRANSPORTED		EMS Agency Identifier	EMS Run #

WISCONSIN MOTOR VEHICLE
CRASH REPORT

UNIT	Hospital		Date of Death		Time of Death	
	Non Motorist		Striking Unit #	Prior Action	Location	To/From School
	Action					
	Action Other					
	Drug & Alcohol		Suspected Alcohol Use NO		Suspected Drug Use NO	
	Alcohol Test Given TEST NOT GIVEN			Alcohol Test Type	Alcohol Test Results	
	Drug Test Given TEST NOT GIVEN			Drug Test Type	Drug Test Results	
	Drug Type					
	Individual Condition NOT OBSERVED					
	01	001				