
# 6TL0B1715H

18-12524

#### WISCONSIN MOTOR VEHICLE CRASH REPORT

#### SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895



18-12524

### WISCONSIN MOTOR VEHICLE **CRASH REPORT**

L	_oc	ation									
Ē	ON S DUTCH HOLLOW RD				Latitude					Longitude	
	324 FT S OF BUNDY HOLLOW RD					<b>43.585832809</b> X Coordinate			-90.183	3276854	
									Y Coordinate		
		HE TOWN OF LA VAL	LE			243008.2			483079		
	IN 3	AUK COUNT I				Structure -	Туре				
					NO STRUCTURE						
(	Cra	sh Scene									
Ī	First	Harmful Event				First Harm	nful Event I	ocation			
	GU/	ARDRAIL FACE				SHOULDER RIGHT					
Ī	Man	ner of Collision				Light Condition					
	NO	COLLISION W/VEHICI				DUSK					
	Road	d Surface Condition(s)				Roadway	Factor(s)				
	ICE										
ŀ	Envi	ronment Factor(s)				-					
	WE	ATHER CONDITIONS				NONE					
-	Wea	ther Condition(s)				-					
	SNC	W									
-	Anim	nal Type				Relation T	o Trafficwa	av			
							Relation To Trafficway TRAFFICWAY - ON ROAD				
ŀ	Cras	h Classification - Location			Crash Cla	ssification	- Jurisdiction				
	PUBLIC PROPERTY					NO SPECIAL JURISDICTION					
	Triba	Tribal Land					Access Control Special Stu NO CONTROL		Special Study		
-	With	in Interchange Area	Junction Location		Intersection Type			I			
ļ	-					T AN INTERSECTION					
1					NOT AN	INTERSE	CHON				
L	Jni	t Summarv 💻			NOTAN	INTERSE	CHON				
ן נ 		t Summary		Vehicle Ope		-		Unit Type			
l	Unit			Vehicle Ope D CLASS		-		Unit Type AUTOMO	BILE		
	Unit IN T	Status				-				ments	
2 1	Unit <b>IN T</b> Vehi	Status RANSIT				-		AUTOMO Operating A		ments	
	Unit IN T Vehi PAS Tota	Status RANSIT cle Type	Train/Bus # Injured	D CLASS	erating As C	lassification	Total Tra	AUTOMO Operating A	s Endorsei Total Haz	ments Mat Types	
	Unit IN T Vehi PAS Tota 1	Status TRANSIT Cle Type SSENGER CAR		D CLASS	erating As C	lassification	Total Tra 0	AUTOMO Operating A ilers	s Endorsei Total Haz <b>0</b>	Mat Types	
01	Unit IN T Vehi PAS Tota 1 Insur	Status TRANSIT Cle Type SSENGER CAR I Occs Trance?	Direction Of Travel	D CLASS	erating As C tions Issued	lassification	Total Tra 0 Speed Li	AUTOMO Operating A ilers	s Endorse Total Haz <b>0</b> Total Lan	Mat Types	
01	Unit IN T Vehi PAS Tota 1 Insur YES	Status (RANSIT cle Type SSENGER CAR I Occs rance? S	Direction Of Travel EASTBOUND	D CLASS	erating As C tions Issued CrashTire Mark	lassification	Total Tra 0	AUTOMO Operating A illers mit	s Endorsei Total Haz 0 Total Lan 2	Mat Types es	
01	Unit IN T Vehi PAS Tota 1 Insur YES	Status <b>RANSIT</b> cle Type <b>SSENGER CAR</b> I Occs rance? <b>S</b> t Harmful Event: Collision V	Direction Of Travel EASTBOUND	D CLASS	erating As C tions Issued CrashTire Mark ction	lassification	Total Tra 0 Speed Li	AUTOMO Operating A illers mit Emergency	s Endorser Total Haz 0 Total Lan 2 Motor Veh	Mat Types es icle Use	
01	Unit IN T Vehi PAS Tota 1 Insur YES Most GU/	Status <b>RANSIT</b> cle Type <b>SSENGER CAR</b> I Occs rance? <b>S</b> I Harmful Event: Collision V <b>ARDRAIL FACE</b>	Direction Of Travel EASTBOUND	D CLASS	tions Issued CrashTire Mark ICTION IAL FUNC	lassification	Total Tra 0 Speed Li	AUTOMO Operating A illers mit Emergency NOT APP	s Endorser Total Haz 0 Total Lan 2 Motor Veh LICABLE	Mat Types es icle Use	
01	Unit IN T Vehi PAS Tota 1 Insur YES Most GU/ Traff	Status <b>RANSIT</b> cle Type <b>SSENGER CAR</b> I Occs rance? <b>S</b> t Harmful Event: Collision V <b>ARDRAIL FACE</b> ic Way	Direction Of Travel EASTBOUND With	D CLASS	tions Issued CrashTire Mark ICTION IAL FUNC	lassification	Total Tra 0 Speed Li	AUTOMO Operating A ilers mit Emergency NOT APP Traffic Cont	s Endorser Total Haz 0 Total Lan 2 Motor Veh LICABLE	Mat Types es icle Use	
01	Unit IN T Vehi PAS Tota 1 Insui YES Most GUA Traff	Status RANSIT Cle Type SSENGER CAR I Occs rance? Harmful Event: Collision V ARDRAIL FACE ic Way D-WAY, NOT DIVIDED	Direction Of Travel EASTBOUND With	D CLASS	tions Issued CrashTire Mark IAL FUNC	lassification	Total Tra 0 Speed Li	AUTOMO Operating A illers mit Emergency NOT APP Traffic Cont NO	Total Haz 0 Total Lan 2 Motor Veh LICABLE rol Inopera	Mat Types es icle Use	
01	Unit IN T Vehi PAS Tota 1 Insur YES Most GU/ Traff TW( Surfa	Status <b>RANSIT</b> cle Type <b>SSENGER CAR</b> I Occs rance? <b>S</b> t Harmful Event: Collision V <b>ARDRAIL FACE</b> ic Way	Direction Of Travel EASTBOUND With	D CLASS	tions Issued CrashTire Mark IAL FUNC rol ROL iture	lassification	Total Tra 0 Speed Li	AUTOMO Operating A ilers mit Emergency NOT APP Traffic Cont	Total Haz 0 Total Lan 2 Motor Veh LICABLE rol Inopera	Mat Types es icle Use	
01	Unit IN T Vehi PAS Tota 1 Insur YES GU/ Traff TW( Surfa BLA	Status RANSIT Cle Type SSENGER CAR I Occs I Occs I Harmful Event: Collision V ARDRAIL FACE ic Way D-WAY, NOT DIVIDED ace Type	Direction Of Travel EASTBOUND With	D CLASS	tions Issued CrashTire Mark IAL FUNC rol ROL iture	lassification	Total Tra 0 Speed Li	AUTOMO Operating A illers mit Emergency NOT APP Traffic Cont NO Road Grade	Total Haz 0 Total Lan 2 Motor Veh LICABLE rol Inopera	Mat Types es icle Use	
01	Unit IN T Vehi PAS Tota 1 Insur YES Most GU/ Traff Surfa BLA Truc NO	Status RANSIT Cle Type SSENGER CAR I Occs rance? ARDRAIL FACE ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS k Bus or HazMat	Direction Of Travel EASTBOUND With	D CLASS	tions Issued CrashTire Mark IAL FUNC rol ROL iture	lassification	Total Tra 0 Speed Li	AUTOMO Operating A illers mit Emergency NOT APP Traffic Cont NO Road Grade	Total Haz 0 Total Lan 2 Motor Veh LICABLE rol Inopera	Mat Types es icle Use	
01	Unit IN T Vehi PAS Tota 1 Insur YES Most GU/ Traff Surfa BLA Truc NO	Status RANSIT Cle Type SSENGER CAR I Occs rance? Tharmful Event: Collision V ARDRAIL FACE ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS k Bus or HazMat Vehicle	Direction Of Travel EASTBOUND With	D CLASS	tions Issued CrashTire Mark ICTION IAL FUNC rol ROL Iture EFT	lassification	Total Tra 0 Speed Li 45	AUTOMO Operating A illers mit Emergency NOT APP Traffic Cont NO Road Grade DOWNHIL	Total Haz 0 Total Lan 2 Motor Veh LICABLE rol Inopera	Mat Types es icle Use	
01	Unit IN T Vehi PAS Tota 1 Insur YES Most GU/ Traff Surfa BLA Truc NO	Status RANSIT Cle Type SSENGER CAR I Occs rance? Tharmful Event: Collision V ARDRAIL FACE ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS k Bus or HazMat Vehicle License Plate Number	Direction Of Travel EASTBOUND With	D CLASS	tions Issued CrashTire Mark ICTION IAL FUNC rol ROL Iture EFT	lassification	Total Tra 0 Speed Li 45	AUTOMO Operating A illers mit Emergency NOT APP Traffic Cont NO Road Grade DOWNHIL	suance	Mat Types es icle Use	
UNIT 01	Unit IN T Vehi PAS Tota 1 Insur YES Most GU/ Traff Surfa BLA Truc NO	Status RANSIT Cle Type SSENGER CAR I Occs rance? ARDRAIL FACE ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS k Bus or HazMat Vehicle License Plate Number 256PZU	Direction Of Travel EASTBOUND With	D CLASS	tions Issued CrashTire Mark ICTION IAL FUNC rol ROL Iture EFT	lassification	Total Tra 0 Speed Li 45 St MN	AUTOMO Operating A illers mit Emergency NOT APP Traffic Cont NO Road Grade DOWNHIL	suance	Mat Types es icle Use	
UNIT 01	Unit IN T Vehi PAS Tota 1 Insur YES Most GU/ Traff Surfa BLA Truc NO	Status RANSIT Cle Type SSENGER CAR I Occs rance? Tharmful Event: Collision V ARDRAIL FACE ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS k Bus or HazMat Vehicle License Plate Number	Direction Of Travel EASTBOUND With S)	D CLASS	tions Issued CrashTire Mark IAL FUNC rol ROL iture EFT	lassification	Total Tra 0 Speed Li 45	AUTOMO Operating A illers mit Emergency NOT APP Traffic Cont NO Road Grade DOWNHIL	In the second se	Mat Types es icle Use	
UNIT 01	Unit IN T Vehi PAS Tota 1 Insur YES GU/ Traff TWC Surfa BLA Truc	Status RANSIT Cle Type SSENGER CAR I Occs I Occs I Harmful Event: Collision V ARDRAIL FACE ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS k Bus or HazMat Vehicle License Plate Number 256PZU Vehicle Identification Num 1NXBR12E52Z608683 Color	Direction Of Travel EASTBOUND With S)	D CLASS	tions Issued CrashTire Mark IAL FUNC rol ROL iture EFT	lassification	Total Tra 0 Speed Li 45 St MN Year	AUTOMO Operating A illers mit Emergency NOT APP Traffic Cont NO Road Grade DOWNHIL Country of Is UNITED S <sup>*</sup> Model COROLLA Bus Use	In the second se	Mat Types es icle Use	
UNIT 01	Unit IN T Vehi PAS Tota 1 Insu YES GUA Traff TWC Surfa BLA NO	Status Status RANSIT Cle Type SSENGER CAR COCS Trance?	Direction Of Travel EASTBOUND With S)	D CLASS	tions Issued CrashTire Mark IAL FUNC rol ROL iture EFT	lassification	Total Tra 0 Speed Li 45 St MN Year	AUTOMO Operating A illers mit Emergency NOT APP Traffic Cont NO Road Grade DOWNHIL Country of Is UNITED S <sup>T</sup> Model COROLLA	In the second se	Mat Types es icle Use	
01 01 01	Unit IN T Vehi PAS Tota 1 Insu YES GUA Traff TWC Surfa BLA NO	Status Status RANSIT Cle Type SSENGER CAR COCS Trance?	Direction Of Travel EASTBOUND With S)	D CLASS	tions Issued CrashTire Mark IAL FUNC rol ROL iture EFT	lassification	Total Tra 0 Speed Li 45 St MN Year	AUTOMO Operating A illers mit Emergency NOT APP Traffic Cont NO Road Grade DOWNHIL Country of Is UNITED S <sup>*</sup> Model COROLLA Bus Use	In the second se	Mat Types es icle Use	
UNIT 01	Unit IN T Vehi PAS Tota 1 Insur YES GU/ Traff TWC Surfa BLA Truc	Status Status RANSIT Cle Type SSENGER CAR COCS Trance?	Direction Of Travel EASTBOUND With S)	D CLASS Total # Cita 0 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva CURVE Li Plate Type AUT - AL Make TOYOTA Body Style 4D - 4DR Vehicle Da 1RIGHT	tions Issued CrashTire Mark ction IAL FUNC rol ROL iture EFT JTOMOBIL	LE CORNER,	Total Tra 0 Speed Li 45 St MN Year 2002 2RIGHT	AUTOMO Operating A illers mit Emergency NOT APP Traffic Cont NO Road Grade DOWNHIL Country of Is UNITED S <sup>T</sup> Model COROLLA Bus Use NOT A BU	IT otal Haz 0 Total Lan 2 Motor Veh LICABLE rol Inopera - L Suance TATES S IT, 3RIG	Mat Types es icle Use tive/Missing SHT SIDE MIDDLE, 4	

UNIT

### 6TL0B1715H

18-12524

## WISCONSIN MOTOR VEHICLE **CRASH REPORT**

					Vehicle Removed By				
			DISABLING DAMAGE	STE	VES AUTO SERVICE				
		What Driver Was Doing		Vehi	cle Factors				
		NEGOTIATING CURVE			NOT APPLICABLE				
		Driver Prior Action Other							
		Driver Actions							
	ш	FAILURE TO CONTROL							
E	VEHICLE								
UNIT	Ī								
	ž								
	-								
		Driver Distractions NOT DISTRACTE	D						
01	0								
		Owner Name							
		GIUSEPPE K PROTO (608) 387-2095			E2017 N DUTCH HOLLOW ROAD LAVALLE, WI 53941, US				
		(008) 387-2093			, , ,				
		Sequence Of E	vonte						
		Event	Events ACE						
	6								
	02	Event							
	Event								
	0								
	04	Event							
E	I	Policy Holder							
UNIT		Insurance Company WEST-BEND-MUTUAL-INS-CO			Individual GIUSEPPE PROTO				
		Individual							
		Driver			itations Issued	Sex			
	_	GIUSEPPE K PRO	ото	0		MALE			
		(608) 387-2095		Da	ate of Birth	Race			
E	ğ					WHITE			
UNIT		Address E2017 N DUTCH HOLLOW ROAD LAVALLE, WI 53941, US		Di	Driver License Number STATE: WISCONSIN COUNTRY: UNITED STATES				
_	Ĭ			S					
			On Duty Crash	Sa	afety Equipment				
		Equipment							
		Seat Position		S	HOULDER & LAP BELT				
		1FRONT SEAT-LEFT SIDE (DRIVER/MOTORCY							
		Helmet Use		He	Helmet Compliance				
		Eye Protection		Ti	Tint Compliance				
	~	Injury Severity		Ai	rbag				
01	001	Injury	NO APPARENT INJURY		ON DEPLOYED				
		Ejected	1		ection Path	Trapped/Extricated			
		NOT EJECTED		N	OT EJECTED/NOT APPLICABL	NOT TRAPPED			
Wisco	nsin N	Notor Vehicle Crash	This rep	port do	es not include any CJIS data.	Crash Date	11/09/2018		

6TL0B1715H

18-12524

#### WISCONSIN MOTOR VEHICLE CRASH REPORT

#### SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

		Medical Transport NOT TRANSPORTED			EMS Agency Identifier		EMS Run #				
		Hospital			Date of Death		Time of Death				
		Non Motorist	Striking Unit #	Prior Action		Location		To/From School			
UNIT	INDIVIDUAL	Action									
	Ľ	Action Other Drug & Alcoho	Suspected Alcohol	Use	Suspected Drug Us	e					
		Alcohol Test Given			Alcohol Test Type		Alcohol Test Results				
		Drug Test Given			Drug Test Type		Drug Test Results				
01	001	Drug Type									
		Individual Condition									
		APPEARED NORMAL									
Property Owner											
PROP OWNER 01	(608	ernment VNSHIP OF LAV 3) 985-7695			Address 218 COMMERCIA PO BOX 30 LAVALLE, WI 539						
	Fixe	ed Objects St									
	6	0	Struck Object GUARDRAIL FACE				Structure Number	Damage Tag Number 337797			