6TL09JDKWD

18-12782

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

	Document Number Override	Primary Crash Document #		Agency Crash Number 18-12782		Investigating Officer/Deputy DEPUTY B. SCHLOUGH			
2	Crash Date 11/16/2018	Crash Time 10:50 AM		Date Arrived 11/16/2018		Time Arrived 11:02 AM			
	Date Notified 11/16/2018				nits	Total Injured	Total Injured Total Killed 00 00		
OILUSSDAWE		t and Run	Lane Closu	01 ure	Work Zone		or Towed	Reporting Threshold	
	Government Property	Active Sc	re School Zone		School Bus Related NO		Tags		
	▼ Reportable	Crash Type DT4000 (STA	sh Type 4000 (STANDARD CRASH)			Amended Secondary Crash			
	Description								
	Diagram			S TH	136		Photos By	n By	
				Suar	STH 136 		Additional Info	ormation	
	DRAWING NOT TO S	SCALE		POINT	OF ROCKS RD				
	I, a sworn law enforceme	ent officer, agre	ee that I have no	ot added	any CJIS data in thi	s report.			
	UNIT 1 WAS WAS TRAVELING S	/B ON STH 136.	UNIT 1 PROCEED	ED THRO	OUGH THE INTERSECT	ON AND WAS A			
	ONTO STH 136 AND PROCEED E UNIT 1 PULLED ONTO THE E/B S			THE LEFT	TURN UNIT 1 STRUCK	THE STOP SIG	SN POST HEAD	OON. AFTER IMPACT	

6TL09JDKWD 18-12782

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT **BARABOO, WI 53913** (608) 356-4895

	Loc	ation								
- 1	ON	STH136 SB			Latit	Latitude		Longitude		
	5 F									
		STH136 EB		X Co	X Coordinate		Y Coordinate			
		THE TOWN OF BARAB SAUK COUNTY	300							
		DAGIT GOOM I		Stru	Structure Type					
					NO	NO STRUCTURE				
(Cra	sh Scene								
1		Harmful Event		First	: Harmful Event L	ocation				
		HER POST, POLE OR	SUPPORT		ROADWAY	-coation				
		ner of Collision				Condition				
	NO	COLLISION W/VEHICI	LE IN TRANSPORT			DAYLIGHT				
	Road	d Surface Condition(s)					Roadway Factor(s)			
	DRY									
		ironment Factor(s)								
	NOI	NE			NOI	NE				
	Wea	ather Condition(s)								
	CLC	OUDY								
	Anim	nal Type		Pela	Relation To Trafficway					
	,	nai Typo			TRAFFICWAY					
	Cras	sh Classification - Location			Cras	Crash Classification - Jurisdiction				
		BLIC PROPERTY			NO SPECIAL JURISDICTION					
	I riba	al Land				Access Control Special Study NO CONTROL				
	With	in Interchange Area	Junction Location		Intersection Typ	on Type				
	NO		INTERSECTION		OTHER					
į	Uni	t Summary			•					
		t Summary Status		Vehicle Ope	erating As Classific	cation	Unit Type			
	Unit			Vehicle Ope	erating As Classifi	cation	Unit Type AUTOMOE	BILE		
	Unit IN T Vehi	Status FRANSIT icle Type	_	-	erating As Classifi	cation	AUTOMOE	BILE s Endorsements		
01	Unit IN T Vehi (SP	Status TRANSIT icle Type ORT) UTILITY VEHICL		D CLASS			AUTOMOE Operating As	s Endorsements		
	Unit IN T Vehi (SP	Status FRANSIT icle Type	E Train/Bus # Injured	D CLASS	erating As Classifications Issued	Total Tra	AUTOMOE Operating As	s Endorsements Total HazMat Types		
	Unit IN T Vehi (SP Tota 1	Status FRANSIT icle Type ORT) UTILITY VEHICL	Train/Bus # Injured	Total # Cita	tions Issued	Total Tra	AUTOMOE Operating As	s Endorsements Total HazMat Types 0		
01	Unit IN T Vehi (SP) Tota 1	Status FRANSIT icle Type ORT) UTILITY VEHICL II Occs rance?	Train/Bus # Injured Direction Of Travel	Total # Cita	tions Issued CrashTire	Total Tra 0 Speed Li	AUTOMOE Operating As	Total HazMat Types O Total Lanes		
01	Unit IN T Vehi (SP) Tota 1 Insur YES	Status FRANSIT icle Type ORT) UTILITY VEHICL II Occs rance?	Train/Bus # Injured Direction Of Travel EASTBOUND	Total # Cita 0 Pre	tions Issued CrashTire Mark	Total Tra	AUTOMOE Operating Asillers	Total HazMat Types Total Lanes 2		
01	Unit IN T Vehi (SP) Tota 1 Insur YES	Status TRANSIT icle Type ORT) UTILITY VEHICL Il Occs rance? S t Harmful Event: Collision V	Train/Bus # Injured Direction Of Travel EASTBOUND With	Total # Cita 0 Pre Special Fur	tions Issued CrashTire Mark	Total Tra 0 Speed Li 55	AUTOMOE Operating Asillers	Total HazMat Types O Total Lanes 2 Motor Vehicle Use		
01	Unit IN T Vehi (SP Tota 1 Insur YES	Status FRANSIT icle Type ORT) UTILITY VEHICL II Occs rance?	Train/Bus # Injured Direction Of Travel EASTBOUND With	Total # Cita 0 Pre Special Fur	tions Issued CrashTire Mark Iction	Total Tra 0 Speed Li 55	AUTOMOE Operating Asillers mit Emergency NOT APPL	Total HazMat Types O Total Lanes 2 Motor Vehicle Use		
01	Unit IN T Vehi (SP) Tota 1 Insur YES Most OTH	Status FRANSIT icle Type ORT) UTILITY VEHICL II Occs rance? S t Harmful Event: Collision V HER POST, POLE OR S	Train/Bus # Injured Direction Of Travel EASTBOUND With SUPPORT	Total # Cita 0 Pre Special Fur NO SPEC	tions Issued CrashTire Mark action :IAL FUNCTION	Total Tra 0 Speed Li 55	AUTOMOE Operating Asiliers mit Emergency NOT APPL Traffic Contr	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE ol Inoperative/Missing		
01	Unit IN T Vehi (SP) Tota 1 Insur YES Most OTH Traff	Status TRANSIT icle Type ORT) UTILITY VEHICL II Occs rance? S It Harmful Event: Collision WHER POST, POLE OR S fic Way O-WAY, NOT DIVIDED ace Type	Train/Bus # Injured Direction Of Travel EASTBOUND Nith SUPPORT	Total # Cita 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva	crashTire Mark action EIAL FUNCTION TOI CROL	Total Tra 0 Speed Li 55	AUTOMOE Operating As iilers mit Emergency NOT APPL Traffic Contr NO Road Grade	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE ol Inoperative/Missing		
01	Unit IN T Vehi (SP Tota 1 Insur YES OTH Traff TW0 Surfa BLA	Status TRANSIT icle Type ORT) UTILITY VEHICL II Occs rance? S t Harmful Event: Collision V HER POST, POLE OR S fic Way O-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS)	Train/Bus # Injured Direction Of Travel EASTBOUND Nith SUPPORT	Total # Cita 0 Pre Special Fur NO SPEC Traffic Cont	crashTire Mark action EIAL FUNCTION TOI CROL	Total Tra 0 Speed Li 55	AUTOMOE Operating Asiliers mit Emergency NOT APPL Traffic Contr	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE ol Inoperative/Missing		
01	Unit IN T Vehi (SP Tota 1 Insur YES OTH Traff TW0 Surfa BLA	Status TRANSIT icle Type ORT) UTILITY VEHICL al Occs rance? St Harmful Event: Collision Vereign Co	Train/Bus # Injured Direction Of Travel EASTBOUND Nith SUPPORT	Total # Cita 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva	crashTire Mark action EIAL FUNCTION TOI CROL	Total Tra 0 Speed Li 55	AUTOMOE Operating As iilers mit Emergency NOT APPL Traffic Contr NO Road Grade	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE ol Inoperative/Missing		
01	Unit IN T Vehi (SP Tota 1 Insury YES Most OTH Traff T TWC Surfa BLA Truc	Status TRANSIT icle Type ORT) UTILITY VEHICL al Occs rance? St Harmful Event: Collision Vereign Co	Train/Bus # Injured Direction Of Travel EASTBOUND Nith SUPPORT	Total # Cita 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva	crashTire Mark action EIAL FUNCTION TOI CROL	Total Tra 0 Speed Li 55	AUTOMOE Operating As iilers mit Emergency NOT APPL Traffic Contr NO Road Grade	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE ol Inoperative/Missing		
01	Unit IN T Vehi (SP Tota 1 Insury YES Most OTH Traff T TWC Surfa BLA Truc	Status FRANSIT icle Type ORT) UTILITY VEHICL II Occs rance? St Harmful Event: Collision WHER POST, POLE OR Stic Way O-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS Ek Bus or HazMat Vehicle License Plate Number	Train/Bus # Injured Direction Of Travel EASTBOUND Nith SUPPORT	Total # Cita 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva	tions Issued CrashTire Mark cition EIAL FUNCTION rol TROL ature T	Total Tra 0 Speed Lii 55	AUTOMOE Operating As illers mit Emergency I NOT APPL Traffic Contr NO Road Grade LEVEL Country of Iss	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE ol Inoperative/Missing		
01	Unit IN T Vehi (SP Tota 1 Insury YES Most OTH Traff T TWC Surfa BLA Truc	Status FRANSIT icle Type ORT) UTILITY VEHICL II Occs rance? St Harmful Event: Collision V HER POST, POLE OR St fic Way O-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS Ek Bus or HazMat Vehicle License Plate Number 914WZY	Train/Bus # Injured Direction Of Travel EASTBOUND With SUPPORT	Total # Cita 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva STRAIGH	tions Issued CrashTire Mark cition EIAL FUNCTION rol TROL ature T	Total Tra 0 Speed Li 55	AUTOMOE Operating As iilers mit Emergency I NOT APPL Traffic Contr NO Road Grade LEVEL Country of Iss UNITED ST	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE ol Inoperative/Missing		
UNIT 01	Unit IN T Vehi (SP Tota 1 Insur YES OTH Traff TWO Surfa BLA Truc NO	Status FRANSIT icle Type ORT) UTILITY VEHICL II Occs rance? St Harmful Event: Collision V HER POST, POLE OR St fic Way O-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS ck Bus or HazMat Vehicle License Plate Number 914WZY Vehicle Identification Num	Train/Bus # Injured Direction Of Travel EASTBOUND Nith SUPPORT S)	Total # Cita 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva STRAIGH Plate Type AUT - AU Make	tions Issued CrashTire Mark action EIAL FUNCTION TOI TROL ature T	Total Tra 0 Speed Li 55 N St WI Year	AUTOMOE Operating As illers mit Emergency I NOT APPL Traffic Contr NO Road Grade LEVEL Country of Iss UNITED ST Model	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE ol Inoperative/Missing		
UNIT 01	Unit IN T Vehi (SP Tota 1 Insury YES Most OTH Traff T TWC Surfa BLA Truc	Status TRANSIT icle Type ORT) UTILITY VEHICL II Occs rance? S t Harmful Event: Collision Vehicle ACKTOP (BITUMINOUSE) Ick Bus or HazMat Vehicle License Plate Number 914WZY Vehicle Identification Num 1C4PJMDS5EW2762	Train/Bus # Injured Direction Of Travel EASTBOUND Nith SUPPORT S)	Total # Cita 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva STRAIGH Plate Type AUT - AU Make JEEP	crashTire Mark Inction IAL FUNCTION IROL IATURE T	Total Tra 0 Speed Li 55	AUTOMOE Operating As illers mit Emergency I NOT APPL Traffic Contr NO Road Grade LEVEL Country of Iss UNITED ST Model CHEROKEI	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE ol Inoperative/Missing		
	Unit IN T Vehi (SP Tota 1 Insur YES OTH Traff TWO Surfa BLA Truc NO	Status FRANSIT icle Type ORT) UTILITY VEHICL II Occs rance? St Harmful Event: Collision V HER POST, POLE OR St fic Way O-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS ck Bus or HazMat Vehicle License Plate Number 914WZY Vehicle Identification Num	Train/Bus # Injured Direction Of Travel EASTBOUND Nith SUPPORT S)	Total # Cita 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva STRAIGH Plate Type AUT - AU Make JEEP Body Style	crashTire Mark Inction IAL FUNCTION IROL IATURE T	Total Tra 0 Speed Li 55 St WI Year 2014	AUTOMOE Operating As illers mit Emergency I NOT APPL Traffic Contr NO Road Grade LEVEL Country of Iss UNITED ST Model	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE ol Inoperative/Missing		
01 UNIT 01	Unit IN T Vehi (SP Tota 1 Insury YES OTH Traff TWO Surfa BLA	Status TRANSIT icle Type ORT) UTILITY VEHICL II Occs Trance? St Harmful Event: Collision Vehicle ACKTOP (BITUMINOUSE) Ick Bus or HazMat Vehicle License Plate Number 914WZY Vehicle Identification Num 1C4PJMDS5EW2762 Color	Train/Bus # Injured Direction Of Travel EASTBOUND Nith SUPPORT S)	Total # Cita 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva STRAIGH Plate Type AUT - AU Make JEEP Body Style	CrashTire Mark Oction IAL FUNCTION TO T	Total Tra 0 Speed Li 55 St WI Year 2014	AUTOMOE Operating Asilers mit Emergency NOT APPL Traffic Contr NO Road Grade LEVEL Country of Iss UNITED ST Model CHEROKEI Bus Use	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE ol Inoperative/Missing		
01 UNIT 01	Unit IN T Vehi (SP Tota 1 Insury YES OTH Traff TWO Surfa BLA	Status TRANSIT icle Type ORT) UTILITY VEHICL II Occs Trance? St t Harmful Event: Collision Well HER POST, POLE OR St fic Way O-WAY, NOT DIVIDED Tace Type ACKTOP (BITUMINOUS Tek Bus or HazMat Vehicle License Plate Number 914WZY Vehicle Identification Num 1C4PJMDS5EW2762 Color BLK - BLACK Initial Contact Point 12FRONT	Train/Bus # Injured Direction Of Travel EASTBOUND Nith SUPPORT S)	Total # Cita 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva STRAIGH Plate Type AUT - AU Make JEEP Body Style UT - SPC Vehicle Da	CrashTire Mark Inction ITAL FUNCTION ITAL ITAL ITAL ITAL ITAL ITAL ITAL ITAL	Total Tra 0 Speed Li 55 St WI Year 2014	AUTOMOE Operating Asilers mit Emergency NOT APPL Traffic Contr NO Road Grade LEVEL Country of Iss UNITED ST Model CHEROKEI Bus Use	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE ol Inoperative/Missing		
UNIT 01	Unit IN T Vehi (SP Tota 1 Insur YES OTH Traff TWO Surfa BLA	Status TRANSIT icle Type ORT) UTILITY VEHICL II Occs Trance? St Harmful Event: Collision Well Collision Wel	Train/Bus # Injured Direction Of Travel EASTBOUND With SUPPORT S)	Total # Cita 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva STRAIGH Plate Type AUT - AU Make JEEP Body Style UT - SPC	CrashTire Mark Inction ITAL FUNCTION ITAL ITAL ITAL ITAL ITAL ITAL ITAL ITAL	Total Tra 0 Speed Li 55 St WI Year 2014	AUTOMOE Operating Asilers mit Emergency NOT APPL Traffic Contr NO Road Grade LEVEL Country of Iss UNITED ST Model CHEROKEI Bus Use	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE ol Inoperative/Missing		

Crash Date 11/16/2018 Crash Time 10:50 AM

6TL09JDKWD

18-12782

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

	Towed Due To Damage			Vehicle Removed By							
		NOT TOWED		OWNER							
		What Driver Was Doing		Vehicle Factors							
		LEFT TURN									
		Driver Prior Action Ot	her	NO	T APPLICABLE						
		Dilver i noi Action Ot	i lei		-						
		Dei Astisus									
		Driver Actions	•								
	Щ	IMPROPER TURN									
느	<u>၂</u>										
E I	VEHICL										
71	Æ										
	_										
		Driver Distractions									
		Driver Distractions NOT DISTRACTED									
			NOT DISTRACTED								
_	_										
2	01										
		Owner Name LINDA L LAUFENBERG (608) 356-9015			Owner Address						
				1208 11TH ST BARABOO, WI 53913 , US							
	Ġ	Sequence Of Events									
	ì	Event	VCIIIS								
	7	OTHER POST, POLE OR SUPPORT									
	Event										
	0										
	~	Event									
	03										
		Event Event									
	04	270									
\vdash	ı	Policy Holder									
		Insurance Company		lr	ndividual						
\supset		ACUITY,-A-MUTUAL-INSURANCE-CO			INDA LAUFENBERG						
	i	Individual									
				1.0	Stational Insurad						
		Driver LINDA L LAUFENBERG (608) 356-9015			itations Issued	Sex					
	إ			0		FEMALE					
	Y				ate of Birth	Race					
$\vdash 1$	INDIVIDUA					WHITE					
	⋝	Address		Driver License Number							
⊃	⊒∣	1208 11TH ST									
	Z	BARABOO, WI 53	913 , US	STATE: WISCONSIN COUNTRY: UNITED STATES							
		On Duty Crash									
		Equipment	On Duty Crash	٥	afety Equipment						
		Seat Position 1FRONT SEAT-LEFT SIDE (DRIVER/MOTORCY Helmet Use		SHOULDER & LAP BELT							
				Helmet Compliance							
		Eye Protection		 	Tint Compliance						
				'	Titt Compilation						
			Injury Savarity		irbag						
2	Injury Severity NO APPARENT INJURY				-						
			NO APPARENT INJURY		ION DEPLOYED						
		Ejected			jection Path	Trapped/Extricated					
		NOT EJECTED		1	IOT EJECTED/NOT APPLICABL	NOT TRAPPED					

6TL09JDKWD

18-12782

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

	INDIVIDUAL	Medical Transport NOT TRANSPORTED			EMS Agency Identifier		EMS Run#			
		Hospital			Date of Death		Time of Death			
		Non Motoris	Striking Unit #	Prior Action		Location		To/From School		
LINO		Action								
		Action Other								
					Suspected Drug Use NO					
		Alcohol Test Giver			Alcohol Test Type		Alcohol Test Results			
		Drug Test Given TEST NOT GIVEN			Drug Test Type		Drug Test Results			
01	001	Drug Type								
		Individual Condition								
		APPEARED NO								
	Pro	roperty Owner								
PROP OWNER 01	(608	ernment JK COUNTY HW 3) 356-3855			Address 620 STH 136 PO BOX 26 BARABOO, WI 53913 , US					
	Fixe	ed Objects St	ruck							
	2		Struck Object OTHER POST, POL	E OR SUPPORT			Structure Number	Damage Tag Number 322856		