
# 6TL0BGSFC5

### WISCONSIN MOTOR VEHICLE **CRASH REPORT**

#### SAUK COUNTY SHERIFFS DEPARTMEN **1300 LANGE COURT BARABOO, WI 53913** (608) 356-4895

18-12566



Crash Date 11/10/2018 Crash Time 03:58 PM

6TL0BGSFC5

#### 18-12566

# WISCONSIN MOTOR VEHICLE CRASH REPORT

ſ	ON CEMETERY RD					Latitude		Longitude		
	454 FT W					43.546296561			-90.095310231	
		DECKER RD		-	X Coordinate 249946.671875			Y Coordinate		
		HE TOWN OF IRONT						4826138.5		
	IN C	BAUK COUNT I		-	Structure Type					
Ċ	Cra	sh Scene								
T	First	Harmful Event				First Harm	iful Event I	ocation		
	DITCH					OUTSIDE RIGHT-OF-WAY (TRAFFICWAY)				
-	Man	ner of Collision					Light Condition			
	NO	COLLISION W/VEHIC				DAYLIGHT				
	Road	d Surface Condition(s)				Roadway Factor(s)				
	DR١	r								
F	Envi	ronment Factor(s)								
	NO	NE				NONE				
F	Wea	ther Condition(s)								
	CLC	DUDY								
ŀ	Anim	nal Type			Relation To Trafficway			ay		
					TRAFFICWA Crash Classific			-		
		sh Classification - Location						on - Jurisdiction URISDICTION		
-	PUBLIC PROPERTY Tribal Land					Access Co		RISDICTION		Special Study
					NO CONTROL					
		-				tion Type N INTERSECTION				
-		in Interchange Area			Intersection		CTION			
	NO						CTION			
   	NO Unit	t Summary		Vehicle Ope		INTERSE		Unit Type		
   	NO Unit Unit	t Summary Status		Vehicle Ope	NOT AN I	INTERSE		AUTOMO		
     	NO Unit Unit HIT Vehi	t Summary Status AND RUN Cle Type	NON-JUNCTION		NOT AN I	INTERSE				nents
   	NO Unit Unit HIT Vehi (SP	t Summary Status AND RUN cle Type ORT) UTILITY VEHICL	NON-JUNCTION	D CLASS	NOT AN I	INTERSE		AUTOMO Operating A	s Endorser	
l	NO Unit Unit HIT Vehi (SP	t Summary Status AND RUN Cle Type	NON-JUNCTION	D CLASS	NOT AN I	INTERSE		AUTOMO Operating A	s Endorser	ments Mat Types
     	NO Unit HIT Vehi (SP Tota 1	t Summary Status AND RUN cle Type ORT) UTILITY VEHICL	NON-JUNCTION	D CLASS Total # Cita 0	NOT AN I	INTERSE	Total Tra	AUTOMO Operating A	s Endorser	Mat Types
10	NO Unit HIT Vehi (SP Tota 1 Insu	t Summary Status AND RUN cle Type ORT) UTILITY VEHICL I Occs	NON-JUNCTION	D CLASS Total # Cita 0	NOT AN I	INTERSE	Total Tra 0	AUTOMO Operating A	As Endorser Total Haz 0	Mat Types
10	NO Unit HIT Vehi (SP Tota 1 Insut UNI Most	t Summary Status AND RUN cle Type ORT) UTILITY VEHICL I Occs rance? KNOWN t Harmful Event: Collision 1	NON-JUNCTION E Train/Bus # Injured Direction Of Travel NORTHBOUND	D CLASS	NOT AN I erating As Cla tions Issued CrashTire Mark Inction	assification	Total Tra <b>0</b> Speed Li	AUTOMO Operating A illers mit Emergency	s Endorser Total Haz 0 Total Lan 2 Motor Veh	Mat Types es icle Use
10	NO Unit HIT Vehi (SP Tota 1 Insui UNI Most DIT	t Summary Status AND RUN cle Type ORT) UTILITY VEHICL I Occs rance? KNOWN t Harmful Event: Collision <sup>1</sup> CH	NON-JUNCTION E Train/Bus # Injured Direction Of Travel NORTHBOUND	D CLASS	NOT AN I erating As Cla tions Issued CrashTire Mark CIAL FUNCT	assification	Total Tra <b>0</b> Speed Li	AUTOMO Operating A illers mit Emergency NOT APP	s Endorser Total Haz 0 Total Lan 2 Motor Veh LICABLE	Mat Types es icle Use
0	NO Unit Unit HIT Vehi (SP Tota 1 Insu UNI Most DIT Traff	t Summary Status AND RUN cle Type ORT) UTILITY VEHICL I Occs rance? KNOWN t Harmful Event: Collision <sup>1</sup> CH ic Way	NON-JUNCTION E Train/Bus # Injured Direction Of Travel NORTHBOUND With	D CLASS	NOT AN I erating As Cla tions Issued CrashTire Mark CIAL FUNCT trol	assification	Total Tra <b>0</b> Speed Li	AUTOMO Operating A illers mit Emergency NOT APP Traffic Cont	s Endorser Total Haz 0 Total Lan 2 Motor Veh LICABLE	Mat Types es icle Use
0	NO Unit HIT Vehi (SP Tota 1 Insur UNI Most DIT Traff	t Summary Status AND RUN cle Type ORT) UTILITY VEHICL I Occs rance? KNOWN t Harmful Event: Collision <sup>1</sup> CH	NON-JUNCTION E Train/Bus # Injured Direction Of Travel NORTHBOUND With	D CLASS	NOT AN I erating As Cla tions Issued CrashTire Mark inction CIAL FUNC1 trol TROL	assification	Total Tra <b>0</b> Speed Li	AUTOMO Operating A illers mit Emergency NOT APP	Total Haz 0 Total Lan 2 Motor Veh LICABLE rol Inoperat	Mat Types es icle Use
UNIT 01	NO Unit HIT Vehi (SP Tota 1 Insu UNI Moss DIT Traff TWO Surfa	t Summary Status AND RUN Cle Type ORT) UTILITY VEHICL I Occs rance? KNOWN t Harmful Event: Collision ' CH ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU	NON-JUNCTION E Train/Bus # Injured Direction Of Travel NORTHBOUND With	D CLASS	NOT AN I erating As Cla tions Issued CrashTire Mark Inction ClAL FUNCT trol TROL ature	assification	Total Tra <b>0</b> Speed Li	AUTOMO Operating A illers mit Emergency NOT APP Traffic Cont NO	Total Haz 0 Total Lan 2 Motor Veh LICABLE rol Inopera	Mat Types es icle Use
UNIT 01	NO Unit HIT Vehi (SP Tota 1 Insu UNI Moss DIT Traff TWO Surfa	t Summary Status AND RUN Cle Type ORT) UTILITY VEHICL OCCS rance? KNOWN t Harmful Event: Collision T CH fic Way D-WAY, NOT DIVIDED ace Type	NON-JUNCTION E Train/Bus # Injured Direction Of Travel NORTHBOUND With	D CLASS	NOT AN I erating As Cla tions Issued CrashTire Mark Inction ClAL FUNCT trol TROL ature	assification	Total Tra <b>0</b> Speed Li	AUTOMO Operating A iilers mit Emergency NOT APP Traffic Cont NO Road Grade	Total Haz 0 Total Lan 2 Motor Veh LICABLE rol Inopera	Mat Types es icle Use
UNIT 01	NO Unit HIT Vehi (SP Tota 1 Insuu UNI Most DIT Traff TWO Surfa BLA Truc NO	t Summary Status AND RUN Cle Type ORT) UTILITY VEHICL I Occs rance? KNOWN t Harmful Event: Collision ' CH ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU	NON-JUNCTION E Train/Bus # Injured Direction Of Travel NORTHBOUND With	D CLASS	NOT AN I erating As Cla tions Issued CrashTire Mark Inction ClAL FUNCT trol TROL ature	assification	Total Tra <b>0</b> Speed Li	AUTOMO Operating A iilers mit Emergency NOT APP Traffic Cont NO Road Grade	Total Haz 0 Total Lan 2 Motor Veh LICABLE rol Inopera	Mat Types es icle Use
UNIT 01	NO Unit HIT Vehi (SP Tota 1 Insuu UNI Most DIT Traff TWO Surfa BLA Truc NO	t Summary Status AND RUN cle Type ORT) UTILITY VEHICL I Occs rance? KNOWN t Harmful Event: Collision 1 CH ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU k Bus or HazMat Vehicle License Plate Number	NON-JUNCTION E Train/Bus # Injured Direction Of Travel NORTHBOUND With	D CLASS	NOT AN I erating As Cla tions Issued CrashTire Mark Cial FUNC Trol TROL ature IGHT	TION	Total Tra 0 Speed Li 45	AUTOMO Operating A illers mit Emergency NOT APP Traffic Cont NO Road Grade DOWNHIL	Is Endorser Total Haz Total Lan 2 Motor Veh LICABLE rol Inoperation	Mat Types es icle Use
UNIT 01	NO Unit HIT Vehi (SP Tota 1 Insuu UNI Most DIT Traff TWO Surfa BLA Truc NO	t Summary Status AND RUN Cle Type ORT) UTILITY VEHICL OCCS Trance? KNOWN t Harmful Event: Collision 1 CH fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU k Bus or HazMat Vehicle License Plate Number ADR7171	NON-JUNCTION  E Train/Bus # Injured Direction Of Travel NORTHBOUND With S S)	D CLASS	NOT AN I erating As Cla tions Issued CrashTire Mark ClAL FUNCT trol TROL ature IGHT	TION	Total Tra 0 Speed Li 45 St WI	AUTOMO Operating A iilers mit Emergency NOT APP Traffic Cont NO Road Grade DOWNHIL	Is Endorser Total Haz Total Lan 2 Motor Veh LICABLE rol Inoperation	Mat Types es icle Use
UNIT 01	NO Unit HIT Vehi (SP Tota 1 Insuu UNI Most DIT Traff TWO Surfa BLA Truc NO	t Summary Status AND RUN cle Type ORT) UTILITY VEHICL I Occs rance? KNOWN t Harmful Event: Collision 1 CH ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU k Bus or HazMat Vehicle License Plate Number	NON-JUNCTION  E Train/Bus # Injured Direction Of Travel NORTHBOUND With S S)	D CLASS	NOT AN I erating As Cla tions Issued CrashTire Mark Inction ClAL FUNCT trol TROL ature IGHT	TION	Total Tra 0 Speed Li 45	AUTOMO Operating A illers mit Emergency NOT APP Traffic Cont NO Road Grade DOWNHIL	Is Endorser Total Haz Total Lan 2 Motor Veh LICABLE rol Inoperation	Mat Types es icle Use
UNIT 01	NO Unit HIT Vehi (SP Tota 1 Insuu UNI Most DIT Traff TW( Surfa BLA Truc NO	t Summary Status AND RUN Cle Type ORT) UTILITY VEHICL OCCS Trance? KNOWN t Harmful Event: Collision 1 CH Tic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU k Bus or HazMat Vehicle License Plate Number ADR7171 Vehicle Identification Nur	NON-JUNCTION  E Train/Bus # Injured Direction Of Travel NORTHBOUND With S S)	D CLASS	NOT AN I erating As Cla tions Issued CrashTire Mark notion ClAL FUNCT trol TROL ature IGHT JTOMOBILI ER	TION	Total Tra 0 Speed Li 45 St WI Year	AUTOMO Operating A iilers mit Emergency NOT APP Traffic Cont NO Road Grade DOWNHII Country of Is UNITED S <sup>**</sup> Model PACIFICA Bus Use	In Sendorser Total Haz Total Lan 2 Motor Veh LICABLE rol Inopera C L	Mat Types es icle Use
UNIT 01	NO Unit HIT Vehi (SP Tota 1 Insuu UNI Most DIT Traff TW( Surfa BLA Truc NO	t Summary Status AND RUN Cle Type ORT) UTILITY VEHICL OCCS rance? (NOWN t Harmful Event: Collision ' CH fic Way O-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU k Bus or HazMat Vehicle License Plate Number ADR7171 Vehicle Identification Nur 2C4GF48485R308344 Color RED - RED	NON-JUNCTION  E Train/Bus # Injured Direction Of Travel NORTHBOUND With S S)	D CLASS	NOT AN I erating As Cla tions Issued CrashTire Mark notion IAL FUNCT trol rROL ature IGHT JTOMOBILI	INTERSE assification TION E	Total Tra 0 Speed Li 45 St WI Year 2005	AUTOMO Operating A iilers mit Emergency NOT APP Traffic Cont NO Road Grade DOWNHII Country of Is UNITED S Model PACIFICA	In Sendorser Total Haz Total Lan 2 Motor Veh LICABLE rol Inopera C L	Mat Types es icle Use
01 UNIT 01	NO Unit HIT Vehi (SP Tota 1 Insuu UNH Most DIT Traff BLA Truc NO	t Summary Status AND RUN Cle Type ORT) UTILITY VEHICL OCCS rance? (NOWN t Harmful Event: Collision ' CH fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU k Bus or HazMat Vehicle License Plate Number ADR7171 Vehicle Identification Nur 2C4GF48485R308344 Color RED - RED Initial Contact Point	NON-JUNCTION  E Train/Bus # Injured Direction Of Travel NORTHBOUND With S S)	D CLASS	NOT AN I erating As Cla tions Issued CrashTire Mark notion IAL FUNCT trol rROL ature IGHT JTOMOBILI	INTERSE assification TION E	Total Tra 0 Speed Li 45 St WI Year 2005	AUTOMO Operating A iilers mit Emergency NOT APP Traffic Cont NO Road Grade DOWNHII Country of Is UNITED S <sup>**</sup> Model PACIFICA Bus Use	In Sendorser Total Haz Total Lan 2 Motor Veh LICABLE rol Inopera C L	Mat Types es icle Use
UNIT 01	NO Unit HIT Vehi (SP Tota 1 Insuu UNI Most DIT Traff TW( Surfa BLA Truc NO	t Summary Status AND RUN Cle Type ORT) UTILITY VEHICL OCCS rance? (NOWN t Harmful Event: Collision ' CH fic Way O-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU k Bus or HazMat Vehicle License Plate Number ADR7171 Vehicle Identification Nur 2C4GF48485R308344 Color RED - RED	NON-JUNCTION  E Train/Bus # Injured Direction Of Travel NORTHBOUND With S S)	D CLASS	NOT AN I erating As Cla tions Issued CrashTire Mark action CrashTire Mark action CrashTire Mark ature CrashTire Mark ature IGHT JTOMOBILI ER DRT UTILIT amage	INTERSE assification TION E	Total Tra 0 Speed Li 45 St WI Year 2005	AUTOMO Operating A iilers mit Emergency NOT APP Traffic Cont NO Road Grade DOWNHII Country of Is UNITED S <sup>**</sup> Model PACIFICA Bus Use	In Sendorser Total Haz Total Lan 2 Motor Veh LICABLE rol Inopera C L	Mat Types es icle Use



18-12566

# WISCONSIN MOTOR VEHICLE CRASH REPORT

		Towed Due To Dama	5						
			DISABLING DAMAGE	STEVES AUTO SERVICE					
		What Driver Was Doi		Vehicle Factors					
		NEGOTIATING C		NOT APPLICABLE					
		Driver Prior Action O	ther						
		Driver Actions							
	ш		NTROL, UNKNOWN						
F	U U								
UNIT	Ĭ								
	VEHICLE								
	-								
			UNKNOWN IF DISTRACTED						
0	6								
-	-								
		Owner Name		Owner Address					
			MIRANO MORAZAN	32602 COUNTY HWY V					
		(608) 477-3821		CAZENOVIA, WI 53924 , US					
		Sequence Of E	vents						
	2	Event MOTOR VEH IN T	RANSPORT						
	-	Event							
	02	DITCH							
	e	Event							
	03	TREE							
	64	Event							
	-								
	l	Individual		Citations logued	0				
		Driver		Citations Issued	Sex				
	AL			Date of Birth	Race				
<b>L</b>	DIVIDUAL			Date of Birth					
UNIT	Ξ	Address		Driver License Number					
	Ē								
	Z	, ,							
		Equipment	On Duty Crash	Safety Equipment					
		Seat Position 1FRONT SEAT-LEFT SIDE (DRIVER/MOTORCY		RESTRAINT USE UNKNOWN					
		Helmet Use       Eye Protection		Helmet Compliance					
				Tint Compliance					
01	001	Injury		Airbag NOT APPLICABLE					
	0		NO APPARENT INJURY	Ejection Path	Trapped/Extricated				
		Ejected NOT APPLICABLE		NOT EJECTED/NOT APPLICABL	NOT APPLICABLE				
		Medical Transport		EMS Agency Identifier	EMS Run #				
		NOT TRANSPOR	TED						

### 6TL0BGSFC5

18-12566

## WISCONSIN MOTOR VEHICLE CRASH REPORT

#### SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

	Hospital			Date of Death		Time of Death	
ľ	Non Motorist	Striking Unit #	Prior Action		Location		To/From School
	Action	•					
JAL							
וחר							
=							
	Action Other						
		Suspected Alcohol L	Jse	Suspected Drug Us	Se		
Ľ	-						
		1		Alcohol Test Type		Alcohol Test Results	
				Drug Test Type		Drug Test Results	
001	Drug Type						
•							
	NOT OBSERVED						
	INDIVIDUAL	Non Motorist         Action         Action Other         Action Other         Drug & Alcohol         Alcohol Test Given         TEST NOT GIVEN         Drug Type         Individual Condition	Non Motorist     Striking Unit #       Action     Action       Action Other     Suspected Alcohol I       Action I Test Given     Suspected Alcohol I       Test NOT GIVEN     Drug Test Given       Drug Type     Drug Type	Non Motorist       Striking Unit #       Prior Action         Action       Action         Action Other       Suspected Alcohol Use         Action Test Given       TEST NOT GIVEN         Drug Test Given       TEST NOT GIVEN         Drug Type       Individual Condition	Non Motorist       Striking Unit #       Prior Action         Action       Action         Action Other       Action Other         Drug & Alcohol       Suspected Alcohol Use       Suspected Drug Use         Alcohol Test Given       Alcohol Test Given       Alcohol Test Type         TEST NOT GIVEN       Drug Test Given       Drug Test Type         Drug Type       Individual Condition       Drug Type	Non Motorist       Striking Unit #       Prior Action       Location         Action       Action       Action       Action         Action Other       Suspected Alcohol Use       Suspected Drug Use         Drug & Alcohol       Suspected Alcohol Use       Suspected Drug Use         Alcohol Test Given       Alcohol Test Type         TEST NOT GIVEN       Drug Test Type         Drug Type       Individual Condition	Non Motorist       Striking Unit #       Prior Action       Location         Action       Action       Action       Action         Action Other       Suspected Alcohol Use       Suspected Drug Use         Drug & Alcohol       Suspected Alcohol Use       Suspected Drug Use         Alcohol Test Given       Alcohol Test Type       Alcohol Test Results         TEST NOT GIVEN       Drug Test Type       Drug Test Results         Drug Type       Individual Condition       Individual Condition