6TL0BJ1GHC

18-12879

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Document Number Override	ash Date Crash Time /19/2018 01:00 AM ste Notified Time Notified		18-12879		Investigating Officer/Deputy DEPUTY J. MACASKILL Time Arrived 01:35 AM		
Crash Date 11/19/2018							
Date Notified			nits	Total Injured			
11/19/2018	01:27 AM	01		00	00	Reporting	
On Emergency Hit	and Run La	ane Closure	Work Zone		or Towed	Threshold	
Government Active School Zone NC			Bus Related	Tags			
✓ Reportable	Crash Type DT4000 (STANDARI	D CRASH)		Amende	ed	Secondary Crash	
Description						1	
Unit 1 Fern Dell Rd	Unit 1	Unit 1	Unit 1		Photos By Additional Infor		
I, a sworn law enforcement on 11/19/18 AT AN UNKNOWN THE RIGHT, ENTERING THE DITCUNIT 1 THEN LEFT THE SCENE CONTRACTOR OF T	ME, UNIT 1 WAS DRIVI CH AND CRASHING HIS DF THE ACCIDENT AND	NG EASTBOUND O VEHICLE AT THE WENT HOME. AN	ON FERN DELL RD WH BOTTOM OF THE DIT UNKNOWN AMOUNT	his report. EN UNIT 1 GRADU CH, STRIKING TWO OF TIME PASSED	O GUIDE WIRE BEFORE UNIT	S FOR A POWER POLE.	

6TL0BJ1GHC 18-12879

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 11/19/2018

Crash Time 01:00 AM

	Loc	ation								
į		FERN DELL RD (1)			L	atitude			Longitud	le
		T E		43.561301106			-89.798589637			
	OF ISHNALA RD							Y Coordinate		
	IN THE TOWN OF DELTON									
	IN SAUK COUNTY									
						Structure Type				
	Cra	sh Scene								
,		Harmful Event			T e					
						irst Harmful Ev		ation		
	DIT	ner of Collision			_	N ROADWA	41			
			I E IN TO ANGROOT			ight Condition				
		COLLISION W/VEHIC	LE IN TRANSPORT			DARK/UNLIT				
	Road	d Surface Condition(s)			R	Roadway Facto	r(s)			
	DRY	Y								
	Envi	ronment Factor(s)								
	ANI	MAL (S) IN ROADWA	Y		N	IONE				
	Wea	ther Condition(s)								
	CLC	OUDY								
	Anim	nal Type			Relation To Trafficway TRAFFICWAY - ON ROAD					
	DEE	**						ROAD		
		sh Classification - Location				rash Classifica				
		BLIC PROPERTY				IO SPECIAL				
	Triba	al Land			A	ccess Control	s Control Specia		Special Study	
					NO CONTROL		L			
	With NO	in Interchange Area	Junction Location NON-JUNCTION			rsection Type T AN INTERSECTION				
			11011 0011011011							
					NOT AIT III	TEROLOTIC	/14			
		t Summary		L Vahiala One				Hair Tone		
	Unit	Status			erating As Clas			Unit Type	DII E	
	Unit IN T	Status TRANSIT		Vehicle Ope	erating As Clas			AUTOMO		monte
	Unit IN T Vehi	Status RANSIT icle Type			erating As Clas					nents
	Unit IN T Vehi PAS	Status TRANSIT	Train/Bus # Injured	D CLASS	erating As Clas	sification	al Traile	AUTOMOI Operating A	s Endorser	ments Mat Types
	Unit IN T Vehi PAS	Status FRANSIT Icle Type SSENGER CAR	Train/Bus # Injured	D CLASS	erating As Clas	sification		AUTOMOI Operating A	s Endorser	
	Unit IN T Vehi PAS Tota 1	Status FRANSIT Icle Type SSENGER CAR	Train/Bus # Injured Direction Of Travel	Total # Cita	erating As Class	resification Tota		AUTOMOI Operating A	s Endorser Total Haz	Mat Types
	Unit IN T Vehi PAS Tota 1 Insur UNP	Status RANSIT ICIE Type SSENGER CAR I Occs rance? KNOWN	Direction Of Travel EASTBOUND	Total # Cita 0 Pre	erating As Class tions Issued CrashTire Mark	resification Tota	al Traile	AUTOMOI Operating A	Total Haz Total Land	Mat Types es
	Unit IN T Vehi PAS Tota 1 Insui UNI Most	Status RANSIT ICIE Type SSENGER CAR I Occs rance? KNOWN t Harmful Event: Collision N	Direction Of Travel EASTBOUND	Total # Cita 0 Pre Special Fun	tions Issued CrashTire Mark	Tota 0 Spe 35	al Traile	AUTOMOI Operating A	Total Haz Total Land Total Land Motor Vehi	Mat Types es cle Use
	Unit IN T Vehi PAS Tota 1 Insui UNP	Status RANSIT Icle Type SSENGER CAR II Occs rance? KNOWN t Harmful Event: Collision \ CH	Direction Of Travel EASTBOUND	Total # Cita 0 Pre Special Fun NO SPEC	tions Issued CrashTire Mark action EIAL FUNCTION	Tota 0 Spe 35	al Traile	AUTOMOI Operating A	Total Haz Total Land Total Land Motor Vehi	Mat Types es cle Use
	Unit IN T Vehi PAS Tota 1 Insui UNI Most DITG	Status RANSIT icle Type SSENGER CAR I Occs rance? KNOWN t Harmful Event: Collision \ CH fic Way	Direction Of Travel EASTBOUND With	Total # Cita 0 Pre Special Fun NO SPEC Traffic Cont	tions Issued CrashTire Mark action EIAL FUNCTION	Tota 0 Spe 35	al Traile	AUTOMOI Operating A TS Emergency NOT APPI Traffic Cont	Total Haz Total Land Total Land Motor Vehi	Mat Types es cle Use
	Unit IN T Vehi PAS Tota 1 Insui UNP Most DITO	Status FRANSIT ICIDE Type SSENGER CAR II Occs FRANCE FRANCE FRANCE	Direction Of Travel EASTBOUND With	Total # Cita 0 Pre Special Fun NO SPEC Traffic Cont	erating As Class tions Issued CrashTire Mark cition CIAL FUNCTION CIAL FUNCTION CITICAL	Tota 0 Spe 35	al Traile	AUTOMOI Operating A TS Emergency NOT APPI Traffic Conti	Total Haz O Total Lane 2 Motor Vehi LICABLE rol Inoperat	Mat Types es cle Use
	Unit IN T Vehi PAS Tota 1 Insui UNI Most DITC Traff TWC	Status RANSIT icle Type SSENGER CAR Il Occs rance? KNOWN t Harmful Event: Collision V CH fic Way D-WAY, NOT DIVIDED ace Type	Direction Of Travel EASTBOUND With	Total # Cita 0 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva	tions Issued CrashTire Mark Cidal FUNCTION CIAL FUNCTION	Tota 0 Spe 35	al Traile	AUTOMOI Operating A s Emergency NOT APPI Traffic Cont NO Road Grade	Total Haz 0 Total Land 2 Motor Vehi LICABLE	Mat Types es cle Use
	Unit IN T Vehi PAS Tota 1 Insui UNI Most DITC Traff TWC Surfa	Status TRANSIT Icle Type SSENGER CAR Il Occs rance? KNOWN It Harmful Event: Collision of CH Iclic Way D-WAY, NOT DIVIDED IACKTOP (BITUMINOU	Direction Of Travel EASTBOUND With	Total # Cita 0 Pre Special Fun NO SPEC Traffic Cont	tions Issued CrashTire Mark Cidal FUNCTION CIAL FUNCTION	Tota 0 Spe 35	al Traile	AUTOMOI Operating A TS Emergency NOT APPI Traffic Conti	Total Haz 0 Total Land 2 Motor Vehi LICABLE	Mat Types es cle Use
	Unit IN T Vehi PAS Tota 1 Insui UNI Most DITC Traff TWC Surfa	Status TRANSIT Icle Type SSENGER CAR II Occs France? KNOWN It Harmful Event: Collision of CH Ific Way D-WAY, NOT DIVIDED France Type ACKTOP (BITUMINOU Ik Bus or HazMat	Direction Of Travel EASTBOUND With	Total # Cita 0 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva	tions Issued CrashTire Mark Cidal FUNCTION CIAL FUNCTION	Tota 0 Spe 35	al Traile	AUTOMOI Operating A s Emergency NOT APPI Traffic Cont NO Road Grade	Total Haz 0 Total Land 2 Motor Vehi LICABLE	Mat Types es cle Use
	Unit IN T Vehi PAS Tota 1 Insur UNIT Most DITC Traff TWC Surfa BLA	Status TRANSIT Icle Type SSENGER CAR II Occs France? KNOWN It Harmful Event: Collision of CH Ific Way D-WAY, NOT DIVIDED France Type ACKTOP (BITUMINOU Ik Bus or HazMat	Direction Of Travel EASTBOUND With	Total # Cita 0 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva	tions Issued CrashTire Mark Cidal FUNCTION CIAL FUNCTION	Tota 0 Spe 35	al Traile	AUTOMOI Operating A s Emergency NOT APPI Traffic Cont NO Road Grade	Total Haz 0 Total Land 2 Motor Vehi LICABLE	Mat Types es cle Use
	Unit IN T Vehi PAS Tota 1 Insur UNIT Most DITC Traff TWC Surfa BLA	Status RANSIT Icle Type SSENGER CAR I Occs rance? KNOWN It Harmful Event: Collision V CH Ific Way D-WAY, NOT DIVIDED IACKTOP (BITUMINOU Ick Bus or HazMat Vehicle License Plate Number	Direction Of Travel EASTBOUND With	Total # Cita 0 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva STRAIGH	tions Issued CrashTire Mark action EIAL FUNCTION FROL atture T	Tota 0 Spe 35	al Trailer	AUTOMOI Operating A TS Emergency NOT APPI Traffic Cont NO Road Grade DOWNHIL	Total Haz 0 Total Land 2 Motor Vehi LICABLE rol Inoperat	Mat Types es cle Use
	Unit IN T Vehi PAS Tota 1 Insur UNIT Most DITC Traff TWC Surfa BLA	Status RANSIT ICIE Type SSENGER CAR II Occs France? KNOWN It Harmful Event: Collision Note CH Ific Way D-WAY, NOT DIVIDED FACKTOP (BITUMINOU) Ick Bus or HazMat Vehicle	Direction Of Travel EASTBOUND With	Total # Cita 0 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva STRAIGH	tions Issued CrashTire Mark CIAL FUNCTION CIAL FUNCTION CITY TO THE TO	Tota 0 Spe 35	al Trailer	AUTOMOI Operating A TS Emergency NOT APPI Traffic Cont NO Road Grade DOWNHIL	Total Haz 0 Total Land 2 Motor Vehi LICABLE rol Inoperat	Mat Types es cle Use
	Unit IN T Vehi PAS Tota 1 Insuru UNI Most DITC Surfat BLA	Status RANSIT icle Type SSENGER CAR I Occs rance? KNOWN t Harmful Event: Collision of the	Direction Of Travel EASTBOUND With	Total # Cita 0 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva STRAIGH Plate Type AUT - AU Make	tions Issued CrashTire Mark action EIAL FUNCTION FROL atture T	Tota 0 Spe 35 ON	al Trailer ed Limit	AUTOMOI Operating A TS Emergency NOT APPI Traffic Cont NO Road Grade DOWNHIL Country of Is UNITED ST	Total Haz 0 Total Land 2 Motor Vehi LICABLE rol Inoperat	Mat Types es cle Use
	Unit IN T Vehi PAS Tota 1 Insur UNIT Most DITC Traff TWC Surfa BLA	Status RANSIT ICIDE Type SSENGER CAR I OCCS FRANCE? KNOWN I Harmful Event: Collision V CH fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU IK Bus or HazMat Vehicle License Plate Number 467MLL Vehicle Identification Nur 1HGEM22984L04785	Direction Of Travel EASTBOUND With	Total # Cita 0 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva STRAIGH Plate Type AUT - AU Make HONDA	tions Issued CrashTire Mark Action EIAL FUNCTION FROL Acture T	Tota 0 Spe 35 ON	al Trailer ed Limit	AUTOMOI Operating A S Emergency NOT APPI Traffic Cont NO Road Grade DOWNHIL Country of Is UNITED ST Model CIVIC EX	Total Haz 0 Total Land 2 Motor Vehi LICABLE rol Inoperat	Mat Types es cle Use
	Unit IN T Vehi PAS Tota 1 Insuru UNI Most DITC Surfat BLA	Status RANSIT icle Type SSENGER CAR I Occs rance? KNOWN t Harmful Event: Collision of the	Direction Of Travel EASTBOUND With	Total # Cita 0 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva STRAIGH Plate Type AUT - AU Make	tions Issued CrashTire Mark notion EIAL FUNCTION FROL ature T	Tota 0 Spe 35 ON	ed Limit	AUTOMOI Operating A TS Emergency NOT APPI Traffic Cont NO Road Grade DOWNHIL Country of Is UNITED ST	Total Haz Total Land Motor Vehi LICABLE rol Inoperation	Mat Types es cle Use
	Unit IN T Vehi PAS 1 Insur UNIT Most DITC Surface BLA Truc NO	Status RANSIT ICIDE Type SSENGER CAR I OCCS FRANCE? KNOWN I Harmful Event: Collision V CH fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU IK Bus or HazMat Vehicle License Plate Number 467MLL Vehicle Identification Nur 1HGEM22984L04785 Color	Direction Of Travel EASTBOUND With	Total # Cita 0 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva STRAIGH Plate Type AUT - AU Make HONDA Body Style	tions Issued CrashTire Mark Inction IROL Atture T	Tota 0 Spe 35 ON	ed Limit	AUTOMOI Operating A TS Emergency NOT APPI Traffic Cont NO Road Grade DOWNHIL Country of Is UNITED ST Model CIVIC EX Bus Use	Total Haz Total Land Motor Vehi LICABLE rol Inoperation	Mat Types es cle Use
	Unit IN T Vehi PAS 1 Insur UNIT Most DITC Surface BLA Truc NO	Status TRANSIT ICIDIE Type SSENGER CAR I OCCS TRANCE? KNOWN I Harmful Event: Collision V CH Fic Way D-WAY, NOT DIVIDED ACKTOP (BITUMINOU Ick Bus or HazMat Vehicle License Plate Number 467MLL Vehicle Identification Nur 1HGEM22984L04785 Color GRY - GRAY	Direction Of Travel EASTBOUND With	Total # Cita 0 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva STRAIGH Plate Type AUT - AU Make HONDA Body Style CP - COU	tions Issued CrashTire Mark Inction IROL Atture T	Tota 0 Spe 35 ON	ed Limit	AUTOMOI Operating A TS Emergency NOT APPI Traffic Cont NO Road Grade DOWNHIL Country of Is UNITED ST Model CIVIC EX Bus Use	Total Haz Total Land Motor Vehi LICABLE rol Inoperation	Mat Types es cle Use
	Unit IN T Vehi PAS Tota 1 Insuru UNI Most DITC Surfat BLA	Status TRANSIT Icle Type SSENGER CAR I Occs Trance? KNOWN I Harmful Event: Collision V CH fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU Ik Bus or HazMat Vehicle License Plate Number 467MLL Vehicle Identification Nur 1HGEM22984L04785 Color GRY - GRAY Initial Contact Point	Direction Of Travel EASTBOUND With	Total # Cita 0 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva STRAIGH Plate Type AUT - AU Make HONDA Body Style CP - COU	tions Issued CrashTire Mark Inction IROL ITOMOBILE ITOMOBILE ITOMOBILE ITOMOBILE ITOMOBILE	Tota 0 Spe 35 ON	ed Limit	AUTOMOI Operating A TS Emergency NOT APPI Traffic Cont NO Road Grade DOWNHIL Country of Is UNITED ST Model CIVIC EX Bus Use	Total Haz Total Land Motor Vehi LICABLE rol Inoperation	Mat Types es cle Use

6TL0BJ1GHC

18-12879

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT **BARABOO, WI 53913** (608) 356-4895

		Towed Due To Dama TOWED BUT NOT	age ΓDUE TO DISABLING DAMAG	Vehicle Removed By BILLS TOWING				
		What Driver Was Doi	ing	Vehicle Factors				
	UNKNOWN			LINUCALOWAL				
		Driver Prior Action Of	ther	UNKNOWN				
		Driver Actions						
.	쁘	UNKNOWN						
L N N	VEHICL							
⋾	Ψ							
	>							
		Driver Distractions UNKNOWN IF DIS	STRACTED					
			TIMOTES					
5	6							
		Owner Name		Owner Address				
		DAVID CHRISTOI	PHER LARSON	S2243 GROUSE RIDGE CT				
		(608) 432-3448		BARABOO, WI 53913 , US				
	,	Sequence Of E	vents					
	5	RUN OFF ROADV	VAY RIGHT					
	05	Event DITCH						
	03	Event	DLE OR SUPPORT					
		Event	DLE OR SUFFORT					
	04							
	ı	Individual						
		Driver DAVID CHRISTOPHER LARSON		Citations Issued	Sex			
	AL	(608) 432-3448	TIER EAROON	Date of Birth	MALE Race			
⊢│	DIVIDUAL			Bate of Birth	WHITE			
	₹	Address		Driver License Number				
٦		S2243 GROUSE RIDGE CT BARABOO, WI 53913 , US		STATE: WISCONSIN COUNTRY: UNITED STATES				
		Familiana	On Duty Crash	Safety Equipment				
		Equipment						
		Seat Position 1FRONT SEAT-LEFT SIDE (DRIVER/MOTORCY		OTHER				
		Helmet Use	LEI I SIDE (DIVIVEIXIMOTORO)	Helmet Compliance				
		Eye Protection		Tint Compliance				
_	Ξ		Injury Severity	Airbag				
5	00	Injury	NO APPARENT INJURY	NON DEPLOYED				
		Ejected NOT EJECTED		Ejection Path	Trapped/Extricated NOT TRAPPED			
		Medical Transport		NOT EJECTED/NOT APPLICABL EMS Agency Identifier	EMS Run #			
		NOT TRANSPOR	TED					
				•	•			

6TL0BJ1GHC

18-12879

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 11/19/2018

Crash Time 01:00 AM

		Hospital			Date of Death		Time of Death	
	,	Non Motorist	Striking Unit #	Prior Action		Location		To/From School
		Action	•	1				
	AL							
UNIT	IDU							
5	INDIVIDUAL							
	2							
		Action Other						
	E	Prug & Alcoho	Suspected Alcohol I YES	Jse	Suspected Drug Us	S e		
		Alcohol Test Given TEST NOT GIVE			Alcohol Test Type		Alcohol Test Results	
		Drug Test Given TEST NOT GIVE			Drug Test Type		Drug Test Results	
_	1	Drug Type	:IN					
01	001	3 71 -						
		Individual Condition	า					
		NOT OBSERVE	D					
	Pro	perty Owner	•					
10		nization/Company			Address 4902 N BILTMOR	E		
PROP OWNER					MADISON, WI 53	707 1077, US		
	Fixe	d Objects St						
	2		Struck Object UTILITY POLE					Damage Tag Number 337648