

6TL0BLHJPH
18-12576



WISCONSIN MOTOR VEHICLE
CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMENT
1300 LANGE COURT
BARABOO, WI 53913
(608) 356-4895

6TL0BLHJPH

Document Number Override		Primary Crash Document #	Agency Crash Number 18-12576	Investigating Officer/Deputy DEPUTY I. GALVAN	
Crash Date 11/10/2018		Crash Time 09:00 PM	Date Arrived 11/10/2018	Time Arrived 09:08 PM	
Date Notified 11/10/2018		Time Notified 09:02 PM	Total Units 02	Total Injured 00	Total Killed 00
<input type="checkbox"/> On Emergency	<input checked="" type="checkbox"/> Hit and Run	<input type="checkbox"/> Lane Closure	<input type="checkbox"/> Work Zone	<input type="checkbox"/> Trailer or Towed	<input type="checkbox"/> Reporting Threshold
<input type="checkbox"/> Government Property		<input type="checkbox"/> Active School Zone	School Bus Related NO	Tags	
<input checked="" type="checkbox"/> Reportable		Crash Type DT4000 (STANDARD CRASH)		<input type="checkbox"/> Amended	<input type="checkbox"/> Secondary Crash

Description

<p>Diagram</p>  <p>GUDENSCHWAGGER RD</p> <p style="text-align: right;">CTH V</p> <hr/>  <p style="text-align: center;">STH 33</p> <p style="text-align: center;">NOT TO SCALE</p>	Reconstruction By
	Photos By DEPUTY STEPHANIE STACEY
	Additional Information PHOTOS

I, a sworn law enforcement officer, agree that I have not added any CJIS data in this report.

UNIT 2 WAS TRAVELING WESTBOUND ON STH 33 BETWEEN CTH V AND GUDENSCHWAGGER ROAD. UNIT 1 TRAVELING THE SAME DIRECTION STRUCK UNIT 2 REAR TWO TIMES. ONE TIME WEST OF CTH V AND A SECOND TIME EAST OF GUDENSCHWAGGER ROAD. NO INJURIES. VEHICLES REMOVED BY ARRANGEMENTS MADE BY OPERATORS. UNIT 2 CITED FOR OPERATING WHILE UNDER THE INFLUENCE AND FOLLOWING TOO CLOSELY.

6TL0BLHJPH
18-12576

WISCONSIN MOTOR VEHICLE
CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMENT
1300 LANGE COURT
BARABOO, WI 53913
(608) 356-4895

Location

ON STH33 WB 460 FT W OF CTHV WB IN THE TOWN OF LA VALLE IN SAUK COUNTY	Latitude 43.576064069	Longitude -90.108168306
	X Coordinate 249031.59375	Y Coordinate 4829483.5
	Structure Type	

Crash Scene

First Harmful Event MOTOR VEH IN TRANSPORT	First Harmful Event Location ON ROADWAY	
Manner of Collision 02--FRONT TO REAR	Light Condition DARK/UNLIT	
Road Surface Condition(s) DRY	Roadway Factor(s) NONE	
Environment Factor(s) NONE		
Weather Condition(s) CLEAR		
Animal Type	Relation To Trafficway TRAFFICWAY - ON ROAD	
Crash Classification - Location PUBLIC PROPERTY	Crash Classification - Jurisdiction NO SPECIAL JURISDICTION	
Tribal Land	Access Control NO CONTROL	Special Study
Within Interchange Area NO	Junction Location NON-JUNCTION	Intersection Type NOT AN INTERSECTION

Unit Summary

01 UNIT	Unit Status HIT AND RUN	Vehicle Operating As Classification D CLASS	Unit Type TRUCK		
	Vehicle Type UTILITY TRUCK/PICKUP TRUCK			Operating As Endorsements	
	Total Occs 1	Train/Bus # Injured	Total # Citations Issued 2	Total Trailers 0	Total HazMat Types 0
	Insurance? UNKNOWN	Direction Of Travel WESTBOUND	<input type="checkbox"/> Pre Crash Tire Mark	Speed Limit 55	Total Lanes 2
	Most Harmful Event: Collision With MOTOR VEH IN TRANSPORT		Special Function NO SPECIAL FUNCTION	Emergency Motor Vehicle Use NOT APPLICABLE	
	Traffic Way TWO-WAY, NOT DIVIDED		Traffic Control NO CONTROL	Traffic Control Inoperative/Missing NO	
	Surface Type BLACKTOP (BITUMINOUS)		Road Curvature STRAIGHT	Road Grade LEVEL	
	Truck Bus or HazMat NO				

01 UNIT VEHICLE	Vehicle			
	License Plate Number JC3226	Plate Type LTK - LIGHT TRUCK	St WI	Country of Issuance UNITED STATES
	Vehicle Identification Number 1FTSW21589EB18407	Make FORD	Year 2009	Model F250
	Color WHI - WHITE	Body Style PK - PICKUP		Bus Use NOT A BUS
	Initial Contact Point 12--FRONT	Vehicle Damage		
	Extent Of Damage NO DAMAGE	NO DAMAGE		

6TL0BLHJPH
18-12576

WISCONSIN MOTOR VEHICLE
CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMENT
1300 LANGE COURT
BARABOO, WI 53913
(608) 356-4895

UNIT	Towed Due To Damage NOT TOWED		Vehicle Removed By OPERATOR		
	What Driver Was Doing GOING STRAIGHT		Vehicle Factors		
	Driver Prior Action Other		NOT APPLICABLE		
	Driver Actions FOLLOWING TOO CLOSE, OPERATED MOTOR VEHICLE IN INATTENTIVE, CARELESS OR ERRATIC MANNER				
01	01	Driver Distractions OTHER DISTRACTION			
		Owner Name CUT AND RUN TREE SERVICE LLC (608) 393-3763	Owner Address S1051 STATE ROAD 58 LAVALLE, WI 53941 , US		
Sequence Of Events					
UNIT	INDIVIDUAL	01	Event MOTOR VEH IN TRANSPORT		
		02	Event MOTOR VEH IN TRANSPORT		
		03	Event		
		04	Event		
01	001	Individual			
		Driver TROY E ROSE (608) 393-3763		Citations Issued 2	Sex MALE
		Address S1832 STATE ROAD 58 LAVALLE, WI 53941 , US		Date of Birth [REDACTED]	Race WHITE
		Driver License Number [REDACTED]		STATE: WISCONSIN COUNTRY: UNITED STATES	
		Equipment		On Duty Crash	Safety Equipment
		Seat Position 1--FRONT SEAT-LEFT SIDE (DRIVER/MOTORCY		RESTRAINT USE UNKNOWN	
		Helmet Use		Helmet Compliance	
		Eye Protection		Tint Compliance	
		Injury		Injury Severity NO APPARENT INJURY	Airbag NOT APPLICABLE
		Ejected NOT APPLICABLE		Ejection Path NOT EJECTED/NOT APPLICABL	Trapped/Extricated NOT APPLICABLE
Medical Transport NOT TRANSPORTED		EMS Agency Identifier	EMS Run #		

6TL0BLHJPH
18-12576

WISCONSIN MOTOR VEHICLE
CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMENT
1300 LANGE COURT
BARABOO, WI 53913
(608) 356-4895

UNIT	Hospital		Date of Death		Time of Death	
	Non Motorist		Striking Unit #	Prior Action	Location	To/From School
	Action					
	Action Other					
	Drug & Alcohol		Suspected Alcohol Use		Suspected Drug Use	
	Alcohol Test Given TEST NOT GIVEN			Alcohol Test Type	Alcohol Test Results	
	Drug Test Given TEST NOT GIVEN			Drug Test Type	Drug Test Results	
	Drug Type					
	Individual Condition NOT OBSERVED					
	Violations					
01	001	UTC Number AE757505	Issue To? 001	Statute Number 346.63(1)(a)	Seq Num 002	Description OPERATING WHILE UNDER THE INFLUENCE
		UTC Number A1392680	Issue To? 001	Statute Number 346.14(1m)	Seq Num 001	Description AUTOMOBILE FOLLOWING TOO CLOSELY

Unit Summary

UNIT	02	Unit Status IN TRANSIT		Vehicle Operating As Classification D CLASS		Unit Type TRUCK		
		Vehicle Type UTILITY TRUCK/PICKUP TRUCK				Operating As Endorsements		
		Total Occs 1	Train/Bus # Injured	Total # Citations Issued 0	Total Trailers 0	Total HazMat Types 0		
		Insurance? UNKNOWN	Direction Of Travel WESTBOUND	<input type="checkbox"/> Pre Crash Tire Mark	Speed Limit 55	Total Lanes 2		
		Most Harmful Event: Collision With MOTOR VEH IN TRANSPORT			Special Function NO SPECIAL FUNCTION		Emergency Motor Vehicle Use NOT APPLICABLE	
		Traffic Way TWO-WAY, NOT DIVIDED			Traffic Control NO CONTROL		Traffic Control Inoperative/Missing NO	
		Surface Type BLACKTOP (BITUMINOUS)			Road Curvature STRAIGHT		Road Grade LEVEL	
		Truck Bus or HazMat NO						
		02	02	Vehicle				
				License Plate Number PN6556		Plate Type LTK - LIGHT TRUCK	St WI	Country of Issuance UNITED STATES
Vehicle Identification Number 1GCCS1440XK234972				Make CHEVROLET	Year 1999	Model S10		
Color BLK - BLACK				Body Style PK - PICKUP		Bus Use NOT A BUS		

6TL0BLHJPH
18-12576

WISCONSIN MOTOR VEHICLE
CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMENT
1300 LANGE COURT
BARABOO, WI 53913
(608) 356-4895

UNIT	VEHICLE	Initial Contact Point 6--REAR	Vehicle Damage			
		Extent Of Damage FUNCTIONAL DAMAGE	5--RIGHT REAR CORNER, 6--REAR, 7--LEFT REAR CORNER			
		Towed Due To Damage NOT TOWED	Vehicle Removed By OPERATOR			
		What Driver Was Doing GOING STRAIGHT	Vehicle Factors			
		Driver Prior Action Other	NOT APPLICABLE			
UNIT	VEHICLE	Driver Actions NO CONTRIBUTING ACTION				
		Driver Distractions NOT DISTRACTED				
		Owner Name CHRISTOPHER J BROOKS (608) 343-5749				
		Owner Address N9164 2ND AVE CAMP DOUGLAS, WI 54618 , US				
Sequence Of Events						
UNIT	VEHICLE	01	Event MOTOR VEH IN TRANSPORT			
		02	Event MOTOR VEH IN TRANSPORT			
		03	Event			
		04	Event			
Individual						
UNIT	INDIVIDUAL	Driver CHRISTOPHER J BROOKS (608) 343-5749		Citations Issued 0	Sex MALE	
		Date of Birth [REDACTED]		Race WHITE		
		Address N9164 2ND AVE CAMP DOUGLAS, WI 54618 , US		Driver License Number [REDACTED] STATE: WISCONSIN COUNTRY: UNITED STATES		
		Equipment		On Duty Crash		
UNIT	INDIVIDUAL	Seat Position 1--FRONT SEAT-LEFT SIDE (DRIVER/MOTORCY		Safety Equipment SHOULDER & LAP BELT		
		Helmet Use		Helmet Compliance		
		Eye Protection		Tint Compliance		
		Injury		Injury Severity NO APPARENT INJURY		Airbag NON DEPLOYED

