

6TL0BGSFC8
18-13258

WISCONSIN MOTOR VEHICLE
CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMENT
1300 LANGE COURT
BARABOO, WI 53913
(608) 356-4895

Location

ON RAMP IH90 EB 425 FT N OF USH12 EB IN THE VILLAGE OF LAKE DELTON IN SAUK COUNTY	Latitude 43.566214435	Longitude -89.778628347
	X Coordinate 275604.75	Y Coordinate 4827446.5
	Structure Type NO STRUCTURE	

Crash Scene

First Harmful Event DITCH	First Harmful Event Location ON ROADWAY	
Manner of Collision NO COLLISION W/VEHICLE IN TRANSPORT	Light Condition DARK/UNLIT	
Road Surface Condition(s) SNOW, ICE	Roadway Factor(s) NONE	
Environment Factor(s) NONE		
Weather Condition(s) CLOUDY		
Animal Type	Relation To Trafficway TRAFFICWAY - ON ROAD	
Crash Classification - Location PUBLIC PROPERTY	Crash Classification - Jurisdiction NO SPECIAL JURISDICTION	
Tribal Land	Access Control NO CONTROL	Special Study
Within Interchange Area YES	Junction Location EXIT RAMP	Intersection Type NOT AN INTERSECTION

Unit Summary

UNIT 01	Unit Status IN TRANSIT	Vehicle Operating As Classification D CLASS	Unit Type AUTOMOBILE		
	Vehicle Type (SPORT) UTILITY VEHICLE	Operating As Endorsements			
	Total Occs 1	Train/Bus # Injured	Total # Citations Issued 0	Total Trailers 0	Total HazMat Types
	Insurance? UNKNOWN	Direction Of Travel SOUTHBOUND	<input type="checkbox"/> Pre Crash Tire Mark	Speed Limit 65	Total Lanes 4
	Most Harmful Event: Collision With DITCH	Special Function NO SPECIAL FUNCTION		Emergency Motor Vehicle Use NOT APPLICABLE	
	Traffic Way DIVIDED HWY W/O TRAFFIC BARRIER	Traffic Control NO CONTROL		Traffic Control Inoperative/Missing NO	
	Surface Type BLACKTOP (BITUMINOUS)	Road Curvature STRAIGHT		Road Grade LEVEL	
	Truck Bus or HazMat NO				

UNIT 01 VEHICLE	Vehicle			
	License Plate Number 690VCS	Plate Type AUT - AUTOMOBILE	St WI	Country of Issuance UNITED STATES
	Vehicle Identification Number 2CNFLCEW3A6415561	Make CHEVROLET	Year 2010	Model EQUINOX LS
	Color RED - RED	Body Style UT - SPORT UTILITY VEHICLE		Bus Use NOT A BUS
	Initial Contact Point NON-COLLISION	Vehicle Damage		
	Extent Of Damage MINOR DAMAGE	5--RIGHT REAR CORNER		

WISCONSIN MOTOR VEHICLE
CRASH REPORT

UNIT	VEHICLE	Towed Due To Damage TOWED BUT NOT DUE TO DISABLING DAMAG		Vehicle Removed By OPERATOR			
		What Driver Was Doing MERGING		Vehicle Factors TIRES			
		Driver Prior Action Other					
		Driver Actions SPEED TOO FAST/COND					
01	01	Driver Distractions UNKNOWN IF DISTRACTED					
		Owner Name ASHLEY M RETZLAFF (608) 356-2668		Owner Address 134 ATTEWELL ST # 4 MAUSTON, WI 53948 , US			
		Sequence Of Events					
01	01	Event MOTOR VEH IN TRANSPORT					
		Event RUN OFF ROADWAY RIGHT					
		Event DITCH					
		Event					
UNIT	INDIVIDUAL	Individual					
		Driver ASHLEY M RETZLAFF (608) 356-2668		Citations Issued 0	Sex FEMALE		
		Address 134 ATTEWELL ST # 4 MAUSTON, WI 53948 , US		Date of Birth	Race WHITE		
		Driver License Number STATE: WISCONSIN COUNTRY: UNITED STATES		On Duty Crash			
		Equipment		Safety Equipment			
		Seat Position 1--FRONT SEAT-LEFT SIDE (DRIVER/MOTORCY		RESTRAINT USE UNKNOWN			
		Helmet Use		Helmet Compliance			
		Eye Protection		Tint Compliance			
		01	001	Injury		Injury Severity NO APPARENT INJURY	Airbag NON DEPLOYED
				Ejected NOT EJECTED		Ejection Path NOT EJECTED/NOT APPLICABL	Trapped/Extricated NOT TRAPPED
Medical Transport NOT TRANSPORTED				EMS Agency Identifier	EMS Run #		

WISCONSIN MOTOR VEHICLE
CRASH REPORT

UNIT 01 001	Hospital		Date of Death		Time of Death	
	Non Motorist		Striking Unit #	Prior Action	Location	To/From School
	Action					
	Action Other					
	Drug & Alcohol		Suspected Alcohol Use NO		Suspected Drug Use NO	
	Alcohol Test Given TEST NOT GIVEN			Alcohol Test Type	Alcohol Test Results	
	Drug Test Given TEST NOT GIVEN			Drug Test Type	Drug Test Results	
	Drug Type					
	Individual Condition NOT OBSERVED					