

6TL0BGSFCF
18-13667

WISCONSIN MOTOR VEHICLE
CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMENT
1300 LANGE COURT
BARABOO, WI 53913
(608) 356-4895

Location

ON IH90 EB 689 FT S OF XANADU RD IN THE TOWN OF DELTON IN SAUK COUNTY	Latitude 43.582629721	Longitude -89.805239855
	X Coordinate 273517.15625	Y Coordinate 4829342
	Structure Type	

Crash Scene

First Harmful Event DITCH	First Harmful Event Location ON ROADWAY	
Manner of Collision NO COLLISION W/VEHICLE IN TRANSPORT	Light Condition DAYLIGHT	
Road Surface Condition(s) SNOW	Roadway Factor(s) NONE	
Environment Factor(s) NONE		
Weather Condition(s) SNOW		
Animal Type	Relation To Trafficway TRAFFICWAY - ON ROAD	
Crash Classification - Location PUBLIC PROPERTY	Crash Classification - Jurisdiction NO SPECIAL JURISDICTION	
Tribal Land	Access Control NO CONTROL	Special Study
Within Interchange Area NO	Junction Location NON-JUNCTION	Intersection Type NOT AN INTERSECTION

Unit Summary

UNIT	01	Unit Status IN TRANSIT	Vehicle Operating As Classification D CLASS		Unit Type AUTOMOBILE	
		Vehicle Type PASSENGER CAR	Operating As Endorsements			
	Total Occs 1	Train/Bus # Injured	Total # Citations Issued 1	Total Trailers 0	Total HazMat Types	
	Insurance? UNKNOWN	Direction Of Travel EASTBOUND	<input type="checkbox"/> Pre Crash Tire Mark	Speed Limit 70	Total Lanes 4	
	Most Harmful Event: Collision With DITCH		Special Function NO SPECIAL FUNCTION		Emergency Motor Vehicle Use NOT APPLICABLE	
	Traffic Way DIVIDED HWY W/TRAFFIC BARRIER		Traffic Control NO CONTROL		Traffic Control Inoperative/Missing NO	
	Surface Type BLACKTOP (BITUMINOUS)		Road Curvature CURVE RIGHT		Road Grade LEVEL	
	Truck Bus or HazMat NO					

UNIT	01	Vehicle			
		License Plate Number 898ZZV	Plate Type AUT - AUTOMOBILE	St WI	Country of Issuance UNITED STATES
		Vehicle Identification Number 1G11C5SL5FF304813	Make CHEVROLET	Year 2015	Model MALIBU 1LT
		Color BRZ - BRONZE	Body Style 4D - 4DR		Bus Use NOT A BUS
		Initial Contact Point NON-COLLISION	Vehicle Damage		
		Extent Of Damage MINOR DAMAGE	UNDERCARRIAGE		

6TL0BGSFCF
18-13667

WISCONSIN MOTOR VEHICLE
CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMENT
1300 LANGE COURT
BARABOO, WI 53913
(608) 356-4895

UNIT	Towed Due To Damage NOT TOWED		Vehicle Removed By OPERATOR					
	What Driver Was Doing NEGOTIATING CURVE		Vehicle Factors					
	Driver Prior Action Other		NOT APPLICABLE					
	Driver Actions SPEED TOO FAST/COND, FAILURE TO CONTROL							
01	01	Driver Distractions UNKNOWN IF DISTRACTED						
		Owner Name FRANCISCO PAGAN RENDON (608) 617-7324	Owner Address 555 W SLIFER ST # 112 PORTAGE, WI 53901 , US					
Sequence Of Events								
UNIT	INDIVIDUAL	01	Event MOTOR VEH IN TRANSPORT					
			02	Event RUN OFF ROADWAY LEFT				
				Event DITCH				
			04	Event				
Individual								
UNIT	INDIVIDUAL	01	001	Driver RODRIGUEZ NAISY RODRIGUEZ (787) 407-6781	Citations Issued 1	Sex FEMALE		
				Date of Birth		Race		
				Address 934 IOWA AVE # 14 WISCONSIN DELLS, WI 53965 , US		Driver License Number STATE: WISCONSIN COUNTRY: UNITED STATES		
				Equipment	On Duty Crash	Safety Equipment		
				Seat Position 1--FRONT SEAT-LEFT SIDE (DRIVER/MOTORCY		RESTRAINT USE UNKNOWN		
				Helmet Use		Helmet Compliance		
				Eye Protection		Tint Compliance		
				Injury	Injury Severity NO APPARENT INJURY	Airbag NON DEPLOYED		
				Ejected NOT EJECTED		Ejection Path NOT EJECTED/NOT APPLICABL	Trapped/Extricated NOT TRAPPED	
				Medical Transport NOT TRANSPORTED		EMS Agency Identifier	EMS Run #	

WISCONSIN MOTOR VEHICLE
CRASH REPORT

UNIT	Hospital		Date of Death		Time of Death	
	Non Motorist		Striking Unit #	Prior Action	Location	To/From School
	Action					
	Action Other					
	Drug & Alcohol		Suspected Alcohol Use NO		Suspected Drug Use NO	
	Alcohol Test Given TEST NOT GIVEN			Alcohol Test Type	Alcohol Test Results	
	Drug Test Given TEST NOT GIVEN			Drug Test Type	Drug Test Results	
	Drug Type					
	Individual Condition APPEARED NORMAL					
	01	Violations				
UTC Number AE139798		Issue To? 001	Statute Number 343.05(3)(a)	Seq Num 002	Description OPERATE W/O VALID LICENSE	