

6TL0B7D6QM

| | | | | | | | |
|--|---|---|------------------------------------|---------------------------------|---|---|--------------------|
| Document Number Override | | Primary Crash Document # | | Agency Crash Number 18-13956 | | Investigating Officer/Deputy DEPUTY A. SUKOWATEY | |
| Crash Date 12/13/2018 | | Crash Time 99:99 | | Date Arrived 12/16/2018 | | Time Arrived 12:33 PM | |
| Date Notified 12/16/2018 | | Time Notified 11:56 AM | | Total Units 02 | | Total Injured 00 | Total Killed 00 |
| <input type="checkbox"/> On Emergency | <input checked="" type="checkbox"/> Hit and Run | <input type="checkbox"/> Lane Closure | <input type="checkbox"/> Work Zone | | <input type="checkbox"/> Trailer or Towed | <input type="checkbox"/> Reporting Threshold | |
| <input type="checkbox"/> Government Property | | <input type="checkbox"/> Active School Zone | | School Bus Related NO | | Tags | |
| <input type="checkbox"/> Reportable | | Crash Type DT4000 (STANDARD CRASH) | | | | <input type="checkbox"/> Amended | |
| | | | | | | <input type="checkbox"/> Secondary Crash | |

Description

| | |
|--|---|
| Diagram Non-Reportable Piece of debris fell from passing truck and broke windshield, no other damage. | Reconstruction By |
| | Photos By |
| | Additional Information DASH CAMERA VIDEO |

I, a sworn law enforcement officer, agree that I have not added any CJIS data in this report.

THE OPERATOR OF UNIT ONE WAS TRAVELING WESTBOUND ON COUNTY HIGHWAY H LEAVING WISCONSIN DELLS WHEN A MEISTER LOG AND LUMBER TRUCK PASSED HIS LOCATING TRAVELING EASTBOUND. WHILE PASSING UNIT ONE, A PIECE OF CARGO FLEW FROM UNIT TWO AND STRUCK UNIT ONE'S WINDSHIELD CREATING A LARGE CRACK AND HOLE IN THE WINDSHIELD. THIS WAS CAPTURED ON DASHCAM AND FURTHER INFORMATION CAN BE LOCATED IN A TAPED REPORT ATTACHED TO THIS CASE.

6TL0B7D6QM

18-13956

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMENT
1300 LANGE COURT
BARABOO, WI 53913
(608) 356-4895

Location

| | | |
|--|-------------------------------------|-----------------------------------|
| ON CTHH WB 786 FT W OF OLD 12 IN THE TOWN OF DELTON IN SAUK COUNTY | Latitude 43.626259913 | Longitude -89.810091913 |
| | X Coordinate 273289.46875 | Y Coordinate 4834201 |
| | Structure Type | |

Crash Scene

| | | | |
|--|--|---|---------------|
| First Harmful Event STRUCK BY FALLING, SHIFTING CARGO OR ANYTHING SET IN MOTIO | | First Harmful Event Location ON ROADWAY | |
| Manner of Collision NO COLLISION W/VEHICLE IN TRANSPORT | | Light Condition DAYLIGHT | |
| Road Surface Condition(s) DRY | | Roadway Factor(s) NONE | |
| Environment Factor(s) NONE | | | |
| Weather Condition(s) CLOUDY | | | |
| Animal Type | | Relation To Trafficway TRAFFICWAY - ON ROAD | |
| Crash Classification - Location PUBLIC PROPERTY | | Crash Classification - Jurisdiction NO SPECIAL JURISDICTION | |
| Tribal Land | | Access Control NO CONTROL | Special Study |
| Within Interchange Area NO | Junction Location NON-JUNCTION | Intersection Type NOT AN INTERSECTION | |

Unit Summary

| | | | | | | |
|-------------|--|---|---|----------------------------|--|--|
| UNIT | Unit Status IN TRANSIT | | Vehicle Operating As Classification D CLASS | | Unit Type AUTOMOBILE | |
| | Vehicle Type PASSENGER CAR | | | | Operating As Endorsements | |
| | Total Occs 1 | Train/Bus # Recorded | Total # Citations Issued 0 | Total Trailers 0 | Total HazMat Types | |
| | Insurance? YES | Direction Of Travel WESTBOUND | <input type="checkbox"/> Pre CrashTire Mark | Speed Limit 55 | Total Lanes 2 | |
| | Most Harmful Event: Collision With STRUCK BY FALLING, SHIFTING CARGO OR ANYT | | Special Function NO SPECIAL FUNCTION | | Emergency Motor Vehicle Use NOT APPLICABLE | |
| | Traffic Way TWO-WAY, NOT DIVIDED | | Traffic Control NO CONTROL | | Traffic Control Inoperative/Missing NO | |
| | Surface Type BLACKTOP (BITUMINOUS) | | Road Curvature STRAIGHT | | Road Grade LEVEL | |
| | Truck Bus or HazMat NO | | | | | |

| | | | | | |
|---|----------------|---|--|---------------------|---|
| UNIT | VEHICLE | Vehicle | | | |
| | | License Plate Number 736TUN | Plate Type AUT - AUTOMOBILE | St WI | Country of Issuance UNITED STATES |
| | | Vehicle Identification Number YS3ED59Z333002748 | Make SAAB | Year 2003 | Model 9-5 ARC |
| | | Color BLK - BLACK | Body Style SW - STATIONWAGON | | Bus Use NOT A BUS |
| | | Initial Contact Point 12--FRONT | Vehicle Damage 12--FRONT | | |
| Extent Of Damage MINOR DAMAGE | | | | | |

6TL0B7D6QM

18-13956

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMENT
1300 LANGE COURT
BARABOO, WI 53913
(608) 356-4895

| | | | | |
|--|---|--|---|--|
| UNIT VEHICLE | Towed Due To Damage NOT TOWED | | Vehicle Removed By OPERATOR | |
| | What Driver Was Doing GOING STRAIGHT | | Vehicle Factors | |
| | Driver Prior Action Other | | NOT APPLICABLE | |
| | Driver Actions NO CONTRIBUTING ACTION | | | |
| 01 | Owner Name JULIAN TYLKA (608) 448-9309 | | Owner Address S 300 BIRCHWOOD RD WISCONSIN DELLS, WI 53965 , US | |
| | Sequence Of Events | | | |
| 01 | 01 | Event MOTOR VEH IN TRANSPORT | | |
| | 02 | Event STRUCK BY FALLING, SHIFTING CARGO OR ANYTHING SET IN MOTION BY MOTOR VEHICLE | | |
| | 03 | Event | | |
| | 04 | Event | | |
| UNIT | Policy Holder | | | |
| | Insurance Company ERIE-INS-CO | | Individual JULIAN TYLKA | |
| UNIT INDIVIDUAL | Individual | | | |
| | Driver JULIAN TYLKA (608) 448-9309 | | Citations Issued 0 | Sex MALE |
| | Address S 300 BIRCHWOOD RD WISCONSIN DELLS, WI 53965 , US | | Date of Birth | Race WHITE |
| | Driver License Number | | STATE: WISCONSIN COUNTRY: UNITED STATES | |
| 01 | Safety Equipment | | On Duty Crash | |
| | Seat Position 1--FRONT SEAT-LEFT SIDE (DRIVER/MOTORCY | | Safety Equipment SHOULDER & LAP BELT | |
| | Helmet Use | | Helmet Compliance | |
| | Eye Protection | | Tint Compliance | |
| | Injury | | Injury Severity NO APPARENT INJURY | Airbag NON DEPLOYED |
| 001 | Ejected NOT EJECTED | | Ejection Path NOT EJECTED/NOT APPLICABLE | Trapped/Extricated NOT TRAPPED |
| | Medical Transport NOT TRANSPORTED | | EMS Agency Identifier | EMS Run # |
| | Hospital | | Date of Death | Time of Death |
| | Distacted By | | Distacted By Source | |
| Distacted By Action NOT DISTRACTED | | | | |

WISCONSIN MOTOR VEHICLE
CRASH REPORT

| | | | | | |
|---|---|--|------------------------------------|---------------------------------|--|
| UNIT INDIVIDUAL 01 001 | Non Motorist | | Striking Unit # | Location | |
| | Prior Action | | | | |
| | Action | | | | |
| | Action Other | | | To/From School | |
| | Drug & Alcohol | | Suspected Alcohol Use NO | Suspected Drug Use NO | |
| | Alcohol Test Given TEST NOT GIVEN | | Alcohol Test Type | Alcohol Test Results | |
| | Drug Test Given TEST NOT GIVEN | | Drug Test Type | Drug Test Results | |
| | Drug Type | | | | |
| | Individual Condition NOT OBSERVED | | | | |

Unit Summary

| | | | | | | | |
|------------|--|---------------------------------------|---|--------------------------------------|----------------------------|---|--|
| UNIT 02 | Unit Status HIT AND RUN | | Vehicle Operating As Classification A CLASS | | Unit Type TRUCK | | |
| | Vehicle Type STRAIGHT TRUCK (INSERT TRUCK) | | | | Operating As Endorsements | | |
| | Total Occs | | Train/Bus # Recorded | Total # Citations Issued 0 | Total Trailers 0 | Total HazMat Types 0 | |
| | Insurance? UNKNOWN | Direction Of Travel UNKNOWN | <input type="checkbox"/> Pre Crash Tire Mark | | Speed Limit 55 | Total Lanes 2 | |
| | Most Harmful Event: Collision With CARGO/EQUIPMENT LOSS OR SHIFT | | | Special Function UNKNOWN | | Emergency Motor Vehicle Use UNKNOWN | |
| | Traffic Way UNKNOWN | | | Traffic Control UNKNOWN | | Traffic Control Inoperative/Missing UNKNOWN | |
| | Surface Type UNKNOWN | | | Road Curvature UNKNOWN | | Road Grade UNKNOWN | |
| | Truck Bus or HazMat NO | | | | | | |

| | | | | | | |
|-----------------------------|---|--|----------------|---------------------------------------|-----------------------------|--|
| UNIT VEHICLE 02 02 | Vehicle | | | | | |
| | License Plate Number | | Plate Type | St | Country of Issuance | |
| | Vehicle Identification Number | | Make | Year | Model | |
| | Color | | Body Style | | Bus Use NOT A BUS | |
| | Initial Contact Point | | Vehicle Damage | | | |
| | Extent Of Damage | | | | | |
| | Towed Due To Damage NOT TOWED | | | Vehicle Removed By OPERATOR | | |

WISCONSIN MOTOR VEHICLE
CRASH REPORT

| | | | | |
|---------------------------|---|--|--|---------------------------------|
| UNIT | VEHICLE | What Driver Was Doing UNKNOWN | Vehicle Factors | |
| | | Driver Prior Action Other | UNKNOWN | |
| 02 | 02 | Driver Actions UNKNOWN | | |
| | | Owner Name MEISTER LOG AND LUMBER (608) 524-4412 | Owner Address 1440 LAUKANT ST REEDSBURG, WI 53959 , US | |
| Sequence Of Events | | | | |
| UNIT | INDIVIDUAL | 01 | Event MOTOR VEH IN TRANSPORT | |
| | | 02 | Event CARGO/EQUIPMENT LOSS OR SHIFT | |
| | | 03 | Event | |
| | | 04 | Event | |
| 02 | 002 | Unknown | Citations Issued 0 | Sex |
| | | | Date of Birth | Race |
| | | Address , , | Driver License Number | |
| 02 | 002 | Safety Equipment | On Duty Crash | Safety Equipment |
| | | Seat Position | RESTRAINT USE UNKNOWN | |
| | | Helmet Use | Helmet Compliance | |
| | | Eye Protection | Tint Compliance | |
| | | Injury | Injury Severity NO APPARENT INJURY | Airbag NOT APPLICABLE |
| | Ejected NOT APPLICABLE | Ejection Path NOT EJECTED/NOT APPLICABLE | Trapped/Extricated NOT APPLICABLE | |
| | Medical Transport NOT TRANSPORTED | | EMS Agency Identifier | EMS Run # |
| | Hospital | Date of Death | Time of Death | |
| | Distracted By | Distracted By Source | | |
| | Distracted By Action | | | |
| | Non Motorist | Striking Unit # | Location | |
| | Prior Action | | | |

WISCONSIN MOTOR VEHICLE
CRASH REPORT

| | | | | | | |
|------|------------|--|---|--------------------|----------------------|--|
| UNIT | INDIVIDUAL | Action | | | | |
| | | Action Other | | To/From School | | |
| | | Drug & Alcohol | Suspected Alcohol Use | Suspected Drug Use | | |
| | | | Alcohol Test Given TEST NOT GIVEN | Alcohol Test Type | Alcohol Test Results | |
| | | Drug Test Given TEST NOT GIVEN | Drug Test Type | Drug Test Results | | |
| | | Drug Type | | | | |
| | | Individual Condition | | | | |
| | | NOT OBSERVED | | | | |
| | | 02 | 002 | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |