## WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Document Number Override  Crash Date 01/04/2019		Primary Crash	Primary Crash Document #		Agency Crash Number 19-00171		Investigating Officer/Deputy SERGEANT E. VANDENHEUVEL			
		Crash Time 01:55 PM		Date Arrived <b>01/04/2019</b>		Time Arrived 02:08 PM				
Date Notified <b>01/04/2019</b>		Time Notified 02:02 PM	_	Total U 01	nits	Total In	jured	Total Kille	ed	
Date Notified 01/04/2019  On Emerge Gover	ency	Hit and Run	Lane Clo		☐ Work Zone	Tra	ailer or	Towed	Reporting Threshold	
Gover Pro	nment perty		chool Zone	NO School	Bus Related	Tags				
<b>✓</b> Reportable	9	Crash Type DT4000 (ST	ANDARD CRAS	SH)		Am	nended		Secondary Crash	
<b>Description</b> Diagram	) <u> </u>						Re	econstructio	n Bv	
Diagram								econ structio	ПЪу	
							Ph	otos By		
			FOX HILL ROAD  NOT TO SCALE							
					*			Iditional Info	ormation	
				( <b>T</b>	—— <del>——</del>					
				G						
				07	1)					
			0	L	Stant Control of the					
			(	0.1						
			g-71							
				)						
			97773							
		<u> </u>								
J, a sworn	law enfor	cement officer, ag	ree that I have	not added	I any CJIS data in t	his report.				
SLUSH/SNOW C	OVERED A	REAS. OPERATOR	OF UNIT 1 STATE	ES SHE EN		A OF SLUSH	/SNOW \	WHICH CA	USED THE REAR END OF	
									1 WAS LEADING WITH EST ON ITS DRIVER'S	

SIDE. NO INJURIES REPORTED OR OBSERVED. BODY DAMAGE TO MULTIPLE AREAS OF UNIT 1 DUE TO ROLLOVER EVENT.

Location

### WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 01/04/2019

Crash Time 01:55 PM

	243 OF	FOX HILL RD (1) FT N S POPLAR RD				Latitude 43.519214668 X Coordinate			-89.763 Y Coord	532697
		THE TOWN OF DELTON SAUK COUNTY		276650.3125		482218				
				Structure Type						
(	Cra	sh Scene								
1	First	: Harmful Event				First Harmful Ev	vent L	ocation.		
	DIT	СН				SHOULDER I	RIGH	łΤ		
	Man	ner of Collision	Light Condition							
							DAYLIGHT			
	Roa	d Surface Condition(s)				Roadway Facto	or(s)			
	SNO	OW, SLUSH								
	Envi	ronment Factor(s)				DOAD CURE	405	CONDITION	WET IC	N CNOW CLUCH
	NOI	NE				ETC)	ACE	CONDITION	(WEI, IC	CY, SNOW, SLUSH,
	Wea	ather Condition(s)								
	CLE	EAR								
	Anin	nal Type				Relation To Trafficway				
						TRAFFICWAY - ON ROAD				
		sh Classification - Location			Crash Classification - Jurisdiction					
		BLIC PROPERTY al Land				NO SPECIAL JURISDICTION			0	
	TIDO	ai Lanu				Access Control NO CONTRO		Special Study		Special Study
	With	in Interchange Area J	unction Location		Intersection Type					
	NO		NON-JUNCTION		NOT AN I	NTERSECTIO	ON			
	Uni	t Summary								
'		nit Status Vehicle Operating As Cl								
	Unit			1	erating As Cla	assification		Unit Type		
	Unit IN T	RANSIT		Vehicle Ope D CLASS	erating As Cla	assification		TRUCK	s Endorser	ments
1	Unit IN T Vehi		RUCK	1	erating As Cla	assification			s Endorser	ments
1	Unit IN T Vehi UTI	TRANSIT icle Type	RUCK Train/Bus # Recorded	1			al Trai	TRUCK Operating A		ments Mat Types
01	Unit IN T Vehi UTI Tota 1	TRANSIT icle Type LITY TRUCK/PICKUP TI	Train/Bus # Recorded	D CLASS		Tota 0		TRUCK Operating A	Total Haz	Mat Types
1	Unit IN T Vehi UTII Tota 1	TRANSIT icle Type LITY TRUCK/PICKUP TI II Occs rance?	Train/Bus # Recorded  Direction Of Travel	Total # Citat 0 Pre	tions Issued  CrashTire	Tota 0 Spe	al Trai	TRUCK Operating A	Total Haz	Mat Types
1	Unit IN T Vehi UTII Tota 1 Insur YES	TRANSIT icle Type LITY TRUCK/PICKUP TI I Occs rance?	Train/Bus # Recorded  Direction Of Travel  NORTHBOUND	Total # Citat 0 Pre	tions Issued  CrashTire  Mark	Tota 0		TRUCK Operating A	Total Hazi  0  Total Lane 2	Mat Types es
1	Unit IN T Vehi UTII Tota 1 Insu YES	TRANSIT icle Type LITY TRUCK/PICKUP TI I Occs rance? S t Harmful Event: Collision Wi	Train/Bus # Recorded  Direction Of Travel  NORTHBOUND	Total # Citat 0 Pre 0 Special Fun	tions Issued  CrashTire  Mark	Tota 0 Spe 45		TRUCK Operating A	Total Hazi  0 Total Lane 2 Motor Vehi	Mat Types es
1	Unit IN T Vehi UTII Tota 1 Insui YES Mosi	TRANSIT icle Type LITY TRUCK/PICKUP TI I Occs rance?	Train/Bus # Recorded  Direction Of Travel  NORTHBOUND	Total # Citat 0 Pre 0 Special Fun NO SPEC	CrashTire Mark ction	Tota 0 Spe 45		TRUCK Operating A  llers mit	Total Hazi  Total Lane  2  Motor Vehi LICABLE	Mat Types es icle Use
1	Unit IN T Vehi UTII Tota 1 Insu YES Mos: OVE	TRANSIT icle Type LITY TRUCK/PICKUP TI II Occs rance? S t Harmful Event: Collision Wi ERTURN/ROLLOVER	Train/Bus # Recorded  Direction Of Travel  NORTHBOUND	Total # Citat 0 Pre 0 Special Fun	CrashTire Mark ction IAL FUNCT	Tota 0 Spe 45		TRUCK Operating A  llers mit  Emergency NOT APPI	Total Hazi  Total Lane  2  Motor Vehi LICABLE	Mat Types es icle Use
1	Unit IN T Vehi UTII Tota 1 Insu YES Mos: OVE Traff	TRANSIT icle Type LITY TRUCK/PICKUP TI II Occs rance? S t Harmful Event: Collision Wi ERTURN/ROLLOVER fic Way	Train/Bus # Recorded  Direction Of Travel  NORTHBOUND	Total # Citat 0 Pre 0 Special Fun NO SPEC	CrashTire Mark ction IAL FUNCT	Tota 0 Spe 45		TRUCK Operating A  lilers mit  Emergency NOT APPI Traffic Conti	Total Hazi  0 Total Lane  2 Motor Vehi LICABLE rol Inoperat	Mat Types es icle Use
1	Unit IN T Vehi UTII Tota 1 Insu YES Mos: OVE Traff TWO Surfa	TRANSIT icle Type LITY TRUCK/PICKUP TI II Occs rance? S t Harmful Event: Collision Wi ERTURN/ROLLOVER fic Way D-WAY, NOT DIVIDED	Train/Bus # Recorded  Direction Of Travel  NORTHBOUND ith	Total # Citat 0 Pre 0 Special Fun NO SPEC Traffic Contr	CrashTire Mark ction IAL FUNCT	Tota 0 Spe 45		TRUCK Operating A  lers  mit  Emergency NOT APPI Traffic Contr	Total Hazi  0 Total Lane  2 Motor Vehi LICABLE rol Inoperat	Mat Types es icle Use
1	Unit IN T Vehi UTII Tota 1 Insu YES OVE Traff TWO Surfar BLA	TRANSIT icle Type LITY TRUCK/PICKUP TI il Occs rance?  It Harmful Event: Collision Wi ERTURN/ROLLOVER fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS) ik Bus or HazMat	Train/Bus # Recorded  Direction Of Travel  NORTHBOUND ith	Total # Citat 0 Pre 0 Special Fun NO SPEC Traffic Contr NO CONT Road Curva	CrashTire Mark ction IAL FUNCT	Tota 0 Spe 45		TRUCK Operating A  lers  mit  Emergency NOT APPI Traffic Contr NO Road Grade	Total Hazi  0 Total Lane  2 Motor Vehi LICABLE rol Inoperat	Mat Types es icle Use
1	Unit IN T Vehi UTII Tota 1 Insur YES Mosi OVE Traff TWO Surfa BLA	TRANSIT icle Type LITY TRUCK/PICKUP TI II Occs  rance? S t Harmful Event: Collision Wi ERTURN/ROLLOVER fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS) ek Bus or HazMat	Train/Bus # Recorded  Direction Of Travel  NORTHBOUND ith	Total # Citat 0 Pre 0 Special Fun NO SPEC Traffic Contr NO CONT Road Curva	CrashTire Mark ction IAL FUNCT	Tota 0 Spe 45		TRUCK Operating A  lers  mit  Emergency NOT APPI Traffic Contr NO Road Grade	Total Hazi  0 Total Lane  2 Motor Vehi LICABLE rol Inoperat	Mat Types es icle Use
1	Unit IN T Vehi UTII Tota 1 Insur YES Mosi OVE Traff TWO Surfa BLA	TRANSIT icle Type LITY TRUCK/PICKUP TI il Occs rance?  It Harmful Event: Collision Wi ERTURN/ROLLOVER fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS) ik Bus or HazMat	Train/Bus # Recorded  Direction Of Travel  NORTHBOUND ith	Total # Citat 0 Pre Special Fun NO SPEC Traffic Contr NO CONT Road Curva STRAIGH	CrashTire Mark ction IAL FUNCT rol ROL ture	Tota 0 Spe 45		TRUCK Operating A  lers  mit  Emergency NOT APPI Traffic Contr NO Road Grade	Total Hazi 0 Total Lane 2 Motor Vehi LICABLE rol Inoperat	Mat Types es icle Use
1	Unit IN T Vehi UTII Tota 1 Insur YES Mosi OVE Traff TWO Surfa BLA	TRANSIT icle Type LITY TRUCK/PICKUP TI II Occs rance? S t Harmful Event: Collision Wi ERTURN/ROLLOVER fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS) ck Bus or HazMat	Train/Bus # Recorded  Direction Of Travel  NORTHBOUND ith	Total # Citat 0 Pre 0 Special Fun NO SPEC Traffic Contr NO CONT Road Curva STRAIGH	CrashTire Mark ction IAL FUNCT rol ROL ture	Tota 0 Spe 45		TRUCK Operating A  llers  mit  Emergency NOT APPI Traffic Conti NO Road Grade LEVEL	Total Hazi  Total Lane  2  Motor Vehi LICABLE  rol Inoperat	Mat Types es icle Use
UNIT 01	Unit IN T Vehi Vehi UTII Tota 1 Insu YES OVE Traff TWO Surfa BLA Truc NO	TRANSIT  Icle Type  LITY TRUCK/PICKUP TI  II Occs  rance?  S  It Harmful Event: Collision Wi  ERTURN/ROLLOVER  fic Way  D-WAY, NOT DIVIDED  ace Type  ACKTOP (BITUMINOUS)  Ick Bus or HazMat  Vehicle  License Plate Number	Train/Bus # Recorded  Direction Of Travel  NORTHBOUND  ith	Total # Citat 0 Pre 0 Special Fun NO SPEC Traffic Contr NO CONT Road Curva STRAIGH	CrashTire Mark ction IAL FUNCT rol ROL ture T	Tota 0 Spe 45	Lir.	TRUCK Operating A  llers  mit  Emergency NOT APPI Traffic Conti NO Road Grade LEVEL  Country of Is:	Total Hazi  Total Lane  2  Motor Vehi LICABLE  rol Inoperat	Mat Types es icle Use
UNIT 01	Unit IN T Vehi UTII Tota 1 Insur YES Mosi OVE Traff TWO Surfa BLA	TRANSIT  Icle Type  LITY TRUCK/PICKUP TI  II Occs  rance?  S  It Harmful Event: Collision Wi  ERTURN/ROLLOVER  Ific Way  D-WAY, NOT DIVIDED  ace Type  ACKTOP (BITUMINOUS)  Ick Bus or HazMat  Vehicle  License Plate Number  HALYA	Train/Bus # Recorded  Direction Of Travel  NORTHBOUND  ith	Total # Citat 0  Pre 0  Special Fun NO SPEC  Traffic Contr NO CONT  Road Curva STRAIGH  Plate Type LTK - LIG  Make FORD	CrashTire Mark ction IAL FUNCT rol ROL tture T	Tota 0 Spe 45  FION  St WI	r	TRUCK Operating A  lers  mit  Emergency NOT APPI Traffic Contr NO Road Grade LEVEL  Country of Is: UNITED ST Model F150	Total Hazi  Total Lane  2  Motor Vehi LICABLE  rol Inoperat	Mat Types es icle Use
1	Unit IN T Vehi Vehi UTII Tota 1 Insu YES OVE Traff TWO Surfa BLA Truc NO	TRANSIT Icle Type LITY TRUCK/PICKUP TI Icl Occs  rance?  It Harmful Event: Collision Wi ERTURN/ROLLOVER Icl Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS) Ick Bus or HazMat  Vehicle  License Plate Number HALYA  Vehicle Identification Numb 1FTPX14V67FB33570  Color	Train/Bus # Recorded  Direction Of Travel  NORTHBOUND  ith	Total # Citat 0 Pre 0 Special Fun NO SPEC Traffic Contr NO CONT Road Curva STRAIGH  Plate Type LTK - LIG Make FORD Body Style	CrashTire Mark ction IAL FUNCT rol ROL tture T	Tota 0 Spe 45  FION  St WI Year	r	TRUCK Operating A  liers  mit  Emergency NOT APPI Traffic Conti NO Road Grade LEVEL  Country of Is: UNITED ST Model	Total Hazi  Total Lane  2  Motor Vehi LICABLE  rol Inoperat	Mat Types es icle Use
ONI D	Unit IN T Vehi UTII Tota 1 Insu YES Mosi OVE Traff TWO Surfa BLA	TRANSIT Icle Type LITY TRUCK/PICKUP TI Icl Occs  rance?  It Harmful Event: Collision Wi ERTURN/ROLLOVER Icl Way  D-WAY, NOT DIVIDED  ace Type ACKTOP (BITUMINOUS) Ick Bus or HazMat  Vehicle  License Plate Number  HALYA  Vehicle Identification Number  1FTPX14V67FB33570  Color  BLU - BLUE	Train/Bus # Recorded  Direction Of Travel  NORTHBOUND  ith	Total # Citat 0 Pre 0 Special Fun NO SPEC Traffic Contr NO CONT Road Curva STRAIGH  Plate Type LTK - LIG Make FORD Body Style PK - PICK	CrashTire Mark ction IAL FUNCT rol ROL tture T	Tota 0 Spe 45  FION  St WI Year	r	TRUCK Operating A  liers  mit  Emergency NOT APPI Traffic Conti NO Road Grade LEVEL  Country of Is: UNITED S1 Model F150 Bus Use	Total Hazi  Total Lane  2  Motor Vehi LICABLE  rol Inoperat	Mat Types es icle Use
01 UNII 01	Unit IN T Vehi UTII Tota 1 InsuryES OVE Trafft TWO Surfa BLA	TRANSIT Icle Type LITY TRUCK/PICKUP TI Icl Occs  rance?  St Harmful Event: Collision Wi ERTURN/ROLLOVER fic Way  D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS) Ick Bus or HazMat  Vehicle  License Plate Number HALYA  Vehicle Identification Numb 1FTPX14V67FB33570  Color BLU - BLUE Initial Contact Point	Train/Bus # Recorded  Direction Of Travel  NORTHBOUND  ith	Total # Citat 0 Pre 0 Special Fun NO SPEC Traffic Contr NO CONT Road Curva STRAIGH  Plate Type LTK - LIG Make FORD Body Style	CrashTire Mark ction IAL FUNCT rol ROL tture T	Tota 0 Spe 45  FION  St WI Year	r	TRUCK Operating A  liers  mit  Emergency NOT APPI Traffic Conti NO Road Grade LEVEL  Country of Is: UNITED S1 Model F150 Bus Use	Total Hazi  Total Lane  2  Motor Vehi LICABLE  rol Inoperat	Mat Types es icle Use
01 UNII 01	Unit IN T Vehi UTII Tota 1 InsuryES OVE Trafft TWO Surfa BLA	TRANSIT Icle Type LITY TRUCK/PICKUP TI Icl Occs  rance?  It Harmful Event: Collision Wi ERTURN/ROLLOVER Icl Way  D-WAY, NOT DIVIDED  ace Type ACKTOP (BITUMINOUS) Ick Bus or HazMat  Vehicle  License Plate Number  HALYA  Vehicle Identification Number  1FTPX14V67FB33570  Color  BLU - BLUE	Train/Bus # Recorded  Direction Of Travel  NORTHBOUND  ith	Total # Citat 0 Pre 0 Special Fun NO SPEC Traffic Contr NO CONT Road Curva STRAIGH  Plate Type LTK - LIG Make FORD Body Style PK - PICK	CrashTire Mark ction IAL FUNCT rol ROL ture T	Tota 0 Spe 45  FION  St WI Year	r	TRUCK Operating A  liers  mit  Emergency NOT APPI Traffic Conti NO Road Grade LEVEL  Country of Is: UNITED S1 Model F150 Bus Use	Total Hazi  Total Lane  2  Motor Vehi LICABLE  rol Inoperat	Mat Types es icle Use
UNIT 01	Unit IN T Vehi UTII Tota 1 Insu YES Mosi OVE Traff TWO Surfa BLA	TRANSIT Icle Type LITY TRUCK/PICKUP TI II Occs  rance? S t Harmful Event: Collision Wi ERTURN/ROLLOVER fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS) Ick Bus or HazMat  Vehicle License Plate Number HALYA Vehicle Identification Numb 1FTPX14V67FB33570 Color BLU - BLUE Initial Contact Point NON-COLLISION	Direction Of Travel NORTHBOUND ith	Total # Citat 0  Pre 0  Special Fun NO SPEC  Traffic Contr NO CONT  Road Curva STRAIGHT  Plate Type LTK - LIG Make FORD  Body Style PK - PICK  Vehicle Da	CrashTire Mark ction IAL FUNCT rol ROL ture T	Tota 0 Spe 45  FION  St WI Year	r	TRUCK Operating A  liers  mit  Emergency NOT APPI Traffic Conti NO Road Grade LEVEL  Country of Is: UNITED S1 Model F150 Bus Use	Total Hazi  Total Lane  2  Motor Vehi LICABLE  rol Inoperat	Mat Types es icle Use

## WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 01/04/2019

Crash Time 01:55 PM

		Towed Due To Damage		Vehic	le Removed By						
					PLATTS WRECKER						
		What Driver Was Doing			le Factors						
		GOING STRAIGHT									
		Driver Prior Action Other		NOT	APPLICABLE						
		Driver Actions		1							
	Щ	SPEED TOO FAST/COND									
╘	VEHICL										
L	표										
_	VE										
		Owner Name			Owner Address						
_	1	PAUL M HICKEY III			S2010A COUNTY ROAD T						
5	01	(608) 963-9310			3ARABOO, WI 53913 , US						
		Sequence Of Events									
	01	Event	NUT								
	0	RUN OFF ROADWAY RIG	3H1								
	02	Event									
	0	DITCH									
	03	Event OVERTURN/ROLLOVER									
	0	OVERTURN/RULLOVER									
	04	Event									
	0										
_	ı	Policy Holder									
UNIT		Insurance Company		Individual							
$\supset$		AMERICAN-FAMILY-INS-	·co	PAUL HICKEY							
		ndividual									
		Driver		Cita	ations Issued	Sex					
		HALLE ALEXANDRA HIC	KEY	0		FEMALE					
	AL	(608) 963-9310			te of Birth	Race					
_	INDIVIDUAL					WHITE					
	≥	Address		Dri	ver License Number	L					
$\supset$	ቯ	S2010A COUNTY ROAD									
	=	BARABOO, WI 53913 , U	IS	STATE: WISCONSIN COUNTRY: UNITED STATES							
	_ '	On Duty	y Crash	Saf	fety Equipment						
	Sat	ety Equipment									
		Seat Position		SH	SHOULDER & LAP BELT						
		1FRONT SEAT-LEFT SIDE (DRIVER/MOTORCY									
		Helmet Use			Helmet Compliance						
		Eye Protection		Tint Compliance							
5	001	Injury S	-		bag						
0	Ō		PARENT INJURY	NC	ON DEPLOYED						
		Ejected	Ejection Path			Trapped/Extricated					
		NOT EJECTED	NOT EJECTED/NOT APP			NOT TRAPPED					
		Medical Transport		EM	IS Agency Identifier	EMS Run #					
		NOT TRANSPORTED									
		Hospital		Dat	te of Death	Time of Death					
		<b>Distracted By</b> Distract	red By Source								
		Distracted By Action									
		NOT DISTRACTED									

# WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

		Non Motor	Striking Unit #	Location				
		Prior Action						
		Action						
	<b>AL</b>							
UNIT	/IDU							
)	INDIVIDUAL							
	_							
		Action Other						To/From School
•	L	Orug & Alcoh	Suspected Alcohol U	lse	Suspected Drug Use NO			
		Alcohol Test Give		Alcohol Test Type			Alcohol Test Results	
		Drug Test Given TEST NOT GIV		Drug Test Type		Drug Test Results	<u> </u>	
6	001	Drug Type						
		Individual Condition	on					
		APPEARED NO	DRMAL					
	Pro	perty Owne	r <del> </del>					
PROP 01	Government TOWNSHIP OF DELTON (608) 253-4621				Address 30 S WISCONSIN DE PO BOX 148 LAKE DELTON, WI 53			
	Fixe	d Objects St						
	5	Striking Unit <b>01</b>	Struck Object DITCH				Structure Number	Damage Tag Number

Form DT4000