

WISCONSIN MOTOR VEHICLE
CRASH REPORT

Location

ON FERN DELL RD (1) 35 FT E OF ISHNALA RD IN THE TOWN OF DELTON IN SAUK COUNTY	Latitude 43.561302366	Longitude -89.798722375
	X Coordinate 273963.5625	Y Coordinate 4826955.5
	Structure Type	

Crash Scene

First Harmful Event DITCH	First Harmful Event Location ON ROADWAY	
Manner of Collision NO COLLISION W/VEHICLE IN TRANSPORT	Light Condition DARK/UNLIT	
Road Surface Condition(s) ICE	Roadway Factor(s) NONE	
Environment Factor(s) WEATHER CONDITIONS		
Weather Condition(s) CLEAR		
Animal Type	Relation To Trafficway TRAFFICWAY - ON ROAD	
Crash Classification - Location PUBLIC PROPERTY	Crash Classification - Jurisdiction NO SPECIAL JURISDICTION	
Tribal Land	Access Control NO CONTROL	Special Study
Within Interchange Area NO	Junction Location INTERSECTION-RELATED	Intersection Type T-INTERSECTION

Unit Summary

UNIT	Unit Status IN TRANSIT	Vehicle Operating As Classification D CLASS		Unit Type AUTOMOBILE	
	Vehicle Type PASSENGER CAR	Operating As Endorsements			
	Total Occs 1	Train/Bus # Recorded	Total # Citations Issued 0	Total Trailers 0	Total HazMat Types 0
	Insurance? YES	Direction Of Travel EASTBOUND	<input type="checkbox"/> Pre CrashTire Mark	Speed Limit 45	Total Lanes 2
	Most Harmful Event: Collision With DITCH	Special Function NO SPECIAL FUNCTION		Emergency Motor Vehicle Use NOT APPLICABLE	
	Traffic Way TWO-WAY, NOT DIVIDED	Traffic Control NO CONTROL		Traffic Control Inoperative/Missing NO	
	Surface Type BLACKTOP (BITUMINOUS)	Road Curvature STRAIGHT		Road Grade LEVEL	
	Truck Bus or HazMat NO				

UNIT	Vehicle				
	01	License Plate Number 233DEZ	Plate Type AUT - AUTOMOBILE	St WI	Country of Issuance UNITED STATES
		Vehicle Identification Number 1B3ES46C3YD820412	Make DODGE	Year 2000	Model NEON/ES
	VEHICLE	Color TAN - TAN	Body Style 4D - 4DR		Bus Use NOT A BUS
		Initial Contact Point 12--FRONT	Vehicle Damage		
Extent Of Damage NO DAMAGE		NO DAMAGE			

6TL09XQXZR

19-00666

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMENT
1300 LANGE COURT
BARABOO, WI 53913
(608) 356-4895

UNIT VEHICLE	Towed Due To Damage TOWED BUT NOT DUE TO DISABLING DAMAG		Vehicle Removed By CRAIGS TOWING	
	What Driver Was Doing LEFT TURN		Vehicle Factors	
	Driver Prior Action Other		NOT APPLICABLE	
	Driver Actions NO CONTRIBUTING ACTION			
01	01	Owner Name SANDOR A PFEIFER		Owner Address S2292 1ST ST REEDSBURG, WI 53959 , US
Sequence Of Events				
	01	Event DITCH		
	02	Event		
	03	Event		
	04	Event		
UNIT	Policy Holder			
	Insurance Company DAIRYLAND-COUNTY-MUTUAL-INS-CO		Individual SANDOR PFEIFER	
UNIT INDIVIDUAL	Individual			
	Driver SANDOR A PFEIFER		Citations Issued 0	Sex MALE
	Address S2292 1ST ST REEDSBURG, WI 53959 , US		Date of Birth	Race WHITE
	Driver License Number		STATE: WISCONSIN COUNTRY: UNITED STATES	
UNIT INDIVIDUAL	Safety Equipment		On Duty Crash	
	Seat Position 1--FRONT SEAT-LEFT SIDE (DRIVER/MOTORCY		Safety Equipment SHOULDER & LAP BELT	
	Helmet Use		Helmet Compliance	
	Eye Protection		Tint Compliance	
	UNIT INDIVIDUAL	Injury		Injury Severity NO APPARENT INJURY
Ejected NOT EJECTED		Airbag NON DEPLOYED		
Ejection Path NOT EJECTED/NOT APPLICABLE		Trapped/Extricated NOT TRAPPED		
Medical Transport NOT TRANSPORTED		EMS Agency Identifier		
Hospital		EMS Run #		
Date of Death		Time of Death		
Distracted By		Distracted By Source NOT APPLICABLE (NOT DISTRACTED)		
Distracted By Action NOT DISTRACTED				

WISCONSIN MOTOR VEHICLE CRASH REPORT

UNIT	Non Motorist		Striking Unit #	Location		
	Prior Action					
	Action					
	Action Other					
	To/From School					
	Drug & Alcohol		Suspected Alcohol Use NO	Suspected Drug Use NO		
	Alcohol Test Given TEST NOT GIVEN		Alcohol Test Type		Alcohol Test Results	
	Drug Test Given TEST NOT GIVEN		Drug Test Type		Drug Test Results	
	Drug Type					
	Individual Condition APPEARED NORMAL					