

6TL09KMLZQ
19-00763

WISCONSIN MOTOR VEHICLE
CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMENT
1300 LANGE COURT
BARABOO, WI 53913
(608) 356-4895

6TL09KMLZQ

Document Number Override		Primary Crash Document #	Agency Crash Number 19-00763	Investigating Officer/Deputy DEPUTY S. FINNEGAN	
Crash Date 01/18/2019		Crash Time 04:16 PM	Date Arrived 01/18/2019	Time Arrived 05:32 PM	
Date Notified 01/18/2019		Time Notified 04:24 PM	Total Units 01	Total Injured 00	Total Killed 00
<input type="checkbox"/> On Emergency	<input type="checkbox"/> Hit and Run	<input type="checkbox"/> Lane Closure	<input type="checkbox"/> Work Zone	<input type="checkbox"/> Trailer or Towed	<input type="checkbox"/> Reporting Threshold
<input type="checkbox"/> Government Property	<input type="checkbox"/> Active School Zone	School Bus Related NO		Tags	
<input checked="" type="checkbox"/> Reportable		Crash Type DT4000 (STANDARD CRASH)		<input type="checkbox"/> Amended	<input type="checkbox"/> Secondary Crash

Description

<p>Diagram</p>	Reconstruction By
	Photos By
	Additional Information NONE

I, a sworn law enforcement officer, agree that I have not added any CJIS data in this report.

UNIT 1 WAS S/B ON MINI CREEK RD AND DRIVER WAS NEGOTIATING A LEFT CURVE WHEN HE LOST CONTROL ON THE SLIPPERY SNOW COVERED ROADWAY AND WENT INTO THE DITCH WHERE HE HIT A CULVERT AT 113 RIVER ST. I ALSO OBSERVED HIS TIRED TO BE LESS THAN ACCEPTABLE FOR WINTER DRIVING.

6TL09KMLZQ

19-00763

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMENT
1300 LANGE COURT
BARABOO, WI 53913
(608) 356-4895

Location

ON 113 RIVER RD S 869 FT W OF CENTER ST/ STH58 SB (HOUSE/BUILDING 113) IN THE VILLAGE OF LA VALLE IN SAUK COUNTY	Latitude 43.578715467	Longitude -90.13717871
	X Coordinate 246700.171875	Y Coordinate 4829866.5
	Structure Type HOUSE/BUILDING	

Crash Scene

First Harmful Event CULVERT		First Harmful Event Location SHOULDER RIGHT	
Manner of Collision NO COLLISION W/VEHICLE IN TRANSPORT		Light Condition DUSK	
Road Surface Condition(s) SNOW		Roadway Factor(s) NONE	
Environment Factor(s) WEATHER CONDITIONS			
Weather Condition(s) SNOW			
Animal Type		Relation To Trafficway TRAFFICWAY - ON ROAD	
Crash Classification - Location PUBLIC PROPERTY		Crash Classification - Jurisdiction NO SPECIAL JURISDICTION	
Tribal Land		Access Control NO CONTROL	Special Study
Within Interchange Area NO	Junction Location NON-JUNCTION	Intersection Type NOT AN INTERSECTION	

Unit Summary

UNIT 01	Unit Status IN TRANSIT		Vehicle Operating As Classification D CLASS		Unit Type AUTOMOBILE	
	Vehicle Type (SPORT) UTILITY VEHICLE				Operating As Endorsements	
	Total Occs 1	Train/Bus # Recorded	Total # Citations Issued 0	Total Trailers 0	Total HazMat Types 0	
	Insurance? YES	Direction Of Travel SOUTHBOUND	<input type="checkbox"/> Pre CrashTire Mark	Speed Limit 35	Total Lanes 2	
	Most Harmful Event: Collision With CULVERT		Special Function NO SPECIAL FUNCTION		Emergency Motor Vehicle Use NOT APPLICABLE	
	Traffic Way TWO-WAY, NOT DIVIDED		Traffic Control NO CONTROL		Traffic Control Inoperative/Missing NO	
	Surface Type BLACKTOP (BITUMINOUS)		Road Curvature CURVE LEFT		Road Grade LEVEL	
	Truck Bus or HazMat NO					

UNIT 01 VEHICLE	Vehicle				
	License Plate Number 575PDM		Plate Type AUT - AUTOMOBILE	St WI	Country of Issuance UNITED STATES
	Vehicle Identification Number JTJBT20X060107712		Make LEXUS	Year 2006	Model GX 470
	Color BLK - BLACK		Body Style UT - SPORT UTILITY VEHICLE		Bus Use NOT A BUS
	Initial Contact Point 12--FRONT		Vehicle Damage 1--RIGHT FRONT CORNER, 2--RIGHT SIDE FRONT, 12--FRONT, UNDERCARRIAGE		
Extent Of Damage DISABLING DAMAGE					

6TL09KMLZQ

19-00763

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMENT
1300 LANGE COURT
BARABOO, WI 53913
(608) 356-4895

UNIT VEHICLE	Towed Due To Damage TOWED DUE TO DISABLING DAMAGE		Vehicle Removed By STEVES AUTO SERVICE	
	What Driver Was Doing NEGOTIATING CURVE		Vehicle Factors	
	Driver Prior Action Other		TIRES	
	Driver Actions SPEED TOO FAST/COND, FAILURE TO CONTROL, RAN OFF ROADWAY, FAILED TO KEEP IN DESIGNATED LANE			
01	01	Owner Name DAVID B GREENING (920) 251-6429		Owner Address 372 S LAWSON DR GREEN LAKE, WI 54941 , US
Sequence Of Events				
	01	Event RUN OFF ROADWAY RIGHT		
	02	Event CULVERT		
	03	Event		
	04	Event		
UNIT	Policy Holder			
	Insurance Company WEST-BEND-MUTUAL-INS-CO		Individual DAVID GREENING	
UNIT INDIVIDUAL	Individual			
	Driver DAVID B GREENING (920) 251-6429		Citations Issued 0	Sex MALE
	Address 372 S LAWSON DR GREEN LAKE, WI 54941 , US		Date of Birth	Race WHITE
	Driver License Number		STATE: WISCONSIN COUNTRY: UNITED STATES	
UNIT 001	Safety Equipment		On Duty Crash	
	Seat Position 1--FRONT SEAT-LEFT SIDE (DRIVER/MOTORCY		Safety Equipment SHOULDER & LAP BELT	
	Helmet Use		Helmet Compliance	
	Eye Protection		Tint Compliance	
	Injury		Injury Severity NO APPARENT INJURY	Airbag NON DEPLOYED
Ejected NOT EJECTED		Ejection Path NOT EJECTED/NOT APPLICABLE		Trapped/Extricated NOT TRAPPED
Medical Transport NOT TRANSPORTED		EMS Agency Identifier		EMS Run #
Hospital		Date of Death		Time of Death
Distracted By		Distracted By Source		
Distracted By Action NOT DISTRACTED				

6TL09KMLZQ

19-00763

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMENT
1300 LANGE COURT
BARABOO, WI 53913
(608) 356-4895

UNIT	Non Motorist	Striking Unit #	Location			
		Prior Action				
	INDIVIDUAL	Action				
		Action Other			To/From School	
		Drug & Alcohol	Suspected Alcohol Use NO	Suspected Drug Use NO		
		Alcohol Test Given TEST NOT GIVEN	Alcohol Test Type		Alcohol Test Results	
	01	001	Drug Test Given TEST NOT GIVEN	Drug Test Type	Drug Test Results	
			Drug Type			
			Individual Condition APPEARED NORMAL			
			Property Owner			
PROP OWNER	01	Individual WILLIAM E SWOPE (608) 963-8568		Address 113 RIVER ST LA VALLE, WI 53941 , US		
		Fixed Objects Struck				
01	Striking Unit 01	Struck Object CULVERT		Structure Number	Damage Tag Number	