

6TL09PBQB3

19-00925

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMENT
1300 LANGE COURT
BARABOO, WI 53913
(608) 356-4895

Location

ON CTHH EB 0.59 MI N OF CTHP SB IN THE TOWN OF DELLONA IN SAUK COUNTY	Latitude 43.599915716	Longitude -89.905984039
	X Coordinate 265450.375	Y Coordinate 4831541.5
	Structure Type	

Crash Scene

First Harmful Event DITCH	First Harmful Event Location SHOULDER RIGHT	
Manner of Collision NO COLLISION W/VEHICLE IN TRANSPORT	Light Condition DAYLIGHT	
Road Surface Condition(s) SNOW	Roadway Factor(s) ROAD SURFACE CONDITION (WET, ICY, SNOW, SLUSH, ETC)	
Environment Factor(s) WEATHER CONDITIONS		
Weather Condition(s) SNOW		
Animal Type	Relation To Trafficway TRAFFICWAY - ON ROAD	
Crash Classification - Location PUBLIC PROPERTY	Crash Classification - Jurisdiction NO SPECIAL JURISDICTION	
Tribal Land	Access Control NO CONTROL	Special Study
Within Interchange Area NO	Junction Location NON-JUNCTION	Intersection Type NOT AN INTERSECTION

Unit Summary

UNIT	Unit Status IN TRANSIT	Vehicle Operating As Classification D CLASS		Unit Type AUTOMOBILE	
	Vehicle Type PASSENGER CAR	Operating As Endorsements			
	Total Occs 1	Train/Bus # Recorded	Total # Citations Issued 0	Total Trailers 0	Total HazMat Types
	Insurance? YES	Direction Of Travel EASTBOUND	<input type="checkbox"/> Pre CrashTire Mark	Speed Limit 55	Total Lanes 2
	Most Harmful Event: Collision With DITCH	Special Function NO SPECIAL FUNCTION		Emergency Motor Vehicle Use NOT APPLICABLE	
	Traffic Way TWO-WAY, NOT DIVIDED	Traffic Control NO CONTROL		Traffic Control Inoperative/Missing NO	
	Surface Type BLACKTOP (BITUMINOUS)	Road Curvature CURVE RIGHT		Road Grade LEVEL	
	Truck Bus or HazMat NO				

UNIT	Vehicle				
	01	License Plate Number AAH2601	Plate Type AUT - AUTOMOBILE	St WI	Country of Issuance UNITED STATES
		Vehicle Identification Number 4T4BF3EK6AR063277	Make TOYOTA	Year 2010	Model CAMRY/SE/L
		Color GRY - GRAY	Body Style 4D - 4DR		Bus Use NOT A BUS
	VEHICLE	Initial Contact Point 12--FRONT	Vehicle Damage		
Extent Of Damage NO DAMAGE		NO DAMAGE			

WISCONSIN MOTOR VEHICLE
CRASH REPORT

UNIT VEHICLE	Towed Due To Damage NOT TOWED		Vehicle Removed By OWNER	
	What Driver Was Doing NEGOTIATING CURVE		Vehicle Factors	
	Driver Prior Action Other		NOT APPLICABLE	
	Driver Actions SPEED TOO FAST/COND			
01	01	Owner Name ROGER A ENNIS (608) 415-2817		Owner Address 421 WASHINGTON ST WONEWOC, WI 53968 , US
Sequence Of Events				
	01	Event DITCH		
	02	Event		
	03	Event		
	04	Event		
UNIT	Policy Holder			
	Insurance Company PROGRESSIVE-ADVANCED-INSURANCE-CO		Individual ANGEL ENNIS	
UNIT INDIVIDUAL	Individual			
	Driver ANGEL MARIE ENNIS (608) 415-2817		Citations Issued 0	Sex FEMALE
	Address 421 WASHINGTON ST WONEWOC, WI 53968 , US		Date of Birth	Race WHITE
			Driver License Number STATE: WISCONSIN COUNTRY: UNITED STATES	
UNIT INDIVIDUAL	Safety Equipment		On Duty Crash	
	Seat Position 1--FRONT SEAT-LEFT SIDE (DRIVER/MOTORCY		Safety Equipment SHOULDER & LAP BELT	
	Helmet Use		Helmet Compliance	
	Eye Protection		Tint Compliance	
	01 001	Injury		Injury Severity NO APPARENT INJURY
		Airbag NON DEPLOYED		
Ejected NOT EJECTED		Ejection Path NOT EJECTED/NOT APPLICABLE		
Medical Transport NOT TRANSPORTED		Trapped/Extricated NOT TRAPPED		
Hospital		EMS Agency Identifier	EMS Run #	
		Date of Death	Time of Death	
Distracted By		Distracted By Source		
Distracted By Action UNKNOWN				

WISCONSIN MOTOR VEHICLE
CRASH REPORT

UNIT	Non Motorist		Striking Unit #	Location		
	Prior Action					
	Action					
	Action Other					
	To/From School					
	Drug & Alcohol		Suspected Alcohol Use NO	Suspected Drug Use NO		
	Alcohol Test Given TEST NOT GIVEN		Alcohol Test Type		Alcohol Test Results	
	Drug Test Given TEST NOT GIVEN		Drug Test Type		Drug Test Results	
	Drug Type					
	Individual Condition APPEARED NORMAL					