6TL0BGSFCR 19-00764

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

	Document Number Override	Primary Crash [Primary Crash Document # Crash Time 04:39 PM		y Crash Number 764	Investigating Officer/Deputy DEPUTY B. LUBER Time Arrived 05:24 PM		
CR	Crash Date 01/18/2019				rrived /2019			
GSF	Date Notified 01/18/2019	Time Notified 05:20 PM			Inits	Total Injured 00	Total Killed 00	
	On Emergency	Hit and Run	t and Run Lane Closu		☐ Work Zone	Trailer or Towed		Reporting Threshold
6TL	Government Active S		School Bus Related NO		Tags			
_	✓ Reportable	NDARD CRASH	CRASH)		Amended		Secondary Crash	
	Dan and a than	•				•		•

Diagram Photos By Additional Information NONE Reconstruction By Google

UNIT 1 WAS SOUTH ON HWY 23. WHILE TRAVELING UP THE HILL UNIT 1 LOST CONTROL, ENTERED OPPOSITE LANE, AND CAME TO REST DOWN THE HILL AGAINST A TREE. AT THE TIME OF THE CRASH IT WAS SNOWING AND THE ROADWAYS WERE SLIPPERY. MINOR DAMAGE OBSERVED ON VEHICLE. DUE TO WEATHER AND LOCATION DELAYED RECOVERY WAS COMPLETED ON 1/20/19. VEHICLE PULLED OUT BY GEORGES AND REMOVED FROM SCENE BY OPERATOR.

6TL0BGSFCR 19-00764

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 01/18/2019

Crash Time 04:39 PM

_	_OC	ation									
F	ON	STH23 WB				Latitude			Longitude		
	0.66	S MI N			43.250694743			-90.067889865			
		PAULUS RD			X Coordinate			Y Coordinate			
	IN THE TOWN OF FRANKLIN					250952.9375			4793225.5		
	IN SAUK COUNTY										
						Structure Type					
C	Cra	sh Scene									
Ī	First	Harmful Event				First Harm	ful Event L	ocation.			
							E RIGHT-	OF-WAY (TE	RAFFICWAY)		
Manner of Collision						Light Condition					
	NO COLLISION W/VEHICLE IN TRANSPORT					DARK/U	NLIT				
Road Surface Condition(s)						Roadway Factor(s)					
	SNC	ow									
-	Envi	ronment Factor(s)									
	NON	NE				ROAD S	URFACE	CONDITION	(WET, ICY, SNOW, SLUSH,		
ŀ	Wea	ther Condition(s)				•					
	SNC										
-	Anim	nal Type			Relation To Trafficway TRAFFICWAY - ON F			ay			
L	_										
		h Classification - Location	1					Jurisdiction			
L	_	BLIC PROPERTY			NO SPECIAL JUF						
	Triba	al Land		Access Control Special S NO CONTROL			Special Study				
t	Withi	in Interchange Area	Junction Location		Intersection	and Intersection					
	NO	· ·	NON-JUNCTION		NOT AN I						
ŀ	Init	t Summary =									
				Vahiola One	aratina Aa Cla	nacification		I I In it Town			
	-			Unit Status Vehicle Operating As C				21.2			
L		IN TRANSIT D CLASS						TDUCK			
				D CLASS				TRUCK			
		cle Type	TRUCK	D CLASS					s Endorsements		
	UTIL	cle Type LITY TRUCK/PICKUP						Operating A			
	UTII Total	cle Type	TRUCK Train/Bus # Recorded	Total # Cita	tions Issued		Total Trai	Operating A	Total HazMat Types		
	UTIL Total 1	cle Type LITY TRUCK/PICKUP I Occs	Train/Bus # Recorded	Total # Cita			0	Operating A	Total HazMat Types 0		
	Total 1 Insur	cle Type LITY TRUCK/PICKUP I Occs rance?	Train/Bus # Recorded Direction Of Travel	Total # Cita	CrashTire		0 Speed Lin	Operating A	Total HazMat Types 0 Total Lanes		
	Total 1 Insur YES	cle Type LITY TRUCK/PICKUP I Occs rance?	Train/Bus # Recorded Direction Of Travel SOUTHBOUND	Total # Cita 0 Pre	CrashTire Mark		0	Operating A	Total HazMat Types 0 Total Lanes 2		
-	Total 1 Insur YES	cle Type LITY TRUCK/PICKUP I Occs rance? S t Harmful Event: Collision	Train/Bus # Recorded Direction Of Travel SOUTHBOUND	Total # Cita 0 Pre Special Fun	CrashTire Mark	TION	0 Speed Lin	Operating A	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use		
-	Total Insur YES Most	cle Type LITY TRUCK/PICKUP I Occs rance? St Harmful Event: Collision	Train/Bus # Recorded Direction Of Travel SOUTHBOUND	Total # Cita 0 Pre Special Fun NO SPEC	CrashTire Mark action	TION	0 Speed Lin	Operating A llers mit Emergency NOT APP	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE		
-	Total Insur YES Most TRE	cle Type LITY TRUCK/PICKUP I Occs rance? t Harmful Event: Collision EE	Train/Bus # Recorded Direction Of Travel SOUTHBOUND With	Total # Citat 0 Pre Special Fun NO SPEC Traffic Cont	CrashTire Mark action IAL FUNC	TION	0 Speed Lin	Operating A Clers Tit Emergency NOT APP	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use		
	Total Insur YES Most TRE	cle Type LITY TRUCK/PICKUP I Occs rance? t Harmful Event: Collision EE ic Way D-WAY, NOT DIVIDED	Train/Bus # Recorded Direction Of Travel SOUTHBOUND With	Total # Cita 0 Pre Special Fun NO SPEC Traffic Cont NO CONT	CrashTire Mark lection IAL FUNC	TION	0 Speed Lin	Operating A Continue of the c	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing		
	Total Insur YES Most TRE Traffi TWC	cle Type LITY TRUCK/PICKUP I Occs rance? L Harmful Event: Collision EE iic Way D-WAY, NOT DIVIDED ace Type	Train/Bus # Recorded Direction Of Travel SOUTHBOUND With	Total # Cita 0 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva	CrashTire Mark iction IAL FUNCTOR TROL iture	TION	0 Speed Lin	Operating A lers mit Emergency NOT APP Traffic Cont NO Road Grade	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing		
-	Total Total Insur YES Most TRE Traffi TWO Surfa BLA	cle Type LITY TRUCK/PICKUP I Occs rance? L Harmful Event: Collision E ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU	Train/Bus # Recorded Direction Of Travel SOUTHBOUND With	Total # Cita 0 Pre Special Fun NO SPEC Traffic Cont NO CONT	CrashTire Mark iction IAL FUNCTOR TROL iture	TION	0 Speed Lin	Operating A Continue of the c	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing		
	Total Total Insur YES Most TRE Traffi TWO Surfa BLA	cle Type LITY TRUCK/PICKUP I Occs rance? L Harmful Event: Collision EE iic Way D-WAY, NOT DIVIDED ace Type	Train/Bus # Recorded Direction Of Travel SOUTHBOUND With	Total # Cita 0 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva	CrashTire Mark iction IAL FUNCTOR TROL iture	TION	0 Speed Lin	Operating A lers mit Emergency NOT APP Traffic Cont NO Road Grade	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing		
-	Traffi Total Insur YES Most TRE Traffi TWC Surfa BLA Truck	cle Type LITY TRUCK/PICKUP I Occs rance? L Harmful Event: Collision E ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU	Train/Bus # Recorded Direction Of Travel SOUTHBOUND With	Total # Cita 0 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva	CrashTire Mark iction IAL FUNCTOR TROL iture	TION	0 Speed Lin	Operating A lers mit Emergency NOT APP Traffic Cont NO Road Grade	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing		
	Traffi Total Insur YES Most TRE Traffi TWC Surfa BLA Truck	cle Type LITY TRUCK/PICKUP I Occs rance? St Harmful Event: Collision EE ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU k Bus or HazMat	Train/Bus # Recorded Direction Of Travel SOUTHBOUND With	Total # Cita 0 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva	CrashTire Mark Inction IIAL FUNCT TOI ROL Inture T	TION	0 Speed Lin	Operating A lers mit Emergency NOT APP Traffic Cont NO Road Grade	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE ol Inoperative/Missing		
	Traffi Total Insur YES Most TRE Traffi TWC Surfa BLA Truck	cle Type LITY TRUCK/PICKUP I Occs rance? St Harmful Event: Collision EE iic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU k Bus or HazMat	Train/Bus # Recorded Direction Of Travel SOUTHBOUND With	Total # Cita 0 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva STRAIGH	CrashTire Mark Inction IIAL FUNCT TOI ROL Inture T		Speed Lii	Operating A llers mit Emergency NOT APP Traffic Cont NO Road Grade UPHILL	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing		
	Total Insur YES Most TRE Traff TWC Surfa BLA	cle Type LITY TRUCK/PICKUP I Occs rance? St Harmful Event: Collision EE ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU k Bus or HazMat Vehicle License Plate Number	Train/Bus # Recorded Direction Of Travel SOUTHBOUND With	Total # Cita 0 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva STRAIGH	CrashTire Mark oction IIAL FUNC rol ROL atture T		Speed Lii 55	Operating A llers mit Emergency NOT APP Traffic Cont NO Road Grade UPHILL Country of Is	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing		
	Traffi Total Insur YES Most TRE Traffi TWC Surfa BLA Truck	cle Type LITY TRUCK/PICKUP I Occs rance? St Harmful Event: Collision EE ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU k Bus or HazMat Vehicle License Plate Number JW5970	Train/Bus # Recorded Direction Of Travel SOUTHBOUND With Direction Of Travel SOUTHBOUND	Total # Cita 0 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva STRAIGH	CrashTire Mark oction IIAL FUNC rol ROL atture T		Speed Lin 55 St WI	Operating A lers mit Emergency NOT APP Traffic Cont NO Road Grade UPHILL Country of Is UNITED ST	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing		
	Total Insur YES Most TRE Traff TWC Surfa BLA	cle Type LITY TRUCK/PICKUP I Occs rance? St Harmful Event: Collision EE ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU k Bus or HazMat Vehicle License Plate Number JW5970 Vehicle Identification Nu	Train/Bus # Recorded Direction Of Travel SOUTHBOUND With Direction Of Travel SOUTHBOUND	Total # Citar 0 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva STRAIGH Plate Type LTK - LIG Make	CrashTire Mark loction IIAL FUNC rol ROL sture T		Stem WI	Operating A lers mit Emergency NOT APP Traffic Cont NO Road Grade UPHILL Country of Is UNITED ST Model RANGER Bus Use	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing		
	Total Insur YES Most TRE Traff TWC Surfa BLA	cle Type LITY TRUCK/PICKUP I Occs rance? St Harmful Event: Collision EE ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU k Bus or HazMat Vehicle License Plate Number JW5970 Vehicle Identification Nu 1FTCR10A9NPA890	Train/Bus # Recorded Direction Of Travel SOUTHBOUND With Direction Of Travel SOUTHBOUND	Total # Cita 0 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva STRAIGH Plate Type LTK - LIG Make FORD	CrashTire Mark Mark IAL FUNC rol ROL sture T		Stem WI	Operating A llers mit Emergency NOT APPI Traffic Cont NO Road Grade UPHILL Country of Is UNITED ST Model RANGER	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing		
	UTIII Total 1 Insur YES Most TREF TWO Surfa BLA Trucl NO	cle Type LITY TRUCK/PICKUP I Occs rance? St Harmful Event: Collision EE ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU k Bus or HazMat Vehicle License Plate Number JW5970 Vehicle Identification Nu 1FTCR10A9NPA890 Color	Train/Bus # Recorded Direction Of Travel SOUTHBOUND With Direction Of Travel SOUTHBOUND	Total # Citar 0 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva STRAIGH Plate Type LTK - LIG Make FORD Body Style	CrashTire Mark Inction IIAL FUNCT ITAL ITAL ITAL ITAL ITAL ITAL ITAL ITA		Stem WI	Operating A lers mit Emergency NOT APP Traffic Cont NO Road Grade UPHILL Country of Is UNITED ST Model RANGER Bus Use	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing		
	UTIII Total 1 Insur YES Most TREF TWO Surfa BLA Trucl NO	cle Type LITY TRUCK/PICKUP I Occs rance? St Harmful Event: Collision EE ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU k Bus or HazMat Vehicle License Plate Number JW5970 Vehicle Identification Nu 1FTCR10A9NPA890 Color BLU - BLUE	Train/Bus # Recorded Direction Of Travel SOUTHBOUND With Direction Of Travel SOUTHBOUND With	Total # Citar 0 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva STRAIGH Plate Type LTK - LIG Make FORD Body Style PK - PICI	CrashTire Mark Inction IIAL FUNCT ITAL ITAL ITAL ITAL ITAL ITAL ITAL ITA		Stem WI	Operating A lers mit Emergency NOT APP Traffic Cont NO Road Grade UPHILL Country of Is UNITED ST Model RANGER Bus Use	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing		
	UTIII Total 1 Insur YES Most TREF TWO Surfa BLA Trucl NO	cle Type LITY TRUCK/PICKUP I Occs rance? St Harmful Event: Collision EE ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU k Bus or HazMat Vehicle License Plate Number JW5970 Vehicle Identification Nu 1FTCR10A9NPA890 Color BLU - BLUE Initial Contact Point	Train/Bus # Recorded Direction Of Travel SOUTHBOUND With Direction Of Travel SOUTHBOUND With	Total # Cita 0 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva STRAIGH Plate Type LTK - LIG Make FORD Body Style PK - PICI Vehicle Da	CrashTire Mark Inction IIAL FUNCT ITAL ITAL ITAL ITAL ITAL ITAL ITAL ITA	K	Stem WI	Operating A lers mit Emergency NOT APP Traffic Cont NO Road Grade UPHILL Country of Is UNITED ST Model RANGER Bus Use	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing		
	Truck NO	cle Type LITY TRUCK/PICKUP I Occs rance? St Harmful Event: Collision EE ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU k Bus or HazMat Vehicle License Plate Number JW5970 Vehicle Identification Nu 1FTCR10A9NPA890 Color BLU - BLUE Initial Contact Point 1RIGHT FRONT CO	Train/Bus # Recorded Direction Of Travel SOUTHBOUND With Direction Of Travel SOUTHBOUND With	Total # Cita 0 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva STRAIGH Plate Type LTK - LIG Make FORD Body Style PK - PICI Vehicle Da	CrashTire Mark Identification IIAL FUNCT ITAL INTERIOR IN	K	Stem WI	Operating A lers mit Emergency NOT APP Traffic Cont NO Road Grade UPHILL Country of Is UNITED ST Model RANGER Bus Use	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing		

6TL0BGSFCR 19-00764

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT **BARABOO, WI 53913** (608) 356-4895

		Towed Due To Damage		Vehicle Removed By					
				OPERATOR					
				Vehicle Factors					
		GOING STRAIGHT							
				NOT APPLICABLE					
		Driver Actions							
	ш	SPEED TOO FAST/COM	ND						
⊨	VEHICL								
LNO	Ĭ								
ر	/E								
		Owner Name		Owner Address					
_		STEVEN H ROBERTS		E5610 JONES RD					
6	01	(608) 206-4082		SPRING GREEN, WI 53588 , US					
		Sequence Of Event	S						
		Event							
	01	RUN OFF ROADWAY L	EFT						
	02	Event TREE							
	0								
	03	Event							
		Event							
	04	Lvein							
		Policy Holder							
LINO		Insurance Company		Individual					
5			CO-(ATTN:-CLAIMS-DEPT)	STEVEN ROBERTS					
		,							
		Individual							
	۸L	Driver STEVEN H ROBERTS		Citations Issued	Sex				
		(608) 206-4082		O Date of Dirth	MALE Race				
	INDIVIDUAL			Date of Birth	WHITE				
	M	Address		Driver License Number					
\neg		E5610 JONES RD SPRING GREEN, WI 53588 , US							
	Z			STATE: WISCONSIN COUNTRY: UNITED STATES					
		On Di	uty Crash	Safety Equipment					
	Sat	fety Equipment							
		Seat Position		SHOULDER & LAP BELT					
		1FRONT SEAT-LEFT SIDE (DRIVER/MOTORCY							
		Helmet Use		Helmet Compliance					
		Eye Protection		Tint Compliance					
									
5	90	I	Severity	Airbag					
	0	7 7 110 7	APPARENT INJURY Ejection Path	NON DEPLOYED	Transad/Extrinated				
		Ejected	NOT EJECTED/NOT API	DI ICADI E	Trapped/Extricated NOT TRAPPED				
			INOT EJECTED/NOT AP	PLICABLE					
		NOT EJECTED Medical Transport		EMS Agonov Identifier	I EMS Dup #				
		Medical Transport		EMS Agency Identifier	EMS Run #				
		Medical Transport NOT TRANSPORTED							
		Medical Transport		EMS Agency Identifier Date of Death	EMS Run # Time of Death				
		Medical Transport NOT TRANSPORTED Hospital Distra	acted By Source						
		Medical Transport NOT TRANSPORTED Hospital	acted By Source						
		Medical Transport NOT TRANSPORTED Hospital Distra	acted By Source						

Crash Date 01/18/2019 Crash Time 04:39 PM

6TL0BGSFCR 19-00764

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 01/18/2019

Crash Time 04:39 PM

		Non Motorist	Striking Unit #	Location				
		Prior Action						
TINO	INDIVIDUAL	Action						
		Action Other						To/From School
	L	Drug & Alcohol	Suspected Alcohol L NO	Jse	Suspected Drug Use NO			
		Alcohol Test Given TEST NOT GIVEN		Alcohol Test Type			Alcohol Test Results	
		Drug Test Given TEST NOT GIVEN	I	Drug Test Type		Drug Test Results		
2	001	Drug Type						
		Individual Condition						
		APPEARED NOR	MAL					