19-00947

WISCONSIN MOTOR VEHICLE CRASH REPORT

	Document Number Override	Primary Crash Document #	Agency Crash Number 19-00947	Investigating DEPUTY A	Officer/Deputy		
66	Crash Date 01/23/2019	Crash Time 06:18 PM			ne Arrived : :19 PM		
6TL09426S9	Date Notified 01/23/2019	Time Notified 06:19 PM	Total Units 02	Total InjuredTotal Killed0000		d	
-060	On Emergency	and Run	ure Work Zone	Trailer	or Towed	Reporting Threshold	
6TL	Government Property	Active School Zone	School Bus Related	Tags		•	
	Reportable	Crash Type DT4000 (STANDARD CRASH)	Amend	ed	Secondary Crash	
	Description				Reconstruction		
	Not to S	calo			Reconstruction	Бу	
	Not to 3						
	C				Photos By		
					Additional Infor	mation	
			(===				
)2			
	<u> </u>						
	Sheriff Squad	Security Van	(Tow Truc	k)			
			Vabiala in dita	_			
			Vehicle in ditcl	n			
	Christmas Mnt. Rd						
		nt officer, agree that I have no			ED GIVING OV	'ER A BRIGHT LIGHT.	
	UNIT 1 WAS PARKED IN FRONT GREEN/RED EMERGENCY LIGHT	OF A VEHICLE THAT WAS IN THE TS ACTIVATED AND FLASHING. B	DITCH. BEHIND THE VEHICLE IN EHIND THE SECURITY VAN WAS	THE DITCH W A FULL MARKI	AS A SECURIT	Y VAN THAT HAD QUAD CAR WITH	
		NG ACTIVATED. UNIT 2 PROCEED IDED WITH THE REAR DRIVER SI					

19-00947

WISCONSIN MOTOR VEHICLE CRASH REPORT

_ L	.oc	ation								
		CHRISTMAS MOUNT	AIN RD			Latitude			Longitude	
		FTE				43.61205	53471		-89.865437904	
	OF COON BLUFF RD IN THE TOWN OF DELLONA IN SAUK COUNTY						ate		Y Coordinate	
							268769.625		4832776	
							Туре			
						NO STR	UCTURE			
(Cra	sh Scene								
Γ	First	Harmful Event				First Harm	nful Event L	ocation		
							DWAY			
F	Manner of Collision					Light Cond	dition			
						DARK/U	NLIT			
	Road	d Surface Condition(s)				Roadway	Factor(s)			
	SNC	wc								
-	Envi	ronment Factor(s)				-				
	NO					NONE				
	_					NONE				
ſ	Wea	ther Condition(s)								
	CLC	DUDY								
-	Anim	nal Type				Relation T	o Trafficwa	av		
								N ROAD		
╞	Cras	sh Classification - Location	1					Jurisdiction		
	PUE	BLIC PROPERTY				NO SPE	CIAL JUF	RISDICTION		
F	Triba	al Land				Access Co	ontrol		Special Study	
						NO CONTROL				
	With	in Interchange Area	Junction Location		Intersectio	on Type NINTERSECTION				
	NO		NON-JUNCTION		NOT AN					
ι	Jni	t Summary 🛛 💻								
Τ	Unit	Status	Unit Status Vehicle Operating As Cl				Classification Unit Type			
	LEGALLY PARKED D CLASS					accinication				
								TRUCK		
-	Vehi	icle Type						TRUCK	s Endorsements	
5	Vehi STR	icle Type RAIGHT TRUCK (INSE		D CLASS				TRUCK Operating A		
5	Vehi STR Tota	icle Type	RT TRUCK)	D CLASS			Total Tra	TRUCK Operating A	Total HazMat Types	
5	Vehi STR Tota 0	icle Type RAIGHT TRUCK (INSE I Occs	Train/Bus # Recorded	D CLASS			Total Tra 0	TRUCK Operating A	Total HazMat Types 0	
5	Vehi STR Tota 0 Insu	icle Type RAIGHT TRUCK (INSE I Occs rance?	Train/Bus # Recorded Direction Of Travel	D CLASS	tions Issued		Total Tra 0 Speed Li	TRUCK Operating A	Total HazMat Types 0 Total Lanes	
5	Vehi STR Tota 0 Insui YES	icle Type RAIGHT TRUCK (INSE I Occs rance?	Train/Bus # Recorded Direction Of Travel EASTBOUND	D CLASS	tions Issued CrashTire Mark		Total Tra 0	TRUCK Operating A illers	Total HazMat Types 0 Total Lanes 2	
	Vehi STR Tota 0 Insui YES	icle Type RAIGHT TRUCK (INSE I Occs rance? S t Harmful Event: Collision	Train/Bus # Recorded Direction Of Travel EASTBOUND With	D CLASS	tions Issued CrashTire Mark ction	1	Total Tra 0 Speed Li	TRUCK Operating A illers	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use	
	Vehi STR Tota 0 Insur YES Most	icle Type RAIGHT TRUCK (INSE I Occs rance? S t Harmful Event: Collision RKED MOTOR VEHICI	Train/Bus # Recorded Direction Of Travel EASTBOUND With	D CLASS	tions Issued CrashTire Mark ction IAL FUNC	1	Total Tra 0 Speed Li	TRUCK Operating A illers mit Emergency NOT APP	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE	
	Vehi STR Tota 0 Insui YES Most PAF Traff	icle Type RAIGHT TRUCK (INSE I Occs rance? S t Harmful Event: Collision RKED MOTOR VEHICI fic Way	Train/Bus # Recorded Direction Of Travel EASTBOUND With LE	D CLASS	tions Issued CrashTire Mark ction IAL FUNC	1	Total Tra 0 Speed Li	TRUCK Operating A illers mit Emergency NOT APP Traffic Cont	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use	
	Vehi STR Tota 0 Insur YES Most PAF Traff	icle Type RAIGHT TRUCK (INSE I Occs rance? S t Harmful Event: Collision RKED MOTOR VEHICI	Train/Bus # Recorded Direction Of Travel EASTBOUND With LE	D CLASS	tions Issued CrashTire Mark ction IAL FUNC rol ROL	1	Total Tra 0 Speed Li	TRUCK Operating A illers mit Emergency NOT APP	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing	
	Vehi STR Tota 0 Insur YES Most PAF Traff TWO Surfa	icle Type RAIGHT TRUCK (INSE il Occs rance? S t Harmful Event: Collision RKED MOTOR VEHICI fic Way O-WAY, NOT DIVIDED ace Type	Train/Bus # Recorded Direction Of Travel EASTBOUND With LE	D CLASS	tions Issued CrashTire Mark ction IAL FUNC rol ROL ture	1	Total Tra 0 Speed Li	TRUCK Operating A illers mit Emergency NOT APP Traffic Cont NO Road Grade	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing	
	Vehi STR Tota 0 Insu YES Most PAF Traff TW(Surfa	icle Type RAIGHT TRUCK (INSE I Occs rance? S t Harmful Event: Collision RKED MOTOR VEHICI fic Way O-WAY, NOT DIVIDED	Train/Bus # Recorded Direction Of Travel EASTBOUND With LE	D CLASS	tions Issued CrashTire Mark ction IAL FUNC rol ROL ture	1	Total Tra 0 Speed Li	TRUCK Operating A illers mit Emergency NOT APP Traffic Cont NO	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing	
	Vehi STR Tota 0 Insu YES Most PAF Traff TW(Surfa	icle Type RAIGHT TRUCK (INSE I Occs rance? S t Harmful Event: Collision RKED MOTOR VEHICI fic Way O-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU ik Bus or HazMat	Train/Bus # Recorded Direction Of Travel EASTBOUND With LE	D CLASS	tions Issued CrashTire Mark ction IAL FUNC rol ROL ture	1	Total Tra 0 Speed Li	TRUCK Operating A illers mit Emergency NOT APP Traffic Cont NO Road Grade	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing	
	Vehi STR Tota 0 Insu YES Most PAF Traff TWC Surfa BLA Truc NO	icle Type RAIGHT TRUCK (INSE I Occs rance? S t Harmful Event: Collision ' RKED MOTOR VEHICI fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU k Bus or HazMat	Train/Bus # Recorded Direction Of Travel EASTBOUND With LE	D CLASS	tions Issued CrashTire Mark ction IAL FUNC rol ROL ture	1	Total Tra 0 Speed Li	TRUCK Operating A illers mit Emergency NOT APP Traffic Cont NO Road Grade	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing	
	Vehi STR Tota 0 Insu YES Most PAF Traff TWC Surfa BLA Truc NO	icle Type RAIGHT TRUCK (INSE I Occs rance? S t Harmful Event: Collision RKED MOTOR VEHICI fic Way O-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU ik Bus or HazMat	Train/Bus # Recorded Direction Of Travel EASTBOUND With LE	D CLASS	tions Issued CrashTire Mark ction IAL FUNC rol ROL ture T	1	Total Tra 0 Speed Li	TRUCK Operating A illers mit Emergency NOT APP Traffic Cont NO Road Grade	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing	
	Vehi STR Tota 0 Insu YES Most PAF Traff TWC Surfa BLA Truc NO	icle Type RAIGHT TRUCK (INSE I Occs rance? T Harmful Event: Collision RKED MOTOR VEHICI fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU Ik Bus or HazMat Vehicle	Train/Bus # Recorded Direction Of Travel EASTBOUND With LE	D CLASS	tions Issued CrashTire Mark ction IAL FUNC rol ROL ture T	TION	Total Tra 0 Speed Li 15	TRUCK Operating A ilers mit Emergency NOT APP Traffic Cont NO Road Grade LEVEL	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing suance	
	Vehi STR Tota 0 Insur YES Most PAF Traff TWC Surfa BLA Truc	icle Type RAIGHT TRUCK (INSE RAIGHT TRUCK (INSE I Occs rance? S t Harmful Event: Collision RKED MOTOR VEHICI fic Way O-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU k Bus or HazMat Vehicle License Plate Number	Train/Bus # Recorded Direction Of Travel EASTBOUND With LE S	D CLASS	tions Issued CrashTire Mark ction IAL FUNC rol ROL ture T	TION	Total Tra 0 Speed Li 15	TRUCK Operating A ilers mit Emergency NOT APPI Traffic Cont NO Road Grade LEVEL Country of Is	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing suance	
	Vehi STR Tota 0 Insu YES Most PAF Traff TWC Surfa BLA Truc NO	icle Type RAIGHT TRUCK (INSE RAIGHT TRUCK (INSE I Occs rance? THARMFUL Event: Collision RKED MOTOR VEHICI fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU Ik Bus or HazMat Vehicle License Plate Number GD73227	Train/Bus # Recorded Direction Of Travel EASTBOUND With LE S IS)	D CLASS	tions Issued CrashTire Mark ction IAL FUNC rol ROL ture T	TION	Total Tra 0 Speed Li 15 St WI	TRUCK Operating A illers mit Emergency NOT APPI Traffic Cont NO Road Grade LEVEL	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE Tol Inoperative/Missing	
	Vehi STR Tota 0 Insur YES Most PAF Traff TWC Surfa BLA Truc	icle Type RAIGHT TRUCK (INSE I Occs rance? S t Harmful Event: Collision RKED MOTOR VEHICI fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU Ik Bus or HazMat Vehicle License Plate Number GD73227 Vehicle Identification Nuu 5PVNJ8JN9G4S5209 Color	Train/Bus # Recorded Direction Of Travel EASTBOUND With LE S IS)	D CLASS	tions Issued CrashTire Mark ction IAL FUNC rol ROL ture T	CK	Total Tra 0 Speed Li 15 St WI Year	TRUCK Operating A ilers mit Emergency NOT APPI Traffic Cont NO Road Grade LEVEL Country of Is UNITED ST Model NO DATA Bus Use	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing suance FATES FO	
	Vehi STR Tota 0 Insur YES Most Traff TWC Surfa BLA Truc NO	icle Type RAIGHT TRUCK (INSE I Occs rance? S t Harmful Event: Collision RKED MOTOR VEHICI fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU k Bus or HazMat Vehicle License Plate Number GD73227 Vehicle Identification Num 5PVNJ8JN9G4S5209 Color WHI - WHITE	Train/Bus # Recorded Direction Of Travel EASTBOUND With LE S IS)	D CLASS	tions Issued CrashTire Mark ction IAL FUNC rol ROL ture T	CK	Total Tra 0 Speed Li 15 St WI Year	TRUCK Operating A illers mit Emergency NOT APPI Traffic Cont NO Road Grade LEVEL Country of Is UNITED ST Model NO DATA	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing suance FATES FO	
	Vehi STR Tota 0 Insu YES Most PAF Traff TWC Surfa BLA Truc NO	icle Type RAIGHT TRUCK (INSE I Occs rance? S t Harmful Event: Collision RKED MOTOR VEHICI fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU k Bus or HazMat Vehicle License Plate Number GD73227 Vehicle Identification Num SPVNJ8JN9G4S5209 Color WHI - WHITE Initial Contact Point	Train/Bus # Recorded Direction Of Travel EASTBOUND With LE 0 IS0 mber 28	D CLASS	tions Issued CrashTire Mark ction IAL FUNC rol ROL ture T	CK	Total Tra 0 Speed Li 15 St WI Year	TRUCK Operating A ilers mit Emergency NOT APPI Traffic Cont NO Road Grade LEVEL Country of Is UNITED ST Model NO DATA Bus Use	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing suance FATES FO	
	Vehi STR Tota 0 Insu YES Most PAF Traff TWC Surfa BLA Truc NO	icle Type AIGHT TRUCK (INSE I Occs rance? S t Harmful Event: Collision ' RKED MOTOR VEHICI fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU k Bus or HazMat Vehicle License Plate Number GD73227 Vehicle Identification Num 5PVNJ8JN9G4S5205 Color WHI - WHITE Initial Contact Point 7LEFT REAR COR	Train/Bus # Recorded Direction Of Travel EASTBOUND With LE 0 IS0 mber 28	D CLASS	tions Issued CrashTire Mark ction IAL FUNC rol ROL ture T CAVY TRU G CHASSI: mage	CK	Total Tra 0 Speed Li 15 St WI Year	TRUCK Operating A ilers mit Emergency NOT APPI Traffic Cont NO Road Grade LEVEL Country of Is UNITED ST Model NO DATA Bus Use	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing suance FATES FO	
	Vehi STR Tota 0 Insu YES Most PAF Traff TWC Surfa BLA Truc NO	icle Type RAIGHT TRUCK (INSE I Occs rance? S t Harmful Event: Collision ' RKED MOTOR VEHICI fic Way O-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU k Bus or HazMat Vehicle Identification Nut 5PVNJ8JN9G4S5205 Color WHI - WHITE Initial Contact Point 7LEFT REAR CORI Extent Of Damage	Train/Bus # Recorded Direction Of Travel EASTBOUND With LE 0 IS0 mber 28	D CLASS	tions Issued CrashTire Mark ction IAL FUNC rol ROL ture T CAVY TRU G CHASSI: mage	CK	Total Tra 0 Speed Li 15 St WI Year	TRUCK Operating A ilers mit Emergency NOT APPI Traffic Cont NO Road Grade LEVEL Country of Is UNITED ST Model NO DATA Bus Use	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing suance FATES FO	
	Vehi STR Tota 0 Insur YES Most Traff TWC Surfa BLA Truc NO	icle Type AIGHT TRUCK (INSE I Occs rance? S t Harmful Event: Collision ' RKED MOTOR VEHICI fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU k Bus or HazMat Vehicle License Plate Number GD73227 Vehicle Identification Nut 5PVNJ8JN9G4S5205 Color WHI - WHITE Initial Contact Point 7LEFT REAR COR	Train/Bus # Recorded Direction Of Travel EASTBOUND With LE 0 IS0 mber 28	D CLASS	tions Issued CrashTire Mark ction IAL FUNC rol ROL ture T CAVY TRU G CHASSI: mage	CK	Total Tra 0 Speed Li 15 St WI Year	TRUCK Operating A ilers mit Emergency NOT APPI Traffic Cont NO Road Grade LEVEL Country of Is UNITED ST Model NO DATA Bus Use	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing suance FATES FO	

19-00947

WISCONSIN MOTOR VEHICLE CRASH REPORT

		Towed Due To Damage Vehicle Removed E NOT TOWED OPERATOR								
		NOT TOWED What Driver Was Doing		-	e Factors					
		LEGALLY PARKED		Venici						
		Driver Prior Action Other		NOT	APPLICABLE					
		Driver Actions								
⊢	Ë	NO CONTRIBUTING /	ACTION							
	Ξ									
	-									
				-	wner Address 147A STH 13					
5	5	HOVELAND'S TOWING (608) 254-7852			ISCONSIN DELLS, WI	53965 ,L	JS			
	-									
	ļ	Sequence Of Ever	nts							
	6	Event MOTOR VEH IN TRAN								
		Event								
	02	_								
	03	Event								
	04	Event								
		Policy Holder								
UNIT		Insurance Company		Ora	Organization/Company					
		UNITED-FIRE-&-CAS			HOVELAND'S TOWING					
			CALL CO							
		t Summary								
	Unit	t Summary		Vehicle	Operating As Classificatio	n	Unit Type			
	Unit IN T	t Summary			Operating As Classificatio	n	AUTOMO			
	Unit IN T Vehi	t Summary		Vehicle	Operating As Classificatio	n	AUTOMO	BILE s Endorsements		
	Unit IN T Vehi PAS	t Summary Status RANSIT icle Type	Train/Bus # Recorded	Vehicle D CLA	Operating As Classificatio	n Total Trai	AUTOMO Operating A			
	Unit IN T Vehi PAS Tota 2	t Summary Status RANSIT icle Type SSENGER VAN I Occs	Train/Bus # Recorded	Vehicle D CLA	Operating As Classificatio	Total Trai 0	AUTOMO Operating A lers	ts Endorsements Total HazMat Types 0		
02	Unit IN T Vehi PAS Tota 2 Insu	t Summary Status TRANSIT icle Type SSENGER VAN I Occs rance?	Train/Bus # Recorded Direction Of Travel	Vehicle D CLA Total # 0	Operating As Classificatio SS Citations Issued Pre CrashTire	Total Trai 0 Speed Lir	AUTOMO Operating A lers	ts Endorsements Total HazMat Types 0 Total Lanes		
02	Unit IN T Vehi PAS Tota 2 Insur YES	t Summary Status RANSIT icle Type SSENGER VAN I Occs rance? S	Train/Bus # Recorded Direction Of Travel EASTBOUND	Total #	Operating As Classificatio SS Citations Issued Pre CrashTire Mark	Total Trai 0	AUTOMO Operating A lers	As Endorsements Total HazMat Types 0 Total Lanes 2		
	Unit IN T Vehi PAS Tota 2 Insur YES	t Summary Status TRANSIT icle Type SSENGER VAN I Occs rance?	Train/Bus # Recorded Direction Of Travel EASTBOUND Vith	Total #	Operating As Classificatio SS Citations Issued Pre CrashTire	Total Trai 0 Speed Lir	AUTOMO Operating A lers	As Endorsements Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use		
02	Unit IN T Vehi PAS Tota 2 Insur YES Most PAF Traff	t Summary Status TRANSIT icle Type SSENGER VAN I Occs rance? t Harmful Event: Collision W RKED MOTOR VEHICL fic Way	Train/Bus # Recorded Direction Of Travel EASTBOUND Vith	Total #	Operating As Classificatio ISS Citations Issued Pre CrashTire Mark Function PECIAL FUNCTION	Total Trai 0 Speed Lir	AUTOMO Operating A lers mit Emergency NOT APP	As Endorsements Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use		
02	Unit IN T Vehi PAS Tota 2 Insur YES Most PAF Traff	t Summary Status TRANSIT icle Type SSENGER VAN I Occs rance? S t Harmful Event: Collision V RKED MOTOR VEHICL fic Way D-WAY, NOT DIVIDED	Train/Bus # Recorded Direction Of Travel EASTBOUND Vith	Vehicle D CLA D CLA O Special NO SP Traffic (NO CC	Operating As Classificatio SS Citations Issued Pre CrashTire Mark Function PECIAL FUNCTION Control DNTROL	Total Trai 0 Speed Lir	AUTOMO Operating A lers nit Emergency NOT APP Traffic Cont NO	As Endorsements Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing		
02	Unit IN T Vehi PAS Tota 2 Insut YES Most PAF Traff TWC Surfa	t Summary Status TRANSIT icle Type SSENGER VAN I Occs rance? S t Harmful Event: Collision W RKED MOTOR VEHICL fic Way D-WAY, NOT DIVIDED ace Type	Train/Bus # Recorded Direction Of Travel EASTBOUND Vith E	Vehicle D CLA D CLA O U Special NO SF Traffic C NO CC Road C	Operating As Classificatio SS Citations Issued Pre CrashTire Mark Function PECIAL FUNCTION Control DNTROL Furvature	Total Trai 0 Speed Lir	AUTOMO Operating A lers mit Emergency NOT APP Traffic Cont NO Road Grade	As Endorsements Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing		
02	Unit IN T Vehi PAS Tota 2 Insuu YES Most PAF Traff TW0 Surfa BLA	t Summary Status TRANSIT icle Type SSENGER VAN I Occs rance? S t Harmful Event: Collision W RKED MOTOR VEHICL fic Way O-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS	Train/Bus # Recorded Direction Of Travel EASTBOUND Vith E	Vehicle D CLA D CLA O Special NO SP Traffic (NO CC	Operating As Classificatio SS Citations Issued Pre CrashTire Mark Function PECIAL FUNCTION Control DNTROL Furvature	Total Trai 0 Speed Lir	AUTOMO Operating A lers nit Emergency NOT APP Traffic Cont NO	As Endorsements Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing		
02	Unit IN T Vehi PAS Tota 2 Insuu YES Most PAF Traff TW0 Surfa BLA	t Summary Status TRANSIT icle Type SSENGER VAN I Occs rance? Thermful Event: Collision W RKED MOTOR VEHICL fic Way O-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS ik Bus or HazMat	Train/Bus # Recorded Direction Of Travel EASTBOUND Vith E	Vehicle D CLA D CLA O U Special NO SF Traffic C NO CC Road C	Operating As Classificatio SS Citations Issued Pre CrashTire Mark Function PECIAL FUNCTION Control DNTROL Furvature	Total Trai 0 Speed Lir	AUTOMO Operating A lers mit Emergency NOT APP Traffic Cont NO Road Grade	As Endorsements Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing		
02	Unit IN T Vehi PAS Tota 2 Insuu YES Most PAF Traff Two Surfa BLA Truc NO	t Summary Status TRANSIT icle Type SSENGER VAN I Occs rance? S t Harmful Event: Collision V RKED MOTOR VEHICL fic Way O-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS ik Bus or HazMat Vehicle	Train/Bus # Recorded Direction Of Travel EASTBOUND Vith E	Total # 0 Special NO SF Traffic 0 NO CO Road C STRA	Operating As Classificatio ISS Citations Issued Pre CrashTire Mark Function PECIAL FUNCTION Control DNTROL Survature IGHT	Total Trai 0 Speed Lir 15	AUTOMO Operating A lers mit Emergency NOT APP Traffic Cont NO Road Grade LEVEL	As Endorsements Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing		
02	Unit IN T Vehi PAS Tota 2 Insuu YES Most PAF Traff Two Surfa BLA Truc NO	t Summary Status Status RANSIT icle Type SSENGER VAN I Occs rance? S t Harmful Event: Collision W RKED MOTOR VEHICL fic Way O-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS ik Bus or HazMat Vehicle License Plate Number	Train/Bus # Recorded Direction Of Travel EASTBOUND Vith E	Vehicle D CLA D CLA Total # 0 Special NO SP Traffic 0 NO CO Road C STRA	Operating As Classificatio ISS Citations Issued Pre CrashTire Mark Function PECIAL FUNCTION Control DNTROL Survature IGHT	Total Trai 0 Speed Lir 15	AUTOMO Operating A lers mit Emergency NOT APP Traffic Cont NO Road Grade LEVEL	As Endorsements Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing e suance		
UNIT 02	Unit IN T Vehi PAS Tota 2 Insuu YES Most PAF Traff Traff Truc NO	t Summary Status TRANSIT icle Type SSENGER VAN I Occs rance? S t Harmful Event: Collision V RKED MOTOR VEHICL fic Way O-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS ik Bus or HazMat Vehicle	Train/Bus # Recorded Direction Of Travel EASTBOUND Vith E	Vehicle D CLA D CLA Total # 0 Special NO SP Traffic 0 NO CO Road C STRA	Operating As Classificatio ISS Citations Issued Pre CrashTire Mark Function PECIAL FUNCTION Control DNTROL Survature IGHT	Total Trai 0 Speed Lir 15	AUTOMO Operating A lers mit Emergency NOT APP Traffic Cont NO Road Grade LEVEL	As Endorsements Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing e suance		
02	Unit IN T Vehi PAS Tota 2 Insuu YES Most PAF Traff Two Surfa BLA Truc NO	t Summary Status TRANSIT icle Type SSENGER VAN il Occs rance? S t Harmful Event: Collision W RKED MOTOR VEHICL fic Way O-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS k Bus or HazMat Vehicle License Plate Number GD4518	Train/Bus # Recorded Direction Of Travel EASTBOUND Vith E	Vehicle D CLA D CLA O Special NO SF Traffic O NO CO Road C STRAI	Operating As Classificatio ISS Citations Issued Pre CrashTire Mark Function PECIAL FUNCTION Control DNTROL Survature IGHT	Total Trai 0 Speed Lir 15 St	AUTOMO Operating A lers mit Emergency NOT APP Traffic Cont NO Road Grade LEVEL	As Endorsements Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing 3 suance TATES		
UNIT 02	Unit IN T Vehi PAS Tota 2 Insuu YES Most PAF Traff Traff Truc NO	t Summary Status Status TRANSIT icle Type SSENGER VAN I Occs rance? S t Harmful Event: Collision W RKED MOTOR VEHICL fic Way O-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS ik Bus or HazMat Vehicle License Plate Number GD4518 Vehicle Identification Num 2A4RR5D13AR39143 Color	Train/Bus # Recorded Direction Of Travel EASTBOUND Vith E	Vehicle D CLA D CLA D CLA C Special NO SF Traffic C NO CC Road C STRA Plate T LTK - Make CHRY Body S	Operating As Classificatio SS Citations Issued Pre CrashTire Mark Function PECIAL FUNCTION Control DNTROL JUTVATURE IGHT Fype LIGHT TRUCK (SLER Style	Total Trai 0 Speed Lir 15 St WI Year	AUTOMO Operating A lers mit Emergency NOT APP Traffic Cont NO Road Grade LEVEL Country of Is UNITED S Model TOWN AN Bus Use	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing suance TATES D C		
UNIT 02	Unit IN T Vehi PAS Tota 2 Insur YES Most PAF Traff Two Surfa BLA Truc NO	t Summary Status Status TRANSIT icle Type SSENGER VAN I Occs rance? Thermful Event: Collision W RKED MOTOR VEHICL fic Way O-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS is Bus or HazMat Vehicle License Plate Number GD4518 Vehicle Identification Num 2A4RR5D13AR39143 Color BLU - BLUE	Train/Bus # Recorded Direction Of Travel EASTBOUND Vith E	Vehicle D CLA D CLA D CLA Special NO SF Traffic C NO CC Road C STRA Plate T LTK - Make CHRY Body S MV -	Operating As Classificatio SS Citations Issued Pre CrashTire Mark Function PECIAL FUNCTION Control DNTROL JUTVATURE IGHT Fype LIGHT TRUCK (SLER Style MINI VAN	Total Trai 0 Speed Lir 15 St WI Year	AUTOMO Operating A lers mit Emergency NOT APP Traffic Cont NO Road Grade LEVEL Country of Is UNITED S Model TOWN AN	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing suance TATES D C		
02 UNIT 02	Unit IN T Vehi PAS Tota 2 Insur YES Mosi PAF Traff TWO Surfa BLA Truc NO	t Summary Status Status TRANSIT icle Type SSENGER VAN I Occs rance? Thermful Event: Collision W RKED MOTOR VEHICL fic Way O-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS ik Bus or HazMat Vehicle License Plate Number GD4518 Vehicle Identification Num 2A4RR5D13AR39143 Color BLU - BLUE Initial Contact Point	Train/Bus # Recorded Direction Of Travel EASTBOUND Vith E	Vehicle D CLA D CLA D CLA O I Special NO SF Traffic (NO CC Road C STRA STRA Plate I LTK - Make CHR Body S MV -	Operating As Classificatio SS Citations Issued Pre CrashTire Mark Function PECIAL FUNCTION Control DNTROL UVVATURE IGHT Type LIGHT TRUCK (SLER Style MINI VAN e Damage	Total Trai 0 Speed Lir 15 St WI Year 2010	AUTOMO Operating A lers mit Emergency NOT APP Traffic Cont NO Road Grade LEVEL Country of Is UNITED S Model TOWN AN Bus Use NOT A BU	As Endorsements Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing suance TATES D C S		
UNIT 02	Unit IN T Vehi PAS Tota 2 Insur YES Most PAF Traff Two Surfa BLA Truc NO	t Summary Status Status TRANSIT icle Type SSENGER VAN I Occs rance? Thermful Event: Collision W RKED MOTOR VEHICL fic Way O-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS is Bus or HazMat Vehicle License Plate Number GD4518 Vehicle Identification Num 2A4RR5D13AR39143 Color BLU - BLUE	Train/Bus # Recorded Direction Of Travel EASTBOUND Vith E	Vehicle D CLA D CLA D CLA C Special NO SF Traffic (NO CC Road C STRA Vehicle UTK - Make CHR Vehicle Vehicle 1RIC	Operating As Classificatio SS Citations Issued Pre CrashTire Mark Function PECIAL FUNCTION Control DNTROL UVVATURE IGHT Type LIGHT TRUCK (SLER Style MINI VAN e Damage	Total Trai 0 Speed Lir 15 St WI Year 2010	AUTOMO Operating A lers mit Emergency NOT APP Traffic Cont NO Road Grade LEVEL Country of Is UNITED S Model TOWN AN Bus Use NOT A BU	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing suance TATES D C		

19-00947

WISCONSIN MOTOR VEHICLE CRASH REPORT

		Towed Due To Damage			icle Removed By			
		NOT TOWED			ERATOR			
		What Driver Was Doing		Vehicle Factors				
	GOING STRAIGHT Driver Prior Action Other			NOT APPLICABLE				
		Driver Prior Action Other						
		Driver Actions						
	щ	NO CONTRIBUTING ACTION						
UNIT	ICL							
5	VEHICL							
	2							
		Owner Name			Owner Address			
	•	ROYAL E HENSCHEL			130 MORAINE DR			
03	02	(920) 876-3807			ELKHART LAKE, WI 53020 , US			
	ļ	Sequence Of Events						
	01	Event PARKED MOTOR VEHIC	LE					
		Event						
	02	Lvent						
	8	Event						
	03							
	04	Event						
				_				
E	ļ	Policy Holder		-				
UNIT		Insurance Company	` 0		ndividual			
		WILSON-MUTUAL-INS-CO ROYAL HENSCHEL						
		Individual Driver			Citations Issued Sex			
		ROYAL E HENSCHEL		Ċ		MALE		
	IAI	(920) 876-3807			Date of Birth	Race		
E	INDIVIDUAL					WHITE		
		Address 130 MORAINE DR		0	Driver License Number			
	IN	ELKHART LAKE, WI 530)20 , US	STATE: WISCONSIN COUNTRY: UNITED STATES				
		On Duty Crash			Safety Equipment			
	Sat	fety Equipment						
		Seat Position			SHOULDER & LAP BELT			
		1FRONT SEAT-LEFT SIDE (DRIVER/MOTORCY						
		Helmet Use		Helmet Compliance				
		Eye Protection		Tint Compliance				
02	001	les le com a						
	0	Ejected	PPARENT INJURY Ejection Path	r	NON DEPLOYED	Trapped/Extricated		
		NOT EJECTED	NOT EJECTED/NOT APP			NOT TRAPPED		
		Medical Transport			MS Agency Identifier	EMS Run #		
		NOT TRANSPORTED						
		Hospital			Date of Death	Time of Death		
		Distrog	ted By Source					
		Distracted By UNKN	IOWN					
		Distracted By Action						
		OTHER ACTION (LOOKI	NG AWAY FROM TASK ET	TC)				

19-00947

WISCONSIN MOTOR VEHICLE CRASH REPORT

		Non Motorist	ng Unit #	Location						
		Prior Action		1						
		Action								
	Ļ									
Ŀ	INDIVIDUAL									
UNIT	IVI									
	Z									
		Action Other						To/From School		
		Drug & Alcohol NO	ected Alcohol L	Jse	Suspected Drug Use					
	-	Alcohol Test Given		Alcohol Test Type	-		Alcohol Test Results			
		TEST NOT GIVEN								
		Drug Test Given TEST NOT GIVEN		Drug Test Type		Drug Test Results				
02	001	Drug Type								
	0									
		Individual Condition								
		APPEARED NORMAL								
	I	Individual								
	_	Passenger JOANN L HENSCHEL (920) 876-3807			Citations Issued Sex 0 FEMALE		Sex FEMALE			
	INDIVIDUAL				Date of Birth Race WHITE					
UNIT	IVI	Address			Driver License Number					
-	Z	130 MORAINE DR ELKHART LAKE, WI 53	8020 , US		STATE: WISCONSIN COUNTRY: UNITED STATES					
	Safety Equipment			Safety Equipment						
		Seat Position			SHOULDER & LAP BELT					
		3FRONT SEAT-RIGHT SIDE (TRAIN ENGINEER Helmet Use			Helmet Compliance					
		Eye Protection			Tint Compliance					
03	002		Severity APPARENT I	NJURY	Airbag NON DEPLOYED					
l		Ejected NOT EJECTED	Ejection Pa				Trapped/Extricated			
		Medical Transport	NOTEJE	CTED/NOT APPI	EMS Agency Identifier		NOT TRAPPED EMS Run #			
		NOT TRANSPORTED Hospital					Time of Death			
					Date of Death					
		Distracted By	acted By Sourc	9						
		Distracted By Action								
I		Non Motorist	ng Unit #	Location						
					t doop not include on CIII	0 data	Oresh Date	01/22/2010		

19-00947

WISCONSIN MOTOR VEHICLE CRASH REPORT

		Prior Action						
		Action						
		Action						
	_							
	٩ſ							
UNIT	D							
5	N							
	INDIVIDUAL							
	-							
		Action Other						To/From School
	,	Drug & Alcohol	Suspected Alcohol Us	se	Suspected Drug Use			
	-	_			NO		•	
		Alcohol Test Given		Alcohol Test Type			Alcohol Test Results	
		TEST NOT GIVEN						
		Drug Test Given TEST NOT GIVEN		Drug Test Type		Drug Test Results	i	
	2	Drug Type						
02	002	Diug Type						
	•							
		Individual Condition						
			MAL					