WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Document Number Override	Primary Crash Document #	Agency Crash Number 19-01345	Investigating DEPUTY B	Officer/Deputy LUBER	
Crash Date 02/02/2019	Crash Time 07:05 AM	Date Arrived 02/02/2019	Time Arrived 07:20 AM		
Crash Date 02/02/2019 Date Notified 02/02/2019 On Emergency Government Property	Time Notified 07:06 AM	Total Units 01	Total Injured 01	Total Kille	d
On Emergency	Hit and Run Lane C	Closure Work Zone	Trailer	or Towed	Reporting Threshold
Government Property	Active School Zone	School Bus Related NO	Tags		
▼ Reportable	Crash Type DT4000 (STANDARD CR	ASH)	Amendo	ed	Secondary Crash
Description ——	•				
Diagram				Reconstruction Photos By	
				Additional Infor NONE	mation
		CTH H 	_		
01					
		NOT TO	SCALE		
, a sworn law enforcen	nent officer, agree that I hav	ve not added any CJIS data in	this report.		
STRUCK A UTILITY POLE. OPI THE TIME OF THE CRASH THE	ERATOR ADMITTED LOOSING C ERE WAS A SNOW/SLEET AND	ATING TOO FAST FOR THE CONI CONTROL OF THE VEHICLE, STRI THE ROADWAY WAS ICE AND SN Y DELLS DELTON EMS, HOWEVE	KING THE POLE, AN NOW COVERED. OP	ND COMING TO ERATOR OF U	O REST ON ITS SIDE. AT NIT 1 WAS GIVEN A

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 02/02/2019

Crash Time 07:05 AM

L	ocatio	on 📉								
C	ON CTHH EB					Latitude		Longitude		
	732 FT E				43.617743152		-89.860840705			
_	OF CHRISTMAS MOUNTAIN RD IN THE TOWN OF DELLONA				X Coordinate		Y Coordinat	te		
	IN SAUK COUNTY				269162.40625 4833395					
					Structure Type					
C	rash	Scene								
F	irst Harn	nful Event				First Harm	ıful Event l	_ocation		
ι	UTILITY POLE				OUTSID	E RIGHT	-OF-WAY (TI	RAFFICWAY	")	
N	Manner of Collision				OUTSIDE RIGHT-OF-WAY (TRAFFICWAY) Light Condition					
N	NO COLLISION W/VEHICLE IN TRANSPORT				DAYLIG	НТ				
R	Road Surface Condition(s)				Roadway	Factor(s)				
s	SLUSH Environment Factor(s)									
Е						BOADS	LIDEACE	CONDITION	WET ICY	CNOW CLUCH
١	IONE					ETC)	UKFACE	CONDITION	I (WEI, ICY,	SNOW, SLUSH,
٧	Veather (Condition(s)				1				
S	SLEET/H	HAIL								
Α	Animal Type					Relation To Trafficway				
								ON ROAD		
_		assification - Location	1					- Jurisdiction		
	PUBLIC PROPERTY				NO SPECIAL JURISDICTION					
ľ	Tribal Land				Access Control Special Study NO CONTROL					
٧	Within Interchange Area Junction Location Intersection			ion Type N INTERSECTION						
IN										
			HON CONCINCIA		NOT AN	INTERSE	CTION			
_		ummary =	NON CONCINCIA		NOT AN	INTERSE	CTION			
U		ummary =	Non concinent	Vehicle Ope				Unit Type		
U	nit Sı	ıs	inon concinen	Vehicle Ope				Unit Type AUTOMO	BILE	
U	nit Su Init Statu N TRAN 'ehicle Ty	us NSIT ype	indication in the second in th	· ·				AUTOMO	BILE s Endorsemen	nts
U III	nit Su Init Statu N TRAN PASSEN	NSIT Vype NGER CAR		D CLASS	erating As C	Classification		AUTOMO Operating A	s Endorsemen	
U III	nit Su Init Statu N TRAN Vehicle Ty PASSEN Total Occ	NSIT Vype NGER CAR	Train/Bus # Recorded	· ·	erating As C	Classification		AUTOMO Operating A		
U III V F T 1	nit Su Init Statu N TRAN Vehicle Ty PASSEN Total Occ	us NSIT ype NGER CAR		D CLASS Total # Cita 2	erating As C	Classification	Total Tra	AUTOMO Operating A	s Endorsemen Total HazMat	
U III V F T 1	nit Su Init Statu N TRAN 'ehicle Ty 'PASSEN Total Occ	us NSIT ype NGER CAR	Train/Bus # Recorded	D CLASS Total # Cita 2	erating As C	Classification	Total Tra	AUTOMO Operating A	s Endorsemen Total HazMat 0	
U III V F T 1	nit Sudnit Statu N TRAN Yehicle Ty PASSEN Total Occursurance YES	us NSIT ype NGER CAR	Train/Bus # Recorded Direction Of Travel EASTBOUND	Total # Cita 2 Pre Special Fun	tions Issued CrashTire Mark	Classification	Total Tra 0 Speed Li	AUTOMO Operating A illers mit Emergency	Total HazMat Total Lanes Motor Vehicle	t Types
U III V F T 1 Ir W	nit Sudnit Statu N TRAN Yehicle Ty PASSEN Total Occursurance YES	NSIT yype NGER CAR es	Train/Bus # Recorded Direction Of Travel EASTBOUND	Total # Cita 2	tions Issued CrashTire Mark	Classification	Total Tra 0 Speed Li	AUTOMO Operating A illers mit Emergency NOT APP	Total HazMat 0 Total Lanes 2 Motor Vehicle	t Types
U III V P T 1 III V N U T	nit Sunit Statu N TRAN Vehicle Ty PASSEN Total Occursurance VES Most Harry VTILITY	NSIT ype NGER CAR es er mful Event: Collision Y POLE ay	Train/Bus # Recorded Direction Of Travel EASTBOUND With	Total # Cita 2 Pre Special Fun NO SPEC Traffic Cont	tions Issued CrashTire Mark action EIAL FUNC	Classification	Total Tra 0 Speed Li	AUTOMO Operating A illers mit Emergency NOT APP Traffic Cont	Total HazMat Total Lanes Motor Vehicle	t Types
	nit Sunit Statu N TRAN Vehicle Ty PASSEN Total Occursurance YES Most Harry JTILITY Traffic Wa	IS NSIT Type NGER CAR TS THE T	Train/Bus # Recorded Direction Of Travel EASTBOUND With	Total # Citar 2 Pre Special Fun NO SPEC Traffic Cont NO CONT	crating As Continued and Conti	Classification	Total Tra 0 Speed Li	AUTOMO Operating A iilers mit Emergency NOT APP Traffic Cont NO	Total HazMat 0 Total Lanes 2 Motor Vehicle LICABLE rol Inoperative/	t Types
U III V P T 1 III Y N L T T S	nit Sunit Statu N TRAN Yehicle Ty PASSEN Total Occ Insurance YES Most Harr JTILITY Traffic Wa WO-WA Surface T	IS NSIT Type NGER CAR SS OF THE STATE OF THE	Train/Bus # Recorded Direction Of Travel EASTBOUND With	D CLASS Total # Citat 2 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva	crating As Continued and Conti	Classification	Total Tra 0 Speed Li	AUTOMO Operating A illers mit Emergency NOT APP Traffic Cont NO Road Grade	Total HazMat 0 Total Lanes 2 Motor Vehicle LICABLE rol Inoperative/	t Types
	nit Sunit Statu N TRAN Yehicle Ty PASSEN Otal Occ Insurance YES Most Harr JTILITY Traffic Wa WO-WA Surface T BLACKT	IS NSIT Type NGER CAR SS OFF OFF OFF OFF OFF OFF OFF OFF OFF	Train/Bus # Recorded Direction Of Travel EASTBOUND With	Total # Citar 2 Pre Special Fun NO SPEC Traffic Cont NO CONT	crating As Continued and Conti	Classification	Total Tra 0 Speed Li	AUTOMO Operating A iilers mit Emergency NOT APP Traffic Cont NO	Total HazMat 0 Total Lanes 2 Motor Vehicle LICABLE rol Inoperative/	t Types
U III V F T T S E	nit Sunit Statu N TRAN Yehicle Ty PASSEN Otal Occ Insurance YES Most Harr JTILITY Traffic Wa WO-WA Surface T BLACKT	IS NSIT Type NGER CAR SS OF THE STATE OF THE	Train/Bus # Recorded Direction Of Travel EASTBOUND With	D CLASS Total # Citat 2 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva	crating As Continued and Conti	Classification	Total Tra 0 Speed Li	AUTOMO Operating A illers mit Emergency NOT APP Traffic Cont NO Road Grade	Total HazMat 0 Total Lanes 2 Motor Vehicle LICABLE rol Inoperative/	t Types
	nit Sunit Statu N TRAN Vehicle Ty PASSEN Otal Occ Insurance VES Most Harr JTILITY Traffic Wa WO-W/ Surface T BLACKT Truck Bus IO	IS NSIT Type NGER CAR SS OFF OFF OFF OFF OFF OFF OFF OFF OFF	Train/Bus # Recorded Direction Of Travel EASTBOUND With	D CLASS Total # Citat 2 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva	crating As Continued and Conti	Classification	Total Tra 0 Speed Li	AUTOMO Operating A illers mit Emergency NOT APP Traffic Cont NO Road Grade LEVEL	Total HazMat 0 Total Lanes 2 Motor Vehicle LICABLE rol Inoperative/	t Types
U II V F T 1 II Y N L T T S E T	nit Sunit Statu N TRAN Vehicle Ty PASSEN Total Occ Insurance VES Most Harr VILLITY Traffic Wa WO-WA Surface T BLACKT Truck Bus NO Veh	IS NSIT Type NGER CAR SS OFF Inful Event: Collision Y POLE TOP (BITUMINOUS OF HAZMAT) NICLE ENSE Plate Number	Train/Bus # Recorded Direction Of Travel EASTBOUND With	D CLASS Total # Citat 2 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva STRAIGH	crating As C CrashTire Mark ICTION CIAL FUNC TO TO TO TO TO TO TO TO TO T	CTION	Total Tra 0 Speed Li 55	AUTOMO Operating A illers mit Emergency NOT APP Traffic Cont NO Road Grade LEVEL Country of Is	Total HazMat 0 Total Lanes 2 Motor Vehicle LICABLE rol Inoperative/	t Types
	nit Sunit Statu N TRAN Vehicle Ty PASSEN Total Occ Insurance VES Most Harr JTILITY Traffic Wa WO-WA Surface T BLACKT Truck Bus NO Veh Lice AC	IS NSIT Type NGER CAR TS THE STATE OF THE ST	Train/Bus # Recorded Direction Of Travel EASTBOUND With	Total # Citar 2 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva STRAIGH	crashTire Mark action EIAL FUNC TROL ature T	CTION	Total Tra 0 Speed Li 55	AUTOMO Operating A illers mit Emergency NOT APP Traffic Cont NO Road Grade LEVEL Country of Is UNITED S	Total HazMat 0 Total Lanes 2 Motor Vehicle LICABLE rol Inoperative/	t Types
	nit Sunit Statu N TRAN Vehicle Ty ASSEN Otal Occ	IS NSIT Type NGER CAR TS ST THE TOP (BITUMINOUS OF TAZMAT NICLE TEST OF LATE OF TAZMAT NICLE CONTROL OF TAZMAT NICLE C	Train/Bus # Recorded Direction Of Travel EASTBOUND With Direction Of Travel With Direction Of Travel EASTBOUND	Total # Cita 2 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva STRAIGH Plate Type AUT - AU Make	crating As Continued and Conti	CTION	Total Tra 0 Speed Li 55	AUTOMO Operating A illers mit Emergency NOT APP Traffic Cont NO Road Grade LEVEL Country of Is UNITED ST Model	Total HazMat Total Lanes Z Motor Vehicle LICABLE rol Inoperative/	t Types
U III V F T 1 III Y N U T T S E T N	nit Statu N TRAN Vehicle Ty PASSEN Total Occ Insurance VES Most Harm JTILITY Traffic Wa WO-WA Surface T BLACKT Truck Bus IO Veh Lice AC Veh 2T1	IS NSIT Type NGER CAR SS PRICE POLE TOP (BITUMINOUS OF HAZMAT NICLE PERSE Plate Number FE5674 Inicle Identification Num 1BR32E44C26070	Train/Bus # Recorded Direction Of Travel EASTBOUND With Direction Of Travel With Direction Of Travel EASTBOUND	Total # Cita 2 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva STRAIGH Plate Type AUT - AU Make TOYOTA	crating As Continued and Conti	CTION	Total Tra 0 Speed Li 55	AUTOMO Operating A illers mit Emergency NOT APP Traffic Cont NO Road Grade LEVEL Country of Is UNITED ST Model COROLLA	Total HazMat Total Lanes Z Motor Vehicle LICABLE rol Inoperative/	t Types
U III V F T 1 III Y N U T T S E T N	nit Statu N TRAN Vehicle Ty PASSEN Total Occ Insurance VES Most Harm JTILITY Traffic Wa WO-WA Surface T BLACKT Truck Bus IO Veh Lice AC Veh 2T1 Colo	IS NSIT Type NGER CAR SS PRICE POLE TOP (BITUMINOUS OF HAZMAT NICLE PERSE Plate Number FE5674 Inicle Identification Num 1BR32E44C26070	Train/Bus # Recorded Direction Of Travel EASTBOUND With Discontinuous process of the second process of the	Total # Cita 2 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva STRAIGH Plate Type AUT - AU Make	tions Issued CrashTire Mark action EIAL FUNC TOI	CTION	Total Tra 0 Speed Li 55	AUTOMO Operating A illers mit Emergency NOT APP Traffic Cont NO Road Grade LEVEL Country of Is UNITED ST Model	Total HazMat 0 Total Lanes 2 Motor Vehicle LICABLE rol Inoperative/	t Types
U III V F T 1 III Y Y N U T T S E T N	nit Sunit Statu N TRAN Vehicle Ty PASSEN Total Occ Insurance VES Most Harr JTILITY Traffic Wa WO-WA Surface T BLACKT Truck Bus NO Veh Lice AC Veh 2T1 Cold SIL Initia	IS NSIT Type NGER CAR SS PROSE	Train/Bus # Recorded Direction Of Travel EASTBOUND With Discontinuous process of the second process of the	Total # Cita 2 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva STRAIGH Plate Type AUT - AU Make TOYOTA Body Style	tions Issued CrashTire Mark action EIAL FUNC TO	CTION	Total Tra 0 Speed Li 55	AUTOMO Operating A illers mit Emergency NOT APP Traffic Cont NO Road Grade LEVEL Country of Is UNITED ST Model COROLLA Bus Use	Total HazMat 0 Total Lanes 2 Motor Vehicle LICABLE rol Inoperative/	t Types
U III V P P T 1 III III S E T N	nit Sunit Statu N TRAN Vehicle Ty PASSEN Total Occ Insurance VES Most Harr JTILITY Traffic Wa WO-WA Surface T BLACKT Truck Bus NO Veh Lice AC Veh 2T1 Cold SIL Initia	IS NSIT Type NGER CAR SS PROSE	Train/Bus # Recorded Direction Of Travel EASTBOUND With Discontinuous process of the second process of the	Total # Citar 2 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva STRAIGH Plate Type AUT - AU Make TOYOTA Body Style SD - SED Vehicle Da	tions Issued CrashTire Mark Inction IROL ITOMOBIL	Classification	St WI Year 2004	AUTOMO Operating A illers mit Emergency NOT APP Traffic Cont NO Road Grade LEVEL Country of Is UNITED S' Model COROLLA Bus Use NOT A BU	Total HazMat 0 Total Lanes 2 Motor Vehicle LICABLE rol Inoperative/	Use //Missing
U III V FF T 1 1 III Y Y N U T T T N N U T T N N N N N N N N N N	nit Sunit Statu N TRAN Vehicle Ty PASSEN Total Occ Total	IS NSIT Type NGER CAR SS PROSE	Train/Bus # Recorded Direction Of Travel EASTBOUND With Direction Of Travel EASTBOUND With Direction Of Travel EASTBOUND With	Total # Citar 2 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva STRAIGH Plate Type AUT - AU Make TOYOTA Body Style SD - SED Vehicle Da	tions Issued CrashTire Mark Inction IROL ITOMOBIL	Classification	St WI Year 2004	AUTOMO Operating A illers mit Emergency NOT APP Traffic Cont NO Road Grade LEVEL Country of Is UNITED ST Model COROLLA Bus Use	Total HazMat 0 Total Lanes 2 Motor Vehicle LICABLE rol Inoperative/	Use //Missing

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 02/02/2019

Crash Time 07:05 AM

		Towed Due To Damage	Vehicle Removed By				
		TOWED DUE TO DISABLING DAMAGE	PLATTS WRECKER				
		What Driver Was Doing	Vehicle Factors				
		GOING STRAIGHT	NOT ARRIVE				
		Driver Prior Action Other	NOT APPLICABLE				
		Driver Actions					
	111	SPEED TOO FAST/COND, FAILURE TO CONTRO	DL				
⊢	ĭ						
LIND	¥						
⊃	VEHICLE						
	>						
		Owner Name	Owner Address				
_		JOSHUA A AULET	1125 17TH #8				
0	01	(608) 448-7326	REEDSBURG, WI 53959 ,	US			
		Sequence Of Events					
	01	Event Provide Republication of the Control of the C					
	0	RUN OFF ROADWAY RIGHT					
	02	Event UTILITY POLE					
	0						
	03	Event					
		Event					
	04	Event					
		Policy Holder					
LIND		Insurance Company	Individual				
5		GEICO-ADVANTAGE-INSURANCE-CO	JOSHUA AULET				
		ndividual					
		Driver	Citations Issued	Sex			
		JOSHUA A AULET	2	MALE			
	AL	(608) 448-7326	Date of Birth	Race			
l <u>⊢</u> ∣	DO			HISPANIC			
7							
_	Σ	Address	Driver License Number	•			
LINO	NDIVI	1125 17TH #8		TRV. HAITED STATES			
5	INDIVIDUAL		Driver License Number STATE: WISCONSIN COUN	TRY: UNITED STATES			
5	INDIN	1125 17TH #8 REEDSBURG, WI 53959 , US	STATE: WISCONSIN COUNT	TRY: UNITED STATES			
5		1125 17TH #8 REEDSBURG, WI 53959 , US On Duty Crash		TRY: UNITED STATES			
ī n		1125 17TH #8 REEDSBURG, WI 53959 , US On Duty Crash	STATE: WISCONSIN COUNTS	TRY: UNITED STATES			
ī		1125 17TH #8 REEDSBURG, WI 53959 , US On Duty Crash Seat Position	STATE: WISCONSIN COUNTS Safety Equipment SHOULDER & LAP BELT	TRY: UNITED STATES			
In .		1125 17TH #8 REEDSBURG, WI 53959 , US Tety Equipment Seat Position 1FRONT SEAT-LEFT SIDE (DRIVER/MOTORCY	STATE: WISCONSIN COUNT Safety Equipment SHOULDER & LAP BELT	TRY: UNITED STATES			
In		1125 17TH #8 REEDSBURG, WI 53959 , US On Duty Crash Seat Position	STATE: WISCONSIN COUNTS Safety Equipment SHOULDER & LAP BELT	TRY: UNITED STATES			
IN .		1125 17TH #8 REEDSBURG, WI 53959 , US Tety Equipment Seat Position 1FRONT SEAT-LEFT SIDE (DRIVER/MOTORCY	STATE: WISCONSIN COUNT Safety Equipment SHOULDER & LAP BELT	TRY: UNITED STATES			
In .		1125 17TH #8 REEDSBURG, WI 53959 , US On Duty Crash Seat Position 1FRONT SEAT-LEFT SIDE (DRIVER/MOTORCY Helmet Use	STATE: WISCONSIN COUNTY Safety Equipment SHOULDER & LAP BELT Helmet Compliance	TRY: UNITED STATES			
	Sat	T125 17TH #8 REEDSBURG, WI 53959 , US On Duty Crash Seat Position 1FRONT SEAT-LEFT SIDE (DRIVER/MOTORCY Helmet Use Eye Protection Injury Severity	STATE: WISCONSIN COUNT Safety Equipment SHOULDER & LAP BELT Helmet Compliance Tint Compliance Airbag	TRY: UNITED STATES			
U UI		Table 1125 17TH #8 REEDSBURG, WI 53959 , US On Duty Crash Seat Position 1FRONT SEAT-LEFT SIDE (DRIVER/MOTORCY Helmet Use Eye Protection Injury Injury Severity SUSPECTED MINOR INJURY	STATE: WISCONSIN COUNT Safety Equipment SHOULDER & LAP BELT Helmet Compliance Tint Compliance				
	Sat	T125 17TH #8 REEDSBURG, WI 53959 , US On Duty Crash Seat Position 1FRONT SEAT-LEFT SIDE (DRIVER/MOTORCY Helmet Use Eye Protection Injury Injury Severity SUSPECTED MINOR INJURY Ejected Ejection Path	STATE: WISCONSIN COUNT Safety Equipment SHOULDER & LAP BELT Helmet Compliance Tint Compliance Airbag NON DEPLOYED	Trapped/Extricated			
	Sat	T125 17TH #8 REEDSBURG, WI 53959 , US On Duty Crash Seat Position 1FRONT SEAT-LEFT SIDE (DRIVER/MOTORCY Helmet Use Eye Protection Injury Severity SUSPECTED MINOR INJURY Ejected NOT EJECTED NOT EJECTED/NOT A	STATE: WISCONSIN COUNT Safety Equipment SHOULDER & LAP BELT Helmet Compliance Tint Compliance Airbag NON DEPLOYED PPLICABLE	Trapped/Extricated TRAPPED/EXTRICATED			
	Sat	Table 1125 17TH #8 REEDSBURG, WI 53959 , US Tety Equipment Seat Position 1FRONT SEAT-LEFT SIDE (DRIVER/MOTORCY) Helmet Use Eye Protection Injury Severity SUSPECTED MINOR INJURY Ejected NOT EJECTED Medical Transport	STATE: WISCONSIN COUNT Safety Equipment SHOULDER & LAP BELT Helmet Compliance Tint Compliance Airbag NON DEPLOYED	Trapped/Extricated			
	Sat	Table 1125 17TH #8 REEDSBURG, WI 53959 , US Tety Equipment Seat Position 1FRONT SEAT-LEFT SIDE (DRIVER/MOTORCY) Helmet Use Eye Protection Injury Suspected MINOR INJURY Ejected Ejection Path NOT EJECTED NOT A Medical Transport NOT TRANSPORTED	STATE: WISCONSIN COUNT Safety Equipment SHOULDER & LAP BELT Helmet Compliance Tint Compliance Airbag NON DEPLOYED PPLICABLE EMS Agency Identifier	Trapped/Extricated TRAPPED/EXTRICATED EMS Run #			
	Sat	Table 1125 17TH #8 REEDSBURG, WI 53959 , US Tety Equipment Seat Position 1FRONT SEAT-LEFT SIDE (DRIVER/MOTORCY) Helmet Use Eye Protection Injury Severity SUSPECTED MINOR INJURY Ejected NOT EJECTED Medical Transport	STATE: WISCONSIN COUNT Safety Equipment SHOULDER & LAP BELT Helmet Compliance Tint Compliance Airbag NON DEPLOYED PPLICABLE	Trapped/Extricated TRAPPED/EXTRICATED			
	Sat	TI25 17TH #8 REEDSBURG, WI 53959 , US Tety Equipment Seat Position 1FRONT SEAT-LEFT SIDE (DRIVER/MOTORCY) Helmet Use Eye Protection Injury Suspected MINOR INJURY Ejected Ejection Path NOT EJECTED NOT A Medical Transport NOT TRANSPORTED Hospital Distracted By Source	STATE: WISCONSIN COUNT Safety Equipment SHOULDER & LAP BELT Helmet Compliance Tint Compliance Airbag NON DEPLOYED PPLICABLE EMS Agency Identifier	Trapped/Extricated TRAPPED/EXTRICATED EMS Run #			
	Sat	TI125 17TH #8 REEDSBURG, WI 53959 , US Tety Equipment Seat Position 1FRONT SEAT-LEFT SIDE (DRIVER/MOTORCY) Helmet Use Eye Protection Injury Suspected MINOR INJURY Ejected NOT EJECTED NOT EJECTED/NOT A Medical Transport NOT TRANSPORTED Hospital	STATE: WISCONSIN COUNT Safety Equipment SHOULDER & LAP BELT Helmet Compliance Tint Compliance Airbag NON DEPLOYED PPLICABLE EMS Agency Identifier	Trapped/Extricated TRAPPED/EXTRICATED EMS Run #			
	Sat	TI25 17TH #8 REEDSBURG, WI 53959 , US Tety Equipment Seat Position 1FRONT SEAT-LEFT SIDE (DRIVER/MOTORCY) Helmet Use Eye Protection Injury Suspected MINOR INJURY Ejected Ejection Path NOT EJECTED NOT A Medical Transport NOT TRANSPORTED Hospital Distracted By Source	STATE: WISCONSIN COUNT Safety Equipment SHOULDER & LAP BELT Helmet Compliance Tint Compliance Airbag NON DEPLOYED PPLICABLE EMS Agency Identifier	Trapped/Extricated TRAPPED/EXTRICATED EMS Run #			

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

		Non Motori	Striking Unit #	Location				
		Prior Action						
		Action						
	4							
⊨	2							
	Ē							
	INDIVIDUAL							
		Action Other						To/From School
	1	Drug & Alcoh	Suspected Alco	hol Use	Suspected Drug Use NO			
		Alcohol Test Giver		Alcohol Test Typ	De .		Alcohol Test Results	
		TEST NOT GIVE	EN			Drug Test Results		
		Drug Test Given TEST NOT GIVE	rug Test Given EST NOT GIVEN		Drug Test Type		S .	
2	001	Drug Type		•				
		Individual Conditio	n					
		APPEARED NO	RMAL					
	,	Violations	_					
	5	UTC Number AE139824	Issue To? 001	Statute Number 346.57(2)	Description FAILURE TO KEEP	VEHICLE UNDE	R CONTROL	
	02	UTC Number AE139825	Issue To? 001	Statute Number 343.07(1g)(a)1	Description OPERATE MOTOR	VEHICLE BY PE	RMITTEE W/O INST	RUCTOR
ı	Pro	perty Owne		I.				
01	Orga	nization/Company			Address 4902 N BILTMORE			
	(800)) 255-4268			MADISON, WI 53707	1077, US		
PROP OWNER								
	Fixe	ed Objects St	ruck					
	5	3 - 1	Struck Object				Structure Number	Damage Tag Number
	0	01	UTILITY POLE					