

WISCONSIN MOTOR VEHICLE
CRASH REPORT

Location

ON CLARA AVE 0.51 MI N OF PILGRIM DR IN THE TOWN OF DELTON IN SAUK COUNTY	Latitude 43.611720965	Longitude -89.798746938
	X Coordinate 274150.3125	Y Coordinate 4832555.5
	Structure Type	

Crash Scene

First Harmful Event DITCH	First Harmful Event Location OUTSIDE RIGHT-OF-WAY (TRAFFICWAY)	
Manner of Collision NO COLLISION W/VEHICLE IN TRANSPORT	Light Condition DAYLIGHT	
Road Surface Condition(s) SLUSH	Roadway Factor(s) ROAD SURFACE CONDITION (WET, ICY, SNOW, SLUSH, ETC)	
Environment Factor(s) NONE		
Weather Condition(s) CLOUDY		
Animal Type	Relation To Trafficway TRAFFICWAY - ON ROAD	
Crash Classification - Location PUBLIC PROPERTY	Crash Classification - Jurisdiction NO SPECIAL JURISDICTION	
Tribal Land	Access Control NO CONTROL	Special Study
Within Interchange Area NO	Junction Location NON-JUNCTION	Intersection Type NOT AN INTERSECTION

Unit Summary

UNIT	Unit Status IN TRANSIT	Vehicle Operating As Classification D CLASS		Unit Type AUTOMOBILE	
	Vehicle Type PASSENGER CAR	Operating As Endorsements			
	Total Occs 1	Train/Bus # Recorded	Total # Citations Issued 0	Total Trailers 0	Total HazMat Types
	Insurance? UNKNOWN	Direction Of Travel NORTHBOUND	<input type="checkbox"/> Pre Crash Tire Mark	Speed Limit 35	Total Lanes 2
	Most Harmful Event: Collision With DITCH	Special Function NO SPECIAL FUNCTION		Emergency Motor Vehicle Use NOT APPLICABLE	
	Traffic Way TWO-WAY, NOT DIVIDED	Traffic Control NO CONTROL		Traffic Control Inoperative/Missing NO	
	Surface Type BLACKTOP (BITUMINOUS)	Road Curvature STRAIGHT		Road Grade DOWNHILL	
	Truck Bus or HazMat NO				

UNIT	Vehicle				
	01	License Plate Number DRN2408	Plate Type AUT - AUTOMOBILE	St MI	Country of Issuance UNITED STATES
		Vehicle Identification Number 1LNHM97V21Y682357	Make LINCOLN	Year 2001	Model CONTINENTA
	VEHICLE	Color WHI - WHITE	Body Style 4D - 4DR		Bus Use NOT A BUS
		Initial Contact Point NON-COLLISION	Vehicle Damage		
		Extent Of Damage NO DAMAGE	NO DAMAGE		

WISCONSIN MOTOR VEHICLE CRASH REPORT

UNIT VEHICLE	Towed Due To Damage TOWED BUT NOT DUE TO DISABLING DAMAG		Vehicle Removed By PLATTS WRECKER	
	What Driver Was Doing GOING STRAIGHT		Vehicle Factors	
	Driver Prior Action Other		NOT APPLICABLE	
	Driver Actions SPEED TOO FAST/COND			
01	01	Owner Name BOONSANER CHIRANAN (702) 894-5141		Owner Address 161 PILGRIM DRIVE WISCONSIN DELLS, WI 53965 , US
Sequence Of Events				
01	01	Event RUN OFF ROADWAY RIGHT		
02	02	Event DITCH		
03	03	Event		
04	04	Event		
Individual				
UNIT INDIVIDUAL	Driver BOONSANER CHIRANAN (702) 894-5141		Citations Issued 0	Sex FEMALE
	Address 161 PILGRIM DRIVE WISCONSIN DELLS, WI 53965 , US		Date of Birth	Race ASIAN
			Driver License Number COUNTRY: THAILAND	
Safety Equipment				
On Duty Crash		Safety Equipment		
Seat Position 1--FRONT SEAT-LEFT SIDE (DRIVER/MOTORCY		SHOULDER & LAP BELT		
Helmet Use		Helmet Compliance		
Eye Protection		Tint Compliance		
01	001	Injury	Injury Severity NO APPARENT INJURY	Airbag NON DEPLOYED
Ejected NOT EJECTED		Ejection Path NOT EJECTED/NOT APPLICABLE		Trapped/Extricated NOT TRAPPED
Medical Transport NOT TRANSPORTED		EMS Agency Identifier		EMS Run #
Hospital		Date of Death		Time of Death
Distracted By				
Distracted By Source				
Distracted By Action UNKNOWN				
Non Motorist				
Striking Unit #		Location		

WISCONSIN MOTOR VEHICLE
CRASH REPORT

UNIT	Prior Action			
	Action			
	Action Other		To/From School	
	Drug & Alcohol	Suspected Alcohol Use NO	Suspected Drug Use NO	
	Alcohol Test Given TEST NOT GIVEN	Alcohol Test Type	Alcohol Test Results	
	Drug Test Given TEST NOT GIVEN	Drug Test Type	Drug Test Results	
	Drug Type			
	Individual Condition APPEARED NORMAL			
	01	001		