

6TL09H5JPB

19-01798

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMENT
1300 LANGE COURT
BARABOO, WI 53913
(608) 356-4895

6TL09H5JPB

Document Number Override		Primary Crash Document #	Agency Crash Number 19-01798	Investigating Officer/Deputy DEPUTY S. MESSNER	
Crash Date 02/13/2019		Crash Time 12:40 PM	Date Arrived 02/13/2019	Time Arrived 01:05 PM	
Date Notified 02/13/2019		Time Notified 12:58 PM	Total Units 01	Total Injured 00	Total Killed 00
<input type="checkbox"/> On Emergency	<input type="checkbox"/> Hit and Run	<input type="checkbox"/> Lane Closure	<input type="checkbox"/> Work Zone	<input type="checkbox"/> Trailer or Towed	<input type="checkbox"/> Reporting Threshold
<input type="checkbox"/> Government Property	<input type="checkbox"/> Active School Zone	School Bus Related NO		Tags	
<input checked="" type="checkbox"/> Reportable		Crash Type DT4000 (STANDARD CRASH)		<input type="checkbox"/> Amended	<input type="checkbox"/> Secondary Crash

Description

<p>Diagram</p> <p>Snow filler ditch</p> <p>Barb-wire fence</p> <p>CTH A</p> <p>Nit to Scale</p> <p>Slush on the shoulder of the roadway</p> <p>CTH A north of Shady Lane Road</p>	Reconstruction By
	Photos By DEP. S. MESSNER
	Additional Information PHOTOS

I, a sworn law enforcement officer, agree that I have not added any CJIS data in this report.

UNIT 1, NORTHBOUND ON CTH A, NORTH OF SHADY LANE ROAD, WENT ONTO THE RIGHT HAND SHOULDER, AN AREA OF SLUSH AND SNOW. UNIT 1 RE-ENTERED THE ROADWAY, CROSSING THE ROADWAY AND INTO THE SOUTHBOUND DITCH, WHERE IT BECAME STUCK. NO APPARENT DAMAGE TO THE VEHICLE. VEHICLE WAS OPERATED BY RO, WHO NOTIFIED CRAIG'S TO REMOVE VEHICLE. VEHICLE WAS TAGGED AND MARKED ON MACH TO BE REMOVED WITHIN 24 HOURS. BY 6:00 PM, THE VEHICLE WAS REMOVED FROM THE DITCH.

6TL09H5JPB
19-01798

WISCONSIN MOTOR VEHICLE
CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMENT
1300 LANGE COURT
BARABOO, WI 53913
(608) 356-4895

Location

ON CTHA NB 0.31 MI N OF SHADY LANE RD IN THE TOWN OF FAIRFIELD IN SAUK COUNTY	Latitude 43.551130063	Longitude -89.738493825
	X Coordinate 278790.84375	Y Coordinate 4825663.5
	Structure Type	

Crash Scene

First Harmful Event DITCH	First Harmful Event Location SHOULDER LEFT	
Manner of Collision NO COLLISION W/VEHICLE IN TRANSPORT	Light Condition DAYLIGHT	
Road Surface Condition(s) WET, SLUSH	Roadway Factor(s) ROAD SURFACE CONDITION (WET, ICY, SNOW, SLUSH, ETC)	
Environment Factor(s) NONE		
Weather Condition(s) CLEAR		
Animal Type	Relation To Trafficway TRAFFICWAY - ON ROAD	
Crash Classification - Location PUBLIC PROPERTY	Crash Classification - Jurisdiction NO SPECIAL JURISDICTION	
Tribal Land	Access Control NO CONTROL	Special Study
Within Interchange Area NO	Junction Location NON-JUNCTION	Intersection Type NOT AN INTERSECTION

Unit Summary

UNIT 01	Unit Status IN TRANSIT	Vehicle Operating As Classification D CLASS		Unit Type AUTOMOBILE	
	Vehicle Type PASSENGER CAR	Operating As Endorsements			
	Total Occs 1	Train/Bus # Recorded	Total # Citations Issued 0	Total Trailers 0	Total HazMat Types 0
	Insurance? UNKNOWN	Direction Of Travel NORTHBOUND	<input type="checkbox"/> Pre CrashTire Mark	Speed Limit 55	Total Lanes 2
	Most Harmful Event: Collision With DITCH	Special Function NO SPECIAL FUNCTION		Emergency Motor Vehicle Use NOT APPLICABLE	
	Traffic Way TWO-WAY, NOT DIVIDED	Traffic Control NO CONTROL		Traffic Control Inoperative/Missing NO	
	Surface Type BLACKTOP (BITUMINOUS)	Road Curvature STRAIGHT		Road Grade UPHILL	
	Truck Bus or HazMat NO				

UNIT 01 VEHICLE	Vehicle			
	License Plate Number 629ZMZ	Plate Type AUT - AUTOMOBILE	St WI	Country of Issuance UNITED STATES
	Vehicle Identification Number KMHD35LE8DU126369	Make HYUNDAI	Year 2013	Model ELANTRA GT
	Color WHI - WHITE	Body Style HB - HATCHBACK		Bus Use NOT A BUS
	Initial Contact Point 12--FRONT	Vehicle Damage		
Extent Of Damage NO DAMAGE	NO DAMAGE			

6TL09H5JPB

19-01798

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMENT
1300 LANGE COURT
BARABOO, WI 53913
(608) 356-4895

UNIT VEHICLE	Towed Due To Damage TOWED BUT NOT DUE TO DISABLING DAMAG		Vehicle Removed By CRAIGS TOWING	
	What Driver Was Doing GOING STRAIGHT		Vehicle Factors	
	Driver Prior Action Other		NOT APPLICABLE	
	Driver Actions EXCEED SPEED LIMIT			
01 01	Owner Name ALYSSA BRITTANY DEAN (608) 495-1350		Owner Address 915 ELLIS AVE # 309 BARABOO, WI 53913 , US	
	Sequence Of Events			
01 02 03 04	Event RUN OFF ROADWAY RIGHT			
	Event REENTERING ROADWAY			
	Event RUN OFF ROADWAY LEFT			
	Event			
UNIT INDIVIDUAL	Individual			
	Driver ALYSSA BRITTANY DEAN (608) 495-1350		Citations Issued 0	Sex FEMALE
	Address 915 ELLIS AVE # 309 BARABOO, WI 53913 , US		Date of Birth	Race
	On Duty Crash		Driver License Number STATE: WISCONSIN COUNTRY: UNITED STATES	
01 001	Safety Equipment		Safety Equipment	
	Seat Position 1--FRONT SEAT-LEFT SIDE (DRIVER/MOTORCY		SHOULDER & LAP BELT	
	Helmet Use		Helmet Compliance	
	Eye Protection		Tint Compliance	
Injury		Injury Severity NO APPARENT INJURY	Airbag NON DEPLOYED	
Ejected NOT EJECTED		Ejection Path NOT EJECTED/NOT APPLICABLE	Trapped/Extricated NOT TRAPPED	
Medical Transport NOT TRANSPORTED		EMS Agency Identifier	EMS Run #	
Hospital		Date of Death	Time of Death	
Distracted By		Distracted By Source NOT APPLICABLE (NOT DISTRACTED)		
Distracted By Action NOT DISTRACTED				
Non Motorist		Striking Unit #	Location	

WISCONSIN MOTOR VEHICLE
CRASH REPORT

UNIT	Prior Action			
	Action			
	Action Other		To/From School	
	Drug & Alcohol	Suspected Alcohol Use NO	Suspected Drug Use NO	
	Alcohol Test Given TEST NOT GIVEN	Alcohol Test Type	Alcohol Test Results	
	Drug Test Given TEST NOT GIVEN	Drug Test Type	Drug Test Results	
	Drug Type			
	Individual Condition APPEARED NORMAL			
	01	001		