

6TL09H5JPH
19-02202



WISCONSIN MOTOR VEHICLE
CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMENT
1300 LANGE COURT
BARABOO, WI 53913
(608) 356-4895

6TL09H5JPH

Document Number Override		Primary Crash Document #	Agency Crash Number 19-02202	Investigating Officer/Deputy DEPUTY S. MESSNER	
Crash Date 02/22/2019		Crash Time 04:35 PM	Date Arrived 02/22/2019	Time Arrived 05:00 PM	
Date Notified 02/22/2019		Time Notified 04:35 PM	Total Units 01	Total Injured 00	Total Killed 00
<input type="checkbox"/> On Emergency	<input type="checkbox"/> Hit and Run	<input type="checkbox"/> Lane Closure	<input type="checkbox"/> Work Zone	<input type="checkbox"/> Trailer or Towed	<input type="checkbox"/> Reporting Threshold
<input type="checkbox"/> Government Property	<input type="checkbox"/> Active School Zone	School Bus Related NO		Tags	
<input checked="" type="checkbox"/> Reportable		Crash Type DT4000 (STANDARD CRASH)		<input type="checkbox"/> Amended	<input type="checkbox"/> Secondary Crash

Description

Diagram  Not to scale  ice from a passing vehicle, eastbound CTH A, westof Lyndon Road	Reconstruction By
	Photos By DEP. S. MESSNER
	Additional Information PHOTOS

I, a sworn law enforcement officer, agree that I have not added any CJIS data in this report.

UNIT 1, BEING OPERATED BY KRISTI MEISTER, WAS WESTBOUND ON CTH P, WEST OF LYNDON ROAD. A MOTOR HOME VEHICLE WAS EASTBOUND AND A PIECE OF ICE CAME OFF OF THE ROOF, STRIKING THE WINDSHIELD AND DRIVER'S SIDE MIRROR. FUNCTIONAL DAMAGE OCCURRED TO UNIT 1 WITHOUT INJURIES TO THE OPERATOR. THE MOTOR HOME TYPE VEHICLE CONTINUED EASTBOUND ON CTH P. PHOTOGRAPHS OF THE VEHICLE WERE TAKEN OF THE VEHICLE AND THE OPERATOR WAS RELEASED. AFTERWARDS, I ATTEMPTED TO LOCATE THE MOTOR HOME IN THE AREA OF THE VILLAGE OF LAKE DELTON, BUT WAS UNSUCCESSFUL IN LOCATING THE VEHICLE.

WISCONSIN MOTOR VEHICLE
CRASH REPORT

Location

ON CTHP WB 811 FT W OF LYNDON RD IN THE TOWN OF DELLONA IN SAUK COUNTY	Latitude 43.590621408	Longitude -89.850536443
	X Coordinate 269890.4375	Y Coordinate 4830354
	Structure Type NO STRUCTURE	

Crash Scene

First Harmful Event STRUCK BY FALLING, SHIFTING CARGO OR ANYTHING SET IN MOTIO		First Harmful Event Location ON ROADWAY	
Manner of Collision NO COLLISION W/VEHICLE IN TRANSPORT		Light Condition DAYLIGHT	
Road Surface Condition(s) DRY		Roadway Factor(s) NONE	
Environment Factor(s) NONE			
Weather Condition(s) CLEAR			
Animal Type		Relation To Trafficway TRAFFICWAY - ON ROAD	
Crash Classification - Location PUBLIC PROPERTY		Crash Classification - Jurisdiction NO SPECIAL JURISDICTION	
Tribal Land		Access Control NO CONTROL	Special Study
Within Interchange Area NO	Junction Location NON-JUNCTION	Intersection Type NOT AN INTERSECTION	

Unit Summary

UNIT	Unit Status IN TRANSIT		Vehicle Operating As Classification D CLASS		Unit Type AUTOMOBILE	
	Vehicle Type (SPORT) UTILITY VEHICLE				Operating As Endorsements	
	Total Occs 1	Train/Bus # Recorded	Total # Citations Issued 0	Total Trailers 0	Total HazMat Types 0	
	Insurance? YES	Direction Of Travel WESTBOUND	<input type="checkbox"/> Pre CrashTire Mark	Speed Limit 55	Total Lanes 2	
	Most Harmful Event: Collision With STRUCK BY FALLING, SHIFTING CARGO OR ANYT		Special Function NO SPECIAL FUNCTION		Emergency Motor Vehicle Use NOT APPLICABLE	
	Traffic Way TWO-WAY, NOT DIVIDED		Traffic Control NO CONTROL		Traffic Control Inoperative/Missing NO	
	Surface Type BLACKTOP (BITUMINOUS)		Road Curvature STRAIGHT		Road Grade LEVEL	
	Truck Bus or HazMat NO					

UNIT	Vehicle						
	01	License Plate Number 267MXE		Plate Type AUT - AUTOMOBILE	St WI	Country of Issuance UNITED STATES	
		Vehicle Identification Number JTJBARBZ1G2089286		Make LEXUS	Year 2016	Model NX	
		Color GRY - GRAY		Body Style UT - SPORT UTILITY VEHICLE		Bus Use NOT A BUS	
	VEHICLE	Initial Contact Point 12--FRONT		Vehicle Damage			
		Extent Of Damage FUNCTIONAL DAMAGE		10--LEFT SIDE FRONT, 12--FRONT			

WISCONSIN MOTOR VEHICLE
CRASH REPORT

UNIT	VEHICLE	Towed Due To Damage NOT TOWED	Vehicle Removed By OPERATOR	
		What Driver Was Doing GOING STRAIGHT	Vehicle Factors	
		Driver Prior Action Other	NOT APPLICABLE	
		Driver Actions NO CONTRIBUTING ACTION		
01	01	Owner Name KRISTI MEISTER	Owner Address REEDSBURG, WI 53959 , US	
		Sequence Of Events		
01	01	Event STRUCK BY FALLING, SHIFTING CARGO OR ANYTHING SET IN MOTION BY MOTOR VEHICLE		
		Event		
		Event		
		Event		
01	01	Policy Holder		
		Insurance Company AMERICAN-FAMILY-INS-CO	Individual KRISTI MEISTER	
01	01	Individual		
		Driver KRISTI MEISTER	Citations Issued 0	Sex FEMALE
			Date of Birth	Race WHITE
		Address REEDSBURG, WI 53959 , US	Driver License Number STATE: WISCONSIN COUNTRY: UNITED STATES	
01	001	Safety Equipment		
		On Duty Crash	Safety Equipment	
		Seat Position 1--FRONT SEAT-LEFT SIDE (DRIVER/MOTORCY	SHOULDER & LAP BELT	
		Helmet Use	Helmet Compliance	
		Eye Protection	Tint Compliance	
		Injury	Injury Severity NO APPARENT INJURY	Airbag NON DEPLOYED
Ejected NOT EJECTED	Ejection Path NOT EJECTED/NOT APPLICABLE	Trapped/Extricated NOT TRAPPED		
Medical Transport NOT TRANSPORTED	EMS Agency Identifier	EMS Run #		
Hospital	Date of Death	Time of Death		
Distracted By		Distracted By Source NOT APPLICABLE (NOT DISTRACTED)		
Distracted By Action		NOT DISTRACTED		

WISCONSIN MOTOR VEHICLE
CRASH REPORT

UNIT	INDIVIDUAL	Non Motorist		Striking Unit #	Location	
		Prior Action				
	Action					
	Action Other				To/From School	
	01	001	Drug & Alcohol		Suspected Alcohol Use NO	Suspected Drug Use NO
			Alcohol Test Given TEST NOT GIVEN	Alcohol Test Type	Alcohol Test Results	
			Drug Test Given TEST NOT GIVEN	Drug Test Type	Drug Test Results	
			Drug Type			
			Individual Condition APPEARED NORMAL			